

11

INS. CASE OWNER:

CC<sup>3</sup>/QBE19016489, 12/10/19 LKK:  
IDAC:

Surveyor:

KALVIN

DOI:

ASSIGNMENT

17/11/19

Date / Time:

17/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 7AB7U

Claim No.:

VLO1296

Name of Insured:

NITON FOOD &amp; BEVERAGE SPECIALISTS

Policy No.:

8-V011042-MRA-R103

Insured Tel No.:

HP:

VIL

Make / Model:

TOYOTA

Excess Sec II :\$5

D.O.A.:

13/11/19

Place of Accident:

Along Sembawang Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

YU HENG GUAN

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final? Yes / No

SHC 29870

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:CDE  
WINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE/ PIC
SHC 29870-13/11/19 15:15/17/11/19	Non-Reporting 1st:	
GBD 7AB7U-14/11/19 10:00/17/11/19	Non-Reporting 1st (2nd):	
	Non-Reporting 1st (Final):	
	Notification 1st (if non-pickup):	
	Call OI:	17/11/19
	After call 1st to OI:	
21.10.19	Documentation Check List:	Handler Typist
	Notification 1st (if non-pickup)	<input type="checkbox"/>
	After call 1st to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	PIP \$5,416.68	( 3 days) Reduction:	25 %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	\$5,046.85	OO 4th TP STATIONARY VEH.	
Loss of Rental (LOR):	\$5,901.76	( 7 days) x \$139.68	
Loss of Use (LOU):	\$5 -	(5 x days)	
Loss of Income (LOI):	\$5,350.00	(530 x 7 days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOI <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/>	(Tick only one)		
GIA/LTA Search	\$5 -		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5,304.61	Global Sum \$5:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$5,304.61	Name 1:	CONFIDENTIAL ENGINEERING PTE LTD
Payee 2 (Strike if N.A.)	\$5	Name 2:	
Payee 3 (Strike if N.A.)	\$5	Name 3:	

COPY SENT  
11/12/19





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/QBE19016489/K1eb3

Date: 18.09.2019

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC2987D**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.09.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,291.24
Revised Estimate Amount	: S\$	4,716.68
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:  
The vehicle sustained damages at the  
O/S Front portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## REPAIR ESTIMATE

VEHICLE NO : SHC 2987P

MAKE :

MODEL : TOYOTA PRIUS

CBE - cp/p) TS

DATE : 17.09.2019

LKK - Calvin

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FENDER SUB-ASSY, FRONT RH			\$ 945.30	
FRONT FENDER SHIELD, RH	X		\$ 196.60	
FRONT FENDER SHIELD CLIP	X		\$ 3.80	
FRONT FENDER HYBRID EMBLEM, RH			\$ 53.50	
PANEL SUB-ASSY, FRONT DOOR, RH			\$ 1,264.00	
MIRROR ASSY, OUTER REAR VIEW, RH			\$ 1,390.10	
CENTRE ROCKER PANEL (GARNISH)			\$ 576.00	
FRONT PILLAR UPPER COVER, RH	X		\$ 96.00	
SUB TOTAL			\$ 4,525.30	
LESS 20% DISCOUNT			\$ 905.06	
DISCOUNTED TOTAL			\$ 3,620.24	
FRONT DOOR COMFORT LOGO			\$ 75.00	NETT
REAR DOOR COMFORT & APPS STICKER			\$ 80.00	NETT
FRONT WINDSCREEN SEALANT	X		\$ 46.00	NETT
			\$ 201.00	
LABOUR CHARGE				
Panel Beating			\$ 1,000.00	
Spray Painting Charge			\$ 1,200.00	
Wiring Charge			\$ 50.00	
Tuff Kote			\$ 100.00	
Transfer of Door			\$ 120.00	
TOW FEE			\$ 60.00	
TOTAL LABOUR			\$ 2,470.00	
ESTIMATE TOTAL			\$ 6,291.24	

\$320/Day

K. L. 1/10/19

17/9/19

3 Days

1100 hr

PIP

Behr

Paint ph

640

650

20

50

50

60 nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305333559

Date : 20/09/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC2987D

Date of Accident : 13-Sep-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: QBE INSURANCE --- GBD7967U
- The finalized amount shall be:
 

(a) Spare Parts after List discount	\$3,246. <sup>68</sup> <del>00</del>
(b) Labour Charges	\$1,470.00
<b>Total for Part-By-Part Repair Cost</b>	<b>\$4,716.<sup>68</sup><del>00</del></b>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
<b>Final Lumpsum Repair cost</b>	

- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 23/9/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305333559  
 REGN NO : SHC2987D  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 14.03.2019  
 DATE/TIME IN : 13.09.2019 16:05  
 ACCIDENT DATE : 13.09.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-0573-G	FRT FENDER RH	1	945.30	25.00	708.97
0002 04-01-0302-2297-G	FRT FENDER (HYBRID) RH	1	53.50	25.00	40.12
0003 04-01-0302-0592-G	FRT DOOR RH	1	1,264.00	25.00	948.00
0004 04-01-0302-0594-G	WING MIRROR RH	1	1,390.10	25.00	1,042.57
0005 28-01-0103-0003-A	Frt Door COMFORTDELGRO RH	1	75.00		75.00
0006 04-01-0302-0810-G	CTR ROCKER PANEL GARNISH	1	576.00	25.00	432.00

SUB-TOTAL : 3,246.66

## JOB NATURE

0000 PB	PANEL BEATING	640.00
0001 SP	SPRAYPAINT CHARGE	650.00
0002 17-01	WIRING CHECK	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00
0004 L	TRANSFER OF DOOR	50.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.09.2019

REPAIR ESTIMATE

Time: 13:44:24

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305333559  
REGN NO : SHC2987D  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 14.03.2019  
DATE/TIME IN : 13.09.2019 16:05  
ACCIDENT DATE : 13.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 23-01 TOWING FEE 60.00

SUB-TOTAL : 1,470.00

TOTAL : 4,716.66

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE  
DATE :

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Date: 13/09/19

Time Received:

☐ New

☐ SPARK Kakis

Name of Customer :

James Au

Contact No. :

97355632

Vehicle No. :

SHC2987D

Make / Model / Colour :

Email :

3. Vehicle Type:

☐ Private

☒ Taxi (CTPL/CCPL)

☐ Fleet

☐ STK (Boon Lay)

4. Type of Towing:

☒ Normal Tow

☐ King Dolly

☐ Flat Bed

☐ Crane-up

5. Nature of Service:

☐ Jumpstart

☒ Recovery

☐ Change Tyre / Battery

6. Parts Replaced/Remarks:

Location:

595 Serangoon Rd

Preferred Workshop:

☐ Braddell

☒ Loyang

☐ Pandan

☐ Sin Ming

☐ Sungei Kadut

☐ Ubi

☐ Senoko

☐ Komoco (UBI / Leng Kee)

☐ Cycle & Carriage (PD)

☐ Others:

8. Vehicle Tow - In Workshop:

☐ Smoky Exhaust

☐ Wheel Jammed

☐ Overheating

☐ Steering Faulty

☐ Brake Faulty

☐ Alternator Faulty

☐ Starting Problem

☐ Loss Power

☐ Accident

☐ Engine Stalled

☐ Return Taxi

0. Odometer Reading :

Fuel Level :

F

1/4

1/2

3/4

E

11. Radio / CD Player

☒ OK

☐ Faulty

☐ Not tested

2. Tow Truck / Recovery Van :

☐ VRS

☐ QA

☐ GAO

☒ TZ

☐ YISHUN

☐ OTHERS

Name of Driver :

Radiy Liao

Vehicle No. :

YH7944K

Time Dispatch :

1644

Time of Arrival :

1645

Time Completed :

ash Invoice Details (if applicable)

3. Cash Invoice No. :

Customer Acknowledgement

I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.  
I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.  
Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time


Signature of Customer

1. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard



# : Cracked X : Dented  
/ : Scratched O : Missing

Signature of Customer



Need Taxi Replacement

Assignment of High Liability Case  
To SubcontractorCOMFORTDELGRO  
ENGINEERING

ComfortDelGro Engineering Pte Ltd

200 Bras Basah Road Singapore 179701

Marine + 65 (6393 6285) Facsimile + 65 (6280 6700)

Workshops

58 Looing Drive Singapore 108899

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 108206

Tel: 6393 6285

14 Serangoon Road Singapore 756156

7 Serangoon Road Singapore 728791

301 Yew Tee Industrial Park A Singapore 760735

member of COMFORTDELGRO

Date/Time: 16.09.2019 16:33

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305333559

MER

COMFORT TRANSPORTATION PTE LTD  
7010045

MER NO.

383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (O)

SS

(R)

(P)

REGN NO.:

SHC2987D

MILEAGE

MAKE:

TOYOTA

FUEL

E 1/2 F

MODEL:

PRIUS HYBRID(G4)13.09.2019 16:05

DATE/TIME IN

YR OF MANU.

14.03.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU003079571

COMPLETION DATE/TIME

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 13.09.2019  
NATURE: 3P 13.09.19

QBE - GBD 7967U

S/NO

LABOR CODE

DESCRIPTION



CHECKED &amp; PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.:

SHC2987D

LIMITS

Vehicle No.:

SHC2987D

## REPAIR ESTIMATE

VEHICLE NO: SHC 2987P

MAKE :

**MODEL : TOYOTA PRIUS**

DATE : 17.09.2019

LKK - Calvin

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	FENDER SUB-ASSY, FRONT RH ✓			\$ 945.30	
	FRONT FENDER SHIELD,RH ✕			\$ 196.60	
	FRONT FENDER SHIELD CLIP ✕			\$ 3.80	
	FRONT FENDER HYBRID EMBLEM, RH ✓			\$ 53.50	
	PANEL SUB-ASSY, FRONT DOOR, RH ✓			\$ 1,264.00	
	MIRROR ASSY, OUTER REAR VIEW, RH ✓			\$ 1,390.10	
	CENTRE ROCKER PANEL (GARNISH) ✕			\$ 576.00	
	FRONT PILLAR UPPER COVER, RH ✕			\$ 96.00	
	SUB TOTAL			\$ 4,525.30	
	LESS 20% DISCOUNT			\$ 905.06	
	DISCOUNTED TOTAL			\$ 3,620.24	
	FRONT DOOR COMFORT LOGO ✓			\$ 75.00	NETT
	REAR DOOR COMFORT & APPS STICKER ✕			\$ 80.00	NETT
	FRONT WINSCREEN SEALANT ✕			\$ 46.00	NETT
				\$ 201.00	
	LABOUR CHARGE				
	Panel Beating			\$ 1,000.00	
	Spray Painting Charge			\$ 1,200.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 100.00	
	Transfer of Door			\$ 120.00	
	TOW FEE			\$ 2,470.00	
	TOTAL LABOUR			\$ 2,470.00	
	ESTIMATE TOTAL			\$ 6,291.24	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## Shu Pei (LKKAUTO)

---

**From:** Janice Goh Siew Geok <janice.goh@qbe.com>  
**Sent:** Tuesday, 24 September 2019 11:49 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving GBD7967U (OI : QBE - VC012996/JG) AND SHC2987D (TP : LKK REF - CC3/QBE19016489/K1eb3) on 13.09.2019  
**Attachments:** GBD7967 - VC012996.pdf

Hi Shu Pei

Our insured has reported. Please see attachment.  
Thank you.

---

**Janice Goh**  
Executive, Claims  
Claims | Asia  
1 Raffles Quay, #29-10 South Tower, Singapore 048583  
+65 6477 1243  
[Website](#) [LinkedIn](#) [Twitter](#)



---

**From:** Janice Goh Siew Geok  
**Sent:** Wednesday, 18 September 2019 5:22 PM  
**To:** Shu Pei (LKKAUTO) <shupeil@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>  
**Subject:** RE: Direct Settlement - Accident Involving GBD7967U (OI : QBE - VC012996/JG) AND SHC2987D (TP : LKK REF - CC3/QBE19016489/K1eb3) on 13.09.2019

Hi Shu Pei

Our insured has not reported the accident to us yet.  
We will forward to you upon receiving.

Thank you.

---

**Janice Goh**  
Executive, Claims  
Claims | Asia  
1 Raffles Quay, #29-10 South Tower, Singapore 048583  
+65 6477 1243  
[Website](#) [LinkedIn](#) [Twitter](#)



---

**From:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>  
**Sent:** Wednesday, 18 September 2019 5:06 PM  
**To:** Jenny Toh <[jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)>; Janice Goh Siew Geok <[janice.goh@qbe.com](mailto:janice.goh@qbe.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Subject:** Direct Settlement - Accident Involving GBD7967U (OI : QBE - TBA) AND SHC2987D (TP : LKK REF - CC3/QBE19016489/K1eb3) on 13.09.2019

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 2987D at M/s ComfortDelGro Engineering Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----- IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

**Foodex Central Kitchen**

Astons Specialities Food &amp; Beverages Pte Ltd

**INCIDENT REPORT**

NAME:	Yu Cheng Qiang		ID/FIN NO.	G2689043N
DEPARTMENT:	Foodex CK kitchen	POSITION:	Driver	DATE JOINED
				14/8/2015

TO: Frankie Yeo  
GENERAL MANAGER

**Details of Damage or Occurrence**

RE: Company Lorry GBD7967U Collided Side by Side with Comfort Taxi SHC2987D @ opposite SSC, Shell Petrol Kiosk exit path(left lane).

*Yu cheng Qiang*


On 13 September 2019, at 4.06 – 4.20pm, our driver Yu was driving company lorry (GBD7967U) was putting diesel at opposite sembawang shopping centre, shell petrol kiosk, on right exit path as picture shown, as driver Yu Cheng Qiang said taxi had move out from petrol kiosk as he turn right to check his blind-spot before moving out, to his surprise, driver Yu suddenly hit the side of comfort taxi on outer lane (left) (please see pic attached)

Our driver Yu, did not realized or saw the taxi is stopping somehow, collided side by side and both vehicles reversed 1-1.5M back to inner part on the side of the petrol kiosk to prevent traffic Jam at that time. (please see pic attached)

Driver Yu did claimed and respond that he didn't realized it, why taxi driver sudden stop just right in front of his lorry (left lane), our lorry need slightly more space when exiting on left lane where at that point lorry need wider space to turn out if he know/could see he could have act to stop immediate.

At that point, comfort taxi driver should not stop for any reasons when moving out/stationary/did not putting any hazard light is on

Both Drivers are unhurt at that point of time.

  
Ken Ang  
Production Manager

Regards,  
Ken Ang  
Production Manger  
Foodex Central Kitchen



# Status of Driving Licence

## Qualified Driving Licence

**Qualified Driving Licence Number**

G2689043N

**Status of Qualified Driving Licence**

Valid

**Class(es) of Qualified Driving Licence**

3C,3

**Expiry Date**

21/10/2020

## Provisional Driving Licence

**Provisional Driving Licence Number**

G2689043N

**Status of Provisional Driving Licence**

No Licence

**Class(es) of Provisional Driving Licence**

**Expiry Date**

-

HOME (<https://www.police.gov.sg/>)

ABOUT US (<https://www.police.gov.sg/about-us>)

SGSECURE (<https://www.police.gov.sg/sgsecure>)

I-WITNESS (<https://www.police.gov.sg/iwitness>)

COMMUNITY PROGRAMMES (<https://www.police.gov.sg/community-programme>)

RESOURCES (<https://www.police.gov.sg/resources>)

NEWS & PUBLICATIONS (<https://www.police.gov.sg/news-and-publications>)

**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Wednesday, 16 October 2019 2:43 PM  
**To:** Catherine Koh Mui Gek  
**Subject:** Your Ref:T0919/SHC2987D/WT(st), ACCIDENT INVOLVING SHC 2987D AND GBD 7967U ON 13/09/2019  
**Attachments:** OI SKETCH PLAN.pdf

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Your Ref:T0919/SHC2987D/WT(st)

Without Prejudice

Hi Sir,

We refer to the above matter.

**ACCIDENT INVOLVING SHC 2987D AND GBD 7967U ON 13/09/2019**

Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We would like to request a copy of your client video footage.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [asher.sng@lkkauto.com](mailto:asher.sng@lkkauto.com) | fax: 6741-4108


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC3/QBE19016489/K1ea3q2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 10-01-2020	
			Code : QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 7967U	Veh. Inspected	SHC 2987D	
Policy No.	8-V0013042-MVA-R003	Coverage (\$)	0.00	
Claim No.	VC012996	Excess (\$)	0.00	
Assign From		Assign Date	17/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU003079571	Colour	BLUE	
Odometer	55870	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	9 mm	
L/H Front Tyre	195/65 R15	DAVANTI	9 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	9 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/09/2019	Inspection Date	17/09/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2987D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FENDER SUB-ASSY ,FRONT RH	BUCKLED	945.30	945.30
1	FRONT FENDER SHIELD ,RH	SERVICEABLE	196.60	-
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	3.80	-
1	FRONT FENDER HYBRID EMBLEM ,RH	NECESSARY	53.50	53.50
1	PANEL SUB-ASSY ,FRONT DOOR ,RH	BUCKLED	1,264.00	1,264.00
1	MIRROR ASSY ,OUTER REAR VIEW ,RH	CRACKED	1,390.10	1,390.10
1	CENTRE ROCKER PANEL (GARNISH)	CRACKED	576.00	576.00
1	FRONT PILLAR UPPER COVER ,RH	SERVICEABLE	96.00	-
	LESS 20% DISCOUNT		-905.06	-
	LESS 25% DISCOUNT		-	-1,057.22
			3,620.24	3,171.68
<b>SPECIAL NETT ITEMS</b>				
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT & APPS STICKER (SN)	NOT NECESSARY	80.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			201.00	75.00
<b>LABOUR</b>				
	PANEL BEATING.		1,000.00	640.00
	SPRAY PAINTING CHARGE.		1,200.00	650.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		100.00	50.00
	TRANSFER OF DOOR .		120.00	50.00
	TOWING FEE.		60.00	60.00
			-	-
			-	-
			-	-
			2,530.00	1,470.00
<b>GRAND TOTAL</b>			<b>6,351.24</b>	<b>4,716.68</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,716.68</b>

Report Ref No. CC3/QBE19016489/K1ea3q2



Report Ref No. CC3/QBE19016489/K1ea3q2

A handwritten signature in black ink, appearing to be 'Calvin'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.