

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19016494/APS3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00003866-01

Claimant
Vehicle No : SLF575J **Insured Vehicle No :** SKC6802S

Date of Loss: 13/09/2019 Nature of Claim: TP Claim No: 1201900027598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF575J**
 Make & Model: HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A) Engine No: G4FJJU496101
 Reg. Date: 12/10/2018 (Man. Year: 2018) Chassis No: KMHJ3812VKU805263
 Colour: Brown Odometer: 15620 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,046.16	9,036.96	6,009.20	39.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,460.00	1,940.00	57.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,446.16	10,496.96	7,949.20	43.09
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	18,446.16	8,400.00	10,046.16	54.46
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		9,029.00		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 17/09/2019

Date Inspected: 19/09/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2020)
Parts: M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF575J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	785.60 FL	*785.60 FL
2	1		*FRONT BUMPER LOWER	Cut	502.70 FL	*502.70 FL
3	1		*FRONT BUMPER LIP	Not Necessary	168.70 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	256.30 FL	*- FL
5	1		*FRONT BUMPER BRACKET	Not Necessary	98.70 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	788.90 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	288.70 FL	*- FL
8	1		*FRONT BUMPER LOWER STIFFENER	Not Necessary	205.30 FL	*- FL
9	1		*FRONT BUMPER RETAINERS LH	Necessary	65.70 FL	*65.70 FL
10	1		*FRONT RADIATOR GRILLE	Not Necessary	598.70 FL	*- FL
11	1		*FRONT RADIATOR GRILLE TOP COVER	Not Necessary	108.30 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Cracked	958.30 FL	*958.30 FL
13	1		*FRONT HEADLAMP LH	Cut	5,867.80 FL	*5,867.80 FL
14	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	78.90 FL	*- FL
15	1		*FRONT FOG LAMP LH	Cut	765.80 FL	*765.80 FL
16	1		*FRONT FOG LAMPS LOWER COVER LH	Not Necessary	97.80 FL	*- FL
17	1		*FRONT FOG LAMPS UPPER COVER LH	Cut	98.60 FL	*98.60 FL
18	1		*FRONT FENDER LH	Dented	697.20 FL	*697.20 FL
19	1		*FRONT FENDER ARCH GARNISH LH	Cut	198.70 FL	*198.70 FL
20	1		*FRONT FENDER INNER COWLING LH	Torn	205.80 FL	*205.80 FL
21	1		*FRONT DRIVEDSHAFT LH	Not Necessary	1,216.80 FL	*- FL
22	1		*FRONT KNUCKLE ARM LH	Not Necessary	438.90 FL	*- FL
23	1		*FRONT WHEEL HUB BEARING LH	Not Necessary	586.30 FL	*- FL
24	1		*FRONT LOWER ARM LH	Not Necessary	458.70 FL	*- FL
25	1		*FRONT ABSORBER LH	Not Necessary	423.60 FL	*- FL
26	1		*FRONT ABSORBER TOP MOUNTING LH	Not Necessary	198.70 FL	*- FL
27	1		*FRONT ABSORBER TOP BEARING LH	Not Necessary	125.80 FL	*- FL
28	1		*FRONT STABILIZER BAR LH	Not Necessary	298.70 FL	*- FL
29	1		*FRONT STABILIZER LINK LH	Not Necessary	187.90 FL	*- FL
30	1		*STEERING TIE ROD	Not Necessary	197.60 FL	*- FL
31	1		*STEERING TIE ROD END	Not Necessary	125.70 FL	*- FL
32	1		*FRONT SPORT RIM LH	Cut	950.00 FS	*800.00 FS
33	1		*SET FRONT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
34	1		*SET FRONT BUMPER CLIPS	Cut	30.00 FS	*30.00 FS
35	1		*SET FRONT LOWER BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*SET FRONT SENSORS	Not Necessary	250.00 FS	*- FS
37	1		*FRONT FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
38	1		*SET FRONT FENDER INNER COWLING	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,465.20	11,066.20
- List Item Discount on L Items 20.00/20.00% (\$)	3,419.04	2,029.24
Total Parts (\$)	15,046.16	9,036.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,200.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	30.00
4	TO REMOVE AND REFIT CONDENSER TO FACILITATE SUPPORT PANEL REPLACEMENT	New	120.00	120.00
5	TO REMOVE AND REFIT /REPLACE FRONT UNDERCARRIAGE	New	350.00	0.00
6	TO PERFORM COMPUTERISED ALIGNMENT BEFORE AND AFTER	New	180.00	80.00
7	TO CONDUCT WIRING CHECK ON THE FRONT HEADLAMP AND SETTING	New	150.00	30.00
			Gross Labour Cost (S\$)	3,400.00
				1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >