



# CAS GARAGE PTE LTD

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

## VEHICLE REPAIR ESTIMATE

Insurance Company: FWD SINGAPORE PTE LTD

Address: 6, TEMASEK BOULEVARD, #18-01  
SUNTEC TOWER FOUR, S(038986)

Xiao Tong

Telephone: 68208888

Fax:

Email [contact.sg@fwd.com](mailto:contact.sg@fwd.com)

Make/ Model : HYUNDAI TUCSON

Date: 18.09.2019

Chassis No : KMHJ3812VKU805263

Vehicle No: SLF575J

Date/Time of Accide 13.09.2019/1120

DATE OF REG: 12.10.2018

### Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Rebond</i>	1	\$ 785.60		\$ ✓ 785.60
2	FRONT BUMPER LOWER <i>ut</i>	1	\$ 502.70		\$ ✓ 502.70
3	FRONT BUMPER LIP <i>neu</i>	1	\$ 168.70		\$ ✗ 168.70
4	FRONT BUMPER SPONGE <i>face</i>	1	\$ 256.30		\$ ✗ 256.30
5	FRONT BUMPER BRACKET	1	\$ 98.70		\$ ✗ 98.70
6	FRONT BUMPER REINFORCEMENT <i>neu</i>	1	\$ 788.90		\$ ✗ 788.90
7	FRONT BUMPER LOWER GRILLE <i>neu</i>	1	\$ 288.70		\$ ✗ 288.70
8	FRONT BUMPER LOWER STIFFENER <i>neu</i>	1	\$ 205.30		\$ ✗ 205.30
9	FRONT BUMPER RETAINERS LH <i>neu</i>	1	\$ 65.70		\$ ✓ 65.70
10	FRONT RADIATOR GRILLE <i>neu</i>	1	\$ 598.70		\$ ✗ 598.70
11	FRONT RADIATOR GRILLE TOP COVER <i>neu</i>	1	\$ 108.30		\$ ✗ 108.30
12	FRONT SUPPORT PANEL <i>neu bonded</i>	1	\$ 958.30		\$ ✗ 958.30
13	FRONT HEADLAMP LH <i>ut</i>	1	\$ 5,867.80		\$ ✓ 5,867.80
14	FRONT HEADLAMP BRACKETS LH <i>neu</i>	1	\$ 78.90		\$ ✗ 78.90
15	FRONT FOGLAMP LH <i>ut</i>	1	\$ 765.80		\$ ✓ 765.80
16	FRONT FOGLAMPS LOWER COVER LH <i>neu</i>	1	\$ 97.80		\$ ✗ 97.80
17	FRONT FOGLAMPS UPPER COVER LH <i>ut</i>	1	\$ 98.60		\$ ✓ 98.60
18	FRONT FENDER LH <i>Dented</i>	1	\$ 697.20		\$ ✓ 697.20
19	FRONT FENDER ARCH GARNISH LH <i>ut</i>	1	\$ 198.70		\$ ✓ 198.70
20	FRONT FENDER INNER COWLING LH <i>neu</i>	1	\$ 205.80		\$ ✓ 205.80
21	FRONT DRIVESHAFT LH <i>neu</i>	1	\$ 1,216.80		\$ ✗ 1,216.80
22	FRONT KNUCKLE ARM LH <i>neu</i>	1	\$ 438.90		\$ ✗ 438.90
23	FRONT WHEEL HUB BEARING LH <i>neu</i>	1	\$ 586.30		\$ ✗ 586.30
24	FRONT LOWER ARM LH <i>neu</i>	1	\$ 458.70		\$ ✗ 458.70
25	FRONT ABSORBER LH <i>neu</i>	1	\$ 423.60		\$ ✗ 423.60
26	FRONT ABSORBER TOP MOUNTING LH <i>neu</i>	1	\$ 198.70		\$ ✗ 198.70
27	FRONT ABSORBER TOP BEARING LH <i>neu</i>	1	\$ 125.80		\$ ✗ 125.80
28	FRONT STABILIZER BAR LH <i>neu</i>	1	\$ 298.70		\$ ✗ 298.70
29	FRONT STABILIZER LINK LH <i>neu</i>	1	\$ 187.90		\$ ✗ 187.90
30	STEERING TIE ROD	1	\$ 197.60		\$ ✗ 197.60
31	STEERING TIE ROD END	1	\$ 125.70		\$ ✗ 125.70

Part Price checked

800(8N)

32	FRONT SPORT RIM LH <i>wt</i>	1	\$ 1,187.50	\$ <del>1,187.50</del>
<b>Total List Price Cost</b>				\$ 18,282.70
				\$ 14,626.16

10146.20  
8116.96  
S.N. 800

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>wt</i>	1 SET	\$ 50.00	\$ + 50.00
2	FRONT BUMPER CLIPS <i>wt</i>	1 SET	\$ 30.00	\$ ✓ 30.00
3	FRONT LOWER BUMPER CLIPS <i>wt</i>	1 SET	\$ 30.00	\$ ✓ 30.00
4	FRONT SENSORS <i>wt</i>	1 SET	\$ 250.00	\$ + 250.00
5	FRONT FENDER ARCH GARNISH CLIPS <i>wt</i>	1 SET	\$ 30.00	\$ ✓ 30.00
6	FRONT FENDER INNER COWLING SET <i>wt</i>	1 SET	\$ 30.00	\$ ✓ 30.00
<b>Total Special Nett Items</b>				\$ 420.00

120

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS		\$ 1,200.00
		<i>800</i>
Spray Painting		Quotation
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 1,200.00
		<i>400</i>
Others Cost (Accident Repair Related Expenses)		Quotation
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ <del>300</del> 200.00
TO REMOVE AND REFIT CONDENSER TO FACILITATE SUPPORT PANEL REPLACEMENT		\$ ✓ 120.00
TO REMOVE AND REFIT/ REPLACE FRONT UNDERCARRIAGE		\$ + 350.00
TO PERFORM COMPUTERISED ALIGNMENT BEFORE AND AFTER		\$ <del>80</del> 180.00
TO CONDUCT WIRING CHECK ON THE FRONT HEADLAMP AND SETTLING		\$ <del>30</del> 150.00
<b>Total Others Cost</b>		\$ 1,000.00
<b>GRAND TOTAL</b>		\$ 18,446.16

1460

**CAS GARAGE PTE LTD**  
 UEN 201828067M  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan  
 Direct Contact: +65 8782 7171  
 Email: allangoh.cas@gmail.com  
 Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lij  
 H/S. 19/09/19.

06 Days

total 10496.96

l/s: 8AK

8AK