

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AXA Insurance

Date 25/7/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLP9741J

Chassis No: JM6BN22A8H0158661

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 18/09/2019

YOUR INSURED VEHICLE NUMBER :CB6283P

MILEAGE : km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear bonnet / <i>Puc</i>	1PC	\$ 1,005.30	\$1,005.30	/
2	Rear windscreen / <i>SM</i>	1PC	\$ 1,015.50	\$ 1,015.50	/
3	Rear boot M emblem / <i>MC</i>	1PC	\$ 78.50	\$78.50	/
4	Rear boot Mazda emblem / <i>MC</i>	1PC	\$ 56.10	\$56.10	/
5	Rear boot Skyactiv emblem / <i>MC</i>	1PC	\$ 66.80	\$66.80	/
6	R/L taillamp / <i>Cut</i>	1PC	\$ 534.90	\$534.90	/
7	R/L taillamp reflector / <i>Cut</i>	1PC	\$ 278.30	\$ 278.30	/
8	R/R taillamp / <i>Cut</i>	1PC	\$ 534.90	\$ 534.90	/
9	R/R taillamp reflector / <i>Cut</i>	1PC	\$ 278.30	\$ 278.30	/
10	Rear boot weatherstrip / <i>Tw</i>	1PC	\$ 180.23	\$180.23	157
11	Rear bumper LH retainer / <i>le</i>	1PC	\$ 76.10	\$76.10	37
12	Rear bumper RH retainer / <i>NN</i>	1PC	\$ 76.10	\$76.10	X
13	Rear boot lock / <i>BT</i>	1PC	\$ 160.70	\$160.70	/
14	Rear boot lock catch / <i>BT</i>	1PC	\$ 35.10	\$35.10	/
15	Rear bumper reinforcement / <i>BT</i>	1PC	\$ 564.20	\$564.20	/
16	Rear bumper / <i>ORA</i>	1PC	\$ 1,287.60	\$1,287.60	1050
17	Rear bumper LH reflector / <i>Cut</i>	1PC	\$ 75.50	\$75.50	/
18	Rear bumper RH reflector / <i>NN</i>	1PC	\$ 75.50	\$75.50	X
19	Rear end panel top garnish / <i>le</i>	1PC	\$ 180.23	\$180.23	90
20	Rear end panel / <i>BT</i>	1PC	\$ 530.4	\$530.40	/
21	Rear bumper RH tow cover / <i>NN</i>	1PC	\$ 35.00	\$35.00	X
22	R/L fender / <i>BT</i>	1PC	\$ 1,233.63	\$ 1,233.63	1180
				\$7,125.26	7728.5
				Less 20%	\$1,425.05
				Total	\$5,700.21
					6182.8

S/Nett

1	Windscreen sealant / <i>MC</i>	\$120.00	40
2	Rear number plate / <i>NN</i>	\$60.00	X
3	Body sealant / <i>NN</i>	\$200.00	X
4	DECAL / <i>MC</i>	\$20.00	/
Total		\$400.00	60

LABOUR CHARGES

- | | | | |
|---|--|------------|----------|
| 1 | To labour charge for removing rear boot, rear end pane and rear bumper out to facilitate repairs and replacement of parts. Also include cuuting out R/L fender out to facilitate replacement of damaged part | \$1,600.00 | 1 Sac |
| | To remove and install rear seat and upholstery out to facilitate repairs and replacement of parts | \$200.00 | 60. |
| 2 | To respray rear boot, rear bumper, end panel , R/L fender and spare tyre panel | \$1,400.00 | 1000. |
| 3 | Transfer rear boot mechanism | \$100.00 | 40. |
| 4 | To remove and install rear windscreen | \$120.00 | 100. ✓ |
| 5 | To provide transport to send car for DECAL | \$100.00 | 50. X NV |

Towing Fee \$45-W ✓

2815
2765

LABOUR TOTAL S\$:	\$3,520.00
TOTAL S\$:	\$9,220.21
7% GST	\$484.00
GRAND TOTAL S\$:	<u>\$9,620.21</u>

\$007.8

8 Days.

part by part.

before paint photos.

Guo Qiap - 82880282

20/9/19.

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>
