

MBM WHEELPOWER PTE LTD

Your Ref: SHC1151E

Our Ref: SKG4842T



To: India Insurance International Pte Ltd

CC

Email

Fax

Date: 13.09.2019

From: Eryx Tan

Fax: 6452 5333

Contact: 8318 7188

Make / Model: BMW 640i

Chassis No.: 14517975N55B30A

Engine No.: WBALW32050C799084

Year of Make: 2011

Accident Date: 13.09.2019

ESTIMATE FOR VEHICLE NO. : SKG4842T

DESCRIPTION	PART NUMBER	QTY	List Price
REAR BUMPER - M SPORT	511280527085	1	\$ 2,650.00
REAR BUMPER RETAINER - LH	51128050385	1	\$ 95.00
REAR BUMPER RETAINER - CENTER	51127223161	1	\$ 125.00
REAR BUMPER TOW HOOK COVER	51128052679	1	\$ 55.00
REAR BUMPER LOWER SPOILER	HAMANN	1	\$ 1,500.00
REAR BUMPER BOTTOM GUIDE - CENTER	51127223162	1	\$ 75.00
REAR BUMPER BOTTOM GUIDE - REAR	51128050516	1	\$ 160.00
REAR BUMPER REFLECTOR - LH	63147844023	1	\$ 85.00
REAR BUMPER REINFORCEMENT	51127223159	1	\$ 1,050.00
REAR BUMPER SPONGE	51127223160	1	\$ 120.00
REAR BUMPER INSULATION LH - 1	51487223431	1	\$ 125.00
REAR BUMPER INSULATION LH - 2	51487223432	1	\$ 195.00
TAIL LAMP LH	632172100575	1	\$ 1,250.00
EXHAUST MUFFLE - EISENMANN	EISENMANN	1	\$ 3,600.00
REAR BUMPER SENSOR	66209275704	2	\$ 500.00
REAR BUMPER SENSOR RING	66209142107	2	\$ 180.00
TOTAL:			\$ 11,765.00
LESS 10%:			\$ (1,176.50)
PARTS TOTAL:			\$ 10,588.50

SPECIALL NETT

ANTIRUST COATING	\$	80.00
STICKER WRAP	\$	800.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	1,000.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	80.00
TO REMOVE & REPLACE EXHAUST PIPE SYSTEM	\$	120.00
TO CHECK & RECONNECT ALL WIRING	\$	50.00
TO SPRAY PAINT ON THE AFFECTED AREA	\$	800.00
Total:	\$	13,518.50
7% GST:	\$	946.30
Grand Total:	\$	14,464.80