

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email: ben@allswellmotortraders.com

(3rd party claim against

Estimate repair

Vehicle No.

Make & Model

Chassis No.

Date of survey

: SUW 9132R

: Prins Alpha

: Hybrid

:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Submitted by

Date: COE expiry

Engine No.

Ben

17-12-2027

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	LH front door / Bnc	01	\$790.00	/	
02	LH skirting X Repair	01	\$319.00	X	
			25%	592.5	
	Special net				
01	Clips / retainer studs for LH front door upholstery / Bnc \$40 / pcr	01	\$40.00	/	
	Labour description				
01	Dismantle / Assembly of LH front door including cables / window / upholstery mechanism	01	\$360.00	300	
02	Spray paint of LH front door interior / exterior including skirting	01	\$400.00	/	
	2 Bnps.				
	Temp sum repair				
	After repair photos				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Gmo Qiaf.

1332.5
20%: 1050