

Hs 170 2014



SERVICE ESTIMATE

0 - I00012 SL: INDIA INTERNATIONAL INSURANCE
 INDIA INTERNATIONAL INSURANCE GST Reg.No:M28920628X
 64 CECIL ST Inv.No. . : B&P 0 Page 1
 #04-05 IOB BUILDING Inv.date. : 30/10/2019
 SINGAPORE 049711 WIP No. . : 36962
 Veh.In/Out: 22/10/2019
 *Tel.No. . : 6347 6100
 Reg.No. . : SML988H
 Reg.date . : 17/12/2014
 Mileage . : 105,795
 Chassis No: SALGA2VE7EA172659

Closed by : Patricia Kueh Anak S
 Svc Consultant : ACC
 Remarks : Dato Kuek Kien Joo,

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, HEADLAMP LH,ETC	0	1200.00	0		1,200.00	S ✓
800	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON FRT BUMPER,ETC	0	1500.00	0		1,500.00	S ✓
280	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	510.00	0		510.00	S ✓
280	TO FOCUS HEADLAMP	0	170.00	0		170.00	S ✓
	BUMPER COVER FRONT R	1.0 EA	2715.10	10		2,443.59	S ✓
	HEADLAMP LH RR3 Adap	1.0 EA	4635.70	10		4,172.13	S ✓

		Gross Total.	9,995.72
Labour Total	3,380.00	Net.....	9,995.72
Parts Total	6,615.72	GST @ 7.0%	699.70
Package Total	0.00	Total.....	10,695.42
		Paid.....	0.00
		Please Pay..	10,695.42

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

4463 - C00001 SL: SERVICE SALES - PC
 Dato Kuek Kien Joo, Andy
 15D Jalan Arif

Singapore
 Singapore 548822

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 17/09/2019

WIP No. : 36962

Veh.In/Out:

*Tel.No. : Mobile: 97334822

Reg.No. : SML988H

Reg.date : 17/12/2014

Mileage : 0

Chassis No: SALGA2VE7EA172659

Closed by : Patricia Kueh Anak S
 Svc Consultant :
 Remarks : Dato Kuek Kien Joo,

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
-------	-------------	----------	-------	-------	-----	----------

802 TO REPLACE FRT BUMPER,
 FOG LAMP FINISHER LH,
 HEADLAMP LH,ETC

0

1800.00 0

~~1,800.00 S~~ (200)

800 TO PUTTY SPRAYPAINT ON
 FRT BUMPER,ETC

0

1500.00 0

~~1,500.00 S~~ (1000) 1500

280 TO CHECK WIRING INCLUDE
 RESETING OF ALL ELECTRICAL MODULES

0

510.00 0

510.00 S

280 TO FOCUS HEADLAMP

0

170.00 0

170.00 S

BUMPER COVER FRONT R

1.0 EA

2715.10

2,715.10 S

KIT - BUMPER VENTS

1.0 EA

859.70

859.70 S

FOG LAMP BRACKET LH

1.0 EA

65.80

65.80 S

FOG LAMP BRACKET RH

1.0 EA

51.60

51.60 S

BUMPER DEFLECTOR LH

1.0 EA

166.10

166.10 S

BUMPER BRACKET FRT C

1.0 EA

175.00

175.00 S

LLR038741/BUMPER MOU

1.0 EA

434.60

434.60 S

BUMPER BRACKET FRT R

1.0 EA

43.30

43.30 S

BUMPER BRACKET FRT L

1.0 EA

54.80

54.80 S

SERVICE ESTIMATE

4463 - C00001 SL: SERVICE SALES - PC
 Dato Kuek Kien Joo, Andy
 15D Jalan Arif

Singapore
 Singapore 548822

Closed by : Patricia Kueh Anak S
 Svc Consultant :
 Remarks : Dato Kuek Kien Joo,

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 17/09/2019
 WIP No. . : 36962
 Veh.In/Out:
 *Tel.No. . : Mobile: 97334822
 Reg.No. . : SML988H
 Reg.date. : 17/12/2014
 Mileage . : 0
 Chassis No: SALGA2VE7EA172659

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	HEADLAMP LH RR3 Adap <i>? on ✓</i>	1.0 EA	4635.70			4,635.70 S	<i>✓ 4172.13</i>
	ADHESIVE SEALER FL2 <i>X nn</i>	1.0 EA	669.10			669.10 S	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
Hp 9000 68
3 days
19/09/19 @ 1100
Revis before part

Labour Total	3,980.00
Parts Total	9,870.80
Package Total	0.00

Gross Total.	13,850.80
Net.....	13,850.80
GST @ 7.0%	969.56
Total.....	14,820.35
Paid.....	0.00
Please Pay..	14,820.35

GST: S=StdRated; O=OutOfScope; Z=ZeroRated