

SERVICE ESTIMATE

4463 - C00001 SL: SERVICE SALES - PC
 Dato Kuek Kien Joo, Andy
 15D Jalan Arif

Singapore
 Singapore 548822

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 17/09/2019

WIP No. . : 36962

Veh.In/Out:

*Tel.No. . : Mobile: 97334822

Reg.No. . : SML988H

Reg.date .: 17/12/2014

Mileage .: 0

Chassis No: SALGA2VE7EA172659

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Dato Kuek Kien Joo,

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, FOG LAMP FINISHER LH, HEADLAMP LH,ETC		0	1800.00	0		1,800.00 \$ (200)	
800	TO PUTTY SPRAYPAINT ON FRT BUMPER,ETC		0	1500.00	0		1,500.00 \$ (1000)	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	510.00	0		510.00 \$	
280	TO FOCUS HEADLAMP		0	170.00	0		170.00 \$?	
	BUMPER COVER FRONT R <i>de</i>	1.0 EA		2715.10			2,715.10 \$	
	KIT - BUMPER VENTS ?	1.0 EA		859.70			859.70 \$	
	FOG LAMP BRACKET LH <i>3X</i>	1.0 EA		65.80			65.80 \$	
	FOG LAMP BRACKET RH <i>X</i>	1.0 EA		51.60			51.60 \$	
	BUMPER DEFLECTOR LH/ <i>?</i>	1.0 EA		166.10			166.10 \$	
	BUMPER BRACKET FRT C <i>?</i>	1.0 EA		175.00			175.00 \$	
	LLR038741/BUMPER MOU <i>X</i>	1.0 EA		434.60			434.60 \$	
	BUMPER BRACKET FRT R <i>?</i>	1.0 EA		43.30			43.30 \$	
	BUMPER BRACKET FRT L <i>?</i>	1.0 EA		54.80			54.80 \$	

SERVICE ESTIMATE

4463 - C00001 SL: SERVICE SALES - PC Dato Kuek Kien Joo, Andy 15D Jalan Arif Singapore Singapore 548822	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 2 Inv.date. : 17/09/2019 WIP No. . : 36962 Veh.In/Out: *Tel.No. . : Mobile: 97334822 Reg.No. . : SML988H Reg.date. : 17/12/2014 Mileage . : 0 Chassis No: SALGA2VE7EA172659
Closed by : Patricia Kueh Anak S Svc Consultant : Remarks : Dato Kuek Kien Joo,	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEADLAMP LH RR3 Adap ?	1.0 EA	4635.70			4,635.70	S
	ADHESIVE SEALER FL2 X	1.0 EA	669.10			669.10	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
Hp 970010068
3 days
19/09/19 @ 1100
Resurvey before paint

Labour Total	3,980.00
Parts Total	9,870.80
Package Total	0.00

Gross Total.	13,850.80
Net.....	13,850.80
GST @ 7.0%	969.56
Total.....	14,820.35
Paid.....	0.00
Please Pay..	14,820.35

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated