

Date: 18.09.2019
 Vehicle No: SJU7849T
 Model: TOYOTA VIOS E AUTO
 Chassis: MR053HY9305135545 - 2009
 Reg.Year: 2009

LINK Auto Consultants hence notify
 Optima Werkz Pte Ltd
 Co. Reg. No. 15578557
 www.ow.sg

Third Party Insurer: AIG
Third Party Vch No: SL79267J
Date of Accident: 18.09.2019

Acknowledged by Repairer
 Signature:
 Date:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>ee.</i>	1		\$948.60
2	REAR BUMPER SIDE BRACKET LH <i>X NN</i>	1		\$112.60
3	REAR BUMPER SIDE RETAINER LH <i>ee.</i>	1		\$98.40
4	REAR BUMPER REFLECTOR LH <i>set</i>	1		\$118.00
5	REAR BUMPER CLIPS <i>7 - m.c.</i>	8	\$5.50	\$44.00
6	REAR END PANEL			REPAIR
7	REAR QUARTER PANEL LH <i>X NN</i>			REPAIR
SUB TOTAL				\$1,321.60
LESS 25%				-\$330.40
PARTS TOTAL				\$991.20

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR SET <i>PM</i>	1		\$300.00 <i>200</i>
S/N TOTAL				\$300.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC *200* \$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL, REAR QUARTER PANEL LH & ETC *400* \$700.00

TO TUFF KOTE & UNDERSEAL MATERIALS & ETC *NNX* \$150.00

TO REMOVE & REPLACED REAR BUMPER REVERSE SENSOR & ETC. BACK TO ORIGINAL CONDITIONS. *40* \$80.00

3 Days.

Lump Sum repair.

After repair photos.

LABOUR TOTAL \$1,430.00

ONG TOTAL \$2,721.20

Gino Riccio - 82880282
19/9/19.

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

