

ASS. REC. BY:

REF:

CS/CT119016521/US f307

Special Instruction:

Surveyor: IVORUS

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CT1

Date/Time: 19.9.19 8:50 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKE 25655

Insured:

at Workshop m/s Z-one Automotive

Tel:

62502115of 1 Eari Butel Ave 6 Bk D #01-87Policy No: DMPCSV150753904Claim No: SNM190204397C01

Sum Insured:

Excess: \$1000.00

Make of Veh:

D.O.A. 16.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 19.9.19 9:53 AM

Person Contacted:

YvonneVehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

minim.

Z-one 16.9.19

Service @ 19.9.19

(08/11/12) wof

REF:

CT1/

ASS. REC. BY: MOCUS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EV / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: 1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / P. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 44957

Date / Time

Action / Instruction

595. Sub Rep. th.

check ins t/s wife 1st prve?

23/09/19

@

11:30 am

received

PA to

Chery

Boon

Ser

via

messenger

23/09/19

@

11:54 pm

mandate

required

authorise

appt to

Boon

Ser

via

messenger.

25/09/19

@

11:11 am

mandate

approved

by

Chery

Boon

Ser.

25/09/19

@

11:54 am

inform

CLA to

Yvonne

via

email.

10/10/19

@

Continued

final

by

\$ 9818.50

with

Yvonne.

Date/Time, File Pass to?

10/10/19

1)

Type

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

3

Survey Fee:

270

Transportation:

Add Fee:



: Site Insp (\$

) \$ + RS \$



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

Report Format :

Lump Sum


N.B.1

(\$ 9,818.90

1/p)

TOTAL

270



Veh No:

SKB25655

Yr Regn:

26/2/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Audi A3

C.C

1395

Colour

wh. R

A/C: Insured / Std / NI / NA

Sp. Reading

61997

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8V9F1092789

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/9/19

D.O.A.

23/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L.L.

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 OCT 2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Created	Sub Folder	Adj Assignment	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2019		19 Sep 2019 08:50 Assign				New Assignment Cancel Case

Begin	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:	MISS TAN GEOK HONG , ID: S15972001								
Vehicle Reg. No.:	SKE2565S	Date of Loss:	16/09/2019 13:00 - :59						
Claim Type:	OD / SNM19D204397C01	Policy/Cover Note No.:	DMPCSN1507531904 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Bldg D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/09/2019]								
Driver/Custodian:	JORDAN TAN (30 / Male) , NRIC: S89267901, Tel: +6590722565 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 200I

Vehicle Details

Vehicle No.: SKE2565S

Vehicle to be Exported: No

Intended Deregistration Date: 23 Sep 2019

Vehicle Make: AUDI

Vehicle Model: A3 SEDAN 1.4 TFSI AMBIENTE MY 15

Primary Colour: White

Manufacturing Year: 2015

Engine No.: CZC232926

Chassis No.: WAUZZZ8V9F1092789

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$27,219.00

Original Registration Date: 26 Feb 2015

First Registration Date: 26 Feb 2015

Transfer Count: 0

Actual ARF Paid: \$15,107.00 7553

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Feb 2025

PARF Rebate Amount: \$11,330.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$62,002.00

COE Rebate Amount: \$33,621.00

Total Rebate Amount: \$44,951.00

The information contained herein is correct as at 23 Sep 2019

OK



Loaded with delectably Sweet deals!

CO-ORGANISER
SGCARMART

audi a3 Price Range Depreciation 2015 Vehicle Type Submit Advanced Search

Home - Used Cars - Autotek Pte Ltd - Audi A3 Sedan 1.4A TFSI S-tronic Ambiente

Audi A3 Sedan 1.4A TFSI S-tronic Ambiente

Overview Financial Insurance Accessories Similar Research Photos Map PREMIUM AD

Price	\$76,800		
Depreciation	\$12,550 /yr View models with similar depre	Reg Date	31-Mar-2015 (5yrs 6mths 7days COE left)
Mileage	N.A.	Manufactured	2014
Road Tax	\$624 /yr	Transmission	Auto
Dereg Value	\$45,203 as of today (change)	OMV	\$27,192
COE	\$61,410	ARF	\$15,069
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight	1,310 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		



Shortlist Compare Add note
Report Error More Actions

Features

1.4L TFSI Engine With Responsive 7 Speed Automatic S-Tronic Transmission, Horsepower Of 123 Bhp For High Fuel Efficiency. View specs of the Audi S3 Sportback (2009-2013)

Accessories

17" Sports Rims, Leather Seats, Retractable Headunit, Bluetooth, Electric Park Brake Button, Rear Aircon, Etc.

Description

Enjoy Low Interest Rate Available. Well Maintained By Previous Owner. 1 Owner Only. Trade In Welcome. Call Us Now For A Non Obligatory Discussion.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Seller Information

Company	Autotek Pte Ltd » dealer's pricelist » 2 vehs sold 10 vehs available	
Address	1 Bukit Batok Crescent #04-06 Search cars nearby this location	
Location	WCEG Plaza	
Office No	69043368	
Contact Person(s)	Frankie Lee	97575401

Posted on: 09-Sep-2019 | Last Updated on: 09-Sep-2019

Upfront Payment » more Financial Info

Transfer Fee \$25

SKE 2565S OD (CTI) DOA - 16/09/2019

Shirley Hiew (LKK Auto)

Wed 25/9/2019 11:54 AM

To: service@z-one.com.sg <service@z-one.com.sg>

Cc: SUR <sur@lkkauto.com>

 1 attachments (183 KB)

CHINA TAIPIING (DV)_0001.pdf;

Hi Yvonne,

As instructed by our client, please proceed to repair the insured vehicle **SKE 2565S** (Excess \$ 1,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKE2565S (SNM19D204397C01)**

OD

Sep 16 2019 1:00PM

{MISS TAN GEOK HONG}

Z-one Automotive Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPIING), sent on **04/10/2019 10:09 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9818.90) - SKE2565S - Claim Handler: Chong Boon Sen

Approved:9818.90.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKE2565S (SNM19D204397C01)**

OD

Sep 16 2019 1:00PM

[MISS TAN GEOK HONG]

Z-one Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **01/10/2019 09:29 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8442.00) - SKE2565S - Claim Handler: Chong Boon Sen

Approved:8442.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKE2565S (SNM19D204397C01)**

OD

Sep 16 2019 1:00PM

[MISS TAN GEOK HONG]

Z-one Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/09/2019 11:11 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6346.70) - SKE2565S - Claim Handler: Chong Boon Sen

Approved:6346.70.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 04 Oct 2019

Preliminary Advice

Vehicle No	: SKE2565S	Accident Date	: 16/09/2019
Make	: AUDI A3	Policy No.	: DMPCSN1507531904
Assignment Date	: 19/09/2019	Excess	: S\$1,000.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,920.10 (inclusive supp)
Revised Amount	:S\$	9,818.90 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,818.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 72,000.00
COE / PARF Rebate	:S\$ 44,951.00
Salvage Value	:S\$
Margin for Repair	:S\$ 27,049.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 30 Sep 2019

Preliminary Advice

Vehicle No	: SKE2565S	Accident Date	: 16/09/2019
Make	: AUDI A3	Policy No.	: DMPCSN1507531904
Assignment Date	: 19/09/2019	Excess	: S\$1,000.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,920.10 (inclusive supp)
Revised Amount	:S\$	8,355.75 (inclusive supp)
Check Items (Estimated)	:S\$	86.25
Total	:S\$	8,442.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	44,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,049.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 2,095.30.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 24 Sep 2019

Preliminary Advice

Vehicle No	: SKE2565S	Accident Date	: 16/09/2019
Make	: AUDI A3	Policy No.	: DMPCSN1507531904
Assignment Date	: 19/09/2019	Excess	: S\$1,000.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,370.05
Revised Amount	:S\$	6,260.45
Check Items (Estimated)	:S\$	86.25
Total	:S\$	6,346.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	44,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,049.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking for part by part basis due to no second hand parts. Estimate prices change to cost prices.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 23 Sep 2019

Preliminary Advice

Vehicle No	: SKE2565S	Accident Date	: 16/09/2019
Make	: AUDI A3	Policy No.	: DMPCSN1507531904
Assignment Date	: 19/09/2019	Excess	: S\$1,000.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,157.67
Revised Amount	:S\$	11,874.20
Check Items (Estimated)	:S\$	225.74
Total	:S\$	12,099.94
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	44,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,049.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking for part by part basis due to no second hand parts.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2019 09:04
Date Of Accident	16/09/2019 13:55
Exact Location Of Accident	JUNC OF UPP THOMSON RD & MANDAI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE2565S
Insured/Policyholder	
Name Of Registered Owner	MISS TAN GEOK HONG
NRIC No	S1597200I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90722565
Alternative Phone No	OFFICE-90722565

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI AMBIENTE MY 15
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1507531904
Cover Note Number	-

Driver

Name of Driver	JORDAN TAN
NRIC No	S8926790J
Date Of Birth	05/08/1989
Occupation	INDOOR
Date Of Driving Pass	22/06/2009
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90722565
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	36 RIVERINA VIEW
Postcode	518365
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	CCB6372 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20190916/2154

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CCB6372
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/wh be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN

A = SKE 25655
B = GCB 6372
Off. Thompson Rd & Mandal Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190916/2154

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

1 of 3

Report No: T/20190916/2154

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/09/2019 19:10	Vide Report No.:	Station Diary No.: 110
--	------------------	---------------------------

Informant's Particulars

Name of Informant: JORDAN TAN			Address: 36 RIVERINA VIEW SINGAPORE 518385		
ID Type / ID No.: NRIC NO / S8926790J			Contact No.: Home/Office: Mobile: 90722565		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 05/08/1989	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Singapore Armed Forces personnel			Driving Licence Information: Class: 2B,2A,3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 16/09/2019 13:55	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 UPPER THOMSON ROAD MANDAI ROAD At the junction				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CCB6372	Car				Slightly Damaged	1
SKE2565S	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT

SINGAPORE
POLICE FORCE

T/20190916/2154

3 of 3

Report No. T/20190916/2154

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:


G /
Staff Sgt IDRIS BIN ROSLI

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
16/09/2019 19:10

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

Authentication Stamp
NP16E

SIGNATURE

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190916/2154

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3

Report No: T/20190916/2154

CONTINUATION OF REPORT

Driver			
Name	Ting See King		ID No. 751126065609
Related Vehicle	CCB5372 (Car)		Contact No. 82851367
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JORDAN TAN		ID No. S8926790J
Related Vehicle	SKE2565S (Car)		Contact No. 90722565
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/09/2019 at about 1354hrs, I was driving my vehicle registration plate number SKE2565S and was travelling along Upper Thomson Road. I was heading to my work place at Nee Soon camp.

While I driving along Upper Thomson Road, there is a traffic light was changing color from green to amber. As I am getting nearer to the traffic light, the car registration plate number CCB5372 was making a stop in the center of the pedestrian.

Upon seeing that I then apply my braking however I unable to stop on time as such, my car had collided onto the rear portion of the said vehicle.

No one was injured during the accident.



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Bldg D #01-85/87, Autobay@Kaki Bukit Singapore 17888

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg enquiry@z-one.com.sg

AUTOMOTIVE @ PERFORMANCE Company Registration No. 201118055N

Not Attached
LKR
24/05/1000
Sdy.
23/9/17
L/S
The part number
cost plus 10%

ESTIMATE

Tan Geok Hong

Code : TEA

Date in: TEA

Vehicle Num. : SKE25655

Model : Audi A3 Sedan 1.4 TFSI Ambiente My

Contact: 90722555

Chassis/ Eng # : WAUZZZ8V9F1092789 / CZC2B2925

Part and Labour Assessment

Description of part	Qty	Unit Price	Amount
1 Front Windscreen	1	1,480.50	1,480.60
2 Front Bonnet	1	2,300.57	2,300.67
3 Front Bonnet Hinges L/R	2	139.57	279.34
4 Front Bonnet Absorber	1	137.33	137.33
5 Front Bonnet Weather Strip	1	139.76	139.76
6 Front Bonnet Mechanism Lock L/R	2	189.30	378.60
7 Front Bonnet Lock Striker L/R	2	137.79	275.58
8 Front Bonnet Heat Insulator Mat	1	237.21	237.21
9 Front Bonnet Heat Insulator Mat Clips	11	7.11	78.21
10 Front Grille Assy	1	999.89	999.89
11 Front Headlamp L/R	2	1,800.97	3,601.94
12 Front Headlamp Nozzle Cover L/R	2	137.63	275.26
13 Front Headlamp Nozzle Motor L/R	2	249.88	499.76
14 Front Bumper	1	1,709.70	1,709.70
15 Front Bumper Side Retainer L/R	2	68.70	137.40
16 Front Bumper Clips	10	7.11	71.10
17 Front Bumper Towing Cover	1	80.97	80.97
18 Front Bumper Fog Lamp Garnish L/R	2	130.77	261.54
19 Front Bumper Reinforcement Beam	1	800.97	800.97
20 Front Bumper Inner Sponge	1	156.70	156.70
21 Front Support Panel	1	699.60	699.60
22 Front Support Panel Top Garnish	1	80.92	80.92
23 Front Support Panel Top Garnish Clips	5	7.11	35.55
Subtotal			14,718.60
Percentage discount 5%			735.93
Sub-total			13,982.67

Front Bumper No. Plate (SN)	1	25.00	<i>Ref</i>	25.00	<i>1</i>
Front Bumper No. Plate Garrison (SN)	1	50.00	<i>647</i>	50.00	<i>1</i>
				75.00	
Percentage Plus 0%				0.00	
	Sub-total 2			75.00	
	Parts Total				

Labour

Description		Price
To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	<i>100</i>	180.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>20</i>	120.00
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	<i>11 X</i>	200.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>800</i>	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>800</i>	1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	<i>11 X</i>	200.00
	Labour Total	3,100.00
	Parts & labour Total	17,157.67

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

NOT Aford
LKR
24155 \$1000
Sdy.
23/9/18
L/S
Take the other way
cost plus 10%

ESTIMATE

Tan Geok Hong

Code : TBA

Date In: TBA

Vehicle Num. : SKE25655

Model : Audi A3 Sedan 1.4 TFSI Ambiente My

Contact: 90722565

Chassis/ Eng # : WAUZZZ8V9F1092789 / CZC232926

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
1 Front Windscreen	1	1,480.60	1,480.60
2 Front Bonnet	1	2,300.67	2,300.67
3 Front Bonnet Hinges L/R	2	139.67	279.34
4 Front Bonnet Absorber	1	137.33	137.33
5 Front Bonnet Weather Strip	1	139.76	139.76
6 Front Bonnet Mechanism Lock L/R	2	189.30	378.60
7 Front Bonnet Lock Striker L/R	2	137.79	275.58
8 Front Bonnet Heat Insulator Mat	1	237.21	237.21
9 Front Bonnet Heat Insulator Mat Clips	11	7.11	78.21
10 Front Grille Assy	1	999.89	999.89
11 Front Headlamp L/R	2	1,800.97	3,601.94
12 Front Headlamp Nozzle Cover L/R	2	137.63	275.26
13 Front Headlamp Nozzle Motor L/R	2	249.88	499.76
14 Front Bumper	1	1,709.70	1,709.70
15 Front Bumper Side Retainer L/R	2	68.70	137.40
16 Front Bumper Clips	10	7.11	71.10
17 Front Bumper Towing Cover	1	80.97	80.97
18 Front Bumper Fog Lamp Garnish L/R	2	130.77	261.54
19 Front Bumper Reinforcement Beam	1	800.97	800.97
20 Front Bumper Inner Sponge	1	156.70	156.70
21 Front Support Panel	1	699.60	699.60
22 Front Support Panel Top Garnish	1	80.92	80.92
23 Front Support Panel Top Garnish Clips	5	7.11	35.55
Subtotal			14,718.60
Percentage discount 5%			735.93
Sub-total			13,982.67

ph.

11

Front Bumper No. Plate (SN)	1	25.00	Set	25.00
Front Bumper No. Plate Garnish (SN)	1	50.00	cut	50.00
				75.00
Percentage Plus 0%				0.00
Sub-total 2				75.00
Parts Total				

Labour

Description		Price
To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	100	180.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	20	120.00
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	11 X	200.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800	1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	11 X	200.00
Labour Total		3,100.00
Parts & labour Total		17,157.67

UDS Auto Consultants hence notify the Registrar of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey.
- Plans drawn are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/claim(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Bldg D #01-85/87, Autobay@Kaki Bukit, Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Attn: Sharly
Mr Allmond
Haw
bus 1000
Sch
23/9/19

ESTIMATE

Tan Geok Hong

Code : C101924

Date In: 23/9/2019

Vehicle Num. : SKE26653

Model : Audi A3 Sedan 1.4 TFSI Ambiente My

Chassis/ Eng # : WAUZZZ8V9F1092789 / CZC232926

Contact: 90722565

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
1 Front Windscreen	1 600	550.00 C/A	550.00 ✓
2 Front Bonnet	1 990	900.00 SUC	900.00 ✓
3 Front Bonnet Hinges L/R	2 35x2=70	30.00 Self	60.00 ✓
4 Front Bonnet Absorber	1	45.00 A7	45.00 X
5 Front Bonnet Weather Strip	1 20	18.00 10L	18.00 ✓
6 Front Bonnet Mechanism Lock L/R	2 88	80.00 NKTW1	150.00 IPC
7 Front Bonnet Lock Striker L/R	2 50	45.00 NKTW1	90.00 IPC
8 Front Bonnet Heat Insulator Mat	1	85.00 A7	85.00 X
9 Front Bonnet Heat Insulator Mat Clips	11	3.00 A7	33.00 X
10 Front Grille Assy	1 265	240.00 C/A	240.00 ✓
11 Front Headlamp L/R	2 825x2=1650	750.00 C/A	1,500.00 ✓
12 Front Headlamp Nozzle Cover L/R	2	25.00 A7	50.00 X
13 Front Headlamp Nozzle Motor L/R	2	90.00 A7	180.00 X
14 Front Bumper	1 770	700.00 20/0e	700.00 ✓
15 Front Bumper Side Retainer L/R	2	13.00 A7	36.00 X
16 Front Bumper Clips	10 40	3.00 20L	30.00 ✓
17 Front Bumper Towing Cover	1	20.00 A7	20.00 X
18 Front Bumper Fog Lamp Garnish L/R	2	45.00 A7	90.00 X
19 Front Bumper Reinforcement Beam	1 275	250.00 Self	250.00 ✓
20 Front Bumper Inner Sponge	1 60	55.00 20L	55.00 ✓
21 Front Support Panel	1 283	260.00 C/A	260.00 ✓
22 Front Support Panel Top Garnish	1	20.00 A7	20.00 X
23 Front Support Panel Top Garnish Clips	5	3.00 A7	15.00 X
Subtotal			5,387.00
Percentage Plus 15%			808.05
Sub-total	5164		6,195.05

P-6980
152

Front Bumper No. Plate (SN)	1	25.00	Self	25.00/15
Front Bumper No. Plate Garnish (SN)	1	50.00	cut	50.00 ✓
				75.00
				0.00
Percentage Plus 0%				75.00

Sub-total 2

Parts Total

Labour

Description		Price
To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	100	180.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	20	120.00
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	X	200.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800	1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	NI X	200.00
	Labour Total	3,100.00
	Parts & labour Total	9,370.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

841000 \$1000
P/P \$9818.90

ESTIMATE

Tan Geok Hong

Code : C101924

Date In: 23/9/2019

Vehicle Num. : SKE25655

Model : Audi A3 Sedan 1.4 TFSI Ambiente My

Contact: 90722565

Chassis/ Eng # : WAUZZZ8V9F1092789 / CZC232926

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
1 Front Windscreen	1	600.00 <i>CRA</i>	600.00 ✓
2 Front Bonnet	1	990.00 <i>Bul</i>	990.00 ✓
3 Front Bonnet Hinges L/R	2	35.00 <i>Self</i>	70.00 ✓
4 Front Bonnet Absorber	1	45.00 <i>11</i>	45.00 X
5 Front Bonnet Weather Strip	1	20.00 <i>new</i>	20.00 ✓
6 Front Bonnet Mechanism Lock L/R	2	88.00 <i>n/s 7w1</i>	176.00 <i>12</i>
7 Front Bonnet Lock Striker L/R	2	50.00 <i>n/s 7w1</i>	100.00 <i>12</i>
8 Front Bonnet Heat Insulator Mat	1	85.00 <i>11</i>	85.00 X
9 Front Bonnet Heat Insulator Mat Clips	11	3.00 <i>11</i>	33.00 X
10 Front Grille Assy	1	265.00 <i>CRA</i>	265.00 ✓
11 Front Headlamp L/R	2	825.00 <i>CRA</i>	1,650.00 ✓
12 Front Headlamp Nozzle Cover L/R	2	25.00 <i>11</i>	50.00 X
13 Front Headlamp Nozzle Motor L/R	2	90.00 <i>11</i>	180.00 X
14 Front Bumper	1	770.00 <i>DO/be</i>	770.00 ✓
15 Front Bumper Side Retainer L/R	2	18.00 <i>11</i>	36.00 X
16 Front Bumper Clips	10	4.00 <i>new</i>	40.00 ✓
17 Front Bumper Towing Cover	1	20.00 <i>11</i>	20.00 X
18 Front Bumper Fog Lamp Garnish L/R	2	45.00 <i>11</i>	90.00 X
19 Front Bumper Reinforcement Beam	1	275.00 <i>Self</i>	275.00 ✓
20 Front Bumper Inner Sponge	1	60.00 <i>Top</i>	60.00 ✓
21 Front Support Panel	1	286.00 <i>CRA</i>	286.00 ✓
22 Front Support Panel Top Garnish	1	20.00 <i>11</i>	20.00 X
23 Front Support Panel Top Garnish Clips	5	3.00 <i>11</i>	15.00 X
Subtotal			5,876.00
Percentage Plus 15%			881.40
Sub-total			6,757.40

P- 6988
157
P- 8033.90
S.N- 65.00
L- 1722.00
8018.90

Front Bumper No. Plate (SN)	1	25.00	<i>sent</i>	25.00	<i>15</i>
Front Bumper No. Plate Garnish (SN)	1	50.00	<i>cut</i>	50.00	<i>✓</i>
				75.00	
				0.00	
Percentage Plus 0%					
	Sub-total 2			75.00	
	Parts Total				

Labour

Description	Price
To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	<i>100</i> 180.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>20</i> 120.00
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	<i>12 X</i> 200.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>800</i> 1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>800</i> 1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	<i>21 X</i> 200.00
Labour Total	3,100.00
Parts & labour Total	9,932.40

12482.45



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Tan Geok Hong

Code : C101924

Date In: 23/9/2019

Vehicle Num. : SKE2565S

Model : Audi A3 Sedan 1.4 TFSI Ambiente My

Chassis/ Eng # : WAUZZZ8V9F1092789 / CZC232926

Contact: 90722565



Supplementary for Estimate Items

Description of part	Qty	Unit Price	Amount
1 Front Bonnet Lock Striker Center	1	✓ 50.00 <i>Ref</i>	50.00 ✓
2 Front Headlamp Module LH	1	✓ 240.00 <i>one</i>	240.00 ✓
3 Front Bumper Reinforcement Beam Cover	1	✓ 25.00 <i>Ref</i>	25.00 ✓
4 Air Con Condenser	1	✗ 265.00 <i>sent/turn alt</i>	265.00 ✗
5 Radiator Outer	1	✓ 240.00 <i>one</i>	240.00 ✓
6 Radiator Inner	1	✓ 240.00 <i>one</i>	240.00 ✓
7 Radiator Top Cover	1	✓ 30.00 <i>one</i>	30.00 ✓
8 Radiator Fan Assy	1	✓ 650.00 <i>one</i>	650.00 ✓
9 Radiator Side Air Guide LH	1	✓ 20.00 <i>Ref</i>	20.00 ✓
10 Radiator Coolant	3	✓ 20.00 <i>Ref</i>	60.00 ✓
11 Intake Air Duct Cover Center	1	✓ 25.00 <i>one</i>	25.00 ✓
12 Intake Air Duct Center	1	✓ 40.00 <i>one</i>	40.00 ✓
13 Air Guide Center Upper	1	✓ 12.00 <i>one</i>	12.00 ✓
14 Temperature Sensor Bracket	1	✓ 20.00 <i>Ref/one</i>	20.00 ✓
15 Washer Tank	1	✓ 80.00 <i>Ref</i>	80.00 ✓
16 Wiper Panel Top Garnish	1	✓ 90.00 <i>cut</i>	90.00 ✓
Subtotal			2,087.00
Percentage Plus 15%			313.05
Sub-total			2,400.05
Parts Total		1822	2,400.05

Labour

Description	Price
-------------	-------

To remove, change radiator, parts, pressure test, replace coolant.

Labour Total

150.00^X
150.00

Parts & labour Total

2,550.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD BLADE
Dept Direct: 9417 9791 / 9792 9838



Dept Direct: 9417 9791

Dept Direct: 9417 9792

Dept Direct: 9417 9793

Dept Direct: 9417 9794

Wiper blade: NWS (Nippon Wiper blades), Silper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

WAUZZZ8V9F1092789

PINV00007632

P719274

C101924.

TAX INVOICE : AR201909-13132

DATE : 26/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE25658

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 3

CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1	8V5823029A	FRONT BONNET	CC	1	990.00	990.00
			CC4-G-060			
2	8V0823301G	FRONT BONNET HINGE LH	CC	1	35.00	35.00
			CC5-D-08AA			
3	8V0823302G	FRONT BONNET HINGE RH	CC	1	35.00	35.00
			CC5-D-08AB			
4	8V0823509A	FRT BONNET MECHANISM LOCK LH	CC	1	88.00	88.00
			CC5-F-06A			
5	8V0823480A	FRT BONNET LOCK STRICKER CENTER	CC	1	50.00	50.00
			CC5-D-08AC			
6	8V5853651 1QP	RADIATOR GRILLE	CC	1	265.00	265.00
			CC5-B-09A			
7	N 10354602	FRONT BUMPER CLIP	CC	10	4.00	40.00
			CC5-B-08AQ			

CONTINUE NEXT PAGE

[P] 26/09/2019 16:08:23

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 26/09/2019 3:27:00PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD SCUM
Deal Direct: 8417 8791 / 8746 8008



Deal Direct: 8228 9610

Deal Direct: 8228 9610

Deal Direct: 8417 8790



Deal Direct: 8417 8790

Deal Direct: 8417 8790

Deal Direct: 8417 8790

Deal Direct: 8417 8790

Wiper blades: NWB (Nippon Wiper blades), Sliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

WAUZZZ8V9F1092789

TAX INVOICE : AR201909-13132

DATE : 26/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKK2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 3

CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
8	8V0807109/B	FRT BUMPER REINFORCEMENT	CC CC5-F-070	1	275.00	275.00
9	8V3807550B	FRT BUMPER SPONGE	CC CC5-H-07D	1	60.00	60.00
10	8V0941043D	HEADLAMP LH	CC CC5-C-08B	1	825.00	825.00
11	8V0941044D	HEADLAMP RH	CC CC5-C-05B	1	825.00	825.00
12	8V0820536	TEMPERATURE SENSOR BRACKET	CC CC5-TX-07CF	1	20.00	20.00
13	8V0121283A	RADIATOR SIDE AIR GUIDE LH	CC CC5-E-08BG	1	20.00	20.00
14	5Q0955453MR	WASHER TANK	CC CC5-C-06BD	1	80.00	80.00

CONTINUE NEXT PAGE

[F] 26/09/2019 16:08:23

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 26/09/2019 3:27:00PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Depot Direct: 8417 8701 / 8742 8708



Depot Direct: 8417 8708

Depot Direct: 8417 8708

Depot Direct: 8417 8708

Depot Direct: 8417 8708

Wiper blades: NISSAN (Nissan Wiper blades) Made in Korea
Forch (Made in Germany)

Spark plug: NISSAN (Nissan Spark plug) Made in Japan

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

WAUZZZ8V9F1092789

PINVD00007631 87
P719273
C101924

TAX INVOICE : AR201909-13134

DATE : 26/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 5Q0121203DA/EA/CP	RADIATOR FAN MOTOR WITH COWLING	U1	1	650.00	650.00
2. 8V5807065A GRU	FRONT BUMPER	U1	1	770.00	770.00
3. 8V3807217	FRT REINFORCEMENT COVER	U1	1	25.00	25.00
4. 5Q0129954	INTAKE AIR DUCT COVER CENTER	U1	1	25.00	25.00
5. 5Q0129254B	INTAKE AIR DUCT CENTER	U1	1	40.00	40.00
6. 8V0823126AJS	FRT BONNET WEATHER STRIP	U1	1	20.00	20.00

SUB-TOTAL : 1,530.00
ADD GST 7.00 % 107.10

E & O E TOTAL AMOUNT S\$: 1,637.10

[F] 26/09/2019 4:07:11PM

[E] 26/09/2019 3:27:03PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #E1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO: M2-0119201-3 CO. REG. NO: 199307741M

Depot Direct: 9417 8791 / 8742 8108



Depot Direct: 9417 8791

Depot Direct: 9417 8792

Depot Direct: 9417 8793

Depot Direct: 9417 8794

Wiper blade: NNB (Nippon Wiper blade), Bilpex (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

PINVO00007630

P719272

C101924

TAX INVOICE : AR201909-13259

DATE : 27/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 8V0805588	SUPPORT PANEL	U1	1	286.00	286.00
		SUPPLIER			
2. G A13A8JM1 / G 012A8GM1	COOLANT ADDITIVE (1.5 LITRE)	U1	3	20.00	60.00
		L1-06			

SUB-TOTAL : 346.00

ADD GST 7.00 % 24.22

E & O E

TOTAL AMOUNT S\$: 370.22

[P] 27/09/2019 9:19:11AM

[E] 27/09/2019 9:04:10AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 9 - 1 3 2 5 9 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADES
Dept Street 9417 9700 / 9740 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700



Dept Street 9417 9700

TAX INVOICE : AR201909-13271
DATE : 27/09/2019
CUSTOMER ID : ZON003
VEH REG. NO. : SKE2565S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

Z-ONE AUTOMOTIVE PTE LTD
1 KAKI BUKIT AVE 6
#01-87 Bldg D AUTOBAY @ KAKI BUKIT
AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
TEL : 6634 2112 FAX : 6634 2122
ATTN : ERIK CHAN 9850 2838

PIN V00007629
P719271
C101924

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1	8V0823185B/C	FRT BONNET STRIKER LH	CC	1	50.00	50.00
			CCS-D-08CA			
2	8V5819403C 9B9/401A 9B9	WIPER GARNISH	CC	1	90.00	90.00
			CCS-H-070			

SUB-TOTAL : 140.00
ADD GST 7.00 % 9.80

E & OE TOTAL AMOUNT S\$ 149.80

[P] 27/09/2019 09:19:16

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 27/09/2019 9:15:33

JAE Auto Pte. Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



* AR201909-13271 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

46A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Depot Street: 8412 8791 / 8748 3030



Depot Street: 8412 8791

Depot Street: 8412 8791

Depot Street: 8412 8791

Depot Street: 8412 8791

Wiper blade: NWS (Nippon Wiper blade), Silpar (Made in Korea)

Ford (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

WAUZZZ8V9F1092789

TAX INVOICE : AR201909-13132

DATE : 26/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKS2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 3 of 3

CURR. : S\$

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
15	4G0907397PR	HEADLAMP MODULE	CC	1	240.00	240.00
			CC5-G-05AA			
16	8V5853037	RADIATOR TOP COVER	CC	1	30.00	30.00
			CC5-H-08B			
17	5Q0816411AJ/AN/BF/N	A/C CONDENSER	CC	1	265.00	265.00
			CC5-F-09A			
18	5Q0121251GF/EJ/GB/HS	RADIATOR OUTER	CC	1	240.00	240.00
			CC5-E-04B			
19	5Q0121251GQ/EM/FJ/GQ	RADIATOR INNER	CC	1	240.00	240.00
			CC5-G-08F			
20	8V0121285A	AIR GUIDE CENTER UPPER	CC	1	12.00	12.00
			CC5-E-08AB			

SUB-TOTAL : 4,635.00
ADD GST 7.00 % 324.45

E. & O.E

TOTAL AMOUNT S\$: 4,959.45

[P] 26/09/2019 16:08:23

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[P] 26/09/2019 3:27:00 PM

JAE Auto Pte. Ltd.

Sales Executive: ANN



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jassauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Depot Direct: 6417 8700 / 6748 8000



Depot Direct: 6417 8700

Depot Direct: 6417 8700

Depot Direct: 6417 8700

Depot Direct: 6417 8700

Wiper blade: NISSAN (Nissan Wiper blade), Sliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

PINV00007628

P719270

C101924

TAX INVOICE : AR201909-13670

DATE : 27/09/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. SQ0129621B	INTAKE AIR DUCT (INNER)	U1	1	18.00	18.00
		SUPPLIER			

SUB-TOTAL : 18.00
ADD GST 7.00 % 1.26

E & OE TOTAL AMOUNT S\$ 19.26

[P] 27/09/2019 3:02:23PM

[E] 27/09/2019 3:01:16PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 9 - 1 3 6 7 0 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADES: NISSAN
Dept Direct: 8417 8786 / 8788 8828



Wiper blade: NNB (Nissan Wiper blade), Silver (Made in Korea)

Ford (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

WAUZZZ8V9F1092789

TAX INVOICE : AR201910-00360

DATE : 01/10/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	8V5845099B NVB AUDI A3 13"	FRT W/S GLASS LHX	MO Y28 863	1	600.00	600.00
2.	8U0955609 A5, A4 Q3	SENSOR TAPE (ROUND)	MO WEI JIAN	1	50.00	50.00 ?

SUB-TOTAL : 650.00

ADD GST 7.00 % 45.50

E. & O.E

TOTAL AMOUNT S\$: 695.50

[P] 01/10/2019 12:16:22PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 01/10/2019 12:14:42PM

JAE Auto Pte. Ltd.

Sales Executive : WEI JIAN

This is computer generated document.

No signature is required.



* AR201910-00360 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

80 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADE
Dept Direct: 6417 8791 / 8740 8838



Dept Direct: 6417 8796

Dept Direct: 6417 8796

Dept Direct: 6417 8796

Dept Direct: 6417 8796

Wiper blade: NIPPON (Nippon Wiper blade), Silver (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

Z-ONE AUTOMOTIVE PTE LTD

1 KAKI BUKIT AVE 6

#01-87 Blk D AUTOBAY @ KAKI BUKIT

AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6634 2112 FAX: 6634 2122

ATTN: ERIK CHAN 9850 2838

TAX INVOICE : AR201910-00488

DATE : 01/10/2019

CUSTOMER ID : ZON001

VEH REG. NO. : SKE2565S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
N 0385012	FRONT FENDER SHIELD CKIP	U1	10	3.00	30.00
		2H2-L			

SUB-TOTAL : 30.00
ADD GST 7.00 % 2.10

E & OE TOTAL AMOUNT S\$ 32.10

[P] 01/10/2019 2:27:49PM

[E] 01/10/2019 2:27:32PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN

This is computer generated document.

No signature is required.



* 1 8 2 0 1 9 1 0 - 0 0 4 8 8 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

p. 7349



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Our Ref : SKE2565S

Your Ref : SKE2565S

08th October 2019

EMAIL & POST
WITHOUT PREJUDICE

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attention: Boon Seng – Motor Claims Dept.

Dear Boon Seng,

CLAIMANT: TAN GEOK HONG

ACCIDENT INVOLVING SKE2565S & CCB6372 ALONG JUNCTION OF UPPER THOMSON ROAD & MANDAI ROAD ON 16/09/2019 AT 1355HRS

We refer to the above matter.

As the quantum was agreed between your surveyor and our Ms Yvonne, we are submitting our claims as follows:

1. Cost of Repair	\$ 9,818.90
2. Deduction of Excess	\$ 1,000.00
	\$ 8,818.90
Add GST (7%)	\$ 617.33
Total	
	\$ 9,436.23

A copy each of the following supporting documents is enclosed:

- (1) Final Bill
- (2) Satisfaction Voucher
- (3) Letter of Authority
- (4) Supplier Invoice

Yours faithfully

Z-one Automotive Pte Ltd
Encls





Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Tan Geok Hong
36 Riverina View
Singapore 518385
Contact: 90722565 Jordan

TAX INVOICE

Date : 04/10/2019
Date in : 23/09/2019
Vehicle Num. : SKE2565S
Make/Model : Audi A3 Sedan 1.4 TFSI Ambiente MY 15-2015
Chassis/Eng# : WAUZZZ8V8F1092789/CZC232926
Accident Date : 16/09/2019
Claim No : C101924
Reference :
Policy No. : DMPCSN1507531904 (25/02/2020)

PART BY PART REPAIR
AS PER SURVEYOR REPORT
DATED 04/10/2019
BY LKK Auto Consultants Pte Ltd

Amount \$
9,818.90

DEDUCTION OF EXCESS

-1,000.00



Z-ONE AUTOMOTIVE PTE LTD

E. & O.E.	Sub \$:	8,818.90
Add GST (7%)	\$:	617.33
Total Amount	\$:	9,436.23

SATISFACTION VOUCHER

Name & Address of Insured: Tan Geok Hong 36 Riverina View Singapore 518385

Name & Address of Repairers: Z-One Automotive Pte Ltd 1 Kaki Bukit Ave 6 #01-87 (3) 417883

Date & Place of Accident: 16/09/2019 along Junction of Upper Thomson Road & Mandai Road

Policy No: DMPCCN150T531904 Claim No: _____

Vehicle No: SKE 25658 Cost of Repairs: \$9818.90

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**, settling the repair costs stated above with the said repairers I/We hereby release and discharge the said Insurers from all further obligations and liabilities under the aforesaid policy in respect of an accident involving my/our said motor vehicle on the above-mentioned date and place.

I/We agree that by virtue of such payment the said Insurers are **subrogated** to all my/our rights and remedies in respect of the damage to the said Motor Vehicle in accordance with the laws governing the Contract of Insurance.

I/We hereby grant the said Insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefor, I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their part they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:-



[Signature]

Company's Chop & Signature

INSURED:-

[Signature]

Company's Chop & Signature

WITNESS:-

YONG YUKE FONG *[Signature]*
Name & Signature

1 Kaki Bukit Avenue 6 #01-87 (3) 417883
Address

02/10/2019
Date

WITNESS:-

JORDAN TAN *[Signature]*
Name & Signature

36 Riverina View Singapore 518385
Address

02/10/2019
Date

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING VEHICLE NOS SKE 25658 &
CCB 6372 ALONG
Junction of Upper Thomson Road & Mandai Road
ON 16/09/2019 1355hrs

1. I/ We, hereby appoint Z-ONE AUTOMOTIVE PTE LTD to be my agent and I/We authorize my said agent to give you all instructions pertaining to the conduct of own damage claim against my insurer.
2. My said agent also has my authority to decide on my behalf whether to accept any offer of settlement from the insurer.
3. I understand and accept that until I revoke my said agent's authority in writing to you, I am bound by all instructions given by my said agent to you
4. Upon settlement of the own damage claim and in case the settlement monies was sent to me/us by the insurer, I/We undertake to pay the cost of repair settled and related expenses and disbursement incurred.
5. My vehicle is repaired on my own will without any inducement, threat or promise.


Signature
(Company's stamp if applicable)
Name: Tan Geok Hong
NRIC No: S15972001
Address 36 Riverina View
Singapore 518 385



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2019		19 Sep 2019 08:50 Edit Adj Rpt	\$9,818.90 Edit Estimates	\$9,818.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	MISS TAN GEOK HONG, ID: S15972001								
Vehicle Reg. No.:	SKE25655	Date of Loss:	16/09/2019 13:00 - :59 [54 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D204397C01	Policy/Cover Note No.:	DMPCSN1507531904 (Comprehensive)						
		Excess:	\$1,000.00						
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Bld D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/09/2019]								
Driver/Custodian:	JORDAN TAN (30 / Male), NRIC: S8926790J, Tel: +6590722565 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (04/10/2019): Alert - Adj Mandate Approved (\$9818.90) - SKE25655 - Claim Handler: Chong Boon ... - CHINA_TAIPING (01/10/2019): Alert - Adj Mandate Approved (\$8442.00) - SKE25655 - Claim Handler: Chong Boon ... - CHINA_TAIPING (25/09/2019): Alert - Adj Mandate Approved (\$6346.70) - SKE25655 - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE2565S (SNM19D204397C01)

OD

Sep 16 2019 1:00PM

[MISS TAN GEOK HONG]

Z-one Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	17/09/19 09:13	Accident Statement							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	23/09/19 11:50	Adjuster Immediate Advice							Load HTM		
2	24/09/19 13:28	Adjuster Immediate Advice							Load HTM		
3	30/09/19 09:45	Adjuster Immediate Advice							Load HTM		
4	04/10/19 09:33	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
2	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
3	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
4	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
5	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
6	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
7	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
8	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
9	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
10	17/09/19 09:12	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	24/09/19 13:32	General View							Load JPG	☒	
2	24/09/19 13:32	General View							Load JPG	☒	
3	24/09/19 13:32	General View							Load JPG	☒	
4	24/09/19 13:32	General View							Load JPG	☒	
5	24/09/19 13:32	General View							Load JPG	☒	
6	24/09/19 13:32	General View							Load JPG	☒	
7	24/09/19 13:32	General View							Load JPG	☒	
8	24/09/19 13:32	General View							Load JPG	☒	
9	24/09/19 13:32	General View							Load JPG	☒	
10	24/09/19 13:32	General View							Load JPG	☒	
11	24/09/19 13:32	General View							Load JPG	☒	
12	24/09/19 13:32	General View							Load JPG	☒	
13	24/09/19 13:32	General View							Load JPG	☒	
14	24/09/19 13:32	General View							Load JPG	☒	
15	24/09/19 13:32	General View							Load JPG	☒	
16	24/09/19 13:32	General View							Load JPG	☒	
17	24/09/19 13:32	General View							Load JPG	☒	
18	24/09/19 13:32	General View							Load JPG	☒	
19	24/09/19 13:32	General View							Load JPG	☒	
20	24/09/19 13:32	General View							Load JPG	☒	
21	24/09/19 13:32	General View							Load JPG	☒	
22	24/09/19 13:32	General View							Load JPG	☒	
23	24/09/19 13:32	General View							Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
24	24/09/19 13:32	General View		☒
25	24/09/19 13:32	General View		☒
26	24/09/19 13:32	General View		☒
27	24/09/19 13:32	General View		☒
28	24/09/19 13:32	General View		☒
29	24/09/19 13:32	General View		☒
30	24/09/19 13:32	General View		☒
31	24/09/19 13:32	General View		☒
32	24/09/19 13:32	General View		☒
33	24/09/19 13:32	General View		☒
34	24/09/19 13:32	General View		☒
35	24/09/19 13:32	General View		☒
36	24/09/19 13:32	General View		☒
37	24/09/19 13:32	General View		☒
38	24/09/19 13:32	General View		☒
39	24/09/19 13:32	General View		☒
40	24/09/19 13:32	General View		☒
41	24/09/19 13:32	General View		☒
42	24/09/19 13:32	General View		☒
43	24/09/19 13:32	General View		☒
44	24/09/19 13:32	General View		☒
45	24/09/19 13:32	General View		☒
46	24/09/19 13:32	General View		☒
47	24/09/19 13:32	General View		☒
48	24/09/19 13:32	General View		☒
49	24/09/19 13:32	General View		☒
50	24/09/19 13:32	General View		☒
51	24/09/19 13:32	General View		☒
52	24/09/19 13:32	General View		☒
53	24/09/19 13:32	General View		☒
54	24/09/19 13:32	General View		☒
55	24/09/19 13:32	General View		☒
56	24/09/19 13:32	General View		☒
57	24/09/19 13:32	General View		☒
58	24/09/19 13:32	General View		☒
59	24/09/19 13:32	General View		☒
60	24/09/19 13:32	General View		☒
61	24/09/19 13:32	General View		☒
62	24/09/19 13:32	General View		☒
63	24/09/19 13:32	General View		☒
64	24/09/19 13:32	General View		☒
65	24/09/19 13:32	General View		☒
66	24/09/19 13:32	General View		☒
67	24/09/19 13:32	General View		☒
68	24/09/19 13:32	General View		☒
69	24/09/19 13:32	General View		☒
70	24/09/19 13:32	General View		☒
71	24/09/19 13:32	General View		☒
72	24/09/19 13:32	General View		☒
73	24/09/19 13:32	General View		☒
74	24/09/19 13:32	General View		☒
75	24/09/19 13:32	General View		☒
76	24/09/19 13:32	General View		☒
77	24/09/19 13:32	General View		☒
78	24/09/19 13:32	General View		☒
79	24/09/19 13:32	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
80	24/09/19 13:32	General View	 Load JPG	☒
81	24/09/19 13:32	General View	 Load JPG	☒
82	24/09/19 13:32	General View	 Load JPG	☒
83	24/09/19 13:32	General View	 Load JPG	☒
84	24/09/19 13:32	General View	 Load JPG	☒
85	24/09/19 13:32	General View	 Load JPG	☒
86	24/09/19 13:32	General View	 Load JPG	☒
87	24/09/19 13:32	General View	 Load JPG	☒
88	24/09/19 13:32	General View	 Load JPG	☒
89	24/09/19 13:32	General View	 Load JPG	☒
90	24/09/19 13:32	General View	 Load JPG	☒
91	24/09/19 13:32	General View	 Load JPG	☒
92	24/09/19 13:32	General View	 Load JPG	☒
93	24/09/19 13:32	General View	 Load JPG	☒
94	26/09/19 17:14	Reinspection Photo	 Load JPG	☒
95	26/09/19 17:14	Reinspection Photo	 Load JPG	☒
96	26/09/19 17:14	Reinspection Photo	 Load JPG	☒
97	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
98	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
99	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
100	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
101	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
102	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
103	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
104	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
105	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
106	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
107	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
108	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
109	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
110	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
111	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
112	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
113	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
114	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
115	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
116	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
117	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
118	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
119	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
120	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
121	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
122	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
123	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
124	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
125	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
126	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
127	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
128	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
129	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
130	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
131	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
132	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
133	26/09/19 17:15	Reinspection Photo	 Load JPG	☒
134	26/09/19 17:15	Reinspection Photo	Load JPG	☒
135	26/09/19 17:15	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
136	26/09/19 17:15	Reinspection Photo		☒
137	26/09/19 17:15	Reinspection Photo		☒
138	26/09/19 17:15	Reinspection Photo		☒
139	26/09/19 17:15	Reinspection Photo		☒
140	26/09/19 17:15	Reinspection Photo		☒
141	26/09/19 17:15	Reinspection Photo		☒
142	26/09/19 17:15	Reinspection Photo		☒
143	26/09/19 17:15	Reinspection Photo		☒
144	26/09/19 17:15	Reinspection Photo		☒
145	26/09/19 17:15	Reinspection Photo		☒
146	26/09/19 17:15	Reinspection Photo		☒
147	26/09/19 17:15	Reinspection Photo		☒
148	26/09/19 17:15	Reinspection Photo		☒
149	26/09/19 17:15	Reinspection Photo		☒
150	26/09/19 17:15	Reinspection Photo		☒
151	26/09/19 17:15	Reinspection Photo		☒
152	27/09/19 17:41	Reinspection Photo		☒
153	27/09/19 17:41	Reinspection Photo		☒
154	27/09/19 17:41	Reinspection Photo		☒
155	27/09/19 17:41	Reinspection Photo		☒
156	27/09/19 17:41	Reinspection Photo		☒
157	27/09/19 17:41	Reinspection Photo		☒
158	27/09/19 17:41	Reinspection Photo		☒
159	27/09/19 17:41	Reinspection Photo		☒
160	27/09/19 17:41	Reinspection Photo		☒
161	27/09/19 17:41	Reinspection Photo		☒
162	27/09/19 17:41	Reinspection Photo		☒
163	27/09/19 17:41	Reinspection Photo		☒
164	27/09/19 17:41	Reinspection Photo		☒
165	27/09/19 17:41	Reinspection Photo		☒
166	27/09/19 17:41	Reinspection Photo		☒
167	27/09/19 17:41	Reinspection Photo		☒
168	27/09/19 17:41	Reinspection Photo		☒
169	27/09/19 17:41	Reinspection Photo		☒
170	27/09/19 17:41	Reinspection Photo		☒
171	27/09/19 17:41	Reinspection Photo		☒
172	27/09/19 17:41	Reinspection Photo		☒
173	27/09/19 17:41	Reinspection Photo		☒
174	04/10/19 09:27	Reinspection Photo		☒
175	04/10/19 09:27	Reinspection Photo		☒
176	04/10/19 09:27	Reinspection Photo		☒
177	04/10/19 09:27	Reinspection Photo		☒
178	04/10/19 09:27	Reinspection Photo		☒
179	04/10/19 09:27	Reinspection Photo		☒
180	04/10/19 09:27	Reinspection Photo		☒
181	04/10/19 09:27	Reinspection Photo		☒
182	04/10/19 09:27	Reinspection Photo		☒
183	04/10/19 09:27	Reinspection Photo		☒
184	04/10/19 09:27	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/19 08:50	od estimate		☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/09/19 09:11	Accident Sketch Plan [Linked Accident Report Documents]		☒
2	17/09/19 09:12	Accident Sketch Plan [Linked Accident Report Documents]		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
3	17/09/19 09:12	POLICE REPORT [Linked Accident Report Documents]		Load JPG ☒
4	17/09/19 09:12	POLICE REPORT [Linked Accident Report Documents]		Load JPG ☒
5	17/09/19 09:12	POLICE REPORT [Linked Accident Report Documents]		Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/09/19 11:51	ESTIMATE.pdf		Load PDF
2	24/09/19 13:29	SKE 2565S GIA.pdf		Load PDF
3	24/09/19 13:29	POLICE REPORT.pdf		Load PDF
4	24/09/19 13:29	ESTIMATE 1.pdf		Load PDF
5	30/09/19 09:52	SUPP.pdf		Load PDF
6	04/10/19 09:26	ESTIMATE & SUPP MARKED.pdf		Load PDF
7	11/10/19 13:52	Workshop Invoice		Load PDF
8	11/10/19 13:52	Discharge Voucher		Load PDF
9	11/10/19 13:52	Parts Invoice		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/09/19 09:13	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/09/19 09:12	Accident Photo		Load JPG ☒
2	17/09/19 09:12	Accident Photo		Load JPG ☒
3	17/09/19 09:12	Accident Photo		Load JPG ☒
4	17/09/19 09:12	Accident Photo		Load JPG ☒
5	17/09/19 09:12	Accident Photo		Load JPG ☒
6	17/09/19 09:12	Accident Photo		Load JPG ☒
7	17/09/19 09:12	Accident Photo		Load JPG ☒
8	17/09/19 09:12	Accident Photo		Load JPG ☒
9	17/09/19 09:12	Accident Photo		Load JPG ☒
10	17/09/19 09:12	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/09/19 09:11	Accident Sketch Plan		Load JPG ☒
2	17/09/19 09:12	Accident Sketch Plan		Load JPG ☒
3	17/09/19 09:12	POLICE REPORT		Load JPG ☒
4	17/09/19 09:12	POLICE REPORT		Load JPG ☒
5	17/09/19 09:12	POLICE REPORT		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119016521/USF3E2

Date: 11/10/2019

REFERENCE

Insured/Claimant: MISS TAN GEOK HONG Policy No: DMPCSN1507531904

Date of Loss: 16/09/2019

Nature of Claim: OD

Claim No: SNM19D204397C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE2565S

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)

Engine No: CZC232926

Reg. Date: 26/02/2015 (Man. Year: 2015)

Chassis No: WAUZZZ8V9F1092789

Colour: White

Odometer: 61997 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$72,000.00

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size:

215/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,232.45	8,098.90	1,133.55	12.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,720.00	1,530.00	47.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,482.45	9,818.90	2,663.55	21.34
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	11,482.45	8,818.90	2,663.55	23.20
+ GST 7.00/7.00% (S\$)	803.77	617.32	186.45	23.20
Nett Amount (S\$)	12,286.22	9,436.22	2,850.00	23.20

INSPECTION

Date of Assignment: 19/09/2019

Date Inspected: 23/09/2019 Inspected At:

Z-one Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6., Blk D #01-87,
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2019)
Parts: 144	AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE2565S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	600.00 F	*600.00 F
2	1		*FRONT BONNET	Buckled	990.00 F	*990.00 F
3	2		*FRONT BONNET HINGES L/R	Bent	70.00 F	*70.00 F
4	1		*FRONT BONNET ABSORBER	Not Necessary	45.00 F	*- F
5	1		*FRONT BONNET WEATHER STRIP	Necessary	20.00 F	*20.00 F
6	1		*FRONT BONNET MECHANISM LOCK L/R	N/S Twisted	176.00 F	*88.00 F
7	1		*FRONT BONNET LOCK STRIKER L/R	N/S Twisted	100.00 F	*50.00 F
8	1		*FRONT BONNET HEAT INSULATOR MAT	Not Necessary	85.00 F	*- F
9	11		*FRONT BONNET HEAT INSULATOR MAT CLIPS	Not Necessary	33.00 F	*- F
10	1		*FRONT GRILLE ASSY	Cracked	265.00 F	*265.00 F
11	2		*FRONT HEADLAMP L/R	Cracked	1,650.00 F	*1,650.00 F
12	2		*FRONT HEADLAMP NOZZLE COVER L/R	Not Necessary	50.00 F	*- F
13	2		*FRONT HEADLAMP NOZZLE MOTOR L/R	Not Necessary	180.00 F	*- F
14	1		*FRONT BUMPER	Dented / Deformed	770.00 F	*770.00 F
15	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	36.00 F	*- F
16	10		*FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 F
17	1		*FRONT BUMPER TOWING COVER	Not Necessary	20.00 F	*- F
18	2		*FRONT BUMPER FOG LAMP GARNISH L/R	Not Necessary	90.00 F	*- F
19	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	275.00 F	*275.00 F
20	1		*FRONT BUMPER INNER SPONGE	Torn	60.00 F	*60.00 F
21	1		*FRONT SUPPORT PANEL	Cracked	286.00 F	*286.00 F
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	20.00 F	*- F
23	5		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	15.00 F	*- F
24	1		*FRONT BUMPER NO. PLATE	Bent	25.00 FS	*15.00 FS
25	1		*FRONT BUMPER NO. PLATE GARNISH	Cut	50.00 FS	*50.00 FS
26	1		*FRONT BONNET LOCK STRIKER CENTER	Bent	50.00 F	*50.00 F
27	1		*FRONT HEADLAMP MODULE LH	Cracked	240.00 F	*240.00 F
28	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Torn	25.00 F	*25.00 F
29	1		*AIR CON CONDENSER (BENT / PUNCTURED)	Not Consistent With The Impact	265.00 F	*- F
30	1		*RADIATOR OUTER	Cracked	240.00 F	*240.00 F
31	1		*RADIATOR INNER	Cracked	240.00 F	*240.00 F
32	1		*RADIATOR TOP COVER	Cracked	30.00 F	*30.00 F
33	1		*RADIATOR FAN ASSY	Cracked	650.00 F	*650.00 F
34	1		*RADIATOR SIDE AIR GUIDE LH	Torn	20.00 F	*20.00 F
35	3		*RADIATOR COOLANT	Necessary	60.00 F	*60.00 F
36	1		*INTAKE AIR DUCT COVER CENTER	Cracked	25.00 F	*25.00 F
37	1		*INTAKE AIR DUCT CENTER	Cracked	40.00 F	*40.00 F
38	1		*AIR GUIDE CENTER UPPER	Cracked	12.00 F	*12.00 F
39	1		*TEMPERATURE SENSOR BRACKET	Bent / Cracked	20.00 F	*20.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*WASHER TANK	Deformed	80.00 F	*80.00 F
41	1		*WIPER PANEL TOP GARNISH	Cut	90.00 F	*90.00 F
						F=Franchise part. S=SpcNett.
Sub Total (S\$)					8,038.00	7,051.00
+ Margin on L,N Items 15.00/15.00% (S\$)					1,194.45	1,047.90
Total Parts (S\$)					9,232.45	8,098.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS (TO FR)	New	180.00	100.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	120.00	20.00
3	DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNTIONING	New	200.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL	New	200.00	0.00
7	TO REMOVE, CHANGE RADIATOR, PARTS, PRESSURE TEST, REPLACE COOLANT	New	150.00	0.00
Gross Labour Cost (S\$)			3,250.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >