

REC. BY: Steve.

REF:

NTUC

NSI/INC 19016523/Envf32v

ASSIGNMENT

From: _____ Date: 18/9/19

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 6128 K

at Workshop m/s: SMRT

of: Woodlands Depot

Insured: SKS 7070X

Policy No: 5097726394-01C 30/01/2019-29/01/2020

Claims No: MT 1064577-001


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 6128 K. Yr Regn: 06/Nov/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius. C.C 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 379274 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: JTPKN364805766681

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken.

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 16/09/2019 D.O.I. 18/09/2019

Survey held at SMRT

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 6128 K - NSI/INC 19016523/2019 D.O.A. - 14/07/2019 TP
	SKS 7070X - (LS) SKS 7070X
27/9/19	Finalize Confir 9950, 2 days (Red 5152, 8410) 09/19/2063.
	RECEIVED 30 SEP 2019

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: 2

1)

☐: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 30/9 - typist

Report Format: TP

Lump Sum / U.C. 950k

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Insp (\$)☐: Wheel end (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Other:

TOTAL

160

160

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5097726394-01		DAVID WONG CHIN WAH @ISKANDAR ABDULLAH WONG	S1617646Z	GPC	drivo CLASSIC	SKS7070X	SKS7070X	30/01/2019	29/01/2020

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHD6128K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6551643
Chassis No.:	JTDKN36U805766681
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	06 Nov 2015 ✓
First Registration Date:	06 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2023
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	05 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$23,381.00
Total Rebate Amount:	\$27,131.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Sep 2019

OK

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Monday, 30 September 2019 11:43 AM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi,

Claim created

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 30 September 2019 9:01 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number

Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
MT/1064577-001	SMRT TAXIS PTE LTD	SHD 6128K	SKS 7070X

D.O.A	Time of Accident	Estimate	Tentative repair cost
16/9/2019	18:50	\$6,102.00	\$950.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2019 16:06
Date Of Accident	16/09/2019 18:50
Exact Location Of Accident	OASIA HOTEL DRIVEWAY PECK SEAH STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6128K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	S MOGANARUBAN
NRIC No	S0072875F
Date Of Birth	23/04/1951
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG OASIA HOTEL DRIVEWAY, PECK SEAH STREET AS I WAS COLLECTING FARE FROM MY PASSENGER. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKS7070X HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS7070X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

A- SHD 6128K
B- SKS 7070X

[illegible]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

 17/9/2019
Driver's Signature
(If driver is not the policyholder)
Date & Time:

 17/9/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number :

TAX/09/19/2063

Type of Repair : Accident Repair

Vehicle Registration Number : SHD6128K

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8548-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 16/09/2019 10:50 AM

Vehicle Age(in Months) : 46

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ / PP
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓ / NEC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓ / short
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ / NEC
Total Spare Part Cost									3,383.89	Surveyor Total 730.80				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									2,707.11	Final Sur Total 584.64				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER LINE RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	* X SVC
Total Spare Part Cost									3,383.89	Surveyor Total		730.80		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,707.11	Final Sur Total		584.64		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	0	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			936.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	/ nec
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ nec
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ nec
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec.
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,707.11	584.64
Total Labour Cost	507.00	200.00
Total Spray Painting	936.00	200.00
Other	460.00	80.00
Overall Total	4,610.11	1,064.64
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,600.00	1,050.00
Surveyor Approved Amount		1,050.00
No of Repair Days*	5	2
Remarks	-	Lum-Sum Repair, Take after spray
Surveyor Name		STEVE CHEN

Signature

Estimator Assessment(\$)



Surveyor Assessment(\$)


19/9/19

Save

Clear

Survey Date

18/09/2019

18/09/2019.

Lump Sum Repair.

Repair Day - 2 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63655592
Estimator Telephone Number: 68062823
Accident Reporting Number: 68602072



Date Generated : 27/09/2019

User ID : PohSuan

Section A - Accident Details

Registration Number	SHD6128K
Case Reference Number	TAX/09/19/2063
Registration Date	6/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	S MOGANARUBAN
Type of Accident	Head to Rear
Accident Date and Time	16/9/2019 6:50 PM
Accident Reported Date and Time	17/9/2019 4:13 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103412
Special Instruction to ARC, if any	TP
Prepared Date and Time	17/9/2019 8:11 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$936.00	\$200.00
Total Spare Part Cost	\$3,383.89	\$730.80
Total Other Cost	\$460.00	(\$180.80)
TOTAL COST	\$5,286.89	\$950.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	19/09/2019 2:29 PM	18/09/2019 1:49 PM
Signature		
Remarks		Lum-Sum Repair, Take after spray

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0392	Invoice Number	
Quotation Date	23.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$260.80)
Total Other Costs	\$460.00	(\$180.80)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	PD
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	NEL
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	NEL
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given	X SVC
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X SVC
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X SVC
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	X SVC
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	short
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X SVC
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	NEL
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X SVC
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X SVC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 6552223
Accident Reporting Number : 60552672

Date Generated : 27/08/2018

User ID : PohHuan

	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	65637-47021	FENDER LINE RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
Total				\$4,180.10		\$730.80			

SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

730.80
+ 200.00
+ 280.00

1210.80

- 20%

968.64

L/S \$950/-

662

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Saturday, 28 September 2019 8:38 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHD6128K

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Friday, 27 September 2019 4:58 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: SHD6128K

Dear Poh Suan,

We confirm the finalize \$950 (L/S, before GST). 2 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Friday, September 27, 2019 11:26 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHD6128K

Hi Steve,

Attached herewith the repair estimate of SHD 6128K having Case No: TAX/09/19/2063.

There is no change to the approved amount of \$950 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Friday, 27 September 2019 11:28 AM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016523/Evf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 03-10-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 7070X	Veh. Inspected	SHD 6128K
Policy No.	5097726394-01	Coverage (\$)	0.00
Claim No.	MT/1064577-001	Excess (\$)	0.00
Assign From		Assign Date	18/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U805766681	Colour	MAROON
Odometer	379274	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2019	Inspection Date	18/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6128K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
2	PIXEL STICKER (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	SERVICEABLE	514.50	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	FENDER RR/RH	SERVICEABLE	766.80	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 65558888	SERVICEABLE	21.60	-
1	FENDER LINE RR/RH	SERVICEABLE	141.30	-
1	TAIL LAMP RH	SERVICEABLE	557.80	-
			4,259.00	730.80
<u>LABOUR</u>				
PANEL BEATING & BODY WORK.			507.00	200.00
SPRAY PAINT.			936.00	200.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	20.00
TO REPLACE SUNDRY PARTS.			100.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	20.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00

Report Ref No. NS/INC19016523/Evf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,903.00	480.00
GRAND TOTAL			6,162.00	1,210.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			950.00
---	--	--	--------

Report Ref No. NS/INC19016523/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.