



HUA HONG PRIVATE LIMITED

25D SUNGAI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

17 September 2019

QUOT201909-000022
HHTPCLAIMS19-173

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD, #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLS7014Y & SHC8539A ON 12/09/2019 ALONG WOODLANDS ROAD (CARWASH) AT ABOUT 1705 HOURS

Insured : FELIX NGU LEH ANG
Vehicle Registration No. : SLS7014Y
Vehicle Make : MAZDA
Vehicle Model : MAZDA3 SEDAN 1.5 AT LED EU6
Vehicle Chassis No. : JM6BN22A8J0175771
Policy No. : P10093164R00
Date of Accident : 12/09/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper		\$ / 866.00 / DD
2	1 SET 10	Front Bumper Clip	\$ 5.60	\$ 30 56.00 / NEC
3	1	Front Grille		\$ / 570.00 / CUT
4	1 2	Front Grille Chrome (LH/RH) Right	\$ 191.00	\$ 180 382.00 / CRA
5	1 SET 10	Front Grille Clip	\$ 5.80	\$ 30 58.00 / NEC
6	1	Emblem		\$ 75 196.00 / CRA
7	1	Emblem Base		\$ 102 196.00 / CRA
8	1	Front Grille Top Garnish		\$ X 95.00 X SVC
9	1 2	Front Grille Bracket (LH/RH) RH / CRA	\$ 34.00	\$ 34 68.00 / CRA
10	2	Front Grille Bracket Grommet	\$ 6.90	\$ / 13.80 / NEC
11	10	Rivet	\$ 6.80	\$ / 68.00 / NEC
12	1	Front Support Top Shroud		\$ / 130.00 / DD
13	1	Front Reinforcement		\$ / 501.00 / BT
14	1	Front Reinforcement Garnish		\$ / 135.00 / CRA
15	1	Front Lock Stay		\$ X 40.80 X SVC
16	1 2	Front Headlamp (LH/RH) Right	\$ 3,778.00	\$ 7,556.00 / CRA
17	1 2	Front Headlamp bracket (LH/RH) Right 1 / CRA	\$ 34.00	\$ 34 68.00 / CRA
18	1	Front No Plate Garnish		\$ / 68.00 / BY
19	1	Rear Bumper		\$ / 1,227.00 / PD
20	2	Rear Bumper Retainer (LH/RH)	\$ 38.00	\$ / 76.00 / NEC
21	1 SET 10	Rear Bumper Clip	\$ 4.80	\$ 30 48.00 / NEC
22	1	Rear Bumper Tow Cover		\$ X 16.90 X SVC
23	2 4	Rear Bumper Reverse Sensor 2 / OR 2 pcs NEW	\$ 202.00	\$ 300 808.00 /
24	1	Rear End Panel		\$ X 530.00 X R
25	1	Rear Reinforcement / BT		\$ / 563.00 / BT

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

17 September 2019

QUOT201909-000022
HHTPCLAIMS19-173

ACCIDENT INVOLVING SLS7014Y & SHC8539A ON 12/09/2019 ALONG WOODLANDS ROAD (CARWASH) AT ABOUT 1705 HOURS

Estimate Repair List for vehicle SLS7014Y - MAZDA MAZDA3 SEDAN 1.5 AT LED EU6

S/N	Quantity	Description	Unit Price S\$	Amount S\$
				\$ 14,336.50
			Less 20%	\$ 2,867.30
				\$ 11,469.20
26	1	Front No. Plate SCR	NETT	\$ 35.00 ³⁵
		To dismantle & change front bumper, front grille, front reinforcement, front LH/RH headlamp, rear bumper, rear reinforcement, knocking and pull straight front chassis frame, rear panel and rear tyre floor panel		\$ 1,200.00 ⁷⁰⁰
		To perform wire checking		\$ 20.00 ✓
		To dismantle & refit rear bumper sensor		\$ 60.00 ³⁰
		To spray front bumper, front grille garnish, front reinforcement, rear panel, rear reinforcement and rear tyre floor panel		\$ 1,200.00 ⁸⁰⁰
				\$ 13,984.20
			7% GST	\$ 978.89
			Total	\$ 14,963.09

[Signature]
8/10/19 Sun PM / 8661 2627
01/10/2019

Lump Sum Repair
Resurvey After Spray
TP without Prejudice.

L/S
\$ 6,950
5 days

Repair Day - 5 days

8,510.8
- 20%
P = 6,808.64
N = 335
L = 1,550
8,643.64
- 20%
6,914.91

[Signature]



Authorised by Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: