

ASS. REC. BY:

REF: CS/SM01901653L/DTf30 Special Instruction:

Surveyor Ronan ASSIGNMENT (Office)From (Person): Hwang Shiang Yi of Smo Date/Time: 19.9.19 11:14 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBV 9011 L Insured: FBP 4272 Yat Workshop m/s SG 98 Motor Tel: 64524898of Blk 401 Ame Industrial Park 1 #01-21Policy No: D19MIMC01002572 Claim No: CMTD1904378

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10.9.2019

(Client's Record)


CA / REV / REP. / REV 24 HRS mpn H.O.D. Endorsement: \_\_\_\_\_Date/Time: 19.9.19 11:38 a.m Person Contacted: Rose Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FBV 9011 L - x</u>
	<u>FBP 4272 Y - x</u>
<u>23/9-</u>	<u>revised via mennen</u>

# ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop No: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: FBN 9011L yr Regn: 2019 Jan  
 Type: M/Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Yamaha MX King CC: 150  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA  
 Eng. No: G3E6E0434488  
 C/No: MH3UG0710JK276601  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 70/90 R17  
 R: 70/90 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Maxxis  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 3 mm R/Bal: 3 mm  
 L/Bal: \_\_\_\_\_ mm L/Bal: \_\_\_\_\_ mm  
 D.O.A. 10/09/2019 D.O.I. 19/09/2019  
 Survey held at SG 98 AMK  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop of  
N/S Front y H/S Body y H/S Rear  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Sompo FBP 4272Y</u>
	<u>MV 8K</u>
	<u>LIA 3K</u>
	<u>HL 5K</u>
RECEIVED 05 FEB 2020	
<u>31/01/2020</u>	<u>Invoice 215 3250/- with 4 days of inv</u> <u>(cred 1748.10 34%)</u>

Site Title: For Pass out ☐ : Preli. Report  
☒ : Final Report  
 Days Of Repair: 4  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Ins (\$)  
☐ : (VISA) (\$)  
 Survey Fee: 250  
 Transportation: \_\_\_\_\_  
 S + PC: \$  
 Fuel: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 Total: 11  
261  
 TP  
3250/-

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2019		19 Sep 2019 11:14 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	KOH WEI KIAT BENJAMIN, ID: S9049049D, Tel: +6583416577, Email: xuweijie90@hotmail.com								
Main Claimant:	AHMAD SOLEHIN BIN MUHAMAD RIZAL, ID: S9902220E								
Vehicle Reg. No.:	FBN9011L	Date of Loss:	10/09/2019 12:00 - :59						
Claim Type:	TP / CMTD1904378	Policy/Cover Note No.:	D19MTMC01002572 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBP4272Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/09/2019]								
Driver/Custodian (Insured):	KOH WEI KIAT BENJAMIN (28 / Male), NRIC: S9049049D, Tel: +6583416577 Email: xuweijie90@hotmail.com								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 23 Sep 2019

## Preliminary Advice

Insured Vehicle No	: FBP4272Y	Accident Date	: 10/09/2019
TP Vehicle No	: FBN9011L	Assignment Date	: 19/09/2019
Make	: YAMAHA MX KING T150	Est. Duration of Repair	: 4.00
Date of Inspection	: 19/09/2019		
Inspection At	: SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front, n/s body, n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,998.10
Revised Amount	:S\$	4,124.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,124.30

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on "WP"

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	18/09/2019 11:30
Date Of Accident	10/09/2019 12:00
Exact Location Of Accident	JURONG WEST CENTRAL 1
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN9011L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AHMAD SOLEHIN BIN MUHAMAD RIZAL
NRIC No	S9902220E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97796854
Alternative Phone No	OFFICE-97796854

#### Vehicle Particulars

Manufacturer	YAMAHA
Model	MX KING T150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5106808516
Cover Note Number	

#### Driver

Name of Driver	AHMAD SOLEHIN BIN MUHAMAD RIZAL
NRIC No	S9902220E
Date Of Birth	27/01/1999
Occupation	INDOOR
Date Of Driving Pass	24/04/2017
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97796854
Fax Number	
Contact Number	OFFICE-97796854
EMail Address	NOEMAIL

Address	BLK 474 JURONG WEST STREET 41 #07-406
Postcode	640474
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HONG KAH SOUTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 510 JURONG WEST STREET 52 , POSTCODE: 640510 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5648999 - FAX NO: 66655797
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBP4272Y
Vehicle Make/Model/Colour	
Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

REFER POLICE REPORT AND ATTACHED

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

AHMAD SOLEHIN BIN MUHAMAD RIZAL

Approximate Age

Injuries Sustain

JAW UPCUTS, TEETH BROKEN & ABRASION BOTH HAND

Injured person in which vehicle?

FBN9011L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRC/FIN No.:



# Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report M: T 20190911 2193.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Amo  
Policyholder's Signature  
Date & Time:

Amo  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190911/2183

1 of 3

Police Station Of Origin:  
Hong Kah South NPP  
51 0 Jurong West Street 52 #01-90  
SINGAPORE 640510  
Tel No: 1800-5648999

Report No. T/20190911/2183

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/09/2019 20:48	Vide Report No.:	Station Diary No.: 32
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: AHMAD SOLEHIN BIN MUHAMAD RIZAL			Address: APT BLK 474 JURONG WEST STREET 41 #07-406 SINGAPORE 640474		
ID Type / ID No.: NRIC NO / S9902220E			Contact No.: Home/Office: Mobile: 97796854		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 20	Date of Birth: 27/01/1999	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation: DELIVERY RIDER			Driving Licence Information: Class: 2B Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/09/2019 12:00	Type of Location: Straight Road
Location: Along Road 1 JURONG WEST CENTRAL 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN9011L	Motorcycle	YAMAHA	MX KING T150 MANUAL	Black	Slightly Damaged	0
FBP4272Y	Motorcycle					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



# SINGAPORE POLICE FORCE



T/20190911/2183

Police Station Of Origin:  
Jurong Kah South NPP  
1 Jurong West Street 52 #01-90  
SINGAPORE 640510  
No: 1800-5648999

2 of 3

Report No. T/20190911/2183

## CONTINUATION OF REPORT

### Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
N9011L	NTUC Income Insurance Co-Operative Limited	5106808516	04/01/2019	03/01/2020

### Details of Person Involved

Any Pedestrian Involved: No			
Number of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	AHMAD SOLEHIN BIN MUHAMAD RIZAL		ID No. S9902220E
Related Vehicle	FBN9011L (Motorcycle)		Contact No. 97796854
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B Date of Expiry: NIL
Date of Treatment	10/09/2019		Date Discharge 11/09/2019
Number of Days granted Medical Leave	14	Degree of Injury	Slight

### Additional Details.

On 10/9/19, around 1200hrs, I was riding V1) FBN9011L, along Jw Ctrl 1 in the first lane going straight. Subsequently, V2) FBP4272Y, which was on the second lane, abruptly changed lane into my lane. As a result, V1 collided into the rear left portion of V2. I passed out and was conveyed to NTFGH where I received 14 days MC.



**SINGAPORE  
POLICE FORCE**



T/20190911/2183

Police Station Of Origin:  
Hong Kah South NPP  
510 Jurong West Street 52 #01-90  
SINGAPORE 640510  
Tel No: 1800-5648999

3 of 3

Report No. T/20190911/2183

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt MUHAMMAD ZHARIF BIN ZAINUDIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/09/2019 20:48

Officer In Charge Of Case:

TP / GIT /

Sgt 2 HO JIEKANG, IVAN

Contact No.: 65476170

Classification Of Case:

Authentication Stamp

NP168

SN 1251

Signature :

**Singapore Police Force**

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 19th September 2019

To : LKK

By Fax:

Attn : Bryan

Tel :

VEHICLE NO : FBN 9011L

Yamaha Jupiter MX King T150

ACCIDENT DATE: 10/9/2019

	Description	Qty	Quotation \$
Front			
1	Front Mudguard <del>broken</del> broken	1	205.00 ✓
2	Handle Bar <del>broken</del> broken	1	165.00 ✓
3	Clutch lever cut	1	95.00 ✓
4	Handle Grip <del>from n/s</del> o/s n/s	1 set	120.00 ✓ 60.00
5	Bar End <del>cut n/s</del> o/s n/s	1 set	130.00 ✓ 65.00
6	Handle Bar Bracket n/s	1	155.00 X
7	Head Lamp cut	1	450.00 ✓
8	Top Cover cut	1	155.00 ✓
9	Mirror <del>broken</del> dislodged n/s o/s n/s	1 set	160.00 ✓ 80.00
10	Front Panel cut	1	190.00 ✓
11	signal Lamp LH cut	1	80.00 ✓
12	Front Inner-Garnish Panel <del>cut</del> cut	1	155.00 ✓
13	Front Side Panel LH (Fairing) cut	1	195.00 ✓
14	Fork Under Bracket <del>dislodged</del> dislodged	1	195.00 ✓
15	Fork Tube <del>broken</del> broken	1 set	480.00 ✓
16	Fork Oil Seal <del>broken</del> broken	1 set	125.00 ✓
17	Front Rim <del>broken</del> dislodged	1	250.00 ✓
18	Head Lamp Switch Cover n/s	1	165.00 X
19	Front Foot Rest LH broken	1	79.00 ✓
20	Gear Pedal cut/broken	1	78.00 ✓
21	Foot Rest Bracket broken	1	125.00 ✓
22	Rear LH Tail Panel cut	1	195.00 ✓
23	Rear LH Signal broken	1	80.00 ✓
24	Pillion Grip n/s	1	69.00 X
25	Radiator Assembly <del>broken</del> punctured	1	395.00 ✓
26	Re Upholstery Seat Cover n/s	1	168.00 X

front basket  
front basket - \$45.00 ✓  
front wheel shaft & 85.00 ✓  
4027.00  
10% 3624.30

Sub-Total 4,659.00  
Less 10% 465.90  
Sub-Total 4,193.10

VEHICLE NO : FBN 9011L

Yamaha Jupiter MX King T150

Nett items

- |   |                   |           |
|---|-------------------|-----------|
| 1 Towing fees   | 40.00             | NH        |
| 2 Remove & replace necessary parts, align & etc               | <del>250.00</del> | 200/-     |
| 3 Remove & replace fork Assembly, Front Rim & top up fork oil | <del>200.00</del> | 80/-      |
| 4 Supply body decal sticker                                   | 120.00            | 80/-      |
| 5 Re Adjust front alignment                                   | 180.00            | 80/-      |
| 6 Front Number Plate  | 15.00             | cut 15.00 |

Sub-Total 805.00

Nett Total 4,998.10

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

4079.30

4/s 3250/-

5115.10

19/09/2019 @ 1800hrs

Not Antenna

2/sum 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Man

LKK Auto

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2019		19 Sep 2019 11:14 <a href="#">Edit Adj Rpt</a>	<b>S\$3,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>KOH WEI KIAT BENJAMIN</b> , ID: S9049049D, Tel: +6583416577, Email: xuweijie90@hotmail.com									
Main Claimant: <b>AHMAD SOLEHIN BIN MUHAMAD RIZAL</b> , ID: S9902220E									
Vehicle Reg. No.:	<b>FBN9011L</b>	Date of Loss:	10/09/2019 12:00 - :59 [8 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1904378</b>	Policy/Cover Note No.:	D19MTMC01002572 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>FBP4272Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Sg 98 Motor Pte Ltd (HQ)</b> BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Hwang Shiang Yi</b> - 6329 5205]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 30/09/2019]								
Driver/Custodian (Insured):	<b>KOH WEI KIAT BENJAMIN</b> (28 / Male), NRIC: S9049049D, Tel: +6583416577 Email: xuweijie90@hotmail.com								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBN9011L (CMTD1904378)  
[FBP4272Y]

TP

AHMAD SOLEHIN BIN MUHAMAD RIZAL


















































Sep 10 2019 12:00PM





























[KOH WEI KIAT BENJAMIN]

Sg 98 Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print		
1	23/09/19 16:38		Adjuster Immediate Advice									Load HTM		
									3 per page			<input checked="" type="checkbox"/>		
Photos/Images														
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print		
1	29/01/20 14:16		Front View Right									Load JPG <input checked="" type="checkbox"/>		
2	29/01/20 14:16		Front View Left									Load JPG <input checked="" type="checkbox"/>		
3	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
4	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
5	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
6	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
7	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
8	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
9	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
10	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
11	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
12	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
13	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
14	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
15	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
16	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
17	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
18	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
19	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
20	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
21	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
22	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
23	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
24	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
25	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
26	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
27	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
28	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
29	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
30	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
31	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
32	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
33	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		
34	29/01/20 14:17		General View									Load JPG <input checked="" type="checkbox"/>		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
60	29/01/20 14:17	General View	 Load JPG	<input checked="" type="checkbox"/>
61	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	29/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	29/01/20 14:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	29/01/20 14:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	29/01/20 14:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	29/01/20 14:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/19 10:38	PRI - LKK	 Load HTM	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19016536/DTF3E2

Date: 06/02/2020

### REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01002572

Claimant Vehicle No : FBN9011L

Insured Vehicle No : FBP4272Y

Date of Loss: 10/09/2019

Nature of Claim: TP

Claim No: CMTD1904378

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN9011L

Make &amp; Model: YAMAHA MX KING T150, 150cc

Engine No: G3E6E0434488

Reg. Date: 02/01/2019 (Man. Year: 2018)

Chassis No: MH3UG0710JK276601

Colour: Black

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size: 70/90 R17

Front Left Side: Maxxis 3 mm

Rear Left Side: Maxxis 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,325.10	3,639.30	685.80	15.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	440.00	350.00	44.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,115.10</b>	<b>4,079.30</b>	<b>1,035.80</b>	<b>20.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,115.10</b>	<b>3,250.00</b>	<b>1,865.10</b>	<b>36.46</b>

### INSPECTION

Date of Assignment: 19/09/2019

Date Inspected: 19/09/2019 Inspected At:

Sg 98 Motor Pte Ltd (HQ)  
BLK 4001 ANG MO KIO INDUSTRIAL  
PARK 1 #01-21  
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 06 Feb 2020)

Parts: N/A YAMAHA MX KING T150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN9011L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Broken	205.00 FL	*205.00 FL
2	1		*HANDLE BAR	Bent	165.00 FL	*165.00 FL
3	1		*CLUTCH LEVER	Cut	95.00 FL	*95.00 FL
4	1		*SET HANDLE GRIP	N/S Torn / O/S Not Necessary	120.00 FL	*60.00 FL
5	1		*SET BAR END	N/S Cut / O/S Not Necessary	130.00 FL	*65.00 FL
6	1		*HANDLE BAR BRACKET	Not Necessary	155.00 FL	*- FL
7	1		*HEAD LAMP	Cut	450.00 FL	*450.00 FL
8	1		*TOP COVER	Cut	155.00 FL	*155.00 FL
9	1		*SET MIRROR (O/S NOT NECESSARY)	N/S Broken / Dislodged	160.00 FL	*80.00 FL
10	1		*FRONT PANEL	Cut	190.00 FL	*190.00 FL
11	1		*SIGNAL LAMP LH	Cut	80.00 FL	*80.00 FL
12	1		*FRONT INNER - GARNISH PANEL	Cut	155.00 FL	*155.00 FL
13	1		*FRONT SIDE PANEL LH (FAIRING)	Cut	195.00 FL	*195.00 FL
14	1		*FORK UNDER BRACKET	Distorted	195.00 FL	*195.00 FL
15	1		*SET FORK TUBE	Bent	480.00 FL	*480.00 FL
16	1		*SET FORK OIL SEAL	Necessary	125.00 FL	*125.00 FL
17	1		*FRONT RIM	Bent / Distorted	250.00 FL	*250.00 FL
18	1		*HEAD LAMP SWITCH COVER	Not Necessary	165.00 FL	*- FL
19	1		*FRONT FOOT REST LH	Bent	79.00 FL	*79.00 FL
20	1		*GEAR PEDAL	Cut / Bent	78.00 FL	*78.00 FL
21	1		*FOOT REST BRACKET	Bent	125.00 FL	*125.00 FL
22	1		*REAR LH TAIL PANEL	Cut	195.00 FL	*195.00 FL
23	1		*REAR LH SIGNAL	Broken	80.00 FL	*80.00 FL
24	1		*PILLION GRIP	Not Necessary	69.00 FL	*- FL
25	1		*RADIATOR ASSEMBLY	Punctured	395.00 FL	*395.00 FL
26	1		*RE UPHOLSTERY SEAT COVER	Not Necessary	168.00 FL	*- FL
27	1		*FRONT BASKET	Bent	45.00 FL	*45.00 FL
28	1		*FRONT WHEEL SHAFT	Bent	85.00 FL	*85.00 FL
29	1		*FRONT NUMBER PLATE	Cut	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,804.00	4,042.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	478.90	402.70

Total Parts (\$\$)	4,325.10	3,639.30
--------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEES	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	250.00	200.00
3	REMOVE & REPLACE FORK ASSEMBLY, FRONT RIM & TOP UP FORK OIL	New	200.00	80.00
4	SUPPLY BODY DECAL STICKER	New	120.00	80.00
5	RE ADJUST FRONT ALIGNMENT	New	180.00	80.00
Gross Labour Cost (\$\$)			<b>790.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >