

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 20 Sep 2019

Preliminary Advice

Vehicle No	: SJP3467P	Accident Date	: 17/09/2019
Make	: HONDA STREAM	Policy No.	: Z19VP05023282
Assignment Date	: 19/09/2019	Excess	: S\$500.00
Date of Inspection	: 19/09/2019	Est. Duration of Repair	: 5.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages FRONT portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,055.35
Revised Amount	:S\$	7,182.60
Check Items (Estimated)	:S\$	672.75
Total	:S\$	7,855.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	14,866.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,134.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :