

Vehicle number	: SGV2142L
Make / Model	: TOYOTA/WISH
Chassis number	: ZNE100368879
Accident date	: 16/9/19
Reference	: 1909-31

Qty Particulars Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	577.40 de ✓
2	FRONT BUMPER COVER	104.88 X
2	FRONT BUMPER RETAINER	145.30 LH X RH ✓
1	FRONT BUMPER REINFORCEMENT	339.36 X
1	FRONT BUMPER SPONGE	194.10 X
1	FRONT BUMPER LOWER GRILLE	217.30 X
1	FRONT GRILLE	193.40 X
1	FRONT SUPPORT PANEL	681.50 X
2	HORN	161.30 X
1	FRONT RH FENDER	697.44 bt ✓
1	FRONT RH FENDER INNER SHIELD	181.55 X
2	HEADLAMP	1635.60 LH X RH X ca ✓
2	FRONT FOG LAMP COVER	248.90 LH X RH X
1	SUPPORT PANEL TOP GARNISH	254.00 X
		5632.03
Less 25%		1408.01
Subtotal		4224.02
Balance C/F		4224.02
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		4224.02
1	FRONT NUMBER PLATE	70.00 X
1 SET	FRONT BUMPER CLIP	60.00 30 net ✓
1 SET	FRONT FENDER INNER SHIELD CLIP	50.00 X
1	FRONT BUMPER LOWER LIP	800.00 X
Subtotal		980.00
Balance C/F		5204.02
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
Balance B/F		5204.02
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30 ✓
2	PANEL BEATING ON AFFECTED AREAS	1600.00 400 ✓
3	SPRAY PAINTING ON AFFECTED AREAS	1600.00 400 ✓
4	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30 ✓
Subtotal		3410.00
Grand total		8614.02
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		

Acknowledged by Repairer
Signature:

Tanph
9/9/19
19/9/19
Lump sum
Repairing after repair
3 days
See Clerk for more