

ASS. REC. BY:

REF: CS/CT1 19016544/04 f322 Special Instructions.

Surveyor MARCUS ASSIGNMENT (Office)

From (Person): Ang din Kint of C71 Date/Time: 19.9.19 10:59 a.m

Estimated Cost: _____ Bill to: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 444T Insured: GBD 1192C

at Workshop m/s Kah Motor Tel: 68465671

15 ubi Road 4

Policy No. bmcvsN30363019011 Claim No. SNM19020439602

Sum Insured:	Excess:
--------------	---------

Make of Veh: _____ D.O.A. 17.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12.9.19 11:29 a.m. Person Contacted: Ah Hien Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
-----------	---------------------------------

579A 4441-X

[illegible]

(08/11/13) wef

REF:

ASS. REC. BY: *MARFAS*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAG Accident Rpt:

GA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

179X

Vehicle: IN / OUT

Veh No: *SMA 4447*Yr Regn: *5-18*Type: *C* Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.A.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$) S + RS (\$)
 Interview (\$) Photos
 Tech. Invs (\$) Others
 Weekend (\$)

Survey Fee:

Transportation:

TOTAL

220

220

RECEIVED 7 NOV 2019

6/11/2019

PP \$18,518-00

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Rptd	Status
Main	19 Sep 2019		19 Sep 2019 10:59 Assign				New Assignment Cancel Case

Topic	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ISO-TEAM CORPORATION PTE LTD, Co. Reg. No.: 199608218E								
Main Claimant:	TAN MING SIEW, ID: S7609179Z								
Vehicle Reg. No.:	SMA444T	Date of Loss:	17/09/2019 18:00 - :59 [16 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204396C02	Policy/Cover Note No.:	DMCVSN30363019011						
Vehicle Reg. No. (Insured):	GBD1192C	Policy No. (Claimant):	18-MT102350-R00						
		Excess:	\$40.00						
Re-insurer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Company's Account:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/09/2019]								
Driver/Custodian (Insured):	MOLLA MOHAMMAD AL HELAL (26 / Male), NRIC: G2150907N Email:								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
To: [Email Address] Case.									
ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Task	Priority	Type	Task Group	Subject	Handler	Assignment By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2019 11:35
Date Of Accident	17/09/2019 18:30
Exact Location Of Accident	JUNCTION TAMPINES AVE 10&TAMPINES INDUSTRIAL AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA444T
Insured/Policyholder	
Name Of Registered Owner	TAN MING SIEW
NRIC No	S7609179Z
Email Address	MINGSIEW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98151127
Alternative Phone No	OFFICE-98151127

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.5 TURBO VTI-S SR (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MT102350-R00
Cover Note Number	

Driver

Name of Driver	TAN MING SIEW
NRIC No	S7609179Z
Date Of Birth	31/03/1976
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1998
Driving Experience	21 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98151127
Fax Number	
Contact Number	OFFICE-98151127
EEmail Address	MINGSIEW@GMAIL.COM

Address	7 TAMPINES AVENUE 8 #15-12
Postcode	529597
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD1192C
Vehicle Make/Model/Colour	TOYOTA/DYNA/GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOLLA MOHAMMAD AL HELAL
NRIC/Passport Number	063840785
Contact Number	98718297
Address	TMS ALLIANCES PTE LTD 8 CHANGI NORTH ST 1
Postcode	498829
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Number: SMN444T

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 18 Sept 2019

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN NO.:

Vehicle Number: SMA 444T

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17 Sept 2019, 630 pm, I was driving home. At traffic junction of Tampines Ave 10 & Tampines Industrial Ave 3, I slow down to stop due to traffic light turning red. My car is SMA 444T.

Suddenly in my stationary mode, a vehicle hit me from behind. It was a commercial lorry with 3 passengers in front including the driver. The lorry is GBD 1192C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18 Sept 19

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo







GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6724 0030 Fax (65) 6724 0030
Operating Hours: Monday To Friday, 09:00 - 17:00
UEN: S405500200 / GST Reg. No.: M400017738

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorized Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No. MWM114123606 Vehicle Registration No. SMA 144T
Name (as shown in NRIC): TAN MING SIEW NRIC/FIN/Passport No.: 576091792
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No.: 98151124
Email Address : Mingsiew@gmail.com
Date of Accident : 17/09/2019 Time of Accident : 18:30
Place of Accident : JUNCTION OF TAMPINES AVE 10 & TAMPINES INDUSTRIAL AVE 2
Insurance Company: TOKIO MARINE


(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amendment of claim type from own damage to
third party claims.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	179Z
Vehicle Details	
Vehicle No.:	SMA444T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	L15B73621201
Chassis No.:	MRHFC1660JT000031
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$25,692.00
Original Registration Date:	23 May 2018
First Registration Date:	23 May 2018
Transfer Count:	0
Actual ARF Paid:	\$27,969.00 13984
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2028
PARF Rebate Amount:	\$20,976.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$32,382.00
Total Rebate Amount:	\$53,358.00

The information contained herein is correct as at 19 Sep 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal Coe Toyota Vios 1.5A E



2.88% P.A. \$0 Down, \$0 Admin,
Monthly From \$438, 2 Year
Warranty Engine
GV Credit Pte Ltd StarAc

ABWIN

ONE


[Browse by Category](#)
[Sort by Date Posted](#)

13 vehicles

civic

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	civic		Any	Any	2018	Any	Any	



Honda Civic 1.6A VTI (OPC)

\$75,800

\$7,660 /yr

25-Apr-2018

1,597 cc

3,800 km

100% Immaculate And Stock Condition! 100% Guarantee Accident Free! Delivery In 5 To 7 Days! 24/7 Road Service Provided! STA Inspection Welcome! Shop With A Peace Of Mind From Car Design, A 22 Years Accredited SVTA Approved Company! Call Our Friendly S

Posted: 18-Sep-2019 Tags: 2018 Honda Civic, 2018 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



Honda Civic 1.6A VTI

\$83,800

\$8,900 /yr

11-Jan-2018

1,597 cc

35,331 km

1 Owner, 5 Years Agent Warranty. High Trade In Possible. Loan From 2.28%. Call Now.

Mayfair Motoring

Posted: 16-Sep-2019 Tags: 2018 Honda Civic, 2018 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



Honda Civic 1.5A VTEC Turbo Sunroof

\$107,800

\$10,240 /yr

25-Oct-2018

1,498 cc

10,000 km

Price Reduced! Huge Savings From New, Buy With Confident With Valid Kah Motors Warranty, 1 Free Servicing With Kah Motor, Accident Free, Low Mileage Done At 10,000km, Condition Like New! In House Financing Available, Do Not Miss, Call Now!

Horizon Motoring

Posted: 15-Sep-2019 Tags: 2018 Honda Civic, 2018 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



Honda Civic 1.5A VTEC Turbo Sunroof

\$97,800

\$9,490 /yr

28-Jun-2018

1,498 cc

26,000 km

Graded A by **STP**

5 Years/100,000km Warranty Until Jun/2023 By Kah Motors. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan At Interest Rate And Competitive Trade In Price! Call Now To Find Out More! GST Included In Price!

Autolink Holdings Pte Ltd

Posted: 14-Sep-2019 Tags: 2018 Honda Civic, 2018 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



Honda BTCC title bid gains momentum

Honda British Touring Car Championship drivers head to Croft for the next three rounds of the series, knowing that the fast circuit will present challenges.

[Read this article](#)

[Compare](#)

1a Civic 1.5A VTEC Turbo
oof

\$105,800

\$9,960 /yr

18-Oct-2018

1,498 cc

10,658 km

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19004108	Page	1
	3 ANSON ROAD #16-00	Date	: 18. Sep 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMA444T	Engine No	: L15B73621201		
Chassis No	: MRHFC1660JT000031	Date Time	: 18. Sep 2019 10:11:49 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: TAN MING SIEW	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TPDS CLAIMS-J/NO: 73466						
	POLICY/CLAIMS NO:						
	OWNER: TAN MING SIEW						
	INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 17/09/2019						
	SURVEYED BY:						
	DATE:						
	AUTHORIZED ON:						
	TP VEH NO: GBD1192C						
	TP INSURER: CHINA TAIPING INSURANCE						
68500-TEA-N00ZZ	LID COMP TRUNK <i>sent/sec</i>	1	486.20	5	461.89	32.33	494.22
74865-TEA-T01	WEATHERSTRIPTRUNK LID <i>twi</i>	1	70.00	5	66.50	4.66	71.16
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE <i>one</i>	1	100.60	5	95.57	6.69	102.26
68660-TEA-T10ZZ	HINGE COMPL.TRUNK <i>sent</i>	1	44.80	5	42.56	2.98	45.54
68610-TEA-T10ZZ	HINGE COMPR.TRUNK <i>sent</i>	1	44.80	5	42.56	2.98	45.54
74851-TEA-003	LOCK ASSYTRUNK <i>twi</i>	1	74.30	5	70.58	4.94	75.52
75724-TBA-A00	EMBLEM <i>set</i>	1	24.20	5	22.99	1.61	24.60
75722-TBA-A00	EMBLEM SETRR. <i>set</i>	1	11.80	5	11.21	0.78	11.99
08F13-TEA-7T0AX	TRUNK SPOILERWING TYPE <i>one</i>	1	700.00	5	665.00	46.55	711.55
39530-TEA-H01	CAMERA ASSY,RR VI <i>su</i>	1	315.60	5	299.82	20.99	320.81
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS <i>su</i>	1	28.10	5	26.69	1.87	28.56
39680-TEX-Y41ZT	SENSOR ASSY,PARKING <i>shwd</i>	4	145.80	5	554.04	38.78	592.82
38387-TZ5-A01	ANTENNA ASSYL.F. <i>su</i>	1	59.30	5	56.33	3.94	60.27
74940-SZW-003	BUZZER ASSYSMART <i>su</i>	1	61.30	5	58.23	4.08	62.31
34155-TEX-Y01	LIGHT ASSYL.LID <i>one</i>	1	122.30	5	116.18	8.13	124.31
34150-TEX-Y01	LIGHT ASSYR.LID <i>su</i>	1	122.30	5	116.18	8.13	124.31
33550-TEA-T01	TAILLIGHT ASSYL. <i>one</i>	1	281.30	5	267.23	18.71	285.94
33500-TEA-T01	TAILLIGHT ASSYR. <i>one</i>	1	261.40	5	248.33	17.38	265.71

Printed on 18/9/2019 3:03:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
Registration No : SMA444T
Chassis No : MRHFC1660JT000031
Model : CIVIC 1.5 TURBO VTIS YM2018
Owner's Name : TAN MING SIEW
Ins Policy No. :
Date of Accident :

Document No. : SQT19004108 **Page** 2
Date : 18. Sep 2019
Customer No. : WZC008
Svc Advisor : RUEBEN THOMAS
Engine No : L15B73621201
Date | Time : 18. Sep 2019 10:11:49 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
34100-TEA-T11	LIGHT ASSYLICENSE	11	62.90	X	5	59.75	63.93
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	0.5	617.20	✓	5	586.34	627.38
91505-TM8-003	CLIP,BUMPER	8	2.30	✓	5	17.48	18.70
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	✓	5	34.58	37.00
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	✓	5	8.26	8.84
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE	1	8.40	✓	5	7.98	8.54
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	11	8.40	X	5	7.98	8.54
71598-TEA-T01	SPACERL,RR.BUMPER SIDE	1	11.50	✓	5	10.92	11.68
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	✓	5	10.92	11.68
71555-TBA-A00	BRACKETL,RR.BUMPER SIDE	1	2.30	✓	5	2.18	2.33
71505-TBA-A00	BRACKETR,RR.BUMPER SIDE	11	2.30	X	5	2.18	2.33
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	✓	5	156.46	167.41
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	✓	5	230.94	247.11
66154-TBA-A00ZZ	STIFFENERL,RR.PANEL SIDE	1	26.70	✓	5	25.36	27.14
66114-TBA-A00ZZ	STIFFENER,R,RR.PANEL SIDE	1	26.70	✓	5	25.36	27.14
04646-TEA-T00ZZ	PANEL SETL,RR.OUTSIDE	1	711.60	✓	5	676.02	723.34
73550-TEA-T02	GLASS ASSY,R.QUARTER WINDSHIELD	1	136.60	✓	5	129.77	148.21
65550-TED-P00ZZ	PAN COMPSPARE TIRE	1	216.70	✓	5	205.86	220.27
65666-TEA-T00ZZ	FRAMEL,RR.FRAME RR.UPPER	1	40.90	✓	5	38.85	41.57
65665-TEA-T00ZZ	STIFFENER BL,RR.FLOOR SIDE	1	27.30	✓	5	25.93	27.75
65663-TEA-T00ZZ	STIFFENER BL,RR.FRAME	1	19.70	✓	5	18.71	20.02
65676-TBA-A00ZZ	GUSSETL,RR.PANEL	1	20.70	✓	5	19.66	21.04
65669-TEA-T00ZZ	BRACKETL,RR.BUMPER BEAM	1	26.20	✓	5	24.89	26.63
65696-TEA-T00ZZ	BRACKETRR.BUMPER BEAM LOWER	1	23.90	✓	5	22.70	24.29
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	32.90	✓	5	31.25	33.44
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	11	50.30	X	5	47.78	51.12
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	60.20	X	5	57.19	61.19
84651-TEA-Q01ZA	LINING ASSYL,TRUNK SIDE	1	48.90	✓	5	46.45	49.70
84601-TEA-Q01ZA	LINING ASSYR,TRUNK SIDE	1	48.90	X	5	46.45	49.70

Printed on 18/9/2019 3:03:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19004108	Page	3
	3 ANSON ROAD #16-00	Date	: 18. Sep 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMA444T	Engine No	: L15B73621201		
Chassis No	: MRHFC1660JT000031	Date Time	: 18. Sep 2019 10:11:49 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: TAN MING SIEW	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84542-TET-H00	BOX COMPTOOL	1	38.00	5	36.10	2.53	38.63
73211-TEA-T02	GLASS SET,RR.WINDSHIELD	1	932.10	5	885.49	61.98	947.47
73227-TEA-003	RUBBER CWINDSHIELD DAM	1	17.20	5	16.34	1.14	17.48
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	9.70	5	27.64	1.93	29.57
91501-S70-003	FASTENER BW/SHIELD	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	7.22	0.51	7.73
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90	5	5.51	0.39	5.90
73125-SR3-000	RUBBER, W/SHIELD	1	12.60	5	11.97	0.84	12.81
73126-SR3-000	RUBBER, W/SHIELD	1	14.40	5	13.68	0.96	14.64
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
Sum Item					6942.85	485.99	7,428.84
BO-3M-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT.	3	100.00		300.00	21.00	321.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG51R	REPLACE RR. L QTR GLASS.(N)	1	200.00		200.00	14.00	214.00
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00		250.00	17.50	267.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00		320.00	22.40	342.40
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		350.00	24.50	374.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	350.00		350.00	24.50	374.50

Printed on 18/9/2019 3:03:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19004108	Page	4
	3 ANSON ROAD #16-00	Date	: 18. Sep 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMA444T	Engine No	: L15B73621201		
Chassis No	: MRHFC1660JT000031	Date Time	: 18. Sep 2019 10:11:49 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: TAN MING SIEW	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	350.00	✓	350.00	24.50	374.50
BKRP22M	CUT RR PANEL, RR FLOOR, RR L FENDER, CUT RRL CHAS.	1	7400.00	6440.	7400.00	518.00	7918.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3300.00	3150	3300.00	231.00	3531.00
Sum Labor					14090.00	986.30	15,076.30

Survey By: Marius Nkh
 Date & Time: 19/9/19 @ 2.20pm.
 Excess: —
 Status: not author
 Signature: Take photo before painting
1 Day.

Total Amount 21,332.85 1,493.29 22,826.14
Total (Inclusive of GST) 22,826.14

USE App Consultants hence notify
 and Customer of the following:
 1. The estimated cost of repair is based on the information provided by the customer.
 2. The estimated cost of repair is based on the information provided by the customer.
 3. The estimated cost of repair is based on the information provided by the customer.
 4. The estimated cost of repair is based on the information provided by the customer.
 5. The estimated cost of repair is based on the information provided by the customer.
 6. The estimated cost of repair is based on the information provided by the customer.
 7. The estimated cost of repair is based on the information provided by the customer.
 8. The estimated cost of repair is based on the information provided by the customer.
 9. The estimated cost of repair is based on the information provided by the customer.
 10. The estimated cost of repair is based on the information provided by the customer.

Authorised by Repeller
 Signature:
 Date:

21418.44

Printed on 18/9/2019 3:03:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMA444T

Chassis No : MRHFC1660JT000031

Model : CIVIC 1.5 TURBO VTIS YM2018

Owner's Name : TAN MING SIEW

Ins Policy No. :

Date of Accident : 17/9/2019

Document No. : SQT19004730 Page 1

Date : 31. Oct 2019

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L15B73621201

Date | Time : 31. Oct 2019 10:22:00 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
SUPPLEMENTARY PARTS & LABOUR							
63321-TEA-T00ZZ	GUTTERR.RR.UPPER	1	29.40	5	27.93	1.96	29.89
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT	1	60.70	5	57.66	4.04	61.70
Sum Item					85.59	6.00	91.59

Survey By

Date & Time

Excess

Status

Signature

Total Amount

85.59

6.00

91.59

Total (Inclusive of GST)

91.59

Printed on 31/10/2019 10:22:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

31/10/2019

PAGE 1/3



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS CHUA

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 17 DAYS

Customer: CU0102455 / CHINA TAIPING
 Chassis No: MRHFC1660JT000031
 License No: SMA444T
 Mileage: 24966
 Engine No: L15B73621201

Document No: SVO19061185
 Printed By: JESHURUEBEN
 Order Date: 20. September 2019
 Order Time: 4:08:43 PM
 Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	TPDS CLAIMS-J/NO: 73466						
	CLAIMS NO: SNM19D204396-GBD1192C-OCK						
	OWNER: TAN MING SIEW						
	INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 17/09/2019						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 18/09/2019						
	AUTHORIZED ON : 20/09/2019						
	TP VEH NO: GBD1192C						
	TP INSURER: CHINA TAIPING INSURANCE						
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20	5	461.89	32.33	494.22
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	5	66.50	4.66	71.16
74890-TEA-T112B	GARNISH ASSYRR.LICENSE	1	100.60	5	95.57	6.69	102.26
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	44.80	5	42.56	2.98	45.54
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	44.80	5	42.56	2.98	45.54
74851-TEA-003	LOCK ASSYTRUNK	1	74.30	5	70.58	4.94	75.52
75724-TBA-A00	EMBLEM	1	24.20	5	22.99	1.61	24.60
75722-TBA-A00	EMBLEM SETRR.	1	11.80	5	11.21	0.76	11.99
08F13-TEA-7T0AX	TRUNK SPOILERWING TYPE	1	700.00	5	665.00	46.55	711.55
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	2	145.80	5	277.02	19.39	296.41
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	5	116.18	8.13	124.31
33550-TEA-T01	TAILLIGHT ASSYL.	1	281.30	5	267.23	18.71	285.94
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	5	248.33	17.38	265.71
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	5	586.34	41.04	627.38
91505-TM8-003	CLIP,BUMPER	8	2.30	5	17.48	1.22	18.70
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	5	34.58	2.42	37.00
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	5	8.26	0.58	8.84
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE	1	8.40	5	7.98	0.56	8.54
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	5	10.92	0.76	11.68
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	5	10.92	0.76	11.68
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	5	2.18	0.15	2.33
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	5	156.46	10.95	167.41
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	5	230.94	16.17	247.11
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	5	25.36	1.78	27.14
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	5	25.36	1.78	27.14
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	1	711.60	5	676.02	47.32	723.34
73550-TEA-T01	GLASS ASSYL.QUARTER WINDSHIEL	1	136.60	5	129.77	9.08	138.85
65550-TED-P00ZZ	PAN COMPSPARE TIRE	1	216.70	5	205.86	14.41	220.27
65666-TEA-T00ZZ	FRAMEL.RR.FRAME RR.UPPER	1	40.90	5	38.65	2.72	41.57
65665-TEA-T00ZZ	STIFFENER BL.RR.FLOOR SIDE	1	27.30	5	25.93	1.82	27.75
65663-TEA-T00ZZ	STIFFENER BL.RR.FRAME	1	19.70	5	18.71	1.31	20.02
65676-TBA-A00ZZ	GUSSETL.RR.PANEL	1	20.70	5	19.66	1.38	21.04
65669-TEA-T00ZZ	BRACKETL.RR.BUMPER BEAM	1	26.20	5	24.89	1.74	26.63
65696-TEA-T00ZZ	BRACKETRR.BUMPER BEAM LOWER	1	23.90	5	22.70	1.59	24.29
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	32.90	5	31.25	2.19	33.44
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	48.90	5	46.45	3.25	49.70
73211-TEA-T02	GLASS SET,RR.WINDSHIELD	1	932.10	5	885.49	61.96	947.47
73227-TEA-003	RUBBER CWINDSHIELD DAM	1	17.20	5	16.34	1.14	17.48
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	9.70	5	27.64	1.93	29.57

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0102455 / CHINA TAIPING
 Chassis No: MRHFC1660JT000031
 License No: SMA444T
 Mileage: 24966
 Engine No: L15B73621201

Document No: SVO19061185
 Printed By: JESHURUEBEN
 Order Date: 20. September 2019
 Order Time: 4:08:43 PM
 Service Advisor: RUEBEN THOMAS

91501-S70-003	FASTENER BW/SHIELD	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	7.22	0.51	7.73
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90	5	5.51	0.39	5.90
73125-SR3-000	RUBBER, W/SHIELD	1	12.60	5	11.97	0.84	12.81
73126-SR3-000	RUBBER, W/SHIELD	1	14.40	5	13.68	0.96	14.64
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
63321-TEA-T00ZZ	GUTTER RR UPPER	1	29.40	5	27.93	1.96	29.89
63722-TEA-T00ZZ	ADAPTER LRR.COMBINATION LIGHT	1	60.70	5	57.66	4.04	61.70
		SUM PARTS:			5,928.00	414.96	6,342.96
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST (N)						
BA02R	1864	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE	1865	1	240.00		240.00	16.80	256.80
	BODY JOINT SEALANT.						
BOBC	1865	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	1865	1	250.00		250.00	17.50	267.50
	APPLY BODY UNDERSIDE COATING (N).						
BG51R	1864	1	180.00		180.00	12.60	192.60
	REPLACE RR. L QTR GLASS.(N)						
BMF00D	1864	1	220.00		220.00	15.40	235.40
	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)						
BC012R	0760	1	280.00		280.00	19.60	299.60
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R	0760	1	280.00		280.00	19.60	299.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BG02D	1864	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BMI03D	1864	1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BMI02D	1864	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)						
BKTRR	1864	1	350.00		350.00	24.50	374.50
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.						
BKRP22M	1864	1	6,440.00		6,440.00	450.80	6,890.80
	CUT RR PANEL. RR FLOOR, RR L FENDER, CUT RRL CHAS. ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM						

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

PAGE 3/3

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0102455 / CHINA TAIPIING
Chassis No: MRHFC1660JT000031
License No: SMA444T
Mileage: 24966
Engine No: L15B73621201

Document No: SVO19061185
Printed By: JESHURUEBEN
Order Date: 20. September 2019
Order Time: 4:08:43 PM
Service Advisor: RUEBEN THOMAS

BP07R	1865	1	3,150.00	3,150.00	220.50	3,370.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)					

SUM LABOUR:	12,590.00	881.30	13,471.30
-------------	-----------	--------	-----------

TOTAL SGD	18,518.00	1,296.26	19,814.26
-----------	-----------	----------	-----------

Total Payable (SGD)	19,814.26
---------------------	-----------

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2019		19 Sep 2019 10:59 Edit Adj Rpt	S\$18,518.00 Edit Estimates	S\$18,518.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ISO-TEAM CORPORATION PTE LTD, Co. Reg. No.: 199608218E								
Main Claimant:	TAN MING SIEW, ID: S7609179Z								
Vehicle Reg. No.:	SMA444T	Date of Loss:	17/09/2019 18:00 - :59 [15 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204396C02	Policy/Cover Note No.:	DMCVSN30363019011						
Vehicle Reg. No. (Insured):	GBD1192C	Policy No. (Claimant):	18-MT102350-R00						
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/09/2019]								
Driver/Custodian (Insured):	MOLLA MOHAMMAD AL HELAL (26 / Male) , NRIC: G2150907N Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMA444T (SNM19D204396C02)
[GBD1192C]
TP
TAN MING SIEW
Sep 17 2019 6:00PM
[ISO-TEAM CORPORATION PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 11:54	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/11/19 10:15	General View	1	Load PDF	
2	22/11/19 10:15	Reinspection Photo	1	Load PDF	
3	22/11/19 10:15	Reinspection Photo	1	Load PDF	
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/09/19 10:52	Estimate	1	Load PDF	
2	19/09/19 10:52	INSURANCE GBD1192C GIA REPORT	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/11/19 10:17	Supplementary	1	Load PDF	

Linked Accident Report Documents

View View in Browser

Video				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 11:45	Video - Accident		Load MP4	

Assessment Reports

				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 11:54	Accident Statement		Load HTM	
2	25/09/19 17:34	Addendum Sheet		Load TIF	
3	25/09/19 17:34	Accident Statement Addm. #1		Load HTM	

Photos/Images

				3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 11:52	Accident Photo		Load JPG	☒
2	18/09/19 11:52	Accident Photo		Load JPG	☒
3	18/09/19 11:52	Accident Photo		Load JPG	☒
4	18/09/19 11:52	Accident Photo		Load JPG	☒
5	18/09/19 11:52	Accident Photo		Load JPG	☒
6	18/09/19 11:52	Accident Photo		Load JPG	☒
7	18/09/19 11:52	Accident Photo		Load JPG	☒
8	18/09/19 11:52	Accident Photo		Load JPG	☒

Documentation

				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 11:45	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016544/UYF3E2

Date: 22/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30363019011
 Claimant Vehicle No: SMA444T Insured Vehicle No: GBD1192C
 Date of Loss: 17/09/2019 Nature of Claim: TP Claim No: SNM19D204396C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA444T
 Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A) Engine No: L15B73621201
 Reg. Date: 23/05/2018 (Man. Year: 2018) Chassis No: MRHFC1660JT000031
 Colour: White Odometer: 24966 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,378.44	5,948.00	1,430.44	19.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,040.00	12,570.00	1,470.00	10.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,418.44	18,518.00	2,900.44	13.54
+ GST 7.00/7.00% (S\$)	1,499.29	1,296.26	203.03	13.54
Nett Amount (S\$)	22,917.73	19,814.26	3,103.47	13.54

INSPECTION

Date of Assignment: 19/09/2019
 Date Inspected: 19/09/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 15 Ubi Road 4
 Singapore 408610
 Estimated Period of Repair: 17.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2019)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA444T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID COMP TRUNK	Bent / Buckled	461.89 FS	*461.89 FS
2	1		*WEATHERSTRIPTRUNK LID	Twisted	66.50 FS	*66.50 FS
3	1		*GARNISH ASSYRR.LICENSE	Cracked	95.57 FS	*95.57 FS
4	1		*HINGE COMPL.TRUNK	Bent	42.56 FS	*42.56 FS
5	1		*HINGE COMPR.TRUNK	Bent	42.56 FS	*42.56 FS
6	1		*LOCK ASSYTRUNK	Twisted	70.58 FS	*70.58 FS
7	1		*EMBLEM	Necessary	22.99 FS	*22.99 FS
8	1		*EMBLEM SETRR.	Necessary	11.21 FS	*11.21 FS
9	1		*TRUNK SPOILERWING TYPE	Cracked	665.00 FS	*665.00 FS
10	1		*CAMERA ASSY, RR VI	Serviceable	299.82 FS	*- FS
11	1		*SUB CORDRR.BUMPER CORNER SENS	Not Necessary	26.69 FS	*- FS
12	1		*SENSOR ASSY, PARKING (4PCS)	Shorted (2Pcs Only)	554.04 FS	*277.02 FS
13	1		*ANTENNA ASSYL.F.	Serviceable	56.33 FS	*- FS
14	1		*BUZZER ASSYSMART	Serviceable	58.23 FS	*- FS
15	1		*LIGHT ASSYL.LID	Cracked	116.18 FS	*116.18 FS
16	1		*LIGHT ASSYR.LID	Serviceable	116.18 FS	*- FS
17	1		*TAILLIGHT ASSYL.	Cracked	267.23 FS	*267.23 FS
18	1		*TAILLIGHT ASSYR.	Cracked	248.33 FS	*248.33 FS
19	1		*LIGHT ASSYLICENSE	Not Necessary	59.75 FS	*- FS
20	1		*FACE ASSY,RR.BUMPER	Distorted	586.34 FS	*586.34 FS
21	1		*CLIP, BUMPER (8PCS)	Necessary	17.48 FS	*17.48 FS
22	1		*GARNISH, RR.BUMPER LOWER	Torn	34.58 FS	*34.58 FS
23	1		*GARNISH,L.RR.BUMPER SIDE	Grazed	7.98 FS	*7.98 FS
24	1		*GARNISH,R.RR.BUMPER SIDE	Not Necessary	7.98 FS	*- FS
25	1		*SPACERL.RR.BUMPER SIDE	Bent	10.92 FS	*10.92 FS
26	1		*SPACERR.RR.BUMPER SIDE	Bent	10.92 FS	*10.92 FS
27	1		*BRACKETL.RR.BUMPER SIDE	Bent	2.18 FS	*2.18 FS
28	1		*BRACKETR.RR.BUMPER SIDE	Not Necessary	2.18 FS	*- FS
29	1		*BEAM COMPRR.BUMPER	Bent	156.46 FS	*156.46 FS
30	1		*PANEL SETRR.	Badly Dented	230.94 FS	*230.94 FS
31	1		*STIFFENERL.RR.PANEL SIDE	Necessary	25.36 FS	*25.36 FS
32	1		*STIFFENER,R.RR.PANEL SIDE	Necessary	25.36 FS	*25.36 FS
33	1		*PANEL SETL.RR.OUTSIDE	Buckled / Cracked	676.02 FS	*676.02 FS
34	1		*GLASS ASSY.,R.QUARTER WINDSHIELD	Necessary	138.51 FS	*129.77 FS
35	1		*PAN COMPSPARE TIRE	Crumpled / Buckled	205.86 FS	*205.86 FS
36	1		*FRAME L.RR.FRAME RR.UPPER	Buckled	38.85 FS	*38.85 FS
37	1		*STIFFENER BL.RR.FLOOR SIDE	Buckled	25.93 FS	*25.93 FS
38	1		*STIFFENER BL.RR.FRAME	Bent	18.71 FS	*18.71 FS
39	1		*GUSSETL.RR.PANEL	Necessary	19.66 FS	*19.66 FS
40	1		*BRACKETL.RR.BUMPER BEAM	Bent	24.89 FS	*24.89 FS
41	1		*BRACKETRR.BUMPER BEAM LOWER	Bent	22.70 FS	*22.70 FS
42	1		*LINING ASSYTRUNK LID	Deformed	31.25 FS	*31.25 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LINING ASSYRR.PANEL	Not Necessary	47.78 FS	*- FS
44	1		*LID ASSYSPARE TIRE	Not Necessary	57.19 FS	*- FS
45	1		*LINING ASSYL.TRUNK SIDE	Distorted	46.45 FS	*46.45 FS
46	1		*LINING ASSYR.TRUNK SIDE	Serviceable	46.45 FS	*- FS
47	1		*BOX COMPTOOL	Not Necessary	36.10 FS	*- FS
48	1		*GLASS SET, RR.WINDSHIELD	Deep Cut	885.49 FS	*885.49 FS
49	1		*RUBBER CWINDSHIELD DAM	Necessary	16.34 FS	*16.34 FS
50	1		*RUBBERRR QTR W/SHIELD (3PCS)	Necessary	27.64 FS	*27.64 FS
51	1		*FASTENER BW/SHIELD (2PCS)	Necessary	10.07 FS	*10.07 FS
52	2		*FASTENER AW/SHIELD	Necessary	7.22 FS	*7.22 FS
53	1		*CLIP, WINDSHIELD UPPER (2PCS)	Necessary	5.51 FS	*5.51 FS
54	1		*RUBBER, W/SHIELD	Necessary	11.97 FS	*11.97 FS
55	1		*RUBBER, W/SHIELD	Necessary	13.68 FS	*13.68 FS
56	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
57	1		*SOLAR FILM ON REAR WINDSCREEN	Not Necessary	300.00 FS	*- FS
58	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
59	1		*GUTTERR.RR.UPPER	Bent	27.93 FS	*27.93 FS
60	1		*ADAPTERL.RR.COMBINATION LIGHT	Cracked	57.66 FS	*57.66 FS
61	1		*COVERRR.TOWING HOOK	Torn	8.26 FS	*8.26 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,378.44	5,948.00
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	100.00	100.00
2	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	150.00	130.00
3	BODY JOINT SEALANT	New	300.00	240.00
4	BODY UNDERSIDE COATING	New	100.00	100.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	250.00
6	REPLACE RR.L QTR GLASS	New	200.00	180.00
7	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	250.00	220.00
8	RESET VEHICLE SMART ENTRY SYSTEM	New	320.00	280.00
9	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	320.00	280.00
10	REMOVE & INSTALL RR. WINDSCREEN	New	300.00	300.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	250.00
12	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	350.00	300.00
13	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	350.00	350.00
14	CUT RR PANEL, RR FLOOR, RR L FENDER, CUT RRL CHAS	New	7,400.00	6,440.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (7P)	New	3,300.00	3,150.00
Gross Labour Cost (S\$)			14,040.00	12,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >