

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

FWD

Owner : Mohammad Zamri Bin Rosli

Accident Date : 12-Sep-19

Vehicle No : FBL 2178 X

Vehicle Model : Brixton BX125R

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 11 155.00 X
1	Headlamp assy	\$ 11 380.00 X
2	Fork inner tubes	\$ 500 620.00 X
1	Handle bar -R/H	\$ 34 145.00
1	Handle bar end -R/H	\$ 4.5 30.00
1	Hand grip (1 set)	\$ 60 80.00
1	Side mirror -R/H	\$ 50 95.00
1	Brake lever	\$ 65 65.00
1	Fuel tank	\$ 20 1,215.00
1	Front footrest -R/H	\$ 60 75.00
1	Front footrest bracket -R/H	\$ 50 145.00 X
1	Brake pedal	\$ 34 98.00
1	Gear pedal	\$ 11 95.00 X
1	Rear footrest -R/H	\$ 60 70.00
1	Side board -R/H	\$ 50 130.00 X
1	Side stand	\$ 11 95.00 X
1	Exhaust pipe	\$ 10/21 755.00
1	Clutch lever	\$ 11 60.00 X
		\$ 4,308.00
	Less 10%	\$ 430.80
		\$ 3,877.20

Not Authorised
 2/5
 2/5
 Hdy.
 Take photo of the repair.
 19/9/19

c/f: \$ 3,877.20

Special Nett Items

1	Rear Front number plate (1 set)	Rear \$ 34	28.00	10
2	Fork oils	\$ 11	30.00	x
2	Fork oil seals	\$ 11	56.00	x
1	Steering cone (1 set)	\$ 11	80.00	x
		\$	194.00	

Rear 2260 reflex box cut —

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$ 11	80.00	x
3	To provide labour.	\$	450.00	220
		\$	580.00	

Grand Total \$ 4,651.20


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: