

(INSUR)

INS. CASE OWNER:

MING YAO

CC 6 / AIG1901 6560, Uebos

LKK:

IDAC:

Surveyor:

MARLUS

DOI:

ASSIGNMENT

19/1/19

Date / Time:

19/1/19

Registered in Merimen:

19/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SIF 56224

Name of Insured:

LEW WAI SON

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

18/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

8848427656

Policy No.:

20008463-11

Make / Model:

KIA

Place of Accident:

PIE TMS PAVU LEPAK

If NO, Driver Name / Age:

Driver Tel No.:

(VAL. YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SIF 56224

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fastech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE/ PIC
23-09-19	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
26/9/19	Call OE:	26/9/19
	After call Itr to OE:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	
	After call Itr to OE:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by: OCS		
Repair Cost: 45 \$510,000	(8 days) Reduction: 75 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 10-12-19 Confirm with: JASON Email ☒ Call ☐		
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia: 100%
Repair Cost: 2/1/19 \$510,700.00	3 YEN (101 LPA)	
Loss of Rental (LOR): \$5 - (days)		
Loss of Use (LOU): \$5 540.00 (5 60 x 9 days)		
Loss of Income (LOI): \$5 - (5 x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)		
GIA/LTA Search \$52.00		
Medical: \$5 -		1) Claim status: Normal/Reject/Private Settle
Disbursement: \$5 -	(e.g. Tow/ Independent)	2) Report Format: TP
Legal Cost \$5 -		3) Survey fee: 330
Total: \$511,242.00	Global Sum \$5:	
FINAL PAYMENT Date/Time: 10-12-19 Confirm with: JASON Email ☒ Call ☐		
Payee 1: \$511,242.00	Name 1: FASTECH ASIO PIE LTD	
Payee 2: (Strike if N.A.) \$5	Name 2:	
Payee 3: (Strike if N.A.) \$5	Name 3:	

COPY SENT

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

A147
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

SLIP PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

597J

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

S + RS (\$)

Photos

Others

TOTAL

LTA 49945 have been rep'd.

net 14053

25/9/19 L/S 10.000 Contacted with Alan.

(USD + 30,336.10 15%)

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
19/9/19
1/5 #10,000 / \$47

VEHICLE NO. SLJ5135

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID 'H' LOGO
1 PCS	BOOTLID 'HYUNDAI' EMBLEM
1 PCS	BOOTLID 'ELANTRA' EMBLEM
1 PCS	BOOTLID 'ELITE' EMBLEM
1 PCS	BOOTLID INNER LOCK 185.80
1 PCS	BOOTLID LOCK STRIKER
1 PCS	BOOTLID WEATHERSTRIP 166.60
2 PCS	BOOTLID REFLECTORS @\$520.30 322.50 x 2 = 645.00
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
1 PCS	REAR BUMPER 495.40
2 PCS	REAR BUMPER REFLECTORS @\$105.00 68.60
1 PCS	REAR BUMPER REINFORCEMENT 365.00
2 PCS	REAR BUMPER REINFORCEMENT STAYS @\$201.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER LOWER GARNISH
2 PCS	REAR BUMPER SPLASH SHIELDS @\$150.50
1 PCS	REAR END PANEL 622.50
1 PCS	REAR END PANEL TOP GARNISH 166.80
1 PCS	REAR END PANEL LOCK SENSOR
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
1 PCS	REAR FLOOR PANEL TOP TOOLS SPONGE
2 PCS	REAR FENDERS @\$1807.00
2 PCS	REAR FENDER INNER TRIMS @\$405.00 312.20
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00
2 PCS	TAILLAMP @\$685.30 650.50 x 2 = 1301.00
2 PCS	TAILLAMP HOUSING PANELS @\$295.00
2 PCS	BOOTLID HINGES @\$145.00
2 PCS	REAR AIR VENTS @\$45.00
1 PCS	FRONT BUMPER 522.30
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00
2 PCS	FRONT BUMPER BRACKETS @\$145.00
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER INNER SPONGE 382.00
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER license plate garnish 105.00
2 PCS	FRONT BUMPER FOG LAMPS @\$385.00
1 PCS	FRONT BUMPER LOWER GRILLE CHROME MOULDING
1 PCS	FRONT GRILLE
1 PCS	FRONT GRILLE top garnish 730
1 PCS	FRONT GRILLE LOGO

20/3uc	\$1,507.30	✓
rel	\$39.90	✓
NF	\$48.50	X
rel	\$52.20	✓
rel	\$50.00	✓
rel/bye	\$291.30	✓
11	\$66.80	X
twi	\$311.30	✓
cha	\$1,040.60	✓
11	\$322.60	X
11	\$50.00	X
11	\$788.20	✓
o/scre	\$210.00	IPC
rel	\$485.10	✓
NS	\$402.00	X
11	\$133.00	X
rel	\$48.00	✓
rel	\$105.60	✓
11	\$301.00	X
306/20	\$892.20	✓
twi	\$288.30	✓
cha	\$250.00	X
rel	\$1,680.30	X
Ward	\$525.40	✓
11	\$311.20	X
R	\$3,614.00	X
o/s to 11	\$810.00	IPC
11	\$188.20	X
11	\$891.30	X
11	\$90.00	X
cha	\$1,370.60	✓
R	\$590.00	X
11	\$290.00	X
11	\$90.00	X
20/2e	\$665.30	✓
11	\$130.00	X
11	\$290.00	X
rel	\$50.00	✓
brn	\$180.50	✓
gent	\$515.10	✓
rel	\$239.00	✓
11	\$770.00	X
11	\$245.10	X
cha	\$425.50	✓
cha	\$130.00	✓
rel	\$38.00	✓

(207)

1 PCS BONNET
 2 PCS BONNET HINGES @\$85.00
 1 PCS BONNET INSULATOR
 1 SET BONNET INSULATOR CLIPS
 1 PCS BONNET LOCK
 2 PCS HEADLAMPS @\$1765.40 1756.00
 2 PCS HEADLAMP LOWER BRACKETS @\$45.00
 1 PCS FRONT SUPPORT PANEL
 1 PCS AIRCON CONDENSER
 2 PCS AIRCON SIDE GARNISH @\$35.00
 1 PCS RADIATOR
 1 PCS RADIATOR FAN ASSY
 1 PCS RADIATOR TOP HOSE
 2 PCS FRONT FENDERS @\$456.10
 1 PCS AIR CLEANER BOX TOP
 1 PCS AIR CLEANER BOX BOTTOM
 1 PCS AIR INTAKE DUCT

1 SET S. NETT
 1 SET REAR BUMPER REVERSE SENSOR
 1 PCS REAR FLOOR PANEL INSULATOR
 1 PCS REAR END PANEL SEALANT
 1 PCS REAR LICENCE PLATE W/HOLDER
 1 PCS REAR WINDSCREEN SEALANT
 1 PCS FRONT LICENCE PLATE W/HOLDER
 1 BOL RADIATOR COOLANT

LABOUR CHARGES:
 TOWING CHARGE
 TO CHECK WIRING
 TO DISMANTLE & REPLACING REVERSE SENSOR
 TO TRANSFER BOOTLID MECHANISM
 TO DISMANTLE & REFIX REAR EXHAUST
 TO DISMANTLE & REFIX REAR SEAT CUSHION UPHOLSTERY
 TO DISMANTLE & REFIX FUEL TANK
 TO DISMANTLE & REFIX REAR WINDSCREEN
 TO SPRAY RUST PROOFING
 TO REFILL AIR CON GAS
 LABOUR FOR PANEL BEATING & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

LKK Auto Consultants hence notify the Franchiser of the following:

- To ensure two-stage spray painting
- To ensure vehicle is not damaged during resurvey
- Repairs must be subject to confirmation
- The survey is on a "Without Prejudice" basis
- No () modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

12 \$1,361.90 X
 11 \$170.00 X
 11 \$175.00 X
 11 \$35.00 X
 11 \$68.50 X
 o/c/c/r \$3,530.80 170
 11 \$90.00 X
 CNA \$994.30
 11 \$892.10 X
 11 \$70.00 X
 11 \$1,055.20 X
 11 \$899.20 X
 11 \$42.90 X
 11 \$912.20 X
 11 \$279.90 X
 11 \$285.50 X
 11 \$153.20 X
 \$32,629.10

shaded \$280.00 200
 11 \$280.00 X
 11 \$50.00
 11 \$50.00 X
 11 \$50.00 X
 11 \$50.00
 11 \$50.00 30

11 \$120.00 X
 \$80.00 30
 \$80.00 50
 \$120.00 60
 11 \$100.00 X
 \$150.00 80
 11 \$100.00 X
 11 \$150.00 X
 \$150.00 80
 \$150.00 100
 \$3,000.00 1200
 \$2,500.00 1500
 TOTAL \$40,339.10

113408
 1907272

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 597J

Vehicle Details

Vehicle No.: SLJ5135

Vehicle to be Exported: No

Intended Deregistration Date: 19 Sep 2019

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: G4FGGU275978

Chassis No.: KMHD841CMHU311120

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$17,756.00

Original Registration Date: 28 Nov 2016

First Registration Date: 28 Nov 2016

Transfer Count: 0

Actual ARF Paid: \$17,756.00 *8878***Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Nov 2026

PARF Rebate Amount: \$13,317.00

Intended COE Rebate Details

COE Expiry Date: 27 Nov 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,951.00

COE Rebate Amount: \$36,628.00

Total Rebate Amount: \$49,945.00

The information contained herein is correct as at 19 Sep 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Get More Cash for Your Car. Post an Ad Today

Receive a higher selling price by selling your car yourself.

Advertise it for sale at just \$58, list till sold.

Elantra

Price Range

Depreciation

2016

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Fu Yiap Motor Trading > Hyundai Elantra 1.6A GLS

Hyundai Elantra 1.6A GLS

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

富業汽車貿易

FU YIAP MOTOR TRADING

SGCARMART.COM

Price	\$65,800		
Depreciation	\$8,230 /yr	Reg Date	18-Nov-2016 (7yrs 1mth 29days COE left)
	View models with similar depre		
Mileage	33,586 km (11.8k /yr)	Manufactured	2016
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$47,927 as of today (change)	OMV	\$13,572
COE	\$52,668	ARF	\$13,572
Engine Cap	1,591 cc	Power	93.8 kW (125 bhp)
Curb Weight	1,345 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L DOHC CVT Engine, Reliable And Responsive Auto Transmission, Cruise Control, Auto Head Lamps, Auto Rain Sensors. [View Specs Of The Hyundai Elantr](#) [View specs of the Hyundai Elantra \(2016-2018\)](#)

Accessories

Leather Seats, Factory Fitted Audio System With USB/AUX Port, Knockdown Rear Seats.

Description

Accredited Company! Accident-Free, 2 Years Pakage Free Serving At Komoco, Low Mileage Done, Low Interest. 1.99%, Fully Maintained/Warranty By Agent, Well Maintained By 1 Owner. High OMV And COE! Low Maintenance! Buy With Peace Of Mind! Low Depreciation, Accept Trade In, In House Finance Available, Excellent Condition, Trade In Available! Call Us Now.

Category

PARF Car

Status

Available

Resources

Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

Compare





Price Chart

Summary

Price (\$000)

Reg Date

Click on the point to view the vehicle

Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

Company

Fu Yiap Motor Trading

» dealer's prce list

» 27 vehs sold | 24 vehs available

Address

31 West Coast Highway #01-13/14

Search cars nearby this location

Location

West Coast Car Mart

Office No

67760119

https://www.sgcarmart.com/used_cars/info.php?ID=827816&DL=1164

19-Sep-19

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

Elantra

Price Range

Depreciation

2016

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Direct Owners > Hyundai Elantra 1.6A GLS

Hyundai Elantra 1.6A GLS

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price	\$63,888		
Depreciation	\$8,080 /yr View models with similar depre	Reg Date	25-Oct-2016 (7yrs 1mth 5days COE left)
Mileage	30,800 km (10.6k /yr)	Manufactured	2016
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$46,014 as of today (change)	OMV	\$13,071
COE	\$50,991	ARF	\$13,071
Engine Cap	1,591 cc	Power	93.8 kW (125 bhp)
Curb Weight	1,345 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

4-cylinder 16-valve DOHC Dual CVT, Auto Head Lamps. View specs of the Hyundai Elantra

Accessories

Leather Seats, Touchscreen GPS, Radio, Bluetooth Audio, USB Port, In-car Camera

Description

First Owner, Low Mileage Done, Regularly Serviced And Polished. Please Email Or Text If You Have Any Questions, Or To Arrange A Test-drive Please Avoid Calling. Thanks.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Car Valuation - Free
Find out the market value of your existing car for free. Get started

100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Preferred Viewing Area

Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Contact Person(s)

Jason Mark

Contact No.

88111859

Enquiry

Contact Seller

ESSENTIAL TRANSACTION FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

» Ownership Transfer

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 23 September 2019 2:08 PM
To: jason@fastechauto.com.sg; 'Nancy Lam'
Subject: Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

m-

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Sep 2019 14:35	Cim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	19 Sep 2019 14:35	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	19 Sep 2019 14:35	Cim Created	Reg No: SLJ513S, Acct Date: 2019/09/18, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Fastech Auto Pte Ltd (HQ)	[A] Lau Shu Pei
4	19 Sep 2019 14:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	19 Sep 2019 14:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/30	[A] Lau Shu Pei
6	19 Sep 2019 14:35	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
7	19 Sep 2019 14:35	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	19 Sep 2019 14:35	Label Added	(19):Fastlane.	[A] Lau Shu Pei
9	19 Sep 2019 14:35	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
10	19 Sep 2019 16:08	Cim Dtl Modified	Claimant's Name: - -> CHEONG YEW LEONG, Claimant's ID: -> S1461597J.	[A] Lau Shu Pei
11	19 Sep 2019 16:08	Cim Veh Model Changed	(206086) -> (200329) HYUNDAI ELANTRA 1.6 (A).	[A] Lau Shu Pei
12	22 Nov 2019 10:44	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	22 Nov 2019 10:44	Cim Dtl Modified	JPJ Reg. Date: -> 2016/11/28.	[A] JOANNE LEE KHANG MIN
14	22 Nov 2019 10:44	Cim Details Notified		[A] JOANNE LEE KHANG MIN
15	22 Nov 2019 16:58	Adj Mandate Request	Cur,Req:11242.00:LIABILITY: 100% B:28 3VEH CC OI LAST	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2286562	20 Sep 2019 11:32:09	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SLJ513S	SJF5622Y	11.77
2353513	22 Nov 2019 10:44:28	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLJ513S	SJF5622Y	11.77

12/10/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SLJ513S (8848432762SG)**
[SJF5622Y]

TP
CHEONG YEW LEONG
Sep 18 2019 12:00AM
[CHEW WAI SON]
Fastech Auto Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on 09/12/2019 17:06 PM.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$11242.00) - SLJ513S - Claim Handler: Lee, Ming-Yao**

Approved:11242.00:Please settle at best

Asher Sng (LKKAUTO)

From: Jason <Jason@fastechauto.com.sg>
Sent: Tuesday, 10 December 2019 3:47 PM
To: Asher Sng (LKKAUTO)
Subject: RE: Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

Without Prejudice

Dear Asher,

We are pleased to accept your offer of \$11,242.00 for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Tuesday, December 10, 2019 3:07 PM
To: Jason <Jason@fastechauto.com.sg>
Subject: RE: Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 10,700.00
2. Loss of Use (9 days x \$60)	\$ 540.00
3. LTA/GIA search fee	\$ 2.00

TOTAL

\$ 11,242.00

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Asher Sng (LKKAuto)

Sent: Monday, 23 September 2019 2:08 PM

To: jason@fastechauto.com.sg; 'Nancy Lam' <nancy.lam@fastechauto.com.sg>

Subject: Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir/Madam,

Accident Involving SLJ 513S & SJF 5622Y on 18/09/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTPV01018336
Insured : CHEONG YEW LEONG
Motor Car (Registration No.) : SLJ513S
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 28 NOVEMBER 2018 00:00
Policy Expiry Date : 27 NOVEMBER 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$500 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP-27.

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 01 NOVEMBER 2018 13:03

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11A14006 & ACCORD INSURANCE AGENCY CI Code: 22A JJDLDBV2_L1D1NA

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2019 Edit Reg		19 Sep 2019 00:00 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHEW WAI SON , ID: S1440404Z									
Main Claimant: CHEONG YEW LEONG , ID: S1461597J									
Vehicle Reg. No.: SLJ513S		Date of Loss: 18/09/2019 00:00 - :59 [33 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8848432762SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SJF5622Y		Policy No. (Claimant): D18MTPV01018336							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (09/12/2019): Alert - Adj Mandate Approved (S\$11242.00) - SLJ513S - Claim Handler: Lee, Ming-Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ513S (88484327625G)
[SJF5622Y]

TP
CHEONG YEW LEONG
Sep 18 2019 12:00AM
[CHEW WAI SON]
Fastech Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Letters/Correspondences						1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown			 Edit	☐	
Photos/Images						3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	19/09/19 15:17	Chassis Number			 Load JPG ☒	☒	
2	19/09/19 15:18	Odometer Reading			 Load JPG ☒	☒	
3	19/09/19 15:18	General View			 Load JPG ☒	☒	
4	19/09/19 15:18	General View			 Load JPG ☒	☒	
5	19/09/19 15:18	General View			 Load JPG ☒	☒	
6	19/09/19 15:18	General View			 Load JPG ☒	☒	
7	19/09/19 15:18	General View			 Load JPG ☒	☒	
8	19/09/19 15:18	General View			 Load JPG ☒	☒	
9	19/09/19 15:18	General View			 Load JPG ☒	☒	
10	19/09/19 15:18	General View			 Load JPG ☒	☒	
11	19/09/19 15:18	General View			 Load JPG ☒	☒	
12	19/09/19 15:18	General View			 Load JPG ☒	☒	
13	19/09/19 15:18	General View			 Load JPG ☒	☒	
14	19/09/19 15:18	General View			 Load JPG ☒	☒	
15	19/09/19 15:18	General View			 Load JPG ☒	☒	
16	19/09/19 15:18	General View			 Load JPG ☒	☒	
17	19/09/19 15:18	General View			 Load JPG ☒	☒	
18	19/09/19 15:18	General View			 Load JPG ☒	☒	
19	19/09/19 15:18	General View			 Load JPG ☒	☒	
20	19/09/19 15:18	General View			 Load JPG ☒	☒	
21	19/09/19 15:18	General View			 Load JPG ☒	☒	
22	19/09/19 15:18	General View			 Load JPG ☒	☒	
23	19/09/19 15:18	General View			 Load JPG ☒	☒	
24	19/09/19 15:18	General View			 Load JPG ☒	☒	
25	19/09/19 15:18	General View			 Load JPG ☒	☒	
26	19/09/19 15:18	General View			 Load JPG ☒	☒	
27	19/09/19 15:18	General View			 Load JPG ☒	☒	
28	19/09/19 15:18	General View			 Load JPG ☒	☒	
29	19/09/19 15:18	General View			 Load JPG ☒	☒	
30	19/09/19 15:18	General View			 Load JPG ☒	☒	
31	19/09/19 15:18	General View			 Load JPG ☒	☒	
32	19/09/19 15:18	General View			 Load JPG ☒	☒	
33	19/09/19 15:18	General View			 Load JPG ☒	☒	
34	19/09/19 15:18	General View			 Load JPG ☒	☒	
35	19/09/19 15:18	General View			 Load JPG ☒	☒	
36	19/09/19 15:18	General View			 Load JPG ☒	☒	
37	19/09/19 15:18	General View			 Load JPG ☒	☒	
38	19/09/19 15:18	General View			 Load JPG ☒	☒	
39	19/09/19 15:18	General View			 Load JPG ☒	☒	
40	19/09/19 15:18	General View			 Load JPG ☒	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	19/09/19 15:18	General View	 Load JPG	☒
42	19/09/19 15:18	General View	 Load JPG	☒
43	19/09/19 15:18	General View	 Load JPG	☒
44	19/09/19 15:18	General View	 Load JPG	☒
45	19/09/19 15:18	General View	 Load JPG	☒
46	19/09/19 15:18	General View	 Load JPG	☒
47	19/09/19 15:18	General View	 Load JPG	☒
48	19/09/19 15:18	General View	 Load JPG	☒
49	19/09/19 15:18	General View	 Load JPG	☒
50	19/09/19 15:18	General View	 Load JPG	☒
51	19/09/19 15:18	General View	 Load JPG	☒
52	19/09/19 15:18	General View	 Load JPG	☒
53	19/09/19 15:18	General View	 Load JPG	☒
54	19/09/19 15:18	General View	 Load JPG	☒
55	19/09/19 15:18	General View	 Load JPG	☒
56	19/09/19 15:18	General View	 Load JPG	☒
57	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
58	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
59	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
60	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
61	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
62	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
63	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
64	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
65	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
66	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
67	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
68	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
69	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
70	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
71	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
72	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
73	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
74	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
75	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
76	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
77	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
78	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
79	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
80	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
81	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
82	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
83	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
84	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
85	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
86	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
87	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
88	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
89	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
90	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
91	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
92	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
93	19/09/19 15:18	Reinspection Photo	 Load JPG	☒
94	19/09/19 15:19	Reinspection Photo	 Load JPG	☒
95	19/09/19 15:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	19/09/19 15:19	Reinspection Photo		☒
97	19/09/19 15:19	Reinspection Photo		☒
98	19/09/19 15:19	Reinspection Photo		☒
99	19/09/19 15:19	Reinspection Photo		☒
100	19/09/19 15:19	Reinspection Photo		☒
101	19/09/19 15:19	Reinspection Photo		☒
102	19/09/19 15:19	Reinspection Photo		☒
103	19/09/19 15:19	Reinspection Photo		☒
104	19/09/19 15:19	Reinspection Photo		☒
105	19/09/19 15:19	Reinspection Photo		☒
106	19/09/19 15:19	Reinspection Photo		☒
107	19/09/19 15:19	Reinspection Photo		☒
108	19/09/19 15:19	Reinspection Photo		☒
109	19/09/19 15:19	Reinspection Photo		☒
110	19/09/19 15:19	Reinspection Photo		☒
111	19/09/19 15:19	Reinspection Photo		☒
112	19/09/19 15:19	Reinspection Photo		☒
113	19/09/19 15:19	Reinspection Photo		☒
114	19/09/19 15:19	Reinspection Photo		☒
115	19/09/19 15:19	Reinspection Photo		☒
116	19/09/19 15:19	Reinspection Photo		☒
117	19/09/19 15:19	Reinspection Photo		☒
118	19/09/19 15:19	Reinspection Photo		☒
119	19/09/19 15:19	Reinspection Photo		☒
120	19/09/19 15:19	Reinspection Photo		☒
121	19/09/19 15:19	Reinspection Photo		☒
122	19/09/19 15:19	Reinspection Photo		☒
123	19/09/19 15:19	Reinspection Photo		☒
124	19/09/19 15:19	Reinspection Photo		☒
125	19/09/19 15:19	Reinspection Photo		☒
126	19/09/19 15:19	Reinspection Photo		☒
127	19/09/19 15:19	Reinspection Photo		☒
128	19/09/19 15:19	Reinspection Photo		☒
129	19/09/19 15:19	Reinspection Photo		☒
130	19/09/19 15:19	Reinspection Photo		☒
131	19/09/19 15:19	Reinspection Photo		☒
132	19/09/19 15:19	Reinspection Photo		☒
133	19/09/19 15:19	Reinspection Photo		☒
134	19/09/19 15:19	Reinspection Photo		☒
135	19/09/19 15:19	Reinspection Photo		☒
136	19/09/19 15:19	Reinspection Photo		☒
137	19/09/19 15:19	Reinspection Photo		☒
138	19/09/19 15:19	Reinspection Photo		☒
139	19/09/19 15:19	Reinspection Photo		☒
140	19/09/19 15:19	Reinspection Photo		☒
141	19/09/19 15:19	Reinspection Photo		☒
142	19/09/19 15:19	Reinspection Photo		☒
143	19/09/19 15:19	Reinspection Photo		☒
144	19/09/19 15:19	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/09/19 17:14	TP GIA REPORT		☐
2	23/09/19 14:07	LETTER TO OI		☐
3	06/11/19 09:10	TP ESTIMATE-MARKED		☐
4	22/11/19 15:15	GIA SEARCH		☐
5	22/11/19 15:15	LOD		☐

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	09/01/20 09:07	WORKSHOP INVOICE		Load PDF	
7	09/01/20 09:07	AUTHORISATION TO ACT FORM		Load PDF	
8	09/01/20 09:07	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	20/09/19 11:25	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJF5622Y (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 (A)
	SLJ513S (TP veh)		
Date of Accident:	18/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	43,269.84
Final Repair Cost	:	\$	10,700.00
Loss of Use	:	\$	540.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	11,242.00

9.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 11,242.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016560/UEA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLJ513S Insured Vehicle No : SJF5622Y

Vehicle No : SLJ513S Nature of Claim: TP Claim No: 8848432762SG

Date of Loss: 18/09/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ513S

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Engine No: G4FGGU275978

Reg. Date: 28/11/2016 (Man. Year: 2016)

Chassis No: KMHD841CMHU311120

Colour: Silver

Odometer: 44716 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,739.10	9,402.72	24,336.38	72.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	3,100.00	3,600.00	53.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,439.10	12,502.72	27,936.38	69.08
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	40,439.10	10,000.00	30,439.10	75.27
+ GST 7.00/7.00% (S\$)	2,830.74	700.00	2,130.74	75.27
Nett Amount (S\$)	43,269.84	10,700.00	32,569.84	75.27
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,242.00		

INSPECTION

Date of Assignment: 19/09/2019

Date Inspected: 19/09/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,507.30 F	*1,507.30 FL
2	1		*BOOTLID H LOGO	Necessary	39.90 F	*39.90 FL
3	1		*BOOTLID HYUNDAI EMBLEM	Not fitted	48.50 F	*- FL
4	1		*BOOTLID ELANTRA EMBLEM	Necessary	52.20 F	*52.20 FL
5	1		*BOOTLID ELITE EMBLEM	Necessary	50.00 F	*50.00 FL
6	1		*BOOTLID INNER LOCK	Bent / Damaged	291.30 F	*185.80 FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	66.80 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	311.30 F	*166.60 FL
9	2		*BOOTLID REFLECTORS	Cracked	1,040.60 F	*645.00 FL
10	1		*BOOTLID INNER TRIM	Not Necessary	322.60 F	*- FL
11	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
12	1		*REAR BUMPER	Distorted	788.20 F	*495.40 FL
13	1		*REAR BUMPER REFLECTORS	O/S Cracked	210.00 F	*68.60 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	485.10 F	*365.00 FL
15	2		*REAR BUMPER REINFORCEMENT STAYS	No such part	402.00 F	*- FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	133.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
18	1		*REAR BUMPER LOWER GARNISH	Deformed	105.60 F	*105.60 FL
19	2		*REAR BUMPER SPLASH SHIELDS	Not Necessary	301.00 F	*- FL
20	1		*REAR END PANEL	Badly Dented	892.20 F	*622.50 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	288.30 F	*166.80 FL
22	1		*REAR END PANEL LOCK SENSOR	Not Necessary	250.00 F	*- FL
23	1		*REAR FLOOR PANEL	Repair	1,680.30 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Warped	525.40 F	*525.40 FL
25	1		*REAR FLOOR PANEL TOP TOOLS SPONGE	Not Necessary	311.20 F	*- FL
26	2		*REAR FENDERS	Repair	3,614.00 F	*- FL
27	1		*REAR FENDER INNER TRIMS	O/S Torn	810.00 F	*312.20 FL
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	188.20 F	*- FL
29	1		*REAR EXHAUST	Not Necessary	891.30 F	*- FL
30	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
31	2		*TAILLAMPS	Cracked	1,370.60 F	*1,301.00 FL
32	2		*TAILLAMP HOUSING PANELS	Repair	590.00 F	*- FL
33	2		*BOOTLID HINGES	Not Necessary	290.00 F	*- FL
34	2		*REAR AIR VENTS	Not Necessary	90.00 F	*- FL
35	1		*FRONT BUMPER	Dented / Deformed	665.30 F	*522.30 FL
36	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
37	2		*FRONT BUMPER BRACKETS	Not Necessary	290.00 F	*- FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
39	1		*FRONT BUMPER INNER SPONGE	Torn	180.50 F	*180.50 FL
40	1		*FRONT BUMPER REINFORCEMENT	Bent	515.10 F	*382.00 FL
41	1		*FRONT BUMPER LICENCE PLATE GARNISH	Deformed	239.00 F	*105.00 FL
42	2		*FRONT BUMPER FOG LAMPS	Not Necessary	770.00 F	*- FL
43	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Not fitted	245.10 F	*- FL
44	1		*FRONT GRILLE	Cracked	425.50 F	*425.50 FL
45	1		*FRONT GRILLE TOP GARNISH	Cracked	230.00 F	*230.00 FL
46	1		*FRONT GRILLE LOGO	Necessary	38.00 F	*38.00 FL
47	1		*BONNET	Repair	1,361.90 F	*- FL
48	2		*BONNET HINGES	Not Necessary	170.00 F	*- FL
49	1		*BONNET INSULATOR	Not Necessary	175.00 F	*- FL
50	1		*SET BONNET INSULATOR CLIPS	Not Necessary	35.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*BONNET LOCK	Not Necessary	68.50 F	*- FL
52	1		*HEADLAMPS	O/S Cracked	3,530.80 F	*1,756.00 FL
53	2		*HEADLAMP LOWER BRACKETS	Not Necessary	90.00 F	*- FL
54	1		*FRONT SUPPORT PANEL	Cracked	994.30 F	*994.30 FL
55	1		*AIRCON CONDENSER	Not Necessary	892.10 F	*- FL
56	2		*AIRCON SIDE GARNISH	Not Necessary	70.00 F	*- FL
57	1		*RADIATOR	Not Necessary	1,055.20 F	*- FL
58	1		*RADIATOR FAN ASSY	Not Necessary	899.20 F	*- FL
59	1		*RADIATOR TOP HOSE	Not Necessary	42.90 F	*- FL
60	2		*FRONT FENDERS	Not Necessary	912.20 F	*- FL
61	1		*AIR CLEANER BOX TOP	Not Necessary	279.90 F	*- FL
62	1		*AIR CLEANER BOX BOTTOM	Not Necessary	285.50 F	*- FL
63	1		*AIR INTAKE DUCT	Not Necessary	153.20 F	*- FL
64	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
65	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
66	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
67	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
68	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
69	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*50.00 FS
70	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 33,739.10 11,670.90
 - List Item Discount on L Items 0.00/20.00% (S\$) 0.00 2,268.18

Total Parts (S\$) 33,739.10 9,402.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	120.00	0.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
4	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
8	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
9	TO SPRAY RUST PROOFING	New	150.00	80.00
10	TO REFILL AIR CON GAS	New	150.00	100.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	3,000.00	1,200.00
12	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,500.00
Gross Labour Cost (\$\$)			6,700.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >