

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016562/KKA3Q2

Date: 06/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLP4975J

Insured Vehicle No : SKM8881Y

Date of Loss: 16/09/2019

Nature of Claim: TP

Claim No: 4298791421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4975J

Make & Model: MAZDA 3, 1.5 SEDAN EU6 (A)

Engine No: P520451411

Reg. Date: 07/06/2017 (Man. Year: 2017)

Chassis No: JM6BN22A8H0158804

Colour: Metallic Grey

Odometer: 112305 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: CST 8 mm

Rear Left Side: CST 8 mm

Front Right Side: CST 8 mm

Rear Right Side: CST 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,716.88	1,882.08	834.80	30.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	850.00	970.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,536.88	2,732.08	1,804.80	39.78
Approved Total (Overridden) (\$\$)		2,150.00		
(\$\$)	4,536.88	2,150.00	2,386.88	52.61
+ GST 7.00/7.00% (\$\$)	317.58	150.50	167.08	52.61
Nett Amount (\$\$)	4,854.46	2,300.50	2,553.96	52.61
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		31.00		
Nett Liability (\$\$)		2,691.50		
Global Sum Settlement (\$\$)		2,630.00		

INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 01/10/2019 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11,
AMK Auto Point
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	866.80 FL	*866.80 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	59.40 FL	*29.70 FL
4	1		*FRONT RH GRILLE CHROME	Serviceable	191.70 FL	*- FL
5	1		*SET FRONT BUMPER FOGLAMP COVER RH	Serviceable	47.30 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP RH	Serviceable	147.00 FL	*- FL
7	1		*FRONT FENDER RH	Buckled	350.60 FL	*350.60 FL
8	1		*FRONT FENDER SHIELD RH	Serviceable	101.90 FL	*- FL
9	1		*FRONT FENDER SHIELD CLIPS	Not Necessary	35.00 FL	*- FL
10	1		*FRONT GRILLE BASE	Serviceable	135.50 FL	*- FL
11	1		*FRONT HEADLAMP RH	Broken	1,070.50 FL	*1,070.50 FL
12	1		*FRONT HEADLAMP TOP PANEL (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT HEADLAMP LOWER BRACKET (NPA)	Repair	0.00 FL	*- FL
14	1		*FRONT BUMPER TOP (RADIATOR TOP) UPPER BUMPER	Serviceable	355.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,396.10	2,352.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	679.22	470.52
Total Parts (\$\$)	2,716.88	1,882.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	700.00	400.00
2	LABOUR REMOVE REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	400.00
3	TO APPLY ANTI RUST TREATMENT	New	100.00	30.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	20.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			1,820.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >