

<u>CHECK LABOUR</u>	<u>CHECK ITEM</u>	<u>S/N ITEM</u>	<u>LABOUR</u>	<u>PARTS</u>
\$100.00	\$364.55	\$30.00	\$60.00	\$1,637.00
\$100.00	\$204.13	\$20.00	\$80.00	\$244.00
	\$121.90	\$200.00	\$30.00	\$66.59
	\$148.00	\$45.00	\$120.00	\$496.80
	\$285.49	\$30.00	\$60.00	\$44.10
	\$92.46	\$60.00	\$1,500.00	\$34.50
	\$496.23	\$60.00	\$1,500.00	\$526.82
	\$687.70		\$80.00	\$779.80
	\$964.51			\$113.28
	\$375.48			\$28.52
	\$507.00			\$961.20
	\$2,824.00			\$109.48
	\$97.30			\$625.20
	\$518.88			\$807.00
	\$575.00			\$451.50
	\$798.00			\$1,045.30
				\$49.68
				\$91.08
				\$657.00
				\$52.40
				\$990.20

\$200.00

\$9,060.63

\$445.00

\$3,430.00

\$9,811.45

\$2,265.16

\$2,452.86

\$6,795.47

\$7,358.59

Parts & Lab: \$11,233.59

Check Item: \$6,995.47

w/o Total: \$11,233.59 **\$8,986.87**

TOTAL W CHECK \$18,229.06 **\$14,583.25**



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Singapore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 Repair Performa Invoice

AIG INSURANCE

Vehicle number	SKK8143E
Make / Model	MAZDA/5
Chassis number	JM6CW10F1E0116402
Accident date	17/9/19
Reference	1909-32

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1631 1882.55 <del>bt</del>
1	TAILGATE LOCK	244 294.63 <del>jm</del>
1	TAILGATE LOCK STRIKER	66.59 <del>bt</del>
2	TAILGATE DAMPER	407.34 <del>X</del>
2	TAILGATE HINGE	88.78 <del>x</del>
1	TAILGATE INNER TRIM	496.80 <del>de</del>
1	TAILGATE EMBLEM -LOGO	48.10 50.72 <del>ne</del>
1	TAILGATE EMBELM -MAZDA 5	31.50 41.75 <del>ne</del>
1	TAILGATE OUTER GARNISH	526.82 <del>des</del>
2	TAILGATE LAMP	@389.90 941.62 <del>on</del> 779.80
1	TAILGATE WIPER ARM	113.28 <del>des</del>
1	TAILGATE WIPER MOTOR	364.55 <del>?</del>
1	TAILGATE WIPER BLADE	28.52 <del>wt</del>
1	TAILGATE WEATHERSTRIP	204.13 <del>?</del>
1	REAR BUMPER	961.20 1105.38 <del>de</del>
2	REAR BUMPER RETAINER	109.48 <del>ne</del>
2	REAR BUMPER REFLECTOR	121.90 <del>?</del>
1	REAR BUMPER REINFORMCENET	148 155.40 178.71 <del>?</del> 1200.40
2	REAR TAILLAMP	@625.20 1383.92 <del>LH-?, RH-?</del>
2	TAILLAMP PANEL	382.72 <del>Ry</del>
2	REAR FENDER	@807 1614 5581.88 <del>LHxR, RH</del> <del>bt</del>
2	REAR FENDER INNER TRIM	570.98 <del>LH-x, RH-?</del>
1	REAR END PANEL - photo.	451.50 593.06 <del>bt</del>
1	REAR END PANEL TOP GANRISH	92.46 <del>?</del>
1	EXHAUST SILENCER	1605.98 <del>x</del>
2	EXHAUST MOUNTING	80.50 <del>x</del>
1	EXHAUST HEATSHIELD	204.36 <del>x</del>
1	SPARE TYRE CENTRE BOARD	496.23 <del>?</del>
2	SPARE TYRE SIDE BOARD	687.70 <del>?</del>
1	FLOOR PANEL	964.51 <del>?</del>
1	3RD BRAKE LIGHT	375.48 <del>?</del>
1	FRONT BUMPER	1045.30 1274.43 <del>de</del>
2	FRONT BUMPER RETAINER	49.68 <del>ne</del>
1	FRONT BUMPER REINFORCEMENT	507 611.34 <del>?</del>
1	FRONT BUMPER SPONGE	91.08 <del>2m</del>

1	FRONT GRILLE	657	807.65	CR ✓
1	FRONT EMBLEM - LOGO		52.44	CR ✓
2	FRONT FOG LAMP COVER		179.86	X
2	FRONT FOG LAMP		782.00	X
2	FRONT HEADLAMP	1412 2824	3408.60	?
2	FRONT HEADLAMP BRACKET		97.30	?
1	FRONT SUPPORT PANEL		518.88	?
1	AIRCON CONDENSER	575	934.38	?
1	AIRCON COMPRESSOR ASSY		1677.62	?
1	AIRCON SUCTION PIPE -HIGH		368.12	X
1	RADIATOR	798	963.59	?
1	RADIATOR COWLING		394.22	X
1	RADIATOR FAN MOTOR		1056.05	X
1	BONNET	990 20	1248.44	ht ✓
2	BONNET HINGE		125.02	RY
1	BONNET LOCK		238.05	RY
1	BONNET LOCK STRIKER		46.12	X
1	BONNET INSULATOR		245.30	X
			35213.50	
		Less 25 %	8803.38	
		Subtotal	26410.13	
		Balance C/F	26410.13	
S/No	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
		Balance B/F	26410.13	
1 SET	REAR BUMPER CLIP		40.00	3over ✓
1 SET	REAR END PANEL TOP GARNISH CLIP		60.00	2over ✓
1 SET	TAILGATE INNER TRIM CLIP		60.00	X
1 SET	REAR FENDER INNER TRIM CLIP		40.00	X
1 SET	REAR REVERSE SENSOR		400.00	2over ✓
1	REAR NUMBER PLATE		80.00	45 ht ✓
1 SET	FRONT BUMPER CLIP		40.00	3over ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP		60.00	X
1 SET	BONNET INSULATOR CLIP		60.00	X
1	JONT SEALANT		150.00	60over ✓
1	WINDSCREEN SEALANT		150.00	60over ✓
		Subtotal	1140.00	
		Balance C/F	27550.13	

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	27550.13
1	CHECK FRONT & REAR WIRING AND LIGHTNING SYSTEM	120.00 60
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 100?
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 100?
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	150.00 80
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120
7	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60
8	PANEL BEATING ON AFFECTED AREAS	3500.00 1500
9	SPRAY PAINTING ON AFFECTED AREAS	3500.00 1500
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 80
	Subtotal	8320.00
	Grand total	34730.13

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Taufik 92495749  
WP  
20/9/19  
Lumpsum  
Repair after repair.  
10 days  
taufik@lkkauto.com  
\* Repair limit \$6000