



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Singapore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 Repair Performa Invoice

AIG INSURANCE

Vehicle number	SKK8143E
Make / Model	MAZDA/5
Chassis number	JM6CW10F1E0116402
Accident date	17/9/19
Reference	1909-32

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1882.55 <i>bt</i>
1	TAILGATE LOCK	294.63 <i>jm</i>
1	TAILGATE LOCK STRIKER	66.59 <i>bt</i>
2	TAILGATE DAMPER	407.34 <i>X</i>
2	TAILGATE HINGE	88.78 <i>x</i>
1	TAILGATE INNER TRIM	496.80 <i>de</i>
1	TAILGATE EMBLEM -LOGO	50.72 <i>nr</i>
1	TAILGATE EMBELM -MAZDA 5	41.75 <i>nr</i>
1	TAILGATE OUTER GARNISH	526.82 <i>des</i>
2	TAILGATE LAMP	941.62 <i>nr</i>
1	TAILGATE WIPER ARM	113.28 <i>des</i>
1	TAILGATE WIPER MOTOR	364.55 <i>?</i>
1	TAILGATE WIPER BLADE	28.52 <i>at</i>
1	TAILGATE WEATHERSTRIP	204.13 <i>?</i>
1	REAR BUMPER	1105.38 <i>de</i>
2	REAR BUMPER RETAINER	109.48 <i>nr</i>
2	REAR BUMPER REFLECTOR	121.90 <i>?</i>
1	REAR BUMPER REINFORMCENET	178.71 <i>?</i>
2	REAR TAILLAMP	1383.92 <i>LH-?, RH-?</i>
2	TAILLAMP PANEL	382.72 <i>Rx</i>
2	REAR FENDER	5581.88 <i>LH x R, RH <i>bt</i></i>
2	REAR FENDER INNER TRIM	570.98 <i>LH-x, RH-?</i>
1	REAR END PANEL <i>- photo.</i>	593.06 <i>bt</i>
1	REAR END PANEL TOP GANRISH	92.46 <i>?</i>
1	EXHAUST SILENCER	1605.98 <i>x</i>
2	EXHAUST MOUNTING	80.50 <i>x</i>
1	EXHAUST HEATSHIELD	204.36 <i>x</i>
1	SPARE TYRE CENTRE BOARD	496.23 <i>?</i>
2	SPARE TYRE SIDE BOARD	687.70 <i>?</i>
1	FLOOR PANEL	964.51 <i>?</i>
1	3RD BRAKE LIGHT	375.48 <i>?</i>
1	FRONT BUMPER	1274.43 <i>de</i>
2	FRONT BUMPER RETAINER	49.68 <i>nr</i>
1	FRONT BUMPER REINFORCEMENT	611.34 <i>?</i>
1	FRONT BUMPER SPONGE	91.08 <i>En</i>

1	FRONT GRILLE	807.65	Crn ✓
1	FRONT EMBLEM - LOGO	52.44	nd ✓
2	FRONT FOG LAMP COVER	179.86	X
2	FRONT FOG LAMP	782.00	X
2	FRONT HEADLAMP	3408.60	?
2	FRONT HEADLAMP BRACKET	97.30	?
1	FRONT SUPPORT PANEL	518.88	?
1	AIRCON CONDENSER	934.38	?
1	AIRCON COMPRESSOR ASSY	1677.62	Y
1	AIRCON SUCTION PIPE -HIGH	368.12	X
1	RADIATOR	963.59	?
1	RADIATOR COWLING	394.22	X
1	RADIATOR FAN MOTORR	1056.05	X
1	BONNET	1248.44	ht
2	BONNET HINGE	125.02	Ry
1	BONNET LOCK	238.05	Ry
1	BONNET LOCK STRIKER	46.12	X
1	BONNET INSULATOR	245.30	X
		35213.50	
	Less 25 %	8803.38	
	Subtotal	26410.13	
	Balance C/F	26410.13	
S/No	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	26410.13	
1 SET	REAR BUMPER CLIP	40.00	3over ✓
1 SET	REAR END PANEL TOP GARNISH CLIP	60.00	2on ✓
1 SET	TAILGATE INNER TRIM CLIP	60.00	X
1 SET	REAR FENDER INNER TRIM CLIP	40.00	X
1 SET	REAR REVERSE SENSOR	400.00	200nw ✓
1	REAR NUMBER PLATE	80.00	45 ht ✓
1 SET	FRONT BUMPER CLIP	40.00	3over ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP	60.00	X
1 SET	BONNET INSULATOR CLIP	60.00	X
1	JONT SEALANT	150.00	60nw ✓
1	WINDSCREEN SEALANT	150.00	60nw ✓
	Subtotal	1140.00	
	Balance C/F	27550.13	

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	27550.13
1	CHECK FRONT & REAR WIRING AND LIGHTNING SYSTEM	120.00 60
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 100?
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 100?
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	150.00 80
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120
7	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60
8	PANEL BEATING ON AFFECTED AREAS	3500.00 1500
9	SPRAY PAINTING ON AFFECTED AREAS	3500.00 1500
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 80
	Subtotal	8320.00
	Grand total	34730.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
'WP'
20/9/19
Lumpsum
Repair after repair.
10 days
taufik@lkharta.com
* Repair limit \$6000