



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Singapore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 Repair Performa Invoice

AIG INSURANCE

Vehicle number	SKK8143E
Make / Model	MAZDA/5
Chassis number	JM6CW10F1E0116402
Accident date	17/9/19
Reference	1909-32

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1,163.7 1882.55 bt ✓
1	TAILGATE LOCK	244 294.63 jm ✓
1	TAILGATE LOCK STRIKER	66.59 bt ✓
2	TAILGATE DAMPER	407.34 X nm ✓
2	TAILGATE HINGE	88.78 x nm ✓
1	TAILGATE INNER TRIM	496.80 de ✓
1	TAILGATE EMBLEM -LOGO	44.10 50.72 ne ✓
1	TAILGATE EMBELM -MAZDA 5	31.50 41.75 ne ✓
1	TAILGATE OUTER GARNISH	526.82 des ✓
2	TAILGATE LAMP	@ 389.90 941.62 or ✓ 119.80
1	TAILGATE WIPER ARM	113.28 ds ✓
1	TAILGATE WIPER MOTOR	364.55 ? bt ✓
1	TAILGATE WIPER BLADE	28.52 wt ✓
1	TAILGATE WEATHERSTRIP	204.13 ? in ✓
1	REAR BUMPER	961.20 1105.38 de ✓
2	REAR BUMPER RETAINER	109.48 ne ✓
2	REAR BUMPER REFLECTOR	121.90 R un ✓
1	REAR BUMPER REINFORMCENET	148 155.70 178.71 bt ✓ 1250.40 bt ✓
2	REAR TAILLAMP	@ 625.20 1383.92 LH-RH ✓ 1,184.00 ✓
2	TAILLAMP PANEL	382.72 R ✓
2	REAR FENDER	@ 807 1614 5587.88 LH x R, RH bt ✓ 807
2	REAR FENDER INNER TRIM	285.49 570.98 LH-RH ✓ 807
1	REAR END PANEL - photo.	451.50 593.06 bt ✓
1	REAR END PANEL TOP GANRISH	92.46 ? de ✓
1	EXHAUST SILENCER	1605.98 x R ✓
2	EXHAUST MOUNTING	80.50 x R ✓
1	EXHAUST HEATSHIELD	204.36 bt ✓
1	SPARE TYRE CENTRE BOARD	496.23 de ✓
2	SPARE TYRE SIDE BOARD	687.70 ? de ✓
1	FLOOR PANEL	964.51 R ✓
1	3RD BRAKE LIGHT	375.48 R un ✓
1	FRONT BUMPER	1045.20 1274.43 de ✓
2	FRONT BUMPER RETAINER	49.68 ne ✓
1	FRONT BUMPER REINFORCEMENT	507 611.34 ? bt ✓
1	FRONT BUMPER SPONGE	91.08 un ✓

11727.11

1	FRONT GRILLE	657	807.65	con ✓
1	FRONT EMBLEM - LOGO		52.44	na ✓
2	FRONT FOG LAMP COVER	89.93	179.86	LH X, RH de ✓
2	FRONT FOG LAMP	391	782.00	LH X, RH con ✓
2	FRONT HEADLAMP	1412	3408.60	? con ✓
2	FRONT HEADLAMP BRACKET		97.30	? de ✓
1	FRONT SUPPORT PANEL		518.88	? con ✓
1	AIRCON CONDENSER	575	934.38	? bt ✓
1	AIRCON COMPRESSOR ASSY		1677.62	X nn ✓
1	AIRCON SUCTION PIPE -HIGH		368.12	X nn ✓
1	RADIATOR	798	963.59	? bt ✓
1	RADIATOR COWLING		394.22	X nn ✓
1	RADIATOR FAN MOTORR		1056.05	X nn ✓
1	BONNET	990	1248.44	bt ✓
2	BONNET HINGE		125.02	Ry ✓
1	BONNET LOCK		238.05	Ry ✓
1	BONNET LOCK STRIKER		46.12	X nn ✓
1	BONNET INSULATOR		245.30	X nn ✓
			18660.86	
			13995.65	Less 25 %
				Subtotal
			26410.13	
			26410.13	Balance C/F
S/No	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
			26410.13	Balance B/F
1 SET	REAR BUMPER CLIP		40.00	30na ✓
1 SET	REAR END PANEL TOP GARNISH CLIP		60.00	20na ✓
1 SET	TAILGATE INNER TRIM CLIP		60.00	X nn ✓
1 SET	REAR FENDER INNER TRIM CLIP		40.00	X nn ✓
1 SET	REAR REVERSE SENSOR		400.00	202na ✓
1	REAR NUMBER PLATE		80.00	45 bt ✓
1 SET	FRONT BUMPER CLIP		40.00	30na ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP		60.00	X nn ✓
1 SET	BONNET INSULATOR CLIP		60.00	X nn ✓
1	JONT SEALANT		150.00	60na ✓
1	WINDSCREEN SEALANT		150.00	60na ✓
			1140.00	Subtotal
			27550.13	Balance C/F

445

S/No	LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F	27550.13
1	CHECK FRONT & REAR WIRING AND LIGHTNING SYSTEM	120.00 60
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 100? ✓
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 100? ✓
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	150.00 80
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120
7	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60
8	PANEL BEATING ON AFFECTED AREAS	3500.00 1500
9	SPRAY PAINTING ON AFFECTED AREAS	3500.00 1500
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 80
	Subtotal	8320.00
	Grand total	34730.13

3630

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjung 92495349

20/9/19

lumpsum
Repair after repair.

10 days

tanj@lkkauto.com

* Repair limit ~~As~~

18070.65

1/5 \$ 14,450 #

Repair limit

1/5 \$ 10,000

10 days

22/11 - email to Darren.