Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 20 September, 2019 9:21 AM

To: Mei Kwan (LKKAuto)

Cc: Hsiao Tong (LKKAuto); CS A Team; Admin A

Subject: DM19HO02604/JT: Direct Settlement - Accident Involving GBD8283CG (OI : EQI -

TBA) AND SJF6534L (TP: LKK REF - CC6/EQI19016573/Apa3) on 18/09/2019

Attachments: TP GIA REPORT.pdf; SAS2671572.PDF

Dear Mei Kwan

Attach OI report.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Thursday, September 19, 2019 4:42 PM **To:** EQI PRS < EQIPRS@eqinsurance.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-

a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBD8283CG (OI: EQI - TBA) AND SJF6534L (TP: LKK REF -

CC6/EQI19016573/Apa3) on 18/09/2019

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

EOI ref: TBA

LKK REF: CC6/EQI19013946/Apa3

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJF 6534L at M/s MG Solution Pte Ltd - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)