

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India Int'l Insurance Pte Ltd
64 Cecil Street #05-10B Building
Singapore 049711
Attn: Claims Department

Date : 17.09.2019
Vehicle No : SLD 1797 P
Veh Make/Model : Toyota Jetta
YOM : 2010
Chassis No : WVWZZZ1KZAM154999
Date of Accident : 17.09.2019

No	Qty	Description	Amount \$
List Items:-			
1	1	Rear boot X	\$ 1,677.60
2	1	Rear boot lock X	\$ 180.97
3	1	Rear boot logo "JETTA" X	\$ 133.75
4	1	Rear boot logo "TS" X	\$ 133.75
5	1 set	Rear boot insulator clips X	\$ 117.77
6	1	Rear bumper / CRA	\$ 1,379.60
7	1	Rear bumper lower / CRA	\$ 799.87 1,009.78
8	1	Rear bumper side reflector (LH) / Auto	\$ 40.97 137.69
9	1 set	Rear bumper clips / MCL	\$ 55 117.77
10	1	Rear lamp (LH) X NN	\$ 400.60
11	1	Rear reinforcement X / BT.	\$ 488.78 999.89
12	1	Rear end panel Report X	\$ 1,379.56
13	1	Rear end panel top garmish X	\$ 287.66
14	1	Rear end panel top garmish clips X	\$ 117.70
15	1	Rear boot lamp (LH) X NN	\$ 377.81
16	1 set	Rear fender shield clips X	\$ 117.77
17	1	Rear weatherstripe X	\$ 333.70
18	1		\$ -
19	1		\$ -
20	1		\$ -
21	1		\$ -
22	1		\$ -
23	1		\$ -
24	1		\$ -
25	1		\$ -
26	1		\$ -
27	1		\$ -
28	1		\$ -
29	1		\$ -
30	1		\$ -
<div style="border: 1px solid black; padding: 5px;"> <p>LMK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>			
Total - List Item			\$ 8,903.37
Less 10%			\$ (890.34)
Total			\$ 8,013.03

2814.22
10%: 2532.78

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India Int'l Insurance Pte Ltd
64 Cecil Street #05-10B Building
Singapore 049711
Attn: Claims Department

Date : 17.09.2019
Vehicle No : SLD 1797 P
Veh Make/Model : Toyota Jetta
YOM : 2010
Chassis No : WVWZZZ1KZAM154999
Date of Accident : 17.09.2019

No	Qty	Description	Amount \$
		Balance c/f	
		Special Nett Items:-	
1	1	Rear reverse sensor DM DM	\$ 330.00
2	1	Rear inner compartment clips X NIV	\$ 80.00
3	1	Rear bumper lower aluminum clips/bracket / MC	\$ 100.00
4	1		\$ -
5	1		\$ -
		Total - SN Item	\$ 510.00
			200
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 200 800.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 200 800.00
3		To apply anti rust treatment.	\$ X 120.00
4		To check wiring system & light.	\$ NIV X 100.00
5		To check & adjust wheel alignment.	\$ X 100.00
6		To remove / replace / refix rear bumper sensor	\$ 40 120.00
7		To remove / replace / refix rear boot inner compartment, lock & etc to new boot	\$ X 150.00
8		To remove / replace / refix rear inner compartment to facilities repairs	\$ NIV X 120.00
9		Computer diagnostic after repair	\$ X 350.00
		Total - L/C	\$ 2,660.00
		3 Days.	450
		Lump Sum repair	
		After repair photos.	
		Car & Car - 82880282	
		19/9/19. 3212.79	
		20%: 2550	
		Sub-Total	\$ 11,183.03
		7% GST	\$ 782.81
		Total	\$ 11,965.84