

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email: ben@allswellmotor.com.sg

(3rd party claim against Indemnity)

Estimate repair

Vehicle No. : SW7923H
 Make & Model : Toyota Vaux
 Chassis No. : hybrid
 Date of survey :

LK Asia Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part(s) to be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Submitted by :

Acknowledged by Repairer :

Signature :

Engine No. :

Ben

15-01-2018

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Tailgate / Balc	01	\$1,819.00	1209	
02	rear bumper / R	01	\$1,690.00	1190.8	
03	Windscreen moulding / R	01	\$125.00		
					2524.8
	special nett.				25%
01	Cups / retainer studs Rr bumper & tailgate @ \$45/bkt / R	01	\$45.00		1893.6
01	Windscreen sealant (rear) / R	01	\$75.00	40	
				85	
	Labour Description				
01	Remove/re-fix windscreen rear	01	\$150.00	100	
02	Drumhülle / Assembly of tailgate & rear bumper	01	\$260.00		
03	Spray painting of tailgate (2x) & rear bumper	01	\$600.00	400	
				760	
	4 Days				
	part by part				
	before paint photos.				
	19/9/19.				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Gmo Riang

2738.6