

China Taiping Insurance (S) Pte Ltd

Third Party

Policy No: _____

18.09.2019

Date: _____

Accident Date : 16.09.2019

承接汽车烧焊喷漆及
代理各种车辆赔偿

in Car Painting, Welding,
and Insurance Claim.

ESTIMATE

货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Axio" Reg. No. SLM7211B Claiming Against Your Insured Veh. No. YN6662E		
Taillamp LH (LED) <i>CRA</i>		655.00 <i>548.4</i>
Taillamp Gasket <i>MC</i>		35.00 -
Boot <i>BT</i>		775.00 -
Boot Emblem		82.60 <i>59.2</i>
Boot Badge "Corolla"		50.20 -
Boot Badge "Axio"		52.70 <i>45</i>
Boot Badge "G"		41.20 -
Boot Badge "RS"		56.50 -
Boot Badge "TRD Sportivo"		60(SN) 141.50 58
Boot Lower Moulding		350.00 <i>150(SN)</i>
Rear Bumper <i>el</i>		682.7 1,180.60 572
Rear Bumper Protector (Chrome)		220(SN) 466.00 18(SN)
Rear Bumper Logo "TRD Sport" <i>MC</i>		60(SN) 143.00 58
	2293.2	4,029.30 2167
Less 25%	1719.9	1,007.33
		<u>3,021.98</u> 17757
Boot Spoiler (Carbon Fiber) <i>CRA</i>		250 450.00 SN
Boot Inner Safety Reflective Stickers <i>MC</i>	30.00	10 60.00 SN
Rear Bumper Spoiler (Carbon Fiber) <i>NN</i>	300	X 550.00 SN
Rear Bumper Inner Infra Distance Sensor "Sticker" <i>NEC</i>	250	X 350.00 SN
Rear Number Plate (Chrome) <i>NEC</i>	60	X 120.00 SN
To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc	1360 60	60 120.00
To Dismantle / Transfer Boot Fittings / Ancillary Accessories		60 100.00
To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel <i>NN</i>		X 50.00
Labour Charge - Panel Beating, Repairing Of Taillamp Panel, Rear Fender, End Panel and Parts Replacement		300 600.00
To Dismantle / Refit Boot Spoiler. Supply Adhesive, Double Sided Tape, Drilling Etc		40 80.00
	C/F	5,501.98

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

China Taiping Insurance (S) Pte Ltd

To: _____

Policy No: _____
 Third Party

18.09.2019

Date: _____

Accident Date : 16.09.2019

Specialised in Car Painting, Welding,
 Metal-Beating and Insurance Claim.

承接汽车烧焊喷漆及
 代理各种车辆赔偿

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Axio" Reg. No. SLM7211B Claiming Against Your Insured Veh. No. YN6662E		
	To Dismantle / Refit Rear Bumper Spoiler. Supply Adhesive, Double Sided Tape, Drilling Etc	B/F	5,501.98
	To Respray Affected Areas		40 . 80.00
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		500 . 600.00
			8 400.00
		Total :	<u>6,581.98</u>
			3327.53
			4079.9

4 Days .
 part by part .
 before part photos .
 Eno Qian - 82880282
 19/9/19 .

**LKK Auto Consultants hence notify
 the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: