

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SDZ8008S
Accident Date : 17-Sep-2019

Our Ref : 219155 (AIG) / CHAN

KOH AI BOCK PRESLEY
BLK 214 BISHAN STREET 23
#05-215
Singapore 570214

No. : 06057

Date : 18-Sep-2019

PAGE : 1

Not Withheld
11 Days @
Resurvey After Painting
3 days

ESTIMATED COST OF REPAIR FOR SUZUKI SX4 1.6A SJV8329R

1 pc Rear bumper fascia
1 pc Rear bumper lower spoiler
1 pc Rear bumper reinforcement
1 pc Rear n/s bumper side retainer
1 pc Rear n/s bumper reflector

Ry 775.25 ✓
Bulim 788.55 ✓
227.20 ✓
D11 38.65 ✓
cm 27.75 ✓

1,857.40

Less 15% : 278.61

1 pc Rear bumper reverse sensor(set

1,578.79
300.00 sn ?

To putty and spray replaced parts

450.00 *400*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *300*

Total : S\$ 2,728.79

Singapore Dollars Two Thousand Seven Hundred
and Twenty Eight and Cents Seventy Nine Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: