

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SDZ8008S
Accident Date : 17-Sep-2019

No. : 06057

Date : 18-Sep-2019

Our Ref : 219155 (AIG) / CHAN

PAGE : 1

KOH AI BOCK PRESLEY
BLK 214 BISHAN STREET 23
#05-215
Singapore 570214

*Not with work
10% → 61 Imp @ 2050
Running After Rain
3 days*

ESTIMATED COST OF REPAIR FOR SUZUKI SX4 1.6A SJV8329R

- 1 pc Rear bumper fascia
- 1 pc Rear bumper lower spoiler
- 1 pc Rear bumper reinforcement
- 1 pc Rear n/s bumper side retainer
- 1 pc Rear n/s bumper reflector

Ry	775.25	✓
Bulb	788.55	✓
A	227.20	7X
D.I	38.65	✓
CM	27.75	✓
	1,857.40	
Less 15%	278.61	
	1,578.79	

- 1 pc Rear bumper reverse sensor(set

Not 200 300.00 sn ✓
450.00 400

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 300

Total : S\$ 2,728.79

Singapore Dollars Two Thousand Seven Hundred
and Twenty Eight and Cents Seventy Nine Only

*L/Sum
2050.00
7
Kenworth Plus Company
TKS*

*P 1385.67
SN 200.00
L 700.00
2285.67
228.57
-10%
2057.10*