

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SGZ5614B

Date: 18/09/2019

Model : Toyota Rush

Damaged Area: (Front Right Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :**Quantity**

1	Front Bumper	11	\$	1,125.60	X
2	Front Bumper RH Side Bracket	11	\$	65.00	X
3	Front Bumper RH Retainer	11	\$	48.00	X
4	Front Bumper Clips	\$6.00 X 10pcs	11	\$	60.00 X
5	Front RH Headlamp	11	\$	525.60	X
6	Front RH Door	11	\$	965.50	X
7	Front RH Door Outer Handle Garnish	11	\$	115.80	X
8	Front RH Door Hinge Top	11	\$	68.30	X
9	Front RH Door Hinge Bottom	11	\$	54.20	X
10	Front RH Door Rubber	11	\$	356.00	X
11	Front RH Door Inner Trimboard	11	\$	368.40	X
12	Front RH Door Inner Lock	11	\$	285.60	X
13	Front RH Door Power Door Linkage	11	\$	275.60	X
14	Front RH Door Power Window Motor	11	\$	195.80	X
15	Front RH Door A-pillar	11	\$	768.20	X
16	Front RH Fender	11	\$	396.80	X
17	Front RH Fender Inner Shield	11	\$	175.70	X
18	Front RH Fender Inner Shield Clips	\$6.00 X 10pcs	11	\$	60.00 X
19	Front RH Alloy Rim	11	\$	786.20	X
20	Front RH Suspension	11	\$	395.00	X
21	Front RH Lower Arm	11	\$	326.80	X
22	Front RH Knuckle Arm	11	\$	452.90	X
23	Front RH Hub Bearing	11	\$	275.90	X

Parts : \$ 8,146.90

Less Parts 25% : \$ 2,036.72

Total Parts : \$ 6,110.17

Special Net Items :

Rocker Garnish Set

Front RH Tyre

11 \$ 580.00 X

11 \$ 450.00 X

Total S/N Parts : \$ 1,030.00

Labour :

To Remove & Renew Front RH Affected Accident Areas

\$ 1,200.00

To Putty, Spray Paint on Affected Accident Areas

\$ 1,400.00

To Check & Re-Connect all electrical wiring

\$ 50.00

To Conduct Wheel Alignment

\$ 200.00

To Remove & Replace Front RH Undercarriage

\$ 11 350.00 X

To Re-Programme & Reset Diagnostic

\$ 11 250.00 X

To Rust Proof Affected Areas

\$ 100.00

Total Labour : \$ 3,550.00

not Affected
2300
1/5 2300
400
Total Affected

1722.50
257
1290.37

TOTAL PARTS : \$ 6,110.17
TOTAL SPECIAL NET ITEM : \$ 1,030.00
TOTAL LABOUR : \$ 3,550.00
TOTAL REPAIR COST : \$ 10,690.17

288037

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No additional modification(s) is allowed
- Scrapped component(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: