

TP Claims against NTUC Income: Follow-Through Survey

Date : 25/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1063968-001	SMRT TAXIS PTE LTD	SHC 4225G	G8D 5726L	18/09/2019	10:20	\$ 6,995.20	\$ 650.00

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No. (For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5093337337-01		AISHWARYA RESTAURANT & CATERING PTE LTD	200601028H	GCV	Preferred Workshop Plan	GBD5726L	GBD5726L	15/12/2018	14/12/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2019 11:28
Date Of Accident	18/09/2019 10:20
Exact Location Of Accident	ADMIRALTY LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4225G
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	LEE GIN CHONG
NRIC No	S7470346A
Date Of Birth	29/04/1974
Occupation	OUTDOOR
Date Of Driving Pass	22/03/2004
Driving Experience	15 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED MY TAXI ALONG ADMIRALTY LANE AS I WAS MAKING A CALL. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE GBD5726L HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI. AFTER WHICH THIRD PARTY CONTINUED TO DRIVE AWAY. I WENT AFTER THIRD PARTY AND MANAGED TO STOP HIM A DISTANCE AWAY.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD5726L
Vehicle Make/Model/Colour	
Details Of Properties	ALLIANCE DIVINE IMPEX PTE LTD
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SELVAM KAKRIKALAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHC4225G

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Sep 2019

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS TAXI (SMRT)

Primary Colour:

Maroon

Manufacturing Year:

2013

Engine No.:

2ZR5934547

Chassis No.:

JTDKN36U805710174

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$33,120.00

Original Registration Date:

29 Nov 2013 ✓

First Registration Date:

29 Nov 2013

Transfer Count:

0

Actual ARF Paid:

\$8,368.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Nov 2021

PARF Rebate Amount:

\$5,857.00

Intended COE Rebate Details

COE Expiry Date:

28 Nov 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

8

PQP Paid:

\$63,297.00

COE Rebate Amount:

\$17,340.00

Total Rebate Amount:

\$23,197.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Sep 2019

OK

Case Details

Case Reference Number :
TAX/09/19/2064
Type of Repair : Accident Repair
Vehicle Registration Number :
SHC4225G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8562-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd
Accident Date and Time : 18/09/2019 02:19 AM
Vehicle Age(In Months) : 70

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SVC
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	X REAR
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓ Nec
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ Nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									4,615.32	Surveyor Total		165.15		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,692.26	Final Sur Total		132.12		

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	✕ SEARCH
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ NPC
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ NPC
One Time Key In	Main			FENDER LINER R/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	✕ SVC
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Give	✕ SVC
Total Spare Part Cost									4,615.32	Surveyor Total			165.15	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									3,692.26	Final Sur Total			132.12	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			507.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY BUMPER BEAM	180.00	0	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
3	Main	TO RESPRAY REAR BUMPER	378.00	200	
4	Main	TO RESPRAY RIM	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec.
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) SH	296.88	296.88	X
Total:			756.88	356.88	60

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,692.26	132.12
Total Labour Cost	507.00	200.00
Total Spray Painting	1,116.00	400.00
Other	756.88	356.88
Overall Total	6,072.14	1,089.00
Lump Sum Repair Option		

8240.42

Estimator Assessment(\$)

Lump Sum Total

6,050.00

Surveyor Approved Amount

No of Repair Days*

5

Remarks

-

Surveyor Name

Signature



Surveyor Assessment(\$)

1,100.00

1,100.00

2

Lump Sum Repair, Take after spray.

STEVE CHEN



23/9/19

Save

Clear

Survey Date

19/09/2019

19/09/2019.

TR without Prejudice.

Lump sum Repair

Repair days - 2.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4225G
Case Reference Number	TAX/09/19/2064
Registration Date	29/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LEE GIN CHONG
Type of Accident	Side Swipe
Accident Date and Time	18/9/2019 10:19 AM
Accident Reported Date and Time	18/9/2019 11:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103418
Special Instruction to ARC, if any	TP
Prepared Date and Time	18/9/2019 6:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$4,615.32	\$165.15
Total Other Cost	\$756.88	(\$115.15)
TOTAL COST	\$6,995.20	\$650.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	19/09/2019 5:30 PM	19/09/2019 2:54 PM
Signature		
Remarks		Lump Sum Repair, Take after spray.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0420	Invoice Number	
Quotation Date	24.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$175.15)
Total Other Costs	\$756.88	(\$115.15)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52578-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given

	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given X
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
	58308-47011	UNDER COVER SUB-ASSY. RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given X
	51604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair ✓
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
		STICKER DECAL 85558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
	65638-47021	FENDER LINER R/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given X
Total				\$5,781.64		\$165.15		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 165.15 \\
 + 200.00 \\
 + 460.00 \\
 \hline
 825.15 \\
 - 20.2 \\
 \hline
 660.12 \\
 415 \$650/-
 \end{array}$$



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016612/Esd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 08-10-2019
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5726L	Veh. Inspected	SHC 4225G
Policy No.	5093337337-01	Coverage (\$)	0.00
Claim No.	MT/1063968-001	Excess (\$)	0.00
Assign From		Assign Date	19/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U805710174	Colour	MAROON
Odometer	788982	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/09/2019	Inspection Date	19/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4225G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
10	BUMPER CLIPS @ \$2.10 (DISC 25%)	NECESSARY	21.00	15.75
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL DISC	SERVICEABLE	1,484.20	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	SERVICEABLE	514.50	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	FENDER LINER R/LH	SERVICEABLE	141.30	-
1	TAIL LAMP LH	SERVICEABLE	548.40	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	ADVERTISEMENT STICKTER (SN)	NOT NECESSARY	296.88	-
			6,157.42	165.15
<u>LABOUR</u>				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER REAR AND FENDER RR/LH.			507.00	200.00

Report Ref No. NS/INC19016612/Esd3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		1,116.00	400.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,083.00	660.00
GRAND TOTAL			8,240.42	825.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				650.00

Report Ref No. NS/INC19016612/Esd3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.