

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12886

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1133/2019/NS
Date	:	18-Sep-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Gao Kang
Address	:	1 Grace Park
	:	Singapore 557761
Telephone	:	HP +65 87813910
Type of Claim	:	Own Damage Claim
Policy No.	:	1900152865
Vehicle No	:	SMN 7489 A
Model Code	:	Audi Q8 3.0 TFSI qu 4MN0X
Model / Year	:	Aug-19
Engine No	:	DCB 051783
Chassis No	:	WAUZZZF10KD010053
Mileage	:	
Date In	:	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Estimated Labour Charges for Accident Vehicle ~~SKB 123 M~~

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 X
3	To remove and reinstall aircon condenser and radiator. To renew lhs air charged cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/N \$ 1,400.00 ?
4	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 X
5	To remove and renew lhs front suspension assy with subframe.	S/N \$ 2,400.00 ? photo
SUB TOTAL LABOUR CHARGES		: \$ <u>4,920.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SUN 7489 A

Estimated Labour Charges for Accident Vehicle SKB 123 M

S/n	Nature of Jobs	Estimated Charges
6	To dismantle and renew front bumper, lhs front fender, bonnet, lhs headlight, lhs rear door and rear bumper assy. To repair lhs rear fender. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 9,000.00 1500
7	To respray front bumper, radiator frame, lhs front fender, bonnet. Both front wheel arch trim, lhs front door, lhs rear door, door handle, door cover, lhs rear fender, lhs rear door wheel arch trim, both rear wheel arch trims, rear upper bumper and rear lower bumper.	\$ 10,850.00 2400
8	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00
9	To carry out diagnostic check.	S/N \$ 384.00
TOTAL LABOUR CHARGES		: \$ 25,434.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SUN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>TORW</i>	\$ 3,189.00	
2	FRONT BUMPER FIXING PARTS <i>?</i>	\$ 342.00	
3	FRONT BUMPER CLOSING ELEMENT - LH <i>MU</i>	\$ 109.00	
4	FRONT BUMPER FRAME - LH <i>?</i>	\$ 74.00	
5	FRONT BUMPER COVER - LH <i>?</i>	\$ 74.00	
6	FRONT BUMPER COVER - CENTRE <i>?</i>	\$ 253.00	
7	FRONT BUMPER TRIM - CENTRE <i>scr</i>	\$ 371.00	
8	FRONT BUMPER GRILLE <i>CA X</i>	\$ 231.00	
9	FRONT BUMPER CLOSING ELEMENT <i>?</i>	\$ 265.00	
10	FRONT BUMPER UNDERRUN BAR <i>X</i>	\$ 735.00	
11	FRONT BUMPER TRIM <i>cm</i>	\$ 493.00	
12	FRONTBUMPER TRIM <i>?</i>	\$ 223.00	
13	FRONT BUMPER TOWING EYE COVER <i>X</i>	\$ 60.00	
14	DECORATIVE FRAME - LH <i>scr</i>	\$ 305.00	
15	FRONT BUMPER AIR GUIDE GRILLE - LH <i>de</i>	\$ 398.00	
16	ULTRASOUND SENSOR SUPPORT - LH <i>scr</i>	\$ 26.00	
17	RADIATOR GRILLE <i>?</i>	\$ 2,269.00	
18	RADIATOR GRILLE COVER <i>X</i>	\$ 66.00	
19	RADIATOR GRILLE COVER CAP <i>X</i>	2 \$ 126.00	
20	RADIATOR GRILLE BRACKET <i>X</i>	\$ 85.00	
	SUB SPARE PARTS CHARGES	\$ 9,694.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489 A

Material List for Accident Vehicle Regn No. SKB-123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	RADIATOR GRILLE COVER - LH / RH X	2	\$ 278.00	
22	FRONT CAMERA X		\$ 852.00	
23	FRONT BUMPER FOAM FILLER PIECE ?		\$ 156.00	
24	FRONT BUMPER CARRIER X		\$ 791.00	
25	FRONT BUMPER COVER X		\$ 119.00	
26	FRONT BUMPER GUIDE SECTION - LH Bro -		\$ 40.00	
27	FRONT BUMPER SUPPORT (LH) RH X	2	\$ 66.00	
28	FRONT BUMPER BRACKET - LH ?		\$ 31.00	
29	CAUTION SIGN X	NEC	\$ 13.00	
30	PEDESTRIAN PROTECTION WARNING SIGN X	NEC	\$ 13.00	
31	AIRCON STICKER X	NEC	\$ 7.00	
32	HORN - LH LOW TONE cut -		\$ 157.00	
33	HORN BRACKET - LH LOW TONE X		\$ 27.00	
34	FRONT PARKING AID SENSOR - OUTER X		\$ 231.00	
35	FRONT PARKING AID SENSOR - INNER X		\$ 231.00	
36	FRONT PARKING AID SEAL RING nec -	4	\$ 12.00	
37	FRONT BUMPER WIRING SET cut -		\$ 582.00	
38	FRONT FENDER - LH bt -		\$ 2,110.00	
39	FRONT FENDER ATTACHMENT PARTS ?		\$ 60.00	
40	FRONT FENDER BRACKET - LH ?		\$ 39.00	
TOTAL SPARE PARTS CHARGES			<u>\$ 5,815.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN F489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT FENDER BRACKET - LH ?	\$	59.00
42	FRONT FENDER BRACE ?	\$	135.00
43	S-LINE INSCRIPTION nee ✓	\$	113.00
44	FRONT WHEEL HOUSING LINER - LH de ✓	\$	232.00
45	REAR WHEEL HOUSING LINER - LH ut ✓	\$	232.00
46	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT nee ✓	\$	66.00
47	FRONT SPOILER - LH ?	\$	62.00
48	BONNET repair	\$	4,511.00
49	BONNET ATTACHMENT PARTS X	\$	114.00
50	BONNET LID HINGE - LH / RH X	2 \$	312.00
51	BONNET IMPACT PROTECTION - LH / RH / CENTRE X	3 \$	107.00
52	BONNET GAS FILLED STRUT BRACKET - LH / RH X	2 \$	78.00
53	BONNET GAS FILLED STRUT BRACKET - LH / RH X	2 \$	265.00
54	FENDER SEAL - LH X	\$	56.00
55	HEADLAMP COVER - LH ?	\$	93.00
56	BONNET STRIKER - LH / RH X	2 \$	218.00
57	BONNET BOWDEN CABLE - CENTRE X	\$	53.00
58	BONNET LID LOCK WITH MICRO SWITCH X	2 \$	391.00
59	BONNET LID LOCK CABLE X	\$	67.00
60	BONNET RELEASE LEVER X	\$	13.00
TOTAL SPARE PARTS CHARGES		\$	<u><u>7,177.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
61	FRONT WHEEL COVER - LH / RH ^{-MS} -nee ✓	2	\$ 1,044.00	
62	MAIN BEAM HEADLIGHT MOUNTING - LH ^{CM} ✓	\$	107.00	
63	HEADLIGHT BRACKET - LH ?	\$	48.00	
64	LED HEADLIGHT WITH MATRIX BEAM - LH ^{bro} ✓	\$	11,694.00	
65	MAIN LIGHT ELECTRONICS POWER MODULE ?	\$	685.00	
66	P.C BOARD ?	\$	858.00	
67	HEADLAMP FAN ?	\$	363.00	
68	HEADLIGHT LIFT CYLINDER BRACKET - LH ?	\$	22.00	
69	HEADLIGHT HOSE - LH ?	\$	35.00	
70	HEADLIGHT LIFT CYLINDER - LH ?	\$	181.00	
71	HEADLIGHT PIPE ?	3	\$ 126.00	
72	HEADLIGHT PUMP ?	\$	147.00	
73	WINDSCREEN WASHER SYSTEM PUMP - UPPER / LOWER ?	\$	118.00	
74	WASHER PUMP INSULATOR ?	\$	19.00	
75	WASH WATER RESERVOIR ?	\$	202.00	
76	COOLANT RADIATOR LOCK CARRIER ?	\$	1,100.00	
77	READY MIX COOLANT ^{nee} ✓	4	\$ 165.00	
78	RADIATOR AIR GUIDE - LH / RH ^{Low} ✓	2	\$ 74.00	
79	CHARGE AIR COOLER ^{lt} ✓	\$	855.00	
80	CHARGE AIR COOLER COVER ^{ca} ✓	\$	19.00	
TOTAL SPARE PARTS CHARGES		:	<u>\$ 17,862.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. ~~SKB 123 M~~

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	CHARGE AIR COOLER PRESSURE HOSE ?	\$	188.00
82	CHARGE AIR COOLER PRESSURE HOSE ?	\$	87.00
83	CHARGE AIR TUBE ?	\$	246.00
84	CHARGE AIR COOLER AIR GUIDE ?	\$	79.00
85	CHARGE AIR TUBE ?	\$	189.00
86	REAR BUMPER X	2 \$	3,390.00
87	REAR BUMPER FIXING PARTS X	\$	154.00
88	REAR BUMPER GUIDE SECTION - LH X	\$	68.00
89	REAR WHEEL HOUSING LINER - LH X	\$	327.00
90	REAR WHEEL HOUSING ATTACHMENT PARTS - FRONT AND REAR X	\$	66.00
91	REAR WHEEL COVER - LH / RH X	2 \$	688.00
92	REAR DOOR WHEEL COVER - LH X	\$	179.00
93	REAR DOOR - LH X	\$	3,570.00
94	REAR DOOR OUTER SEAL - LH X	NEC \$	157.00
95	BONDING AGENT X	NEC \$	45.00
96	CLEANING SOLUTION X	NEC \$	65.00
97	REAR DOOR ATTACHMENT PARTS X	\$	191.00
98	OUTER DOOR SEAL X	\$	234.00
99	REAR DOOR CATCH X	\$	96.00
100	OUTER DOOR SEAL - LH X	\$	174.00
TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,193.00</u>

Inconsistent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SNV 7489 A

Material List for Accident Vehicle Regn No. ~~SKB 123 M~~

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
101	SILL PANEL SEAL X	\$	234.00
102	REAR DOOR COVER - LH X	\$	464.00
103	EXTERIOR DOOR HANDLE - LH X	\$	320.00
104	REAR DOOR HANDLE CAP - LH X	\$	36.00
105	REAR DOOR HANDLE HOUSING X	\$	16.00
106	DOOR HANDLE SENSOR - LH X	\$	237.00
107	REAR DOOR MOUNTING BAR - LH X	NEC \$	118.00
108	ROOF MOLDING - LH X	\$	493.00
109	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X	\$	191.00
110	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X	\$	327.00
111	FRONT ALUMINIUM RIM - LH cut ✓	\$	1,471.00
112	ALUMINIUM RIM RUBBER VALVE ne ✓ 1pc ✓	\$	13.00
113	FRONT WISHBONE LINK - LH ?	\$	379.00
114	FRONT SUSPENSION GUIDE - LH ?	\$	949.00
115	FRONT CONTROL ARM - LH UPPER ?	\$	297.00
116	REAR CONTROL ARM - LH UPPER ?	\$	297.00
117	WHEEL BEARING HOUSING - LH ?	\$	683.00
118	CONTROL ARM SWIVEL JOINT ?	\$	204.00
119	WHEEL HUB ?	\$	451.00
120	DOUBLE ANGLED BALL BEARING WITH FLANGE ?	S/N \$	237.00
TOTAL SPARE PARTS CHARGES		:	<u>\$ 7,417.00</u>

inconsistent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
121	SUSPENSION FORKS - LH ?	\$	345.00
122	COUPLING ROD ?	\$	123.00
123	DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS ?	\$	2,267.00
124	GAS SHOCK ABSORBER ?	\$	1,532.00
125	GAS STRUT - LH ?	\$	1,249.00
126	TIE ROD END - LH ?	\$	186.00
127	FRONT NO PLATE X	S/N \$	40.00
128	SUNDRIES ?	\$	800.00
TOTAL SPARE PARTS CHARGES Type LH - at ✓		\$	64,700.00
TOTAL LABOUR CHARGES 90%		\$	25,434.00
GRAND TOTAL		\$	90,134.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Panel - 1hp 90010068
: 19/09/11 @ 1640
: 9 days
: EXCESS: TBA
: REVERT
: Resurvey before print

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant