



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GAO KANG
Period of Insurance : 27 Aug 2019 To 26 Aug 2020
Engine No. : DCB 051783
Chassis No. : WAUZZZF10KD010053

Vehicle No. : SMN7489A
Policy No. : 1900152865
Endorsement No. :
Issued Date : 04 Sep 2019

ABOUT THE COVER

Make/Model : AUDI Q8 3.0 TFSI QU

Engine Capacity/Tonnage : 2,995.00 CC

Driver Restriction : NA

Person or Classes of Persons Entitled to Drive* :

Any person other than the Policyholder who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify any authorised driver other than the Policyholder only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

HU SHUJUAN - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125292

PREMIUM LEASING - LXL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Sherry Loh

14 Selegie Way #07-15 AIG Building 507-120 | T: 65 6338 6200 | www.aig.sg

AIG Asia Pacific Insurance Pte. Ltd.

DRIVING LICENSE OF THE PEOPLE'S REPUBLIC OF CHINA

License No: 142603199608192027

Name : Guo Jinfeng

Sex : Female

Nationality : China

Address : Room 501, Unit 1, Building 5, West Block of Yunsha, Jian'anchu Residential Area, Xinzhi Town, Huozhou City, Linfen City, Shanxi Province

Issuing Authority :
Linfen Traffic Police
Branch, Linfen Public
Security Bureau, Shanxi

Date of Birth : 19-08-1996

Date of first Issue : 23-02-2018

Type of Vehicle for which this license is issued : C1

Photo of
Guo Jinfeng

Valid Period : 23-02-2018 to 23-02-2024

Driving License Of The People's Republic Of China Supplementary Page

License No: 142603199608192027

Name : Guo Jinfeng

Administration Number : 141050038578

Record : The probationary period ends on 22-02-2019.

Vehicle Classification Code

A1	Large Passenger Vehicle & A3,B1,B2	C4	Tri-wheeled Vehicles
A2	Towing Vehicles & B1, B2	C5	Small Automatic Passenger Vehicles for Disabled
A3	Urban Public Transport Vehicles & C1	D	Ordinary Motor Tricycles & E
B1	Medium-sized Passenger Vehicles & C1, M	E	Ordinary Motorbikes & F
B2	Large Trucks & C1, M	F	Light Motorbikes
C1	Small Passenger Vehicles & C2, C3	M	Drivable Wheeled Machinery
C2	Small Automatic Passenger Vehicles	N	Trolley Bus
C3	Low Speed Goods Trucks & C4	P	Trams

Barcode: *14X0014265753*

Apart from the Vehicle Control Office of the Police, no other organisation or individual is allowed to confiscate the certificate.

Certification: This is to certify that the foregoing text is a true and accurate translation prepared by professional Chinese <> English translator Minghan Deng on the 6 August 2019.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12886

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1133/2019/NS
Date	:	18-Sep-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Gao Kang
Address	:	1 Grace Park
	:	Singapore 557761
Telephone	:	HP +65 87813910
Type of Claim	:	Own Damage Claim
Policy No.	:	1900152865
Vehicle No	:	SMN 7489 A
Model Code	:	Audi Q8 3.0 TFSI qu 4MNOX
Model / Year	:	Aug-19
Engine No	:	DCB 051783
Chassis No	:	WAUZZZF10KD010053
Mileage	:	
Date In	:	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Estimated Labour Charges for Accident Vehicle SKB 123 M

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 X na
3	To remove and reinstall aircon condenser and radiator. To renew lhs air charged cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/N \$ 1,400.00 ? ✓
4	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 X na
5	To remove and renew lhs front suspension assy with subframe.	S/N \$ 2,400.00 ? photo ✓
SUB TOTAL LABOUR CHARGES		: \$ <u>4,920.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

lock carrier = 3 1/2
misc 1/2 = \$4200
fender \$600x3 = 3000
wheel \$500x2 = 400
S/N 7489A

Estimated Labour Charges for Accident Vehicle SKB 123 M

S/n	Nature of Jobs	Estimated Charges
6	To dismantle and renew front bumper, lhs front fender, bonnet, lhs headlight, lhs rear door and rear bumper assy. To repair lhs rear fender. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 9,000.00 + 3300 1800 600x3 = 1800
7	To respray front bumper, radiator frame, lhs front fender, bonnet. Both front wheel arch trim, lhs front door, lhs rear door, door handle, door cover, lhs rear fender, lhs rear door wheel arch trim, both rear wheel arch trims, rear upper bumper and rear lower bumper.	\$ 10,850.00 + 2400 200x2 = 400 3400 2800
8	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
9	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ 25,434.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SUN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>TORN</i>	\$ 3,189.00	2551.20
2	FRONT BUMPER FIXING PARTS <i>? nee</i>	\$ 342.00	253.60
3	FRONT BUMPER CLOSING ELEMENT - LH <i>M</i>	\$ 109.00	86.80
4	FRONT BUMPER FRAME - LH <i>? ca</i>	\$ 74.00	59.20
5	FRONT BUMPER COVER - LH <i>? ca</i>	\$ 74.00	59.20
6	FRONT BUMPER COVER - CENTRE <i>? X svc</i>	\$ 253.00	
7	FRONT BUMPER TRIM - CENTRE <i>scu X svc</i>	\$ 371.00	
8	FRONT BUMPER GRILLE <i>ca X svc</i>	\$ 231.00	
9	FRONT BUMPER CLOSING ELEMENT <i>? X svc</i>	\$ 265.00	
10	FRONT BUMPER UNDERRUN BAR <i>X svc</i>	\$ 735.00	
11	FRONT BUMPER TRIM <i>ca</i>	\$ 493.00	394
12	FRONT BUMPER TRIM <i>? ca</i>	\$ 223.00	178
13	FRONT BUMPER TOWING EYE COVER <i>X svc</i>	\$ 60.00	
14	DECORATIVE FRAME - LH <i>scu</i>	\$ 305.00	243.60
15	FRONT BUMPER AIR GUIDE GRILLE - LH <i>de</i>	\$ 398.00	318
16	ULTRASOUND SENSOR SUPPORT - LH <i>nee</i>	\$ 26.00	20.80
17	RADIATOR GRILLE <i>? X svc</i>	\$ 2,269.00	
18	RADIATOR GRILLE COVER <i>X svc</i>	\$ 66.00	
19	RADIATOR GRILLE COVER CAP <i>X svc</i>	2 \$ 126.00	
20	RADIATOR GRILLE BRACKET <i>X svc</i>	\$ 85.00	
	SUB SPARE PARTS CHARGES	\$ 9,694.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SMN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	RADIATOR GRILLE COVER - LH / RH X <i>suc</i>	2	\$ 278.00	
22	FRONT CAMERA X <i>suc</i>		\$ 852.00	
23	FRONT BUMPER FOAM FILLER PIECE ? X <i>suc</i>		\$ 156.00	
24	FRONT BUMPER CARRIER 7 X <i>suc</i>		\$ 791.00	
25	FRONT BUMPER COVER X <i>suc</i>		\$ 119.00	
26	FRONT BUMPER GUIDE SECTION - LH Bro /		\$ 40.00	31.84
27	FRONT BUMPER SUPPORT (LH) <i>suc</i> RH X <i>suc</i>	2	\$ 66.00	
28	FRONT BUMPER BRACKET - LH ? <i>suc</i>		\$ 31.00	24.16
29	CAUTION SIGN X <i>nn</i>	NEC	\$ 13.00	
30	PEDESTRIAN PROTECTION WARNING SIGN X <i>nn</i>	NEC	\$ 13.00	
31	AIRCON STICKER X <i>nn</i>	NEC	\$ 7.00	
32	HORN - LH LOW TONE at /		\$ 157.00	125.00
33	HORN BRACKET - LH LOW TONE at <i>bt</i> /		\$ 27.00	21.20
34	FRONT PARKING AID SENSOR - OUTER X <i>suc</i>		\$ 231.00	
35	FRONT PARKING AID SENSOR - INNER X <i>suc</i>		\$ 231.00	
36	FRONT PARKING AID SEAL RING <i>nn</i> -	4	\$ 12.00	10.24
37	FRONT BUMPER WIRING SET <i>cut</i> -		\$ 582.00	465.60
38	FRONT FENDER - LH <i>bt</i> /		\$ 2,110.00	1688
39	FRONT FENDER ATTACHMENT PARTS ? X <i>suc</i>		\$ 60.00	
40	FRONT FENDER BRACKET - LH ? X <i>suc</i>		\$ 39.00	
TOTAL SPARE PARTS CHARGES			<u>\$ 5,815.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT FENDER BRACKET - LH ? X SUC	\$ 59.00	
42	FRONT FENDER BRACE ? ✓ 4 ✓	\$ 135.00	108
43	S-LINE INSCRIPTION nee ✓	\$ 113.00	90
44	FRONT WHEEL HOUSING LINER - LH de X X SUC	\$ 232.00	X
45	REAR WHEEL HOUSING LINER - LH ut ✓	\$ 232.00	185.60
46	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT nee ✓	\$ 66.00	52.48
47	FRONT SPOILER - LH ? X SUC	\$ 62.00	
48	BONNET requir	\$ 4,511.00	
49	BONNET ATTACHMENT PARTS X SUC	\$ 114.00	
50	BONNET LID HINGE - LH / RH X SUC	2 \$ 312.00	
51	BONNET IMPACT PROTECTION - LH / RH / CENTRE X 3 nee ✓	\$ 107.00	32
52	BONNET GAS FILLED STRUT BRACKET - LH / RH X SUC	2 \$ 78.00	
53	BONNET GAS FILLED STRUT BRACKET - LH / RH X SUC	2 \$ 265.00	
54	FENDER SEAL - LH X SUC	\$ 56.00	
55	HEADLAMP COVER - LH ? X SUC	\$ 93.00	
56	BONNET STRIKER - LH / RH X	2 \$ 218.00	
57	BONNET BOWDEN CABLE - CENTRE X	\$ 53.00	
58	BONNET LID LOCK WITH MICRO SWITCH X SUC	2 \$ 391.00	
59	BONNET LID LOCK CABLE X	\$ 67.00	
60	BONNET RELEASE LEVER X	\$ 13.00	
TOTAL SPARE PARTS CHARGES		\$ 7,177.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SNN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
61	FRONT WHEEL COVER - LH / RH - ^{MU} nee ✓	2	\$ 1,044.00	834.40
62	MAIN BEAM HEADLIGHT MOUNTING - LH ^{CA} ✓	\$	107.00	85.60
63	HEADLIGHT BRACKET - LH ? X ^{SUC}	\$	48.00	
64	LED HEADLIGHT WITH MATRIX BEAM - LH ^{bro} ✓	\$	11,694.00	9355.20
65	MAIN LIGHT ELECTRONICS POWER MODULE ? X ^{SUC}	\$	685.00	
66	P.C BOARD ? X ^{SUC}	\$	858.00	
67	HEADLAMP FAN ? X ^{SUC}	\$	363.00	
68	HEADLIGHT LIFT CYLINDER BRACKET - LH ? X ^{SUC}	\$	22.00	
69	HEADLIGHT HOSE - LH ? X	\$	35.00	
70	HEADLIGHT LIFT CYLINDER - LH ? X	\$	181.00	
71	HEADLIGHT PIPE ? X	3	\$ 126.00	
72	HEADLIGHT PUMP ? X	\$	147.00	
73	WINDSCREEN WASHER SYSTEM PUMP - UPPER / LOWER ? X ^{SUC}	\$	118.00	
74	WASHER PUMP INSULATOR ? X ^{SUC}	\$	19.00	
75	WASH WATER RESERVOIR ? X ^{SUC}	\$	202.00	
76	COOLANT RADIATOR LOCK CARRIER ? ^{SUC CA}	\$	1,100.00	880
77	READY MIX COOLANT ^{nee} ✓	4	\$ 165.00	131.84
78	RADIATOR AIR GUIDE - LH / RH ^{lower} ^{CA} ✓	2	\$ 74.00	59.04
79	CHARGE AIR COOLER ^{lt} ✓	\$	855.00	684
80	CHARGE AIR COOLER COVER ^{CA} ✓	\$	19.00	14.56
TOTAL SPARE PARTS CHARGES		:	<u>\$ 17,862.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	CHARGE AIR COOLER PRESSURE HOSE ? x sue	\$	188.00
82	CHARGE AIR COOLER PRESSURE HOSE ? x sue	\$	87.00
83	CHARGE AIR TUBE ? x sue	\$	246.00
84	CHARGE AIR COOLER AIR GUIDE ? ✓ ca	\$	79.00 GJ-72
85	CHARGE AIR TUBE ? x sue	\$	189.00
86	REAR BUMPER X	2 \$	3,390.00
87	REAR BUMPER FIXING PARTS X	\$	154.00
88	REAR BUMPER GUIDE SECTION - LH X } nn	\$	68.00
89	REAR WHEEL HOUSING LINER - LH X	\$	327.00
90	REAR WHEEL HOUSING TIE R ATTACHMENT PARTS - FRONT AND REAR X nn	\$	66.00
91	REAR WHEEL COVER - LH / RH X	2 \$	688.00
92	REAR DOOR WHEEL COVER - LH X	\$	179.00
93	REAR DOOR - LH X	\$	3,570.00
94	REAR DOOR OUTER SEAL - LH X	NEC \$	157.00
95	BONDING AGENT X	NEC \$	45.00
96	CLEANING SOLUTION X	NEC \$	65.00
97	REAR DOOR ATTACHMENT PARTS X	\$	191.00
98	OUTER DOOR SEAL X	\$	234.00
99	REAR DOOR CATCH X	\$	96.00
100	OUTER DOOR SEAL - LH X	\$	174.00
TOTAL SPARE PARTS CHARGES		\$	<u>10,193.00</u>

inconsistent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SMN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
101	SILL PANEL SEAL X	\$	234.00
102	REAR DOOR COVER - LH X	\$	464.00
103	EXTERIOR DOOR HANDLE - LH X	\$	320.00
104	REAR DOOR HANDLE CAP - LH X	\$	36.00
105	REAR DOOR HANDLE HOUSING X	\$	16.00
106	DOOR HANDLE SENSOR - LH X	\$	237.00
107	REAR DOOR MOUNTING BAR - LH X	NEC \$	118.00
108	ROOF MOLDING - LH X	\$	493.00
109	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X ny	\$	191.00
110	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X ny	\$	327.00
111	FRONT ALUMINIUM RIM - LH cut	\$	1,471.00 1176.80
112	ALUMINIUM RIM RUBBER VALVE ne - X ny	\$	13.00
113	FRONT WISHBONE LINK - LH ? ✓ bt	\$	379.00 302.80
114	FRONT SUSPENSION GUIDE - LH ? ✓ bt	\$	949.00 758.80
115	FRONT CONTROL ARM - LH UPPER ? ✓ bt	\$	297.00 237.60
116	REAR CONTROL ARM - LH UPPER ? ✓ bt	\$	297.00 237.60
117	WHEEL BEARING HOUSING - LH ? ✓ bt	\$	683.00 546.40
118	CONTROL ARM SWIVEL JOINT ? ✓ bt	\$	204.00 162.80
119	WHEEL HUB ? ✓ bt	\$	451.00 360.40
120	DOUBLE ANGLED BALL BEARING WITH FLANGE ? ✓ bt	S/N \$	237.00 189.20
TOTAL SPARE PARTS CHARGES		\$	7,417.00

Inconsistent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
121	SUSPENSION FORKS - LH ? X Svc	\$	345.00
122	COUPLING ROD ? X Svc	\$	123.00
123	DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS ? X Svc	\$	2,267.00
124	GAS SHOCK ABSORBER ? X Svc	\$	1,532.00
125	GAS STRUT - LH ? X Svc	\$	1,249.00
126	TIE ROD END - LH ? ✓ bt ✓	\$	186.00 148.80
127	FRONT NO PLATE X Svc	S/N \$	40.00
128	SUNDRIES ? ✓ new	\$	800.00 201.36
TOTAL SPARE PARTS CHARGES type LH - at 710		\$	64,700.00
TOTAL LABOUR CHARGES 90%		\$	25,434.00
GRAND TOTAL		\$	90,134.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

90819.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

:
:
:
:
:
:


Panel - 14p 90010068
19/09/11 P 1640
9 days
EXCESS: TBA
REVERT
Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SUN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

glsy / washer

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
✓	FRONT BUMPER TORN ✓	\$ 3,189.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 342.00	
SK-air 23/9 (3)	FRONT BUMPER CLOSING ELEMENT - LH M ✓	\$ 109.00	
(4)	FRONT BUMPER FRAME - LH ? NE M	\$ 74.00 *	
(5)	FRONT BUMPER COVER - LH ? NE M	\$ 74.00 *	
6	FRONT BUMPER COVER - CENTRE ? NE M	\$ 253.00 *	
GER-V 23/9 (7)	FRONT BUMPER TRIM - CENTRE ✓	\$ 371.00	
8	FRONT BUMPER GRILLE ✓	\$ 231.00	
9	FRONT BUMPER CLOSING ELEMENT ? NE M	\$ 265.00 *	
10	FRONT BUMPER UNDERRUN BAR X	\$ 735.00	
GER-V 23/9 (11)	FRONT BUMPER TRIM ✓	\$ 493.00	
12	FRONT BUMPER TRIM ? NE M	\$ 223.00 *	
13	FRONT BUMPER TOWING EYE COVER X	\$ 60.00	
GER-V 23/9 (14)	DECORATIVE FRAME - LH ✓	\$ 305.00	
(15)	FRONT BUMPER AIR GUIDE GRILLE - LH ✓ de	\$ 398.00	
GER-V 23/9 (16)	ULTRASOUND SENSOR SUPPORT - LH ✓	\$ 26.00	
SK-air 23/9 (17)	RADIATOR GRILLE ? NE M	\$ 2,269.00 *	
GER-V 23/9 18	RADIATOR GRILLE COVER X	\$ 66.00	
19	RADIATOR GRILLE COVER CAP X	2 \$ 126.00	
20	RADIATOR GRILLE BRACKET X	\$ 85.00	
SUB SPARE PARTS CHARGES		\$ 9,694.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SUN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	RADIATOR GRILLE COVER - LH / RH X	2	\$ 278.00	
22	FRONT CAMERA X		\$ 852.00	
GER-V 23/9 - 23	FRONT BUMPER FOAM FILLER PIECE ? embd		\$ 156.00	✓
24	FRONT BUMPER CARRIER X		\$ 791.00	
25	FRONT BUMPER COVER X		\$ 119.00	
GER-V 23/9 - 26	FRONT BUMPER GUIDE SECTION - LH Bro		\$ 40.00	
27	FRONT BUMPER SUPPORT (LH) RH X	2	\$ 66.00	
28	FRONT BUMPER BRACKET - LH ? 2nd		\$ 31.00	✓
29	CAUTION SIGN X	NEC	\$ 13.00	
30	PEDESTRIAN PROTECTION WARNING SIGN X	NEC	\$ 13.00	
31	AIRCON STICKER X	NEC	\$ 7.00	
32	HORN - LH LOW TONE at		\$ 157.00	
33	HORN BRACKET - LH LOW TONE X Best		\$ 27.00	✓
34	FRONT PARKING AID SENSOR - OUTER X		\$ 231.00	
35	FRONT PARKING AID SENSOR - INNER X		\$ 231.00	
36	FRONT PARKING AID SEAL RING nec	4	\$ 12.00	
GER-V 23/9 - 37	FRONT BUMPER WIRING SET cut		\$ 582.00	
38	FRONT FENDER - LH 64		\$ 2,110.00	
39	FRONT FENDER ATTACHMENT PARTS ? Not		\$ 60.00	X
40	FRONT FENDER BRACKET - LH ? Not		\$ 39.00	X
TOTAL SPARE PARTS CHARGES			\$ 5,815.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SUN 7489 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT FENDER BRACKET - LH <i>Re new</i>	S 59.00	X
42	FRONT FENDER BRACE <i>Bent</i>	S 135.00	✓
43	S-LINE INSCRIPTION <i>re</i>	S 113.00	
44	FRONT WHEEL HOUSING LINER - LH <i>de</i>	S 232.00	
45	REAR WHEEL HOUSING LINER - LH <i>cut</i>	S 232.00	
46	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT <i>re</i>	66.00	
47	FRONT SPOILER - LH <i>Not new</i>	S 62.00	X
48	BONNET <i>repair</i>	S 4,511.00	
49	BONNET ATTACHMENT PARTS X	S 114.00	
50	BONNET LID HINGE - LH / RH X	2 S 312.00	
51	BONNET IMPACT PROTECTION - <i>cut</i> RH / CENTRE X	3 S 107.00	35.67
52	BONNET GAS FILLED STRUT BRACKET - LH / RH X	2 S 78.00	
53	BONNET GAS FILLED STRUT BRACKET - LH / RH X	2 S 265.00	
54	FENDER SEAL - LH X	S 56.00	
55	HEADLAMP COVER - LH <i>Not new</i>	S 93.00	X
56	BONNET STRIKER - LH / RH X	2 S 218.00	
57	BONNET BOWDEN CABLE - CENTRE X	S 53.00	
58	BONNET LID LOCK WITH MICRO SWITCH X	2 S 391.00	
59	BONNET LID LOCK CABLE X	S 67.00	
60	BONNET RELEASE LEVER X	S 13.00	
TOTAL SPARE PARTS CHARGES		S 7,177.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6356 2323 Fax: 6841 1183

Telefax

SNN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
GER-V 23/9 (62)	FRONT WHEEL COVER - LH / RH - ^{MU} net ✓	2 S	1,044.00
SK-air 23/9 (62)	MAIN BEAM HEADLIGHT MOUNTING - LH cm ✓	S	107.00
SK-air 23/9 (63)	HEADLIGHT BRACKET - LH ?	S	48.00
SK-air 23/9 (64)	LED HEADLIGHT WITH MATRIX BEAM - LH Bro ✓	S	11,694.00
GER-V 23/9 65	MAIN LIGHT ELECTRONICS POWER MODULE ?	S	685.00
66	P.C BOARD ^{Then}	S	858.00 x
67	HEADLAMP FAN ^{Then}	S	363.00 +
68	HEADLIGHT LIFT CYLINDER BRACKET - LH ^{Then}	S	22.00 x
69	HEADLIGHT HOSE - LH ^{Then}	S	35.00 x
70	HEADLIGHT LIFT CYLINDER - LH ^{Then}	S	181.00 x
71	HEADLIGHT PIPE ^{Then}	3 S	126.00 x
72	HEADLIGHT PUMP ^{Then}	S	147.00 +
73	WINDSCREEN WASHER SYSTEM PUMP - UPPER / LOWER	S	118.00
74	WASHER PUMP INSULATOR ^{Then}	S	19.00 +
75	WASH WATER RESERVOIR ^{Then}	S	202.00 +
76	COOLANT RADIATOR LOCK CARRIER ^{Then}	S	1,100.00 ✓
77	READY MIX COOLANT ^{net}	4 S	165.00
GER-V 23/9 (78)	RADIATOR AIR GUIDE - LH / RH ^{Lower} cm ✓	2 S	74.00
GER-V 23/9 (79)	CHARGE AIR COOLER ^{lt}	S	855.00
GER-V 23/9 80	CHARGE AIR COOLER COVER ^{cm}	S	19.00
TOTAL SPARE PARTS CHARGES		S	17,862.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB-123 M

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
81	CHARGE AIR COOLER PRESSURE HOSE <i>7489</i>	\$	188.00	X
82	CHARGE AIR COOLER PRESSURE HOSE <i>7489</i>	\$	87.00	X
83	CHARGE AIR TUBE <i>7489</i>	\$	246.00	X
84	CHARGE AIR COOLER AIR GUIDE <i>2nd</i>	\$	79.00	✓
85	CHARGE AIR TUBE <i>7489</i>	\$	189.00	X
86	REAR BUMPER X	2 \$	3,390.00	
87	REAR BUMPER FIXING PARTS X	\$	154.00	
88	REAR BUMPER GUIDE SECTION - LH X	\$	68.00	
89	REAR WHEEL HOUSING LINER - LH X	\$	327.00	
90	REAR WHEEL HOUSING ATTACHMENT PARTS - FRONT AND REAR X	\$	66.00	
91	REAR WHEEL COVER - LH / RH X	2 \$	688.00	
92	REAR DOOR WHEEL COVER - LH X	\$	179.00	
93	REAR DOOR - LH X	\$	3,570.00	
94	REAR DOOR OUTER SEAL - LH X	NEC \$	157.00	
95	BONDING AGENT X	NEC \$	45.00	
96	CLEANING SOLUTION X	NEC \$	65.00	
97	REAR DOOR ATTACHMENT PARTS X	\$	191.00	
98	OUTER DOOR SEAL X	\$	234.00	
99	REAR DOOR CATCH X	\$	96.00	
100	OUTER DOOR SEAL - LH X	\$	174.00	
TOTAL SPARE PARTS CHARGES			<u>\$ 10,193.00</u>	

GERU
23/9
76R-U
23/9
5K-air
23/9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SUN 7487 A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
101	SILL PANEL SEAL X	\$	234.00
GER-V 23/9 - 102	REAR DOOR COVER - LH X	\$	464.00
103	EXTERIOR DOOR HANDLE - LH X	\$	320.00
104	REAR DOOR HANDLE CAP - LH X	\$	36.00
105	REAR DOOR HANDLE HOUSING X	\$	16.00
106	DOOR HANDLE SENSOR - LH X	\$	237.00
107	REAR DOOR MOUNTING BAR - LH X	NEC \$	118.00
108	ROOF MOLDING - LH X	\$	493.00
109	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X	\$	191.00
110	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER X	\$	327.00
GER-V 23/9 - 111	FRONT ALUMINIUM RIM - LH cut ✓	\$	1,471.00
112	ALUMINIUM RIM RUBBER VALVE ne ✓	1 pc ✓ \$	13.00 3.25
113	FRONT WISHBONE LINK - LH ?	\$	379.00
114	FRONT SUSPENSION GUIDE - LH ?	\$	949.00
SK-air 23/9 - 115	FRONT CONTROL ARM - LH UPPER ?	\$	297.00
116	REAR CONTROL ARM - LH UPPER ?	\$	297.00
SK-air 23/9 - 117	WHEEL BEARING HOUSING - LH ?	\$	683.00
GER-V 23/9 - 118	CONTROL ARM SWIVEL JOINT ?	\$	204.00
119	WHEEL HUB ?	\$	451.00
120	DOUBLE ANGLED BALL BEARING WITH FLANGE ?	S/N \$	237.00
TOTAL SPARE PARTS CHARGES		\$	7,417.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SMN 7489A

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
121	SUSPENSION FORKS - LH ?	S	345.00
122	COUPLING ROD ?	S	123.00
123	DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS ?	S	2,267.00
124	GAS SHOCK ABSORBER ?	S	1,532.00
125	GAS STRUT - LH ?	S	1,249.00
126	TIE ROD END - LH ?	S	186.00
127	FRONT NO PLATE X	S/N S	40.00
128	SUNDRIES ?	S	800.00
TOTAL SPARE PARTS CHARGES Type LH - ext ✓		S	64,700.00
TOTAL LABOUR CHARGES 90%		S	25,434.00
GRAND TOTAL		S	90,134.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/TP/1133/2019/NS

Date

23-Sep-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMN 7489 A

Model No

Audi Q8 3.0 TFSI qu 4MNOX

Quantity Description

Unit Price Amount

Parts

- | | | |
|---|---|-------|
| 1 | Track rod front LHS | Best |
| 2 | Refrigerant line | Best |
| 3 | Refrigerant pipe | ? 4/1 |
| 4 | Flat contact housing with contact locking mechanism | could |

\$	111.00	✓	88.50
\$	234.00	✓	186.80
\$	494.00	?	394.80
\$	19.00	✓	14.96

TOTAL

\$ 858.00

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
01/10/19
flg