

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12567

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1130/2019/NS
Date	:	18-Sep-19

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Goh Chye Kiang (Wu Caiqiang)
Address	:	29 Jurong West Street 41 #04-07 Singapore 649411
Telephone	:	(HP) +65 90228661
Type of Claim	:	Own Damage Claim
Policy No.	:	1700079762-01
Vehicle No	:	SFY 651 T
Model Code	:	Q5 SPORT 2.0 TFSI QU
Model / Year	:	29/11/2017
Engine No	:	DAX 019373
Chassis No	:	WAUZZZF5J2051897
Mileage	:	18637
Date In	:	16-Sep-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Sep-19
Place of Accident	:	Jurong East St 31 Traffic Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 651 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X X
2	To carry out first measurement on car o-liner.	S/N \$ 800.00	phh ✓
3	To remove and renew front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
4	To remove and renew, aircon condenser, charged air cooler, radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
5	To remove centre console. Renew both front seat belts and air bag control unit. Reinstall all parts removed.	S/N \$ 1,800.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 4,560.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 651 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To remove and transfer lhs front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 720.00	✓
7	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carpets, electronic component and fuse trays.	S/N \$ 1,400.00	photos ✓
8	To dismantle engine assy with gearbox assy. Inspect for damages and renew accordingly.	S/N \$ 3,200.00	photos ✓
9	To renew gearbox assy.	S/N \$ 1,800.00	photos ✓
10	To dismantle front suspension assy. Inspect for damages and renew accordingly. Reinstall all parts removed.	S/N \$ 2,400.00	? photos ✓ ✓ 2400
SUB TOTAL LABOUR CHARGES		: \$ 9,520.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 651 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
11	To place vehicle on car o-liner.	S/N \$ 1,200.00	<i>photo</i> ✓
12	To dismantle front bumper, bonnet, both front fenders, lhs front and rear doors. Cut out and weld both front chassis frame shock absorber mounting, lhs b-pillar, reinforcement panels and sill panel reinforcement. Align both front chassis frames to specification of origin. renew front lock carrier and align to position. renew damaged panels. re-organise front crash management components. reinstall all parts removed.	\$ 17,600.00 7500	✓
13	To remove rhs front door panel trims, dismantle rhs wing mirror assy. Renew door chrome molding.	S/N \$ 400.00 250	<i>photo</i> ✓
14	To respray front bumper, lower spoiler, both front fenders, bonnet, hinges, both A-pillars, both front doors, lhs rear door, door covers, lhs B-pillar, sill panel, inner panels door entrances, lhs rear fender and wheel arch trims, and engine compartment. to carry out stone chip treatment and joint sealer works.	\$ 15,000.00 7975	✓
15	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
16	To carry out diagnostic checks.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 48,944.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Steve 14/11/19

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>70RN /</i>	\$ ✓ 2,696.00	2156.80
2	FRONT BUMPER FIXING PARTS ? <i>/ APC nmx</i>	\$ X 244.00	0
3	ULTRASOUND SENSOR SUPPORT - LH / RH ? <i>CLH) / CRH</i>	\$ ✓ 166.00	65.84
4	FRONT BUMPER SECURING STRIP - LH / RH ? <i>DR</i>	\$ 2 ✓ 68.00	52.96
5	FRONT BUMPER CLOSING ELEMENT - LH / RH ? <i>X CRH</i>	\$ ✓ 202.00	164.40
6	FRONT BUMPER GRILLE - CENTRE <i>de /</i>	\$ ✓ 155.00	124.00
7	FRONT BUMPER SPOILER <i>de /</i>	\$ ✓ 725.00	579.00
8	RADIATOR GRILLE <i>CRH /</i>	\$ ✓ 3,258.00	2606.40
9	RADIATOR GRILLE STRIKER PLATE <i>CRH /</i>	\$ ✓ 222.00	177.20
10	FRONT BUMPER AIR GUIDE GRILLE - LH ? <i>/ DR</i>	\$ ✓ 635.00	507.60
11	FRONT BUMPER END CAP - LH X <i>SVC</i>	\$ 83.00	X
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>SCR /</i>	\$ ✓ 635.00	507.60
13	FRONT BUMPER END CAP - RH X <i>SVC</i>	\$ 83.00	X
14	LOCKING CLIP <i>de /</i>	\$ 4 ✓ 15.00	11.52
15	FRONT BUMPER CLOSING ELEMENT <i>CRH /</i>	\$ ✓ 246.00	196.80
16	FRONT BUMPER FOAM FILLER PIECE <i>CRH /</i>	\$ ✓ 259.00	207.20
17	FRONT BUMPER CARRIER <i>BT /</i>	\$ ✓ 831.00	664.40
18	FRONT BUMPER BRACKET - LH / RH <i>RH-BT / LH-7. / DR</i>	\$ 2 ✓ 462.00	368.80
19	FRONT BUMPER COVER <i>de /</i>	\$ 116.00	92.40
20	CAUTION SIGN <i>NEC /</i>	NEC \$ 13.00	9.76
SUB TOTAL SPARE PARTS		\$ 11,114.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Steve 14/11/9

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	AIRCON STICKER <i>nee</i>	NEC \$	18.00	14
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>OR cva</i> <i>LH-? / RH-cm</i>	\$	68.00	68.54.24
23	FRONT WHEEL COVER - LH / RH <i>nee</i>	2 \$	1,212.00	968.80
24	FENDER - LH / RH <i>LH-bt / RH-repair</i>	2 \$	2,602.00	1040.80
25	FENDER BRACKET - LH / RH ? <i>X NN</i>	2 \$	32.00	
26	FENDER BRACE - LH / RH ? <i>X NN</i>	2 \$	412.00	
27	FENDER COVER PANEL - LH / RH <i>nee LH-nee / RH-X₂nee</i>	\$	72.00	56.80
28	FENDER CLOSURE PANEL - LH / RH <i>LH-nee / RH-X₂nee</i>	\$	56.00	44.48
29	FENDER INNER SHIELD - LH / RH OUTER ? <i>/ CV</i>	2 \$	142.00	0 112.96
30	FENDER ATTACHMENT PARTS - FRONT ? <i>/ CV</i>	2 \$	119.00	0 47.52
31	S-LINE INSCRIPTION <i>nee</i>	2 \$	225.00	180
32	FRONT WHEEL HOUSING LINER - LH / RH <i>LH-X₂de / RH-cm</i>	\$	492.00	392.80
33	FRONT WHEEL SPOILER - LH / RH <i>LH-cm / RH-de</i>	2 \$	292.00	233.60
34	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT <i>LH-nee / RH-nee</i>	2 \$	69.00	27.28
35	BONNET <i>nee</i>	\$	3,707.00	2965.60
36	BONNET LID HINGE - LH / RH ? <i>/ RH, LH DT</i>	2 \$	292.00	233.60
37	BONNET ATTACHMENT PARTS ? <i>X SVC</i>	\$	127.00	X
38	BONNET GAS FILLED STRUT X <i>X SVC</i>	2 \$	217.00	X
39	BONNET STRIKER - LH / RH <i>RH-bt / LH-? / DT</i>	2 \$	218.00	174.40
40	BONNET SOUND ABSORBER <i>de</i>	\$	289.00	231.20
SUB TOTAL SPARE PARTS			\$ 10,661.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

from 14/11/9

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>acc</i> / 3	\$ 75.00	59.44
42	PLENUM CHAMBER COVER <i>X SVC</i>	\$ 131.00	X
43	BONNET LID LOCK - FRONT <i>RH bt</i> / 2	\$ 391.00	312.80
44	BONNET RELEASE ELEMENT <i>CR</i> / ? / <i>acc</i>	\$ 53.00	41.68
45	BONNET BOWDEN CABLE - CENTRE <i>ca</i> /	\$ 53.00	41.68
46	BONNET RELEASE LEVER <i>ca</i> /	\$ 13.00	10
47	BONNET LID LOCK CABLE <i>ca</i> /	\$ 67.00	53.36
48	LED HEADLIGHT - LH / RH <i>ca</i> / 2	\$ 14,454.00	11,563.20
49	LIGHT SYSTEM CONTROL UNIT <i>? SVC</i> / <i>Shel</i> 2	\$ 1,383.00	0
50	MAIN LIGHT ELECTRONICS POWER MODULE <i>? SVC</i> / <i>Shel</i> 2	\$ 1,385.00	0
51	LED WITH HEAT SINK - LH / RH <i>? Shel SVC</i> 2	\$ 1,980.00	0
52	HEADLIGHT HOSE - LH / RH <i>? RH, LH CR</i> 2	\$ 70.00	54.88
53	MAIN BEAM HEADLIGHT MOUNTING - LH / RH <i>? RH, LH</i> 2	\$ 214.00	171.20
54	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH <i>LT</i> / <i>X acc</i> 2	\$ 256.00	204
55	HEADLIGHT HOSE - LH / RH <i>? CR</i> / <i>ca</i> 2	\$ 113.00	90
56	COOLANT RADIATOR LOCK CARRIER <i>ca</i> /	\$ 1,169.00	935.20
57	COOLANT BRACE - LH / RH LOWER <i>RH bt / LH - X</i> / <i>bt</i> 2	\$ 104.00	83.20
58	CHARGE AIR COOLER <i>bt</i> /	\$ 724.00	578.80
59	INTER COOLER HOSE - LH <i>X SVC</i>	\$ 477.00	X
60	PRESSURE SENSOR O-RING <i>acc</i> /	\$ 17.00	13.44
SUB TOTAL SPARE PARTS		\$ 23,129.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

5/2/19 14/11/19

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	PRESSURE HOSE - RH ?	\$	283.00	
62	AIR GUIDE - UPPER / CENTRE / LOWER ? ✓ CVA ✓ TN	3 \$	✓ 123.00	97.20
63	AIR GUIDE LH - RH RH-MIS / LH-? CVA	2 \$	✓ 100.00	79.36
64	RADIATOR LOUVRE CVA	\$	✓ 483.00	376
65	SERVOMOTOR ? X JAM	\$	✓ 166.00	132.80
66	RADIATOR LOUVRE bt	\$	✓ 820.00	655.60
67	A/C CONDENSOR bt	\$	✓ 547.00	437.60
68	READY-MIX COOLANT ne	4 \$	✓ 84.00	67.20
69	COOLANT SUPPORT - LH / RH RH-CVA / LH-? X	2 \$	✓ 96.00	48 76.64
70	FAN RING ? ✓ DR	\$	✓ 373.00	298.40
71	RADIATOR FAN WITH CONTROL UNIT ? ✓ DD	\$	✓ 2,159.00	1727.20
72	RUBBER BUSH - LOWER ne	2 \$	✓ 17.00	13.44
73	RUBBER BUSH - LOWER ne	2 \$	✓ 24.00	18.56
74	PRESSURE RELIEF VALVE ? X SVC	\$	48.00	X
75	REFRIGERANT LINE PRESSURE SENSOR ? ✓ MIS	\$	✓ 180.00	0 144.60
76	AC ADAPTER CABLE ? ✓ MIS	\$	27.00	0 X
77	SHOCK ABSORBER MOUNTING - LH / RH RH-bt / LH-? X	2 \$	698.00	X
78	WINDOW SLOT SEAL WITH TRIM STRIP - LH FRONT cut	\$	✓ 537.00	429.60
79	WINDOW SLOT SEAL WITH TRIM STRIP cut	\$	✓ 561.00	448.80
80	WINDOW GUIDE - LH X SVC	\$	440.00	X
SUB TOTAL SPARE PARTS		:	\$ 7,766.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

57620

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

14/11/19
Star

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	WINDOW GUIDE TRIM STRIP - LH / RH X SVC	2 \$ 622.00	X
82	WINDOW GUIDE - RH X SVC	\$ 440.00	X
83	FRONT DOOR bt ✓	\$ ✓ 2,829.00	2263.20
84	FRONT DOOR OUTER SEAL ne ✓	NEC \$ ✓ 185.00	147.60
85	BONDING AGENT ne ✓	NEC \$ ✓ 45.00	35.92
86	CLEANING SOLUTION ne ✓	NEC \$ ✓ 65.00	51.68
87	FRONT DOOR ATTACHMENT PARTS ? xvm / nec	\$ 239.00	0 X
88	FRONT DOOR CATCH ? X / jammed	\$ ✓ 132.00	0 105.60
89	FRONT DOOR COVER - LH de ✓	\$ ✓ 643.00	514
90	WINDOW REGULATOR WITHOUT MOTOR - LH ? ✓ OT	\$ ✓ 270.00	215.60
91	PILLAR B TRIM - LH X SVC	\$ 153.00	X
92	REAR DOOR bt ✓	\$ ✓ 2,829.00	2263.20
93	REAR DOOR SEAL BRACKET ? ✓ cm	\$ ✓ 39.00	30.48
94	REAR DOOR OUTER SEAL - LH ne ✓	NEC \$ ✓ 190.00	152
95	BONDING AGENT ne ✓	NEC \$ ✓ 45.00	35.92
96	CLEANING SOLUTION ne ✓	NEC \$ ✓ 65.00	51.68
97	REAR DOOR SEALING STRIP ? ✓ cm	\$ ✓ 15.00	11.68
98	DOOR HINGE HALF-UPPER PART - LH UPPER ? ✓ OT	\$ ✓ 42.00	33.04
99	DOOR HINGE HALF-LOWER PART - LH UPPER ? ✓ OT	\$ ✓ 42.00	33.04
100	DOOR HINGE HALF-UPPER PART - LH LOWER bt ✓	\$ ✓ 42.00	33.04
SUB TOTAL SPARE PARTS		: \$ 8,932.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

File 14/11/19

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
101	DOOR HINGE HALF-LOWER PART - LH LOWER <i>bt</i>	\$ ✓ 42.00	33.04
102	REAR DOOR CATCH ? <i>bt</i>	\$ ✓ 132.00	105.60
103	REAR OUTER DOOR SEAL - LH <i>re</i>	\$ ✓ 201.00	160.80
104	REAR INNER DOOR SEAL <i>re</i>	\$ ✓ 190.00	152
105	SILL PANEL SEAL - LH <i>re</i>	\$ ✓ 234.00	187.20
106	REAR DOOR SEAL BRACKET - LH ? <i>X nec</i>	\$ ✓ 39.00	30.48
107	REAR DOOR GUIDE RAIL - LH ? <i>BL</i>	\$ ✓ 65.00	51.44
108	PILLAR B TRIM - LH <i>X SVC</i>	\$ 200.00	X
109	WINDOW REGULATOR MOTOR - LH ? <i>X SVC</i>	\$ 329.00	X
110	WINDOW REGULATOR WITHOUT MOTOR - LH ? <i>AT</i>	\$ 277.00	221.20
111	REAR DOOR COVER - LH <i>de</i>	\$ 558.00	446.40
112	REAR WHEEL COVER - LH <i>scu</i>	\$ 473.00	378.40
113	SIDE MEMBER - LH <i>bt</i>	\$ 2,226.00	1780.80
114	INNER B PILLAR - LH ? <i>DD</i>	\$ 511.00	408.40
115	B-PILLAR RINFORCEMENT - LH ? <i>DD</i>	\$ 844.00	674.80
116	B-PILLAR CLOSING PLATE - LH ? <i>DD</i>	\$ 646.00	516.40
117	B-PILLAR CLOSING PLATE REINFORCEMENT - LH ? <i>DD</i>	\$ 17.00	12.96
118	SILL - LH ? <i>DD X SVC</i>	\$ 646.00	X
119	NOISE INSULATION PLATE ? <i>MC</i>	3 \$ 47.00	36.48
120	B-PILLAR PLATE - LH INNER ? <i>MC</i>	\$ 12.00	9.12
SUB TOTAL SPARE PARTS		: \$ 7,689.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

SPR 14/11/19

Material List for Accident Vehicle Regn No. SFY 651 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
121	AIRBAG STICKER <i>rec /</i>	\$ 23.00	17.76
122	DOOR TRIM - LH <i>rear ? / CR4</i>	\$ 2,301.00	1840.80
123	FRONT PARKING AID SENSOR - INNER <i>MIS / 1st / 2</i>	\$ 462.00	83.54
124	FRONT BUMPER WIRING SET <i>? / TN</i>	\$ 378.00	30.2
125	THREE-POINT AUTOMATIC SEAT BELT - LH / RH <i>2 Jan 2 LH, RH Jamb</i>	\$ 2,010.00	1608
126	SEAT BELT HEIGHT ADJUSTER <i>? Jamb - RH, LH 2</i>	\$ 322.00	257.60
127	AIRBAG CONTROL UNIT <i>act /</i>	\$ 1,927.00	1541.160
128	AIRBAG PRESSURE SENSOR <i>act /</i>	\$ 245.00	196
129	AIRBAG CRASH SENSOR <i>act /</i>	\$ 382.00	305.20
130	B-PILLAR TRIM - LH UPPER / LOWER <i>? X de</i>	\$ 489.00	171.20
131	CENTRAL PROTECTION <i>act /</i>	\$ 485.00	388
132	FRONT NO. PLATE <i>bt /</i>	\$ 40.00	40
133	SUNDRIES <i>? X nec</i>	\$ 1,000.00	684.56
TOTAL SPARE PARTS		\$ 79,355.00	
TOTAL LABOUR CHARGES		\$ 48,944.00	
GRAND TOTAL		\$ 128,299.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Suppliers

fd LH Door lock / Jamb

Per LH Door lock / Jamb

293334

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasul - Hp 90010068
Surveyed Date : 19/09/19 @ 1530
Authorised Date :
Excess Cost : 24 days
Liability : EXCESS: TBA
Remarks :
Resin
Resin before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: