

23/09/2019

G/L

ASS. REC. BY:

REF: CS/MSG 19016619/T1+f3e2

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Crystal Lee

of

MSG

Date/Time:

19.9.19 4.20 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 9411B

Insured:

SGL 1559 C

at Workshop m/s

AMA Automotive

Tel:

6000600

of 36 Toh Guan Road East #01-36

Policy No:

29 09 2023

Claim No:

606253

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

my 17

H.O.D. Endorsement:

Date/Time:

2.9.19 9.50 a.m

Person Contacted:

Victor

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 9411B - X

SGL 1559 C - X

ASS. REC. BY:

Taufik

REP:

ASSIGNMENT

CoE 2022 July

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

24,500

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Victor

Veh No:

SKF 94113

Yr Regn:

2007

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Lancer 2.0 SR cc 1998

Colour:

White

NG: Insured / Std / NI / NA

Sp. Reading

283408

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSTCY448400532

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60R15

R:

n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

20/9/19

Survey held at

Amila

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s, F + N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/59 9,500, 9 days (Red: 13788 73: 59%)

Rebate 9 914, 994

RECEIVED 04 DEC 2019

Taufik

Pls see my remarks.

Mam 10
3/12/2019

Date/Time, File Pass in?

☐

Preli. Report

31/2 Typist

☒

Final Report

Date/Time, File Return in?

31

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Wend and (\$)

Survey Fee:

290

Transportation:

S + RS 2

Probe:

Other:

11

TOTAL

261

Rep. Format:

Lump Sum / H.R. /

TP
9500f

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Thursday, 19 September 2019 4:20 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: img-919113622.pdf

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKF9411B & SGL1559C (MSIG) ON 18/09/2019

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 19 September, 2019 3:27 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKF9411B & SGL1559C (MSIG) ON 18/09/2019 resend, got recd?

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 19 September, 2019 3:26 PM
To: AMA Automotive <ama.claim@gmail.com>
Cc: Fievel Foo <Fievel_Foo@sg.msig-asia.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKF9411B & SGL1559C (MSIG) ON 18/09/2019 resend, got recd?

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: AMA Automotive [<mailto:ama.claim@gmail.com>]
Sent: Thursday, 19 September, 2019 3:23 PM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKF9411B & SGL1559C (MSIG) ON 18/09/2019 resend, got recd?

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi

Thank you for your email.

We choose LKK Auto Consultants Pte Ltd

Thank You and Best Regards



Alvin Wee

AMA Automotive Pte Ltd

36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel : +65 6200 0600

www.amaauto.sg



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

On Thu, Sep 19, 2019 at 3:14 PM Helene Phua <helene_phua@sg.msig-asia.com> wrote:

Hi,

We refer to your email dated 19/09/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd

- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) E C Looi
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

(a) *Fast lane settlement is not applicable for cases that liability is in dispute*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: AMA Automotive [<mailto:ama.claim@gmail.com>]

Sent: Thursday, 19 September 2019 1:55 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKF9411B & SGL1559C ON 18/09/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs/Madam

Please find the attached PRS Letter and GIA report for your perusal. Kindly let us have the Pre-Repair Surveyor Lists and advise me about the liability of this accident case.

Take note that the Repair Estimate will be ready upon the Pre-Repair Survey.

Workshop : **AMA Autocare Pte Ltd**

Address

: 36 TOH GUAN ROAD EAST #01-36
ENTERPRISE HUB SINGAPORE 608580

Contact Person

: Alvin Wee
HP: 8778 3636 / 9017 3393 /
Office: 6200 0600

Thank You and Best Regards



Alvin Wee

AMA Automotive Pte Ltd


36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel : +65 6200 0600

www.amaauto.sg



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy.

This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Our Ref: **SKF9411B**

Your Ref: **To be advised**

19/09/2019

MSIG INSURANCE (SINGAPORE) PTE LTD
4 Shenton Way #21-01 SGX Centre 2
Singapore 068807

BY EMAIL ONLY

Dear Sir,

RE: **PROPERTY DAMAGE CLAIM**
CLAIMANT TAY WEIDA
ACCIDENT INVOLVING SKF9411B & SGL1559C ALONG TUAS AVENUE 9 PARALLEL PARKING LOT
ON 18/09/2019 AT ABOUT 0900HRS
PRE-REPAIR SURVEY NOTICE

- 1 We are instructed by **TAY WEIDA**, the owner of motor vehicle no **SKF9411B** which was involved in the aforesaid accident.
- 2 As a result of the accident, Our Client's vehicle has been damaged. Before We proceed to repair the damaged vehicle, Please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. M/s AMA Autocare Pte Ltd at 36 Toh Guan road East #01-36 Singapore (608580) and kindly arrange with Mr. Alvin at 8778 3636.
- 3 If We do not receive any reply from you within the stipulated timeline, We shall proceed to repair the vehicle without further reference to you.

Yours Faithfully,



Alvin Wee

(65) 8778 3636

AMA AUTOCARE PTE LTD

Enterprise Hub

36 Toh Guan Road East

#01-36 S(608580)

HOTTEST NEW CAR
PROMOTIONS



Toyota Sienta Hybrid

Ready stock available with immediate COE registration. Call us now!!

DON'T MISS OUT!

Mitsubishi Lancer

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Advanced Search

Home » Used Cars » A Star Motors Pte Ltd » Mitsubishi Lancer EX 2.0M GT (COE till 08/2022)

Mitsubishi Lancer EX 2.0M GT (COE till 08/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CONSIGNMENT

Price \$23,000

Depreciation ① \$8,430 /yr

Reg Date 22-Aug-2007
(2yrs 8mths 23days COE left)

Mileage 170,690 km (13.9k /yr)

Manufactured ① 2007

Road Tax ① \$1,452 /yr

Transmission Manual

Dereg Value ① \$13,909 as of today (change)

OMV ① \$17,670

COE ① \$25,486

ARF ① \$19,437

Engine Cap 1,998 cc

Power 114.0 kW (152 bhp)

Curb Weight ① 1,397 kg

No. of Owners ① 4

Type of Vehicle Mid-Sized Sedan

Features

4B11 2.0L Engine Mated To A 5 Speed Gearbox. View specs of the Mitsubishi Lancer (2006-2008)

Accessories

Rota Fighter 17 Inch Rims, HKS Approved Exhaust, Pioneer DVD Player.

Description

Cheap And Reliable. Good For Daily Drives. Efficient Fuel Consumption, Easy To Maintain.

Category

COE Car, Consignment Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

A Star Motors Pte Ltd

7 vehicles for sale. 4 sold in past 3 mths

31 Bukit Batok Crescent #01-25

Tel: 63397788

Search cars nearby

Kree

81686947

Posted on: 02-Oct-2019 | Last Updated on: 05-Nov-2019

Upfront Payment

Transfer Fee ① \$25

Down Payment ① \$6,900 (change)

1st Instalment ① \$553


Insurance \$684 onwards (Get a quote)

Maximum 70% Loan

Based on 3.75% interest rate

» more financial info

Powered by



Compare

ITNDEF, MHA & POGIS policyholders stand profile. "Get a quote" for exact figure.

BLACK FRIDAY WEEKEND
DEALS AWAIT. REGISTER FOR DEALS



Mitsubishi Lancer Price Range Depreciation > 10 year(s) Vehicle Type

Advanced Search

Home » Used Cars » Craft Auto Pte Ltd » Mitsubishi Lancer EX 2.0A GT Sunroof (COE till 11/2023)

Mitsubishi Lancer EX 2.0A GT Sunroof (COE till 11/2023)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$25,900	Reg Date	26-Nov-2008 (3yrs 11mths 27days COE left)
Depreciation ⓘ	\$6,490 /yr	Manufactured ⓘ	2008
Mileage	N.A.	Transmission	Auto
Road Tax ⓘ	\$1,331 /yr	OMV ⓘ	\$19,738
Dereg Value ⓘ	\$12,822 as of today (change)	ARF ⓘ	\$19,738
COE ⓘ	\$16,061	Power	114.0 kW (152 bhp)
Engine Cap	1,998 cc	No. of Owners ⓘ	2
Curb Weight ⓘ	1,427 kg		
Type of Vehicle	Mid-Sized Sedan		

Features

2.0L MIVEC Engine, 6 Speed Auto Gearbox With Paddle Shift, ABS, Airbags, Cruise Control, Auto HID Headlights/Rain Sensors, 152Bhp, Steering Audio. View specs of the Mitsubishi Lancer EX (2008-2017)

Accessories

18" Sports Rims, Like New Leather Upholstery, Keyless Entry, Factory Fitted Bodykit, HID Headlights, Reverse Sensors, Racing GT Wing. Sunroof!

Description

Cheapest Unit In Town Yet Good Condition! Not Those Asking Super Cheap Cos The Car Is A Lemon! Don't Believe Come And View And Test Drive To Be Convinced! Interior Is Like New! Super Well Taken Care Of! Totally Don't Look Like A COE Renewed Car! Many Recent Wear And Tear Done! All Got Receipts To Show! Seller Is Upgrading! Not Selling Due To Problems! Welcome Any Form Of Evaluation Or Inspection!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Craft Auto Pte Ltd

11 vehicles for sale. 27 sold in past 3 mths

21 Toh Guan Road East #05-10

Toh Guan Centre

Tel: 62523688

Search cars nearby

Andrew

91054418

Posted on: 31-Oct-2019 | Last Updated on: 26-Nov-2019

Upfront Payment

Transfer Fee ⓘ

Do Compare

» more Financial info

Maximum 70% Loan

HOTTEST NEW CAR
PROMOTIONS



Toyota Sienta Hybrid
Ready stock available with immediate COE registration. Call us now!!

DON'T MISS OUT!

Mitsubishi Lancer

Price Range

Depreciation

> 10 year(s)

Vehicle Type


Advanced
Search

Home » Used Cars » WS Car Leasing Pte Ltd » Mitsubishi Lancer EX 2.0A GT (COE till 05/2023)

Mitsubishi Lancer EX 2.0A GT (COE till 05/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price	\$27,500		
Depreciation ⓘ	\$7,960 /yr	Reg Date	14-May-2008 (3yrs 5mths 14days COE left)
Mileage	N.A.	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,331 /yr	Transmission	Auto
Dereg Value ⓘ	\$13,374 as of today (change)	OMV ⓘ	\$19,923
COE ⓘ	\$19,356	ARF ⓘ	\$19,923
Engine Cap	1,998 cc	Power	114.0 kW (152 bhp)
Curb Weight ⓘ	1,427 kg	No. of Owners ⓘ	More than 6
Type of Vehicle	Mid-Sized Sedan		

Features

2.0 MIVEC Engine, 6 Speed Auto With Paddle Shifters. Wear And Tear Parts Replaced, No Admin Fees Incurred. View specs of the Mitsubishi Lancer

Accessories

17" Sports Rims, Premium Leather Upholstery, Keyless Entry, Reverse Sensors, Rear Spoilers.

Description

Door Step Viewing Available On Appt Basis. No Hard Selling, No Obligation. Full Loan With Monthly \$788, 6 Months Warranty On Engine And Gear Box, Grooming Included. Trade-In Welcome. Come And Test Drive.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more.



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

WS Car Leasing Pte Ltd

4 vehicles for sale, 5 sold in past 3 mths

30A Joo Chiat Place

Tel: 63858344

Search cars nearby

Freda

98332841

Posted on: 04-Nov-2019 | Last Updated on: 04-Nov-2019

Upfront Payment

Transfer Fee ⓘ \$25

Down Payment ⓘ \$8,250 (change)

1st Instalment ⓘ ---

In Compare

a quote)

Maximum 70% Loan

Based on 3.75% interest rate

Powered by

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyao

Date: 25 Sep 2019

Preliminary Advice

Insured Vehicle No	: SGL1559C	Accident Date	: 18/09/2019
TP Vehicle No	: SKF9411B	Assignment Date	: 20/09/2019
Make	: MITSUBISHI LANCER EX	Est. Duration of Repair	: 9.00
Date of Inspection	: 20/09/2019		
Inspection At	: AMA AUTOMOTIVE PTE LTD 36 TOH GUAN ROAD EAST #01-36 SINGAPORE 608580		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s, front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,698.73
Revised Amount	:S\$	12,909.00
Check Items (Estimated)	:S\$	7,276.00
Total	:S\$	20,185.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 999I

Vehicle Details

Vehicle No.: SKF9411B

Vehicle to be Exported: No

Intended Deregistration
Date: 23 Sep 2019

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER 2.0L MIVEC
GT 6-CVT SUNROOF

Primary Colour: White

Manufacturing Year: 2007

Engine No.: 4B11AM5669

Chassis No.: JMYSTCY4A8U000532

Maximum Power
Output: 114.0 kW (152 bhp)

Open Market Value: \$18,965.00

Original Registration
Date: 01 Aug 2007

First Registration Date: 01 Aug 2007

Transfer Count: 3

Actual ARF Paid: \$20,862.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jul 2022

COE Category: B - Car (1601cc &
above)

COE Period(Years): 5

PQP Paid: \$26,237.00

COE Rebate Amount: \$14,980.00

Total Rebate Amount: \$14,980.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2019 13:46
Date Of Accident	18/09/2019 09:00
Exact Location Of Accident	ALONG TUAS AVENUE 9 PARALLEL PARKING LOT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF9411B
Insured/Policyholder	
Name Of Registered Owner	TAY WEIDA
NRIC No	S8209999I
Email Address	WEIDATAY@EZTECH.COM.SG
Mobile Phone No	(LOCAL) +65-90182219
Alternative Phone No	OFFICE-90182219

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX 2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10016419R02
Cover Note Number	

Driver

Name of Driver	TAY WEIDA
NRIC No	S8209999I
Date Of Birth	15/04/1982
Occupation	INDOOR
Date Of Driving Pass	13/01/2004
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90182219
Fax Number	
Contact Number	OFFICE-90182219
EEmail Address	WEIDATAY@EZTECH.COM.SG

Address	BLOCK 385 BUKIT BATOK WEST AVENUE 5 #28-338
Postcode	650385
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Sketch Plan for the accident details.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL1559C
Vehicle Make/Model/Colour	TOYOTA WISH GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM YONG LYE
NRIC/Passport Number	S1527290B
Contact Number	96696803
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	1

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop, my workbench and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/9/19 - 9am.

My vehicle was parked ~~at~~ stationary inside the first parking lot along Tuas Ave 9. I was inside the vehicle. The other vehicle came from behind my vehicle and hit my car from the right. My car was hit out of the lot and ended ~~about~~ about 3-4 metres in front of the lot. The other vehicle came to a stop about 15-20 metres in front of my car. The air bags in that vehicle was activated.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: 18/9/19 12pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36 S(608580)
E: ama.claim@gmail.com T: 87783636
Co Reg no. 201735370W

Page No. 1

Vehicle No. SKF9411EB Mitsubishi Lancer EX 2.0A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front bumper		1280.00	xnn
1	Front bumper lower skirt LH		244.00	xnn
1	Front shock absorber LH		395 672.00	bt - 3xnn
1	Front knuckle arm LH		358 594.00	bt
1	Front wheel bearing LH		292.00	bt
1	Front lower arm LH		398.00	bt
1	Front lower link LH		212.00	?xnn
1	Front trailing arm LH		285.00	xnn
1	Front stabilizing bar		367.00	xnn
1	Front drive shaft LH		381.00	bt
1	Front steering rack & pinion		1885.00	xnn
1	Front crossmember		843.00	xnn
1	Rear bumper		875.80 1250.00	de
1	Rear bumper side retainer RH		98.00	de
1	Rear bumper reinforcement		672.00	xnn
1	Rear fender RH		782.50	bt
1	Rear fender innershield RH		100 272.00	de
1	Rear fender taillamp RH		510.80 780.00	?ann
1	Taillamp lower panel		314.20	Ry
1	Rear end panel		982.00	Ry
1	Rear door RH		811 1172.00	bt
1	Rocker panel RH		970.00	Ry
1	Side skirt RH		512.00	de
1	Fuel tank		600 791.00	?dd
1	Rear shock absorber RH		345 672.00	bt
1	Rear knuckle arm RH		594.00	bt
1	Rear wheel bearing RH		292.00	bt
1	Rear lower arm RH		329 398.00	bt
1	Rear lower link RH		212.00	bt
1	Rear trailing arm RH		285.00	?bt
1	Rear stabilizing bar		367.00	?bt
1	Rear axle subframe		616 916.00	?bt
1	Rear drive shaft RH		391.00	xnn
1	Rear dust shield RH		210 364.00	xnn
1	Rear disc rotor RH		391.00	xnn
1	Rear brake calliper RH		473.00	xnn
1	Rear brake hose RH		206.00	xnn
1	Exhaust muffler		535.70 700.00	de xnn
			21609.70	

10969.80
107. 9872.82

24/9

		less	10%	2160.97	10%	
				19448.73		
	SPECIAL NETT ITEMS					
1	Front sports rim LH		400	1080.00	cut	1080
1	Rear sports rim RH		400	1080.00	as	1080
1	Front tyre LH			480.00	2 in	480
1	Rear tyre RH		70%	480.00	putted 210	X
1set	Front bumper clips			70.00	3 in	X
1set	Front innershield clips			40.00	X in	X
1set	Rear bumper clips			70.00	3 in	30
1set	Rear innershield clips			40.00	2 in	20
1	Rear end panel sealant			100.00	X in	X
1	Rear windscreen sealant		80	120.00	80 in	X
1	Reverse sensor			280.00	X in	
	Total Parts			23288.73		

1740

S/N 2810

1140-



AMA Autocare Pte Ltd
Enterprise Hub
36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636
Co Reg no. 201735370W

Tan Kah 9749 5749
WP

2/9/1904wp

Lumpsum

Result after repair

give 1 month

9 days

Page No. 2

to check repairment

Vehicle No. SKF9411EB Mitsubishi Lancer EX 2.0A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2200.00	1200 1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1000 1200
3	To remove and re-fix wiring and check all electrical components	220.00	30
4	To clear fault code with diagnostic computer and reset to specifications	250.00	100
5	To remove and re-fix fuel tank system	180.00	100 x 200
6	To remove / re-fix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	60
7	To remove and re-install FRONT undercarriage parts LH (suspension system)	250.00	120 150
8	To remove and re-install REAR undercarriage parts RH (suspension system)	250.00	150 150
9	To provide anti-rust treatment on affected areas	180.00	40
10	To conduct full computerised wheel alignment test	150.00	80
11	To remove and replace rear windscreen	300.00	120
12	To remove and replace reverse camera & check function	180.00	x 100
Labour Total :		6410.00	
TOTAL (PARTS & LABOUR):		29698.73	

IMPORTANT NOTE: SUPPLEMENTARY PARTS & LABOUR (IF ANY) WILL BE ADDED TO THIS ESTIMATE AFTER THE DAMAGED PORTION IS DISMANTLED TO DETERMINE THE FULL EXTENT OF DAMAGED VISIBLE INTERNAL PARTS

L/S \$11k

30328.73

P - 9872.82
SLN - 1140
L - 3400.00

limit \$9500

14412.82

2/5/19 \$9500



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36 S(608580)
E: ama.claim@gmail.com T: 87783636
Co Reg no. 201735370W

Page No. 1

Vehicle No. SKF9411EB Mitsubishi Lancer EX 2.0A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Front bumper		1280.00	x nn
1	Front bumper lower skirt LH		244.00	x nn
1	Front shock absorber LH		672.00	bt -
1	Front knuckle arm LH		594.00	bt -
1	Front wheel bearing LH		292.00	bt -
1	Front lower arm LH		398.00	bt -
1	Front lower link LH		212.00	? X }
1	Front trailing arm LH		285.00	? X } nn
1	Front stabilizing bar		367.00	? X }
1	Front drive shaft LH		381.00	? bt -
1	Front steering rack & pinion		1885.00	? X nn
1	Front crossmember		843.00	x X nn
1	Rear bumper		1250.00	de -
1	Rear bumper side retainer RH		98.00	nn -
1	Rear bumper reinforcement		672.00	x X nn
1	Rear fender RH		782.50	bt -
1	Rear fender innershield RH		272.00	nn -
1	Rear fender taillamp RH		780.00	? - con
1	Taillamp lower panel		314.20	Rx X
1	Rear end panel		982.00	Rx X
1	Rear door RH		1172.00	bt -
1	Rocker panel RH		970.00	Rx X
1	Side skirt RH		512.00	de -
1	Fuel tank		791.00	? - dd -
1	Rear shock absorber RH		672.00	bt -
1	Rear knuckle arm RH		594.00	bt -
1	Rear wheel bearing RH		292.00	bt -
1	Rear lower arm RH		398.00	bt -
1	Rear lower link RH		212.00	? - bt -
1	Rear trailing arm RH		285.00	? - bt -
1	Rear stabilizing bar		367.00	? - bt -
1	Rear axle subframe		916.00	? - bt -
1	Rear drive shaft RH		391.00	x nn
1	Rear dust shield RH		364.00	x - de -
1	Rear disc rotor RH		391.00	? - bt -
1	Rear brake calliper RH		473.00	? - bt -
1	Rear brake hose RH		206.00	? - dy -
			21609.70	

		less	10%	2160.97	10%	
				19448.73		
	SPECIAL NETT ITEMS					
1	Front sports rim LH			1080.00	cut	✓
1	Rear sports rim RH			1080.00	cut	✓
1	Front tyre LH			480.00	7 X nn	
1	Rear tyre RH			480.00	perfect	✓
1set	Front bumper clips			70.00	3 X nn	
1set	Front innershield clips			40.00	X nn	
1set	Rear bumper clips			70.00	30 mm	✓
1set	Rear innershield clips			40.00	20 mm	✓
1	Rear end panel sealant			100.00	X nn	
1	Rear windscreen sealant			120.00	80 mm	✓
1	Reverse sensor			280.00	X nn	
	Total Parts			23288.73		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



AMA Autocare Pte Ltd
Enterprise Hub
36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636
Co Reg no. 201735370W

Handwritten signature
2/9/19

Tan Kah 9749 5749
WP
20/9/19 420 pm
Lumpsum
Resolving after repair
SVC / Maintenance
9 days

Page No. 2

* to check repair cost

Vehicle No. SKF9411EB Mitsubishi Lancer EX 2.0A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT ±
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2200.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1000
3	To remove and re-fix wiring and check all electrical components	220.00	30
4	To clear fault code with diagnostic computer and reset to specifications	250.00	100
5	To remove and re-fix fuel tank system	180.00	? photo
6	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	60
7	To remove and re-install FRONT undercarriage parts LH (suspension system)	250.00	120 ? photo
8	To remove and re-install REAR undercarriage parts RH (suspension system)	250.00	150 ? photo
9	To provide anti-rust treatment on affected areas	180.00	40
10	To conduct full computerised wheel alignment test	150.00	80
11	To remove and replace rear windscreen	300.00	120
12	To remove and replace reverse camera & check function	180.00	X
Labour Total :		6410.00	
TOTAL (PARTS & LABOUR):		29698.73	

IMPORTANT NOTE: SUPPLEMENTARY PARTS & LABOUR (IF ANY) WILL BE ADDED TO THIS ESTIMATE AFTER THE DAMAGED PORTION IS DISMANTLED TO DETERMINE THE FULL EXTENT OF DAMAGED VISIBLE INTERNAL PARTS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2019		20 Sep 2019 11:44 Edit Adj Rpt	\$9,500.00 Edit Estimates	\$9,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LIM YONG LYE, ID: S1527290B, Tel: +6596696863, Email: yonglye@gmail.com								
Main Claimant:	TAY WEIDA, ID: S82099991								
Vehicle Reg. No.:	SKF9411B	Date of Loss:	18/09/2019 09:00 - :59 [145 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 606253	Policy/Cover Note No.:	29092023 (Third Party Only) Coverage: 05/09/2019 - 04/09/2020						
Vehicle Reg. No. (Insured):	SGL1559C	Policy No. (Claimant):							
		Excess:							
Repairer:	Ama Automotive Pte Ltd () 36 Toh Guan Road East #01-36, 608580 Jurong East - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 20/10/2019]								
Driver/Custodian (Insured):	LIM YONG LYE (57 / Male) , NRIC: S1527290B, Tel: +6596696863 Email: yonglye@gmail.com								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 19/09/19. (Manual Assign). Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Alvin Wee @ 8778 3636 / 9017 3393 / 6200 0600.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF9411B (606253)
[SGL1559C]








































TP
























































TAY WEIDA

Sep 18 2019 9:00AM

[LIM YONG LYE]

Ama Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print	
1	20/09/19 11:10	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: SGL1559C, Claimant: LIM YONG LYE</small>	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/09/19 11:22	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	22/11/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
39	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
40	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
41	22/11/19 17:01	Odometer Reading		<input checked="" type="checkbox"/>
42	22/11/19 17:01	Chassis Number		<input checked="" type="checkbox"/>
43	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
44	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
45	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
46	22/11/19 17:01	General View		<input checked="" type="checkbox"/>
47	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
48	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
49	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
50	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
51	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
52	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
53	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
54	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
55	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
56	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
57	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
58	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
59	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
60	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
61	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
62	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
63	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
64	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
65	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
66	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
67	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
68	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
69	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
70	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
71	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
72	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
73	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
74	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
75	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
76	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
77	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
78	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
79	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
80	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
81	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
82	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
83	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
84	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
85	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
86	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
87	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
88	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
89	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
90	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
91	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
92	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
93	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
94	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
95	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
96	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
97	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
98	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
99	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
100	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
101	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
102	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
103	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
104	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
105	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
106	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
107	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
108	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
109	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
110	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
111	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
112	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
113	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
114	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
115	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
116	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
117	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
118	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
119	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
120	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
121	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
122	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
123	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
124	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
125	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
126	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
127	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
128	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
129	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
130	22/11/19 17:02	Reinspection Photo		<input checked="" type="checkbox"/>
131	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
132	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
133	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
134	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
135	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
136	22/11/19 17:02	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/19 11:10	PRI From: SC - Reg. No: SGL1559C, Claimant: LIM YONG LYE		<input checked="" type="checkbox"/>
2	20/09/19 11:10	TP SKF94118 E-REPORT From: SC - Reg. No: SGL1559C, Claimant: LIM YONG LYE		<input checked="" type="checkbox"/>
3	20/09/19 11:16	Agree on SJE		<input checked="" type="checkbox"/>
4	28/11/19 18:57	maintain offer		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	20/09/19 11:33	Survey Request - Manual Assigned		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016619/T1TF3E2

Date: 16/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29092023

Claimant Vehicle No: SKF9411B

Insured Vehicle No: SGL1559C

Date of Loss: 18/09/2019

Nature of Claim: TP

Claim No: 606253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF9411B

Make & Model: MITSUBISHI LANCER EX, 2.0 (A)

Engine No: 4B11AM5669

Reg. Date: 01/08/2007 (Man. Year: 2007)

Chassis No: JMYSTCY4A8U000532

Colour: White

Odometer: 283408 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,918.73	10,657.32	13,261.41	55.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,410.00	3,400.00	3,010.00	46.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,328.73	14,057.32	16,271.41	53.65
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	30,328.73	9,500.00	20,828.73	68.68
+ GST 7.00/7.00% (S\$)	2,123.01	665.00	1,458.01	68.68
Nett Amount (S\$)	32,451.74	10,165.00	22,286.74	68.68

INSPECTION

Date of Assignment: 20/09/2019

Date Inspected: 20/09/2019 Inspected At:

Ama Automotive Pte Ltd
36 Toh Guan Road East #01-36
Singapore 608580

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2019)
Parts:	143	MITSUBISHI LANCER EX 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF9411B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,280.00 FL	*- FL
2	1		*FRONT BUMPER LOWER SKIRT LH	Not Necessary	244.00 FL	*- FL
3	1		*FRONT SHOCK ABSORBER LH	Not Necessary	672.00 FL	*- FL
4	1		*FRONT KNUCKLE ARM LH	Bent	594.00 FL	*358.00 FL
5	1		*FRONT WHEEL BEARING LH	Bent	292.00 FL	*292.00 FL
6	1		*FRONT LOWER ARM LH	Bent	398.00 FL	*398.00 FL
7	1		*FRONT LOWER LINK LH	Not Necessary	212.00 FL	*- FL
8	1		*FRONT TRAILING ARM LH	Not Necessary	285.00 FL	*- FL
9	1		*FRONT STABILIZING BAR	Not Necessary	367.00 FL	*- FL
10	1		*FRONT DRIVE SHAFT LH	Bent	381.00 FL	*381.00 FL
11	1		*FRONT STEERING RACK & PINION	Not Necessary	1,885.00 FL	*- FL
12	1		*FRONT CROSSMEMBER	Not Necessary	843.00 FL	*- FL
13	1		*REAR BUMPER	Deformed	1,250.00 FL	*875.80 FL
14	1		*REAR BUMPER SIDE RETAINER RH	Necessary	98.00 FL	*98.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	672.00 FL	*- FL
16	1		*REAR FENDER RH	Buckled	782.50 FL	*782.50 FL
17	1		*REAR FENDER INNER SHIELD RH	Torn	272.00 FL	*100.00 FL
18	1		*REAR FENDER TAILLAMP RH	Cracked	780.00 FL	*510.80 FL
19	1		*TAILLAMP LOWER PANEL	Repair	314.20 FL	*- FL
20	1		*REAR END PANEL	Repair	982.00 FL	*- FL
21	1		*REAR DOOR RH	Bent	1,172.00 FL	*811.00 FL
22	1		*ROCKER PANEL RH	Repair	970.00 FL	*- FL
23	1		*SIDE SKIRT RH	Deformed	512.00 FL	*512.00 FL
24	1		*FUEL TANK	Dented	791.00 FL	*600.00 FL
25	1		*REAR SHOCK ABSORBER RH	Bent	672.00 FL	*345.00 FL
26	1		*REAR KNUCKLE ARM RH	Bent	594.00 FL	*594.00 FL
27	1		*REAR WHEEL BEARING RH	Bent	292.00 FL	*292.00 FL
28	1		*REAR LOWER ARM RH	Bent	398.00 FL	*329.00 FL
29	1		*REAR LOWER LINK RH	Bent	212.00 FL	*212.00 FL
30	1		*REAR TRAILING ARM RH	Bent	285.00 FL	*285.00 FL
31	1		*REAR STABILIZING BAR	Bent	367.00 FL	*367.00 FL
32	1		*REAR AXLE SUBFRAME	Bent	916.00 FL	*616.00 FL
33	1		*REAR DRIVE SHAFT RH	Not Necessary	391.00 FL	*- FL
34	1		*REAR DUST SHIELD RH	Dented	364.00 FL	*210.00 FL
35	1		*REAR BRAKE CALIPER RH	Bent	473.00 FL	*473.00 FL
36	1		*REAR BRAKE HOSE RH	Distorted	206.00 FL	*206.00 FL
37	1		*EXHAUST MUFFLER	Dented	700.00 FL	*535.70 FL
38	1		*FRONT SPORTS RIM LH	Cut	1,080.00 FS	*400.00 FS
39	1		*REAR SPORTS RIM RH	Cracked	1,080.00 FS	*400.00 FS
40	1		*FRONT TYRE LH	Not Necessary	480.00 FS	*- FS
41	1		*REAR TYRE RH (@\$300.00) (70%)	Punctured	480.00 FS	*210.00 FS
42	1		*SET FRONT BUMPER CLIPS	Not Necessary	70.00 FS	*- FS
43	1		*SET FRONT INNERSHIELD CLIPS	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
45	1		*SET REAR INNERSHIELD CLIPS	Necessary	40.00 FS	*20.00 FS
46	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
47	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*80.00 FS
48	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
49	1		*REAR DISC ROTOR RH	Bent	391.00 FL	*391.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	26,149.70	11,714.80
- List Item Discount on L Items 10.00/10.00% (S\$)	2,230.97	1,057.48
Total Parts (S\$)	23,918.73	10,657.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	2,200.00	1,500.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	2,000.00	1,200.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS	New	220.00	30.00
4	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATIONS	New	250.00	100.00
5	TO REMOVE AND RE-FIX FUEL TANK SYSTEM	New	180.00	0.00
6	TO REMOVE / REFIX INNER TRIMS, FITTINGS, GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	250.00	60.00
7	TO REMOVE AND RE-INSTALL FRONT UNDERCARRIAGE PARTS LH (SUSPENSION SYSTEM)	New	250.00	120.00
8	TO REMOVE AND RE-INSTALL REAR UNDERCARRIAGE PARTS RH (SUSPENSION SYSTEM)	New	250.00	150.00
9	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	40.00
10	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	150.00	80.00
11	TO REMOVE AND REPLACE REAR WINDSCREEN	New	300.00	120.00
12	TO REMOVE AND REPLACE REVERSE CAMERA & CHECK FUNCTION	New	180.00	0.00
Gross Labour Cost (S\$)			6,410.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >