

REPAIR ESTIMATE*

VEHICLE NO : SHA 5276M

DATE 18/9/2019 17:00

MODEL : HYUNDAI i40

MODEL	: HYUNDAI i40		Type	Unit Price	Amount
Qty	Parts Description/ Labour				
	Boot Lid				\$ 2,174.90
	Boot Lid Rubber	X sue			\$ 96.50
	Boot Lid Lock Upper	X sue			\$ 102.60
	Boot Lid Lock Lower	X sue			\$ 31.70
	Boot Lid 'H' Emblem	— sue			\$ 28.70
	Boot Lid CRDI Plate	— sue			\$ 27.90
	Boot Lid Lamp (LH/RH)	X sue		\$ 565.60	\$ 1,131.20
	Licence Lamp (LH/RH)	X sue		\$ 33.95	\$ 67.90
	Boot Lid Trimboard	X sue			\$ 116.40
	Boot Lid Trimboard Clips (10pcs)	X sue			\$ 11.00
	Bootlid Moulding	X sue			\$ 85.00
	Bootlid i40 Emblem	— sue			\$ 27.90
	Bootlid Lower Garnish	X sue			\$ 227.90
	Rear Bumper	— sue			\$ 553.00
	Rear Bumper Reinforcement	— sue			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)	CH X sue RH ✓		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs	— sue			\$ 22.00
	Rear Bumper Bracket	X sue		\$ 35.60	\$ 71.20
	Rear Bumper Sponge	— sue			\$ 103.50
	Rear Bumper Under Cover	— sue			\$ 228.00
	Rear Bumper Reflector Lamp (LH/RH)	LH X sue RH ✓		\$ 30.60	\$ 61.20
	Rear Panel	X sue			\$ 526.70
	Rear Panel Garnish	X sue			\$ 57.70
	Rear Panel Lower Panel	X sue			\$ 89.40
	Exhaust Pipe Insulator, RH	X sue			\$ 58.55
	Exhaust Silencer, RH	X sue			\$ 967.70
	Exhaust Pipe Hanger, RH	X sue			\$ 58.55
	Exhaust Pipe Centre	X sue			\$ 730.10
					\$ 8,246.20
					\$ 1,649.24
					\$ 6,596.96
	Boot Lid Comfort Logo & Tel No. Sticker	— sue			\$ 30.00
	Rear Bumper Reverse Sensor	— sue			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH)	— sue		\$ 100.00	\$ 200.00
					\$ 365.70
	Labour Charge				560
	Panel Beating				\$ 850.00
	Spray Painting Charge				\$ 750.00
	Wiring Charge				\$ 50.00
	Tuff Kote				\$ 50.00
	Remove/Refix Reverse Sensor				\$ 80.00
	TOTAL LABOUR				\$ 1,780.00
	ESTIMATE TOTAL				\$ 8,742.66