

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

19 SEP 2019

E S T I M A T E

Estimate No. : b1 52791	Page No. : 1 of 4
Date Estimated : 19/09/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Yu JiYin Blk 445B Bukit Batok West Avenue 8 #19-443 Singapore 652445	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF5300R	VD11411	15/11/2018	216i AT	0

DESCRIPTION	VALUE
Replace rear bumper include attachment etc and knock on accident repair area	850 1,275.00
Spray painting rear bumper	934 1,036.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	40 80.00
Total Labour 1	2,570.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER ?	1	458.10	458.10
SUPPORT ?	1	45.30	45.30
LEFT PROTECT ?	1	5.60	5.60
RIGHT PROTEC ?	1	5.60	5.60
REAR BUMPER TRIM STRIP (BLACK) <i>sun</i>	1	88.20	88.20
REAR BUMPER PANEL PRIMED (LINES PDC <i>repair</i>)	1	1,045.45	1,045.45
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
ULTRASONIC SENSOR ALPINWEISS (U300) ?	4	380.65	1,522.60
Total Parts			3,191.05

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>01/16/17 @ 1015</u>	Claim No. _____
Date & Time <u>19/09/2019</u>	Excess S\$ _____
Surveyor's Name <u>Rtsul</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____	PML Yes / No _____

Labour 1	:	2,570.00
Parts	:	3,191.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	403.27
Grand Total	:	6,164.32

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Page No. : 1 of 4

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF5300R	WBA2X92060VD11411	15/11/2018	216i AT	0

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (BLACK)	88.20	1.00	0.00	88.20

LOSS OF USE=\$60 X 3DAYS
GIA SERACH FEE=\$2.00

	OD	3RD PARTY	DATE	
FAX TO		RASHI	9/14/19	3
FAX NO		LKK		
FAX TO				
FAX NO				
CONT				
PL				