

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6451 G

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00
1 pc	End panel	\$	250.00
<i>Front Bumper repair</i>		\$	2,203.00
Less 10%		\$	220.30
		\$	1,982.70

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00
1 pc	Rear bumper top protector	\$	80.00 50
1 pc	Front no. plate	\$	50.00 35
Sundry		\$	50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. Cut/weld and heat on the end panel. Including knock-out, straighten, repair, reshape and adjust of the front bumper		\$	1,000.00 600
To putty and spray painting on rear bumper, end panel, bootlid lower garnish, end panel, front bumper		\$	1,000.00 900
To apply rustproofing on the repaired and replaced panels.		\$	150.00 50
		\$	4,940.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.