

**VAG Singapore Pte Ltd**  
**#04-123 Enterprise Hub, 48 Toh Guan**  
**Road East**  
**608586**

**Insurer Reference:**  
**Repairer Reference: FILE 364**  
**Date calculated: 20/09/2019 1:10 PM**  
**Summary Information**

**Full Report**  
**Registration: SJY8555M**  
**Printed: 20/09/2019 1:15 PM**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN ONG	Currency:	SGD
Claim Reference:		Date of Incident:	16/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	AUDI
Model:	Q5 (8R)
Sub Model:	BASE MODEL
Model Sheet Number:	00 15 01
Registration:	SJY8555M
VIN number:	WAUZZZ8R0AA047980
Odometer:	

**Model Specs**

FROM 06/2009	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	LAUNCH ASSIST
AIR CON AUTO 3 ZONES	SS SILL MOULDING	FOG LAMPS	STORAGE PACKAGE
AUTO DIPPING MIRROR	ELEC FOLD DR MIRRORS	DIPPING DOOR MIRROR	RADIO SYST SYMPHONY
SOUND BANG/OLUFSEN	XENON HEADLAMPS	ULTRASONIC PARK SYS	HEADLAMP WASHERS
LIGHT-/RAIN SENSOR	TRIM ALCANTARA	KEYLESS ENTRY/SAFE	SPORT SEATS
RR SLIDING S/CUSHION	SPORT S-WHEEL LEATH	ELECT LUMBAR ADJUST	DRIVER INFO COLOUR
THROUGH LOAD SYSTEM	INTERIOR LAMP PACK	FRT ELECT MEM SEAT	FRONT CENTRE ARMREST
HD COOLING	2.0 LTR 155KW	S-TRONIC	DYNAMIC STEERING
SELECT DRIVE	ELECTRIC DAMPER REG	CRUISE CONTROL	TYRES 235/55 WR 19
WHEELS 8J X 19 ALLOY	SPACE SAVER S-WHEEL	QUATTRO	HANDS FREE CONV SYST
ALUMINIUM DECAL	ELEC PANORAMIC ROOF	ROOF RAILS	BASECOAT CLEAR

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495745  
'WP'  
24/9/19 @ 340 pm  
Resurvey before paint  
02 days  
Sur @ khaan.com  
taufik @ khaan.com

**VAG Singapore Pte Ltd**  
**#04-123 Enterprise Hub, 48 Toh Guan**  
**Road East**  
**608586**

**Insurer Reference:**  
**Repairer Reference: FILE 364**  
**Date calculated: 20/09/2019 1:10 PM**

**Full Report**  
**Registration: SJY8555M**  
**Printed: 20/09/2019 1:15 PM**


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 70.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R R/DOOR MIRROR MOTOR	2.0		14.00
70 59 19 00	R + R R/F DOOR TRIM INCLUDES: R + R INNER TRIM COVER	4.0		28.00
66 89 19 50	R + R RIGHT MIRROR (DOOR TRIM REMOVED)	2.0		14.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>0.80</b>	<b>8.0</b>	<b>56.00</b>
<b>Total of Labour</b>				<b>56.00</b>

## Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - BASECOAT CLEAR	WU	Price SGD
66 55 61 50	R/DOOR MIRROR COVER NEW PART PAINTING S1	2.0	14.00
57 29 79 03	RIGHT FRONT DOOR REPAIR PAINT S3	13.0	91.00
51 01 71 33	PAINTING PREPARATION WORK STAGE S3 METAL, PLASTIC S3 (PART/S FITTED)	19.0	133.00

**VAG Singapore Pte Ltd**  
**#04-123 Enterprise Hub, 48 Toh Guan**  
**Road East**  
**608586**

**Insurer Reference:**  
**Repairer Reference: FILE 364**  
**Date calculated: 20/09/2019 1:10 PM**  
 Paint Work

**Full Report**  
**Registration: SJY8555M**  
**Printed: 20/09/2019 1:15 PM**  
 Time Basis 10 WU/h

**Code**                      **Description - BASECOAT CLEAR**                      **WU**    **Price SGD**

**Total Paint**                      **Hrs**    **WU**    **Price SGD**  
    3.40    34.0    238.00

**Material Cost - Paint**                      **Price SGD**  
**Total**    350.00

### Spare Parts

				prices as at 2015-09-02/23
Code	Description	Part Number	Supplier	Price SGD
1738	R/DOOR MIRROR	8R2 857 410 L 01C		cut 980.00
1740	RIGHT MIRROR COVER	8R0 857 528 GRU		cut 890.00
1744	R/DOOR MIRROR GLASS	8R0 857 536 M		? 290.00
1750	R/D/MIRROR INDICATOR	4L0 949 102		cut 310.00
1762	R/DOOR MIRROR MOTOR	8T0 959 578 A		? 150.00
f: OEM Parts <b>Savings</b>				0.00
n: Non-OEM Parts <b>Subtotal</b>				2,620.00
u: Used parts <b>Addition(+ 10.00%)</b>				262.00
<b>Total</b>				<b>2,882.00</b>

**VAG Singapore Pte Ltd**  
**#04-123 Enterprise Hub, 48 Toh Guan**  
**Road East**  
**608586**

**Insurer Reference:**  
**Repairer Reference: FILE 364**  
**Date calculated: 20/09/2019 1:10 PM**

**Full Report**  
**Registration: SJY8555M**  
**Printed: 20/09/2019 1:15 PM**

### **Final Calculation**

	SGD	SGD
<b>Parts</b>	2,620.00	
Addition(+10.00%)	262.00	
<b>Total Parts</b>		<b>2,882.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 8.0 WU X 70.00 SGD/h	56.00	
<b>Total of Labour</b>		<b>56.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 34.0 WU X 70.00 SGD/h	238.00	
Material Cost	350.00	
<b>Total Paint Including Material</b>		<b>588.00</b>
<b>Repair Cost Excludes GST</b>		<b>3,526.00</b>
GST (+7.0%)		<b>246.82</b>
<b>Repair Cost Included GST</b>		<b>3,772.82</b>

### **Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

**No assessment notes entered.**