Musika A	Surveyor W	asmine Lot khu		<u>NMENT</u> (Office MSIG	r) T	ate/Time: 20.0	19 16-10 p.m
MINIMY	Estimated Cost:		<i>0</i>	Bill to:		outs Thire	
	/ \ -	TP RES / OD RES	SIEVAIINVIM 2770 Y		Insured:	SON 9	184×
		Asia Mobil	spoas		Tel;	6745381	a a
	Policy No: 24	09578/AT2		Claim No	60637	16	
	Sum Insured:			Excess			
	Make of Veh:					D.O.A. 19.9.	2019
	(Client's Record) CA / REV / I Date/Time: A.	REP. / REV 24 H 9.19 5.50pm	IRS Person Conta	cted:	V	H.O.D. Endorsen	
	Date/Time	Action/Instruction	(V) EST	mate.		-	
		SMD 27704.	- NA / INC 190	1646/13	Den	- 19/09/	2019
		STN 9284	X - NA/ IM	19016576/1	3 Det	1-19/09/	219
	23/9-	Achdring	estimat	e verised	via	enem	un

08/11/13) wef REF:	M5/4/
From: Date: Estimated Cost: OD TP I WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SMD 2 7 70 / at Workshop m/s As (a) of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh:	Veh No: SMD 2 7/0 Yr Regn: 7: 13 Type: M.Carl M.Cycle Bus Van Lorry Taxi Prime Mover Truck Trailer or A Make: Sular Impre 24 c.c 600 Colour A/C: Insured Std NI NA Sp.Reading 9828 T/Radio: Insured Std NI NA Eng/No: C/No: JF GJ3 kc CCG003900 Gen. Cong. Good Fair Poor Burnt Steering: Inarcte Jammed Leaked Burnt or Brake: Inorder Jammed Leaked Burnt or Modi: Nil S/Rim STD A/Rim or
Date: Person Contacted:	R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front R/Bal. Mm R/Bal. Mm L/Bal. D.O.A. / 9 / 9 / 9 Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or ROOK The U/C / Chassis frame / Body Structure affected due to collision.
100 and 100	10 nh apth AH long. Immorts 1/ED 0 2 DET 2019.
Date/Time, File Pass to? 1) UO TUPET: Preli. Report Date/Time, File Return to? 2) Report Format:	Days Of Repair: 4 Resurvey No. of Trip: Survey Fee: Transportation: 200 Add Fee: : Site insp (\$) \$+R\$,\$I
, Lump Sym / I.B.I: (\$ 3600 L)	: Weekend (\$): TOTAL 211

Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Jasmine Lok Kheng Kwei

Date:

01 Oct 2019

Preliminary Advice

Insured Vehicle No

: SJN9284X

TP Vehicle No : SMD2770Y

Accident Date

: 19/09/2019

Make

: SUBARU IMPREZA

Assignment Date

: 20/09/2019

Date of Inspection : 20/03/2019

Est. Duration of Repair

: 4 DAYS

Inspection At

: ASIA MOTORSPORTS

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,365.96
Revised Amount	:S\$	4,510.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,510.16
Lump Sum Repair	:S\$	3,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

) The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	19 Sep 2019		20 Sep 2019 16:10 Assign				New Ass	
	Main	Re	ference	Cla	nim Details	Docum	nents	Show All
CLAIM S	UBFOLDER DET	TAILS			100	[0	reated by in	surer]
Insured:		NG CH	IN CHEW, ID: S	7907181A		10.700	NOTICE CONTRACTOR AND ADDRESS.	
Main Clair	mant:	STARI	O EXPRESS SERV	/ICES, Co.	Reg. No.: 53077272L			
Vehicle Re	eg. No.:	SMD	2770Y	D	ate of Loss:	[7	/09/2019 07: 4 Months and g Date (Man)	17 Days From LTA
Claim Typ	e;	ТР		P	olicy/Cover Note No.:	Co	095781AT2 (0 verage: 12/10 /10/2019	Comprehensive) 0/2018 -
Vehicle Re	eg. No. (Insured)	: SJN92	84X	P	olicy No. (Claimant):		,10,2015	
	,				xcess:			
Repairer:		Asia M	otorsports Solut	ion Pte Ltd (HQ) 37A Everitt, 428	586 Joo Chiat - T	el:	
Handling 1	Insurer:		Insurance (Sing: 6594 2550]	apore) Pte. L	td. (HQ) - Tel: +65 6	827 7888 [Ha	andled by Jas	mine Lok Kheng
Adjuster:					- Tel: 6256-3561	Imm.Advice	due 21/09	/2019]
Oriver/Cu	stodian (Insured)		IN CHEW (), NR					
Adj Asg. F	Remarks:	on WP. 3811.	Liab: clear, Agree	on SJE. Assig	n: Marcus Chua from	LKK Auto Consu	itants Pte Ltd.	Contact: 6745
ASSOCIA	ATED MAIL REC	EIVED				View	All Cor	npose Case Mail
There are	no mail for this o	case.						
E ALL ASS	OCIATED TASK	(S			View All Sear	ch Tasks C	Create New Tas	sk Complete

View Sent Message

This mail is associated with:

*SMD2770Y (606376) [SJN9284X]

TP STARIO EXPRESS SERVICES Sep 19 2019 8:00AM [NG CHIN CHEW] Asia Motorsports Solution Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/09/2019 17:38 PM.

Subject

jasmine_lok@sg.msig-asia.com SMD2770Y (606376) [SJN9284X]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMD 2770Y on 20/09/2019 We are pending estimate from repairer.

Best Regards, Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.



Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Impreza Singapore, used Impreza Singapore, used Impreza Singapore or even buy used Impreza Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Turner	Business
Owner ID Type:	
Owner ID:	272L
Vehicle Details	SMD2770Y
Vehicle No.:	
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2019
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 4D 1.6I-S AWD CVT
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	FB16R337916
Chassis No.:	JF1GJ3KC5CG003900
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$15,888.00
Original Registration Date:	02 Jul 2013
First Registration Date:	02 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$15,888.00 79 44
Intended PARF Rebate Details	7/2 VA 102 14W
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2023
PARF Rebate Amount:	\$10,327.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$69,903.00
COE Rebate Amount:	\$26,426.00
Total Rebate Amount:	\$36,753.00

The information contained herein is correct as at 20 Sep 2019

OK

MNA119124312 / National Assessment Centre Services - Ubi ENTRY DATE & TIME: 19/09/2019 15:27 SUBMITTED BY: Roslinda Birtte Abdul Wahab

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

alulesalu,		
	ACCIDENT STATEMENT	1
Date Of Report	19/09/2019 15:27	
Date Of Accident	19/09/2019 07:55	
Exact Location Of Accident	KJE TWDS PIONEER RD	
Country/State of Loss	SINGAPORE	
(a)	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMD2770Y	

Insured/Policyholder

STARIO EXPRESS SERVICES Name Of Registered Owner

Co Reg No 53077272L NOEMAIL **Email Address**

Mobile Phone No

OFFICE-88083182 Alternative Phone No

Vehicle Particulars

Manufacturer SUBARU **IMPREZA** Model

Exact Purpose for which vehicle was being used at PRIVATE USE time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5103577596

Cover Note Number

Driver

TAY GENEVIEVE Name of Driver

NRIC No S9903186G Date Of Birth 04/02/1999 Occupation INDOOR Date Of Driving Pass 26/10/2017

1 YEAR AND 10 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-97319689 Mobile Number

Fax Number

792430 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

2

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG KJE TWDS PIONEER RD EXTREME RIGHT LANE OF A5-LANES RD.INFRT OF MY VEH SLOWED DOWN AND I FOLLOWED SUIT, SUDDENLY VEH(B) BEARING REG NO SJN9284X CAME FROM BEHIND AND HIT ONTO MY REAR PORTION OF MY VEH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

VES

Remarks/ Reasons:

NOT WORKING

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJN9284X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG CHIN CHEW

NRIC/Passport Number

S7907181A

Contact Number

93868480

Address

Postcode

Insurance Company Name

Nature Of Damage

DETAILS OF INJURED PERSON 1

Name

TAY GENEVIEVE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

WHIPLASH

SMD2770Y

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

- Piease report correctly the details of the accident to speed up the claims process
- 2 The form must be completed by the Policyholder and/or the Authorised Driver
- 3 information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation
- 5 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- ic) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Holognolder's Signature Cute & Time Oriver's signature

(if driver is not the policyholder)

Date & Time

Syw 19/04/cq Reporting Centre Personnel's Signature

NRIC/FIN No.

SKETCH PLAN

AS PER ATTACHED

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ols repre do the	e attached statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time

Driver's Senature (If driver is not the policyholder)

Date & Time

Type 19/05/19
Report Netentre Personnel's Signature

Name

NRIC/FIN NO

19/9/2019 0756AM SMD 2770Y 动机块697319689 车主好88083182。



ASIA MOTORSPORTS SOLUTION PTE LTD

5 Jalan Masjid, #01-14, (Kembangan Court), Singapore 418924 H/P: 9622 0160 (SG Loo) // Tel: 6745 3811 // Fax: 6746 5110

Email: asiamotorsports@hotmail.com

Vehicle number: S	MD2770Y
-------------------	---------

Vehicle Made & Model: SUBARU IMPREZA

Qty	List Items	Amount \$
1	Rear boot lid	PD/Sey 657.40
1	Rear boot logo \$2.00	M 110.60
1	Rear boot emblem "SUBARU"	m 68.20
1	Rear boot emblem "IMPREZA"	M 68.20/
1	Rear boot emblem "AWD"	M 58.60 /
1	Rear boot inner lock /99.50	1m 280.30
1	Rear boot inner trim	12 241.60 X
10	Rear boot inner trim clips @ 4.50	45.00 A
1	Rear boot w/strip	7~1 131.20
2	Rear boot hinges - L/R @ 89.90	179.80 X
1	Rear boot outer garnish	12.60 X
2	Rear boot licence lamps @ 58.80	17 117.60 X
1	Rear boot reverse camera	17 680.60 X
1	Rear boot lock striker	11 89.95 X
1	Rear bumper 698.20	00/0e 721.60_
1	Rear bumper tow hook cover	11 42.20 X
2	Rear bumper side brackets - L/R @ 68.60	11 137.20 ×
1	Rear bumper reinforcement 3/3-20	Ser 466.10
2	Rear bumper side retainers @ 81.50	17 163.00 X
10	Rear bumper clips @ 4.50	per 45.00
1	Rear end panel	But/ty 487.50
1	Rear end panel trim	カ つ 160.90×
1	Rear exhaust silencer	∧n 896.80 X
2	Rear exhaust mountings @ 42.20	1 1 84.40 X
1	Rear fender - RH	17 1,090.302
2	Rear fender inner trims - L/R @ 321.60	643.20 🔾
10	Rear fender inner trim clips @ 4.50	11 45.00X
1	Rear floor board	11 280.70 →
1	Rear floor sponge tray	11 230.60 ★
1	Rear floor panel	R 781.60 X
1	Rear smart keyless antenna	11 191.60 X

Vehicle number: SMD2770Y

Vehicle Made & Model: SUBARU IMPREZA

Less 20% 2,118.99 Total List 8,475.96

Special Nett Items

1 set Rear reverse sensor 1 set Rear no. plate with holder 280.00 200 60.00 X Total Special Nett 340.00

Labour charges

50.00 30 To check rear electrical wiring 80.00 50 To remove, refix reverse sensor/camera 150.00 RO To remove, refix rear interior trim to assist repair 11 120.00 X To remove, refix rear exhaust systems 150.0050 To respray undercoating 1,400.00 900 To respray painting and etc 1,600.00 600 Panel beating, cut, weld remove & replacing above parts **Total Labour** 3,550.00

> 202 202 2600-16 4510-10 3108

ESTIMATE PARTS AND LABOUR GRAND TOTALS \$ ints hence 12,365.96

he Repairer of the following:

and a very below effer spray painting

- I. do ., damaged part(s) during resurvey
- 4 Par surces are subject to confirmation
- a "The Larvey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer

Onle

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19016680/UTF3N2

Date:

03/10/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29095781AT2

Claimant

SMD2770Y

Insured Vehicle No:

SJN9284X

Vehicle No: Date of Loss:

19/09/2019

Nature of Claim:

TP

Claim No: 606376

JF1GJ3KC5CG003900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMD2770Y

Make & Model:

SUBARU IMPREZA, 1.5 (A) 02/07/2013 (Man. Year: 2012) Engine No: Chassis No: Odometer:

FB16R337916

99828 km

Reg. Date: Colour:

Black

1600 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side:

Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 8,815.96 0.00	Adjuster's 2,800.16 0.00	6,015.80 0.00	Diff % 68.24
Labour Paintwork Labour Towing	3,550.00 0.00 0.00	1,710.00 0.00 0.00	1,840.00 0.00 0.00	51.83
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	12,365.96	4,510.16 3,600.00	7,855.80	63.53
Nett Amount (S\$)	12,365.96	3,600.00	8,765.96	70.89

INSPECTION

Date of Assignment:

20/09/2019

Date Inspected:

20/09/2019 Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)

37A Everitt

Singapore 428586

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2019)

Parts: 143 SUBARU IMPREZA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD2770Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

*REAR BOOT LID *REAR BOOT LOGO *REAR BOOT EMBLEM SUBARU *REAR BOOT EMBLEM IMPREZA *REAR BOOT EMBLEM AWD *REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT LICENCE LAMPS *REAR BOOT LOCK STRIKER *REAR BOOT LOCK STRIKER	Dented/Bent Necessary Necessary Necessary Necessary Twisted Not Necessary Not Necessary Twisted Not Necessary	657.40 FL 110.60 FL 68.20 FL 68.20 FL 58.60 FL 280.30 FL 241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL	*657.40 FL *82.00 FL *68.20 FL *58.60 FL *199.50 FL *-FL *131.20 FL *-FL
*REAR BOOT LOGO *REAR BOOT EMBLEM SUBARU *REAR BOOT EMBLEM IMPREZA *REAR BOOT EMBLEM AWD *REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Necessary Necessary Necessary Twisted Not Necessary Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary Not Necessary Not Necessary	68.20 FL 68.20 FL 58.60 FL 280.30 FL 241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*68.20 FL *68.20 FL *58.60 FL *199.50 FL *-FL *131.20 FL *-FL *-FL
*REAR BOOT EMBLEM SUBARU *REAR BOOT EMBLEM IMPREZA *REAR BOOT EMBLEM AWD *REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Necessary Necessary Twisted Not Necessary Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary Not Necessary	68.20 FL 58.60 FL 280.30 FL 241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*68.20 FL *58.60 FL *199.50 FL *-FL *131.20 FL *-FL *-FL
*REAR BOOT EMBLEM IMPREZA *REAR BOOT EMBLEM AWD *REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Necessary Necessary Twisted Not Necessary Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary Not Necessary	58.60 FL 280.30 FL 241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*58.60 FL *199.50 FL *-FL *-FL *131.20 FL *-FL
*REAR BOOT EMBLEM AWD *REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Twisted Not Necessary Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary	280.30 FL 241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*199.50 FL *-FL *-131.20 FL *-FL *-FL
*REAR BOOT INNER LOCK *REAR BOOT INNER TRIM *REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary	241.60 FL 45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*-FL *-FL *131.20 FL *-FL *-FL
*REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary Twisted Not Necessary Not Necessary Not Necessary Not Necessary	45.00 FL 131.20 FL 179.80 FL 142.60 FL 117.60 FL	*-FL *131.20 FL *-FL *-FL
*REAR BOOT INNER TRIM CLIPS *REAR BOOT W/STRIP *REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Twisted Not Necessary Not Necessary Not Necessary Not Necessary	131.20 FL 179.80 FL 142.60 FL 117.60 FL	*131.20 FL *- FL *- FL
*REAR BOOT HINGES-L/R *REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary Not Necessary Not Necessary Not Necessary	179.80 FL 142.60 FL 117.60 FL	*-FL *-FL
*REAR BOOT OUTER GARNISH *REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary Not Necessary Not Necessary	142.60 FL 117.60 FL	*-FL
*REAR BOOT LICENCE LAMPS *REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary Not Necessary	117.60 FL	
*REAR BOOT REVERSE CAMERA *REAR BOOT LOCK STRIKER *REAR BUMPER	Not Necessary		
*REAR BOOT LOCK STRIKER *REAR BUMPER	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	000 00 51	*-FL
*REAR BUMPER	Not Necessary	680.60 FL	*-FL
	110111000000019	89.95 FL	*-FL
	Dented/Deformed	721.60 FL	*698.20 FL
*REAR BUMPER TOW HOOK COVER	Not Necessary	42.20 FL	*-FL
*REAR BUMPER SIDE BRACKETS-L/R	Not Necessary	137.20 FL	*-FL
*REAR BUMPER REINFORCEMENT	Bent	466.10 FL	*313.20 FL
*REAR BUMPER SIDE RETAINERS	Not Necessary	163.00 FL	*-FL
*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
*REAR END PANEL	Bent/Twisted	487.50 FL	*487.50 FL
*REAR END PANEL TRIM	Not Necessary	160.90 FL	*-FL
*REAR EXHAUST SILENCER	Not Necessary	896.80 FL	*-FL
*REAR EXHAUST MOUNTINGS	Not Necessary	84.40 FL	*-FL
*REAR FENDER-RH	Not Necessary	1,090.30 FL	*-FL
*REAR FENDER INNER TRIMS-L/R	Not Necessary	643.20 FL	*-FL
*REAR FENDER INNER TRIM CLIPS	Not Necessary	45.00 FL	*-FL
*REAR FLOOR BOARD	Not Necessary	280.70 FL	*-FL
*REAR FLOOR SPONGE TRAY	Not Necessary	230.60 FL	*-FL
*REAR FLOOR PANEL	Repair	781.60 FL	*-FL
*REAR SMART KEYLESS ANTENNA	Not Necessary	191.60 FL	*-FL
*REAR TAILLAMPS-L/R	O/s Cracked	882.40 FL	*441.20 FL
*REAR TAILLAMP PANELS-L/R	Not Necessary		*-Fl
	Shorted		*200.00 FS
*SET REAR NO PLATE WITH HOLDER	Not Necessary	60.00 FS	*-F8
part, S=SpcNett, L=ListItemDisc.		- Consideration -	w.s
	Sub Total (S\$)	10,934.95	3,450.20
- List Item Discount on L	Items 20.00/20.00% (S\$)	2,118.99	650.04
	Total Parts (S\$)	8,815.96	2,800.16
par	*REAR TAILLAMP PANELS-L/R *SET REAR REVERSE SENSOR *SET REAR NO PLATE WITH HOLDER t. S=SpcNett. L=ListItemDisc List Item Discount on L	*REAR TAILLAMP PANELS-L/R *SET REAR REVERSE SENSOR *SET REAR NO PLATE WITH HOLDER *SET REAR NO PLATE WITH HOLDER *SET REAR NO PLATE WITH HOLDER *SUB Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	*REAR TAILLAMP PANELS-L/R Not Necessary 373.20 FL *SET REAR REVERSE SENSOR Shorted 280.00 FS *SET REAR NO PLATE WITH HOLDER Not Necessary 60.00 FS t. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 10,934.95 2,118.99 Total Parts (\$\$) 8,815.96

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE, REFIX REVERSE SENSOR/CAMERA	New	80.00	50.00
3	TO REMOVE, REFIX REAR INTERIOR TRIM TO ASSIST REPAIR	New	150.00	80.00
4	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	120.00	0.00
5	TO RESPRAY UNDERCOATING	New	150.00	50.00
6	TO RESPRAY PAINTING AND ETC	New	1,400.00	900.00
7	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,600.00	600.00
	Gross Labour Cost (S\$)		3,550.00	1,710.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >