



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18006165/K1jb3q2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 23-10-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SDN 58M	Veh. Inspected SHB 8769H
	Policy No.	8-V0016622-MVA	Coverage (\$) 0.00
	Claim No.	VC011171	Excess (\$) 0.00
	Assign From		Assign Date 03/04/2018
2. Vehicle Particulars & Condition			
	Make & Model	KIA OPTIMA	c.c 1685
	Engine No.	HIDDEN	Year of Reg. 2014
	Chassis No.	KNAGM414ME5453464	Colour SILVER
	Odometer	545921	Steering IN ORDER
	Brakes	IN ORDER	Modification STANDARD ALLOY RIM
	General	FAIR	
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	205/65 R16	HANKOOK
	L/H Front Tyre	205/65 R16	HANKOOK
	R/H Rear Tyre	205/65 R16	HANKOOK
	L/H Rear Tyre	205/65 R16	HANKOOK
			Balance
			7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	07/02/2018	Inspection Date 03/04/2018
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8769H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER N/S FOG LAMP COVER	SERVICEABLE	66.00	-
1	FRONT BUMPER N/S PROTECTOR	TO REPAIR SEE LABOUR	51.00	-
	LESS 10% DISCOUNT		-64.80	-
			583.20	-
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			133.00	-
LABOUR				
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER N/S PROTECTOR.		500.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,BONNET GRILLE.		400.00	180.00
			900.00	380.00
GRAND TOTAL			1,616.20	380.00
RECOMMENDED COST OF REPAIRS				380.00

Report Ref No. CC3/QBE18006165/K1jb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8769H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8769H

RE-INSPECTION

