

CS3/LPC18021327/ESD3^{SV}-1

2820

12/01/2008

ASS. REC. BY:

REF: CS3/LPC18021327/SS03 Special Instruction:

Surveyor: Nwe Jle

ASSIGNMENT (Office)

19/9/2019

From (Person): Ong H Liof JPCDate/Time: 26/11/18 3:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 6365M

Insured:

SJF 3505R

at Workshop m/s

My Car Consultant

Tel:

8866 8832

of

53 puyen ubi ind. park #01-33

Policy No:

Claim No:

18/18/18/VPO5/021144

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/11/18

(Client's Record)

27/11/18

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS ^{1up}Date/Time: 3:51pm @ 26/11/18

Person Contacted:

Hw Sin

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SMC 6365M - X

SJF 3505R - NA / LPC18021150/24

D.O.A. 21/11/18

Submit L/S \$ 3,800/- @ 6 days

(\$ 1,920.00 Red - 25%)

RECEIVED 26 SEP 2019

- 1x0 Bill

- By email
First

25/9/2019

1pc

ASSIGNMENT


Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 19 September 2019 5:13 PM
To: Admin-D (LKKAuto); assignments
Cc: MT_Claim_SG; SUR
Subject: RE: YOUR REF: AP/2018/000408 OUR REF: 18/18/18/VP05/021144 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 21 NOVEMBER 2018 AT ABOUT 19:20HRS INVOLVING MOTOR VEHICLES NO(S). SMC6365M, SJF3505R AND SLQ5361T ALONG YIO CHU KANG ROAD
Attachments: 21144 TP SR1.pdf

Dear Nivitha

Attached is the TP survey report (part 1). Please conduct paper survey.

Thanks,
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 26 November 2018 3:53 PM
To: ONG LI LI; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: YOUR REF: AP/2018/000408 OUR REF: 18/18/18/VP05/021144 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 21 NOVEMBER 2018 AT ABOUT 19:20HRS INVOLVING MOTOR VEHICLES NO(S). SMC6365M, SJF3505R AND SLQ5361T ALONG YIO CHU KANG ROAD

Dear Li Li,

Thank you for the assignment.

Please be informed, repairer agreed survey on 27/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 16:49
Date Of Accident	21/11/2018 19:20
Exact Location Of Accident	YIO CHU KANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC6365M
Insured/Policyholder	
Name Of Registered Owner	LAI POK KHIN STEPHEN
NRIC No	S1728164Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83399118
Alternative Phone No	OTHERS-83399118
Vehicle Particulars	
Manufacturer	LEXUS
Model	NX300H-2.5 E LUXURY (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2142940
Cover Note Number	

Driver

Name of Driver	LAI POK KHIN STEPHEN
NRIC No	S1728164Z
Date Of Birth	06/03/1965
Occupation	INDOOR
Date Of Driving Pass	31/03/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83399118
Fax Number	
Contact Number	OTHERS-83399118
Email Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LAI POK KHIN STEPHEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SMC6365M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

1. When report is accepted, details of the accident to occur on the first occasion.
2. The report must be completed by the Policyholder in the presence of the Insurer's Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may constitute a breach of policy terms leading to repudiate policy liability.
4. The Insurer and signatories of this form by stamping company's seal on the reverse of policy will sign as a part of the insurance contract.
5. Available report may also be referred to the Police for investigation.
6. The report will be submitted by the Insurer to the Motor Vehicle Manager and Motor Insurance for the purpose of insurance administration or Singapore's IVA for displaying of the report will be available for viewing upon application by interested parties.
7. By the signature of this report to the Insurer, you hereby consent to the collecting, storing, results of the report and to release of the report being made available where said.
8. Consent under the Personal Data Protection Act (PDPA):
9. I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided to me or processed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicles involved in the accident (all Insurer(s) who have "Insurer Vehicle(s)" involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external cover of envelopes/track packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes";
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be stored/disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(Driver is not the policyholder)
Date & Time:

Insuring Company's Representative Signature
Name:
NRIC/ID No.:

Sketch Plan #2



DATE: 15/11
 SJF 3565 R
 2025.17



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle "A" was travelling in the right lane and was behind vehicle "B".
 Suddenly, vehicle "B" moved forward from the rear lane to move into the right lane.
 When I realised that vehicle "B" had moved into the right lane, I pulled out of my
 vehicle "A" and then we both moved forward.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the
 stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 ACC/EN No:



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 9508 Email: pasvos@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0671118

Date of Report : 21/08/2019

To : Mr Lai Pok Khin Stephen
C/o. 53 Ubi Avenue 1 #01-33
Paya Ubi Industrial Park
Singapore 408934

Date of Assignment : 22/11/2018
Report requested by : Mr Lai Pok Khin Stephen
Date of Accident : 21/11/2018
Date of Inspection : 22/11/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SMC6365M
Make & Model : Lexus NX300h (Hybrid)
Date of Registration : 27/06/2018
Colour : Pearl White

Engine Capacity (cc) : 2494cc
Mileage (km) : 3464km
Chassis / Frame No. : JTJBIRBZ202091408
Engine No. : 2AR1936083

TYRE CONDITION

Front LH : 8 mm
Make : Bridgestone

Front RH : 8 mm
Make : Bridgestone

Rear LH : 8 mm
Make : Bridgestone

Rear RH : 8 mm
Make : Bridgestone

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. My Car Consultant Pte Ltd
53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate : \$ 10,263.94
Revised Amount : \$ 9,082.58
Less Excess : \$ -
Recommended Reserve : \$ 7,720.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SMC6365M

Report No. : PAS/TP/0671118

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. My Car Consultant Pte Ltd, 53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear RH portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, RH chassis member, rear fenders, rear exhaust silencer, RH taillamp, RH reflector, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$9,082.58.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,720.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(528890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SMC6365M

Report No. : PAS/TP/0671118

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Taillamp RH	Cracked	\$ 701.60	\$ 701.60 /
2	1 pc	Rr bumper	Dented	\$ 1,051.00	\$ 1,051.00 /
3	1 pc	Rr bumper lower cover	Dented	\$ 794.20	\$ 794.20 /
4	1/2 pcs	Rr ultrasonic sensor RH	Dented/Damaged	\$ 392.80	\$ 785.60 392.80 /
5	1/2 pcs	Rr ultrasonic sensor retainer R/L	Cracked	\$ 16.20	\$ 32.40 16.20 /
6	1 pc	Rr ultrasonic sensor wire	Torn	\$ 263.70	\$ 263.70 /
7	1 pc	Rr bumper reflector RH	Broken	\$ 48.10	\$ 48.10 /
8	1 pc	Rr bumper side chrome trim RH	Broken/Dislodged/Mission	\$ 132.40	\$ 132.40 /
9	1 pc	Rr bumper side grille trim RH	Broken/Dislodged/Mission	\$ 97.50	\$ 97.50 /
10	1 pc	Rr bumper under cover	Cracked/Deformed	\$ 247.60	\$ 247.60 /
11	8 pcs	Rr bumper clip	Cracked/Necessary	\$ 3.40	\$ 27.20
12	2 pcs	Rr bumper retainer R/L	Cracked/Necessary	\$ 90.80	\$ 181.60 90.80 x 2
13	1 pc	Rr bumper reinforcement	Dented	\$ 810.40	\$ 810.40 598
14	1 pc	Rr bumper arm RH	Dented	\$ 145.80	\$ 145.80 80
15	1 pc	Rr end panel	Dented/Distorted	\$ 965.00	\$ 965.00 x R 2
16	1 pc	Rr end panel garnish	Refit	\$ 590.40	\$ -
17	1 pc	Rr fender arch moulding RH	Cracked	\$ 132.00	\$ 132.00 /
18	5 pcs	Rr fender arch moulding clip RH	Necessary	\$ 2.80	\$ 14.00 /
19	1 pc	Rr exhaust silencer	Dented/Bent	\$ 808.70	\$ 808.70 /
20	1 pc	Tailgate emblem (Logo)	Necessary	\$ 57.30	\$ 57.30 x Svc
21	1 pc	Tailgate emblem (LEXUS)	Necessary	\$ 64.80	\$ 64.80 x Svc
22	1 pc	Tailgate emblem (NX300h)	Necessary	\$ 75.30	\$ 75.30 x Svc
23	1 pc	Tailgate	Dented/Repair		(Refer labour no. 5 & 6)
24	1 pc	Rr fender RH	Dented/Repair		(Refer labour no. 2, 5 & 6)
25	1 pc	Rr floor panel	Dented/Repair		(Refer labour no. 2, 5 & 6)
26	1 pc	Rr chassis member RH	Dented/Repair		(Refer labour no. 2, 5 & 6)
				\$ 8,026.60	\$ 7,436.20
Less Discount : 10%				\$ 802.66	10% \$ 743.62
List Parts Sub-Total :				\$ 7,223.94	\$ 6,692.58
1	1 pc	Rr end panel sealant	Necessary	\$ 50.00	\$ 40.00 x 2
Special Nett Sub-Total :				\$ 50.00	\$ 40.00
Parts Total :				\$ 7,273.94	\$ 6,732.58



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SMC6365M

Report No. : PAS/TP/0671118

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 30
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00 50
3	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$ 120.00	\$ 80.00 /
4	To remove, replace and/or transfer rear reverse sensors & reset control unit.	\$ 180.00	\$ 160.00 30
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,200.00	\$ 880.00 600
6	To spray painting (Pearl), blending on affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 500
7	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 60.00 30
Labour Total :		\$ 2,990.00	\$ 2,350.00
Total (Parts & Labour) :		\$ 10,263.94	\$ 9,082.58

1320

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 7,720.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 8 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

84 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

P- 5896.44

NI- 40

L- 1320

7256.44

L/S- 5805.15

= 5800

6 repair days

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18021327/Esd3s2-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 01-10-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 3505R	Veh. Inspected	SMC 6365M
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021144	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	19/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTJBJRBZ202091408	Colour	WHITE
Odometer	3468	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2018	Inspection Date	27/11/2018
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 6365M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLAMP RH	CRACKED	701.60	701.60
1	RR BUMPER	DENTED	1,051.00	1,051.00
1	RR BUMPER LOWER COVER	DENTED	794.20	794.20
2	RR ULTRASONIC SENSOR RH @ \$392.80	DENTED / DAMAGED 1PC ONLY	785.60	392.80
2	RR ULTRASONIC SENSOR RETAINER R/L @ \$16.20	CRACKED 1PC ONLY	32.40	16.20
1	RR ULTRASONIC SENSOR WIRE	TORN	263.70	263.70
1	RR BUMPER REFLECTOR RH	BROKEN	48.10	48.10
1	RR BUMPER SIDE CHROME TRIM RH	BROKEN / DISLODGE	132.40	132.40
1	RR BUMPER SIDE GRILLE TRIM RH	BROKEN / DISLODGE	97.50	97.50
1	RR BUMPER UNDER COVER	CRACKED / DEFORMED	247.60	247.60
8	RR BUMPER CLIP @ \$3.40	CRACKED / NECESSARY	27.20	27.20
2	RR BUMPER RETAINER R/L @ \$90.80	CRACKED / NECESSARY	181.60	181.60
1	RR BUMPER REINFORCEMENT	DENTED	810.40	598.00
1	RR BUMPER ARM RH	DENTED	145.80	80.00
1	RR END PANEL	DENTED / DISTORTED	965.00	965.00
1	RR END PANEL GARNISH	REFIT	590.40	-
1	RR FENDER ARCH MOULDING RH	CRACKED	132.00	132.00
5	RR FENDER ARCH MOULDING CLIP RH @ \$2.80	NECESSARY	14.00	14.00
1	RR EXHAUST SILENCER	DENTED / BENT	808.70	808.70
1	TAILGATE EMBLEM (LOGO)	SERVICEABLE	57.30	-
1	TAILGATE EMBLEM (LEXUS)	SERVICEABLE	64.80	-
1	TAILGATE EMBLEM (NX300H)	SERVICEABLE	75.30	-
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR CHASSIS MEMBER RH (NPA)	TO REPAIR SEE LA	-	-

Report Ref No. CS3/LPC18021327/Esds2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-802.66	-655.16
			7,223.94	5,896.44
	<u>SPECIAL NETT ITEMS</u>			
1	RR END PANEL SEALANT (SN)	NECESSARY	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		60.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		150.00	50.00
	TO STRAIGHTEN, REPAIR, REALIGN CENTER EXHAUST PIPE AND REPLACE EXHAUST SILENCER.		120.00	80.00
	TO REMOVE, REPLACE AND / OR TRANSFER REAR REVERSE SENSOR & RESET CONTROL UNIT.		180.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR END PANEL, TAILGATE, RR FENDER RH, RR FLOOR PANEL AND RR CHASSIS MEMBER RH.		1,200.00	600.00
	TO SPRAY PAINTING (PEARL), BLENDING ON AFFECTED AND ADJACENT AREA.		1,200.00	500.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		80.00	30.00
			2,990.00	1,320.00
	GRAND TOTAL		10,263.94	7,256.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CS3/LPC18021327/Esd3s2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.