

ASS. REC. BY:

REF: CS/MSG 19016710/US f3 n2

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Zheng Han Yang of MSIG Date/Time: 20/09/2019

Merimen

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBG 6513L Insured: SLP 823Rat Workshop m/s Think one Autocare Tel: 91938472of No 18 Defu Ave 2Policy No: 29114756MKF

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 18/09/2019

"wp"

23.9.2019 2pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 20/09/2019 @ 05:45pm Person Contacted: Michell Ng Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 823R : X
	GBG 6513L : X
<u>24/09/19</u>	<u>@ 17:46 pm</u> <u>revised RA to Zheng Han Yang v'g</u> <u>Merimen</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

M5161

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

CA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

609m

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G86 65136

Yr Regn:

9.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Toyota Dyna

c.c

2982

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

39183

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDY/231 8028070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

165 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bearingway

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

18/9/19

D.O.I.

23/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S dt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 15742

3/10/19 confirmed final by \$804.57 with midline
(\$ 2,891.90 Red - 78%)

RECEIVED 03 OCT 2019

3/10/2019

Date/Time, File Pass to?

03/10/19

1)

Type 4

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$

) S + RS, SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format:

Lump Sum (I.B.I.) \$ 804.57 p/r

TOTAL

150
11
161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 24 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLP823R	Accident Date	: 18/09/2019
TP Vehicle No	: GBG6513L	Assignment Date	: 20/09/2019
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 2 days
Date of Inspection	: 23/09/2019		
Inspection At	: Think One Autocare (HQ) NO 18 DEFU AVENUE 2 Singapore 539522		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,750.00
Revised Amount	:S\$	804.57
Check Items (Estimated)	:S\$	0.00
Total	:S\$	804.57

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2019 14:59		20 Sep 2019 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TBA								
Vehicle Reg. No.:	GBG6513L	Date of Loss:	18/09/2019 00:00 - :59 [26 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLP823R	Policy No. (Claimant):							
		Excess:							
Repairer:	Think One Autocare (HQ) NO 18 DEFU AVENUE 2, 539522 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/09/2019]								
Adj Asg. Remarks:	on WP, Oi:Grab. Liab: NA. Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Michael Ng @ 9793 8472.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	609M
Vehicle Details	
Vehicle No.:	GBG6513L
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2682843
Chassis No.:	KDY2318028070
Maximum Power Output:	-
Open Market Value:	\$32,978.00
Original Registration Date:	27 Sep 2017
First Registration Date:	27 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,649.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,665.00
COE Rebate Amount:	\$15,742.00
Total Rebate Amount:	\$15,742.00

The information contained herein is correct as at 24 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2019 11:54
Date Of Accident	18/09/2019 16:10
Exact Location Of Accident	ALONG UPPER CROSS STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG6513L
Insured/Policyholder	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	5107728339-000109
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 D-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5107728339-000109
Cover Note Number	

Driver

Name of Driver	CHEONG KOK KEONG
NRIC No	S6911404J
Date Of Birth	05/04/1969
Occupation	OUTDOOR
Date Of Driving Pass	04/11/1994
Driving Experience	24 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98198071
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 789 CHOA CHU KANG NORTH 6 #11-226
Postcode	680789
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM KENG GUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 18.9.2019 AT ABOUT 16.10HRS I WAS DRIVING ALONG UPPER CROSS STREET HEADING TOWARDS CTE/SLE SUDDENLY VEHICLE BARING NUMBER SLP823K CUT INTO LANE AND DAMAGE DOOR LAMP.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP823R
Vehicle Make/Model/Colour	MAZDA3
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBG6513L TOYOTA DYNA KDY231-8028070

DATE 20/9/2019

No	Qty	DESCRIPTION	AMOUNT S\$
1	1	FRONT DOOR RH	1,758.00 X
2	1	FRONT DOOR LAMP RH 166.10	201.30
3	1	FRONT DOOR HINGE LOWER RH	198.00 X
			\$ 2,157.30
		LESS 25%	\$ 543.82
			\$ 1,631.47

No	Qty	DESCRIPTION	SPECAIL NETT	AMOUNT S\$
1	1	DOOR LTA STICKER		35.00 30
2	1	DOOR COMPANY STICKER		280.00 250
				\$ 315.00

LABOUR & MISCELLANEOUS:

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	800.00 200
2	To spray paint replaced/repainted body parts inclusive of preparatory works and painting materials	800.00 200
3	To transfer front door components with all necessary attachments	150.00 X
		\$ 1,750.00

3696.47

24/9/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3682.97

Not Allred

Take photo After repair

23/9/19

201.

P/P 804.57

2

166.1
25%
124.57
804.57

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016710/USF3N2

Date: 08/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756MKF
Claimant Vehicle No :	GBG6513L	Insured Vehicle No :	SLP823R
Date of Loss:	18/09/2019	Nature of Claim:	TP
		Claim No:	606481

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6513L	Engine No:	1KD2682843
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318028070
Reg. Date:	27/09/2017 (Man. Year: 2016)	Odometer:	39183 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13(D)
Front Left Side:	Bearway 7 mm	Rear Left Side:	Bearway 7/7 mm
Front Right Side:	Bearway 7 mm	Rear Right Side:	Bearway 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,932.97	404.57	1,528.40	79.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	400.00	1,350.00	77.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,682.97	804.57	2,878.40	78.15
+ GST 7.00/7.00% (S\$)	257.81	56.32	201.49	78.15
Nett Amount (S\$)	3,940.78	860.89	3,079.89	78.15

INSPECTION

Date of Assignment:	20/09/2019	Inspected At:	Think One Autocare (HQ)
Date Inspected:	23/09/2019		NO 18 DEFU AVENUE 2
			Singapore 539522

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Oct 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG6513L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,758.00 FL	*- FL
2	1		*FRONT DOOR LAMP RH	Scratched	201.30 FL	*166.10 FL
3	1		*FRONT DOOR HINGE LOWER RH	Not Necessary	198.00 FL	*- FL
4	1		*DOOR LTA STICKER	Necessary	35.00 FS	*30.00 FS
5	1		*DOOR COMPANY STICKER	Necessary	280.00 FS	*250.00 FS
					Sub Total (\$\$)	2,472.30 446.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	539.33 41.53
					Total Parts (\$\$)	1,932.97 404.57

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS/ATTACH-MENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS	New	800.00	200.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	800.00	200.00
3	TO TRANSFER FROTN DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	150.00	0.00
Gross Labour Cost (\$\$)			1,750.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >