

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :13336

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1151/2019/NS
Date	:	24-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle No : SLS 5787 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Chang Wai Yee
Address	:	1F Shelford Road #05-40 Singapore 286891
Telephone	:	HP +65 97101732
Type of Claim	:	Third Party Cliam
Policy No.	:	1800148547
Vehicle No	:	SMG 3791 P
Model Code	:	Audi A3 Sportsback 1.0 TF
Model / Year	:	Dec-18
Engine No	:	CHZ C25867
Chassis No	:	WAUZZZ8V0KA028411
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Sep-19
Place of Accident	:	Junction Of Amk Ave 6 And Amk Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3791 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	to remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	
2	To dismantle and renew rear bumper. To repair rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	500
3	To respray rear bumper and rear lid.	\$ 2,000.00	550
4	To carry out diagnostic checks.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3791 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	\$	1,708.00
2	REAR BUMPER STICKY PAD <i>X</i>	2 \$	11.00
3	REAR BUMPER FIXING PARTS <i>X</i>	\$	175.00
4	REAR BUMPER LOCKING MECHANISM - LH / RH <i>X</i>	2 \$	24.00
5	WHEEL HOUSING LINER ADAPTER - LH / RH <i>X</i>	2 \$	68.00
6	REAR BUMPER SPOILER - LH <i>su</i>	\$	216.00
7	REAR LIGHT REFLECTOR - LH / RH <i>X</i>	2 \$	54.00
8	REAR BUMPER SIDE REINFORCEMENT BEAM <i>X</i>	\$	522.00
9	REAR BUMPER BRACKET - LH / RH <i>?</i>	2 \$	51.00
10	REAR PARKING AID SENSOR - INNER / OUTER <i>X</i>	2 \$	462.00
11	REAR PARKING AID SEAL RING <i>3 ?</i>	4 \$	12.00
12	AUDI EMBLEM <i>X</i>	\$	113.00
13	A3 INSCRIPTION <i>X</i>	\$	87.00
14	PACKING ADHESIVE <i>X</i>	\$	18.00
15	REAR NO PLATE <i>X</i>	S/N \$	40.00
16	SUNDRIES <i>?</i>	\$	200.00
TOTAL SPARE PARTS		: \$	3,761.00
TOTAL LABOUR CHARGES		: \$	3,872.00
GRAND TOTAL		: \$	7,633.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasmi - Hp 90010068
Surveyed Date : 25/09/19 @ 1400
Authorised Date :
Excess Cost : 3 days
Liability :
Remarks : Reply after repair

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is subject to "No Insurance Fraud" clause
- No illegal modification (e.g. engine, suspension)
- Supplementary claim(s) must be submitted within 14 days
is subject to final approval from this company

Acknowledged by Repairer

Signature:

Date: