

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13203

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1156/2019/NS
Date : 25-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 5 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Jeoh Leo
Address : 734 Upper Changi Road East
#02-17
Singapore 486862
Telephone : HP +65 98332075
Type of Claim : Own Damage Claims
Policy No. : 2100492242-02
Vehicle No : **SFF 7183 G**
Model Code : TT Coupe 2.0 TFSI Qu
Model / Year : Nov-16
Engine No : CHH 102826
Chassis No : TRUZZZFV8G1001718
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Sep-19
Place of Accident : Still Road South From Marine Parade Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFF 7183 G

S/N	Nature of Jobs		Estimated Charges	Suveyor's Recommendations
1	To remove and transfer rhs door's multi-lock system and power window devices.	S/N	\$ 280.00	\$ 280.00
2	To dismantle and renew rhs door and rhs side member trim. Repair rhs rear fender. Reinstall all parts removed.		\$ 2,100.00	\$ 1,000.00
3	To respray rhs door, door handle, rhs side member trim and rhs rear fender.		\$ 2,800.00	\$ 1,750.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,372.00	\$ 3,222.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFF 7183 G

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT DOOR - RH	\$ 3,120.00	\$ 2,496.00
2	FRONT DOOR OUTER SEAL	NEC \$ 185.00	\$ 147.60
3	BONDING AGENT	NEC \$ 45.00	
4	CLEANING SOLUTION	NEC \$ 65.00	
5	FRONT DOOR ATTACHMENT PARTS	\$ 603.00	
6	FRONT DOOR CATCH	\$ 96.00	
7	EXTERIOR DOOR HANDLE - RH	\$ 331.00	
8	SILL PANEL TRIMS	\$ 1,006.00	\$ 804.80
9	SILL PANEL TRIM ATTACHMENT PARTS	\$ 254.00	
10	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 6,005.00	\$ 3,448.40
TOTAL LABOUR CHARGES		: \$ 5,372.00	\$ 3,222.00
GRAND TOTAL		: \$ 11,377.00	\$ 6,670.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant