

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 673G**AAD1909-126**

Not Authorised
11 Sep @ 1050h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 SEP 2019

SHF 673G

VF1ABL15AUC278768

RENAULT

LATITUDE

13.9.19

AIG

30/6/2014

PART

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	FRONT BRACE PANEL
15	1	RADIATOR GRILLE
16	1	RADIATOR GRILLE BADGE 'RENAULT'
17	1	RADIATOR GRILLE FRAME
18	1	FRAME FULL SUPPORT PANEL
19	1	FRAME FULL SUPPORT BRACKET
20	1	HEADLAMP LH
21	1	HEADLAMP RH
22	1	HEADLAMP PANEL FRT LH
23	1	HEADLAMP PANEL FRT RH
24	1	BONNET
25	1	BONNET INSULATOR
26	1	BONNET STRUT LH
27	1	BONNET STRUT RH

LIST

\$	<i>Buc 1m</i>	747.20	✓
\$	<i>SL</i>	344.70	X
\$	<i>SL</i>	394.68	X
\$	<i>SL</i>	101.40	X
\$	<i>SL</i>	10.70	X
\$	<i>DIY</i>	101.40	✓
\$	<i>SL</i>	10.70	
\$	<i>SL</i>	292.50	
\$	<i>SL</i>	147.00	
\$	<i>SL</i>	207.21	
\$	<i>SL</i>	207.21	
\$	<i>N</i>	663.70	
\$	<i>SL</i>	60.90	
\$	<i>N</i>	177.22	
\$	<i>SL</i>	969.90	
\$	<i>SL</i>	225.36	
\$	<i>SL</i>	686.00	
\$	<i>SL</i>	592.70	
\$	<i>N</i>	41.60	
\$	<i>SL</i>	743.60	
\$	<i>SL</i>	743.60	
\$	<i>N</i>	127.70	
\$	<i>N</i>	128.30	
\$	<i>N</i>	1,312.70	
\$	<i>SL</i>	294.30	
\$	<i>SL</i>	53.30	
\$	<i>SL</i>	53.30	

Trans-cab Auto Services Pte Ltd**AAD1909-126**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 673G

28	1	BONNET HINGE LH	\$	11	236.50	}	X
29	1	BONNET HINGE RH	\$	11	237.40		
30	1	BONNET CABLE COVER	\$	12	80.60		
31	1	BONNET SEAL OUTER	\$	12	83.20		
32	1	BONNET SEAL INNER	\$	12	70.10		
33	1	BONNET LOCK	\$	11	152.80		
34	1	BONNET CABLE	\$	12	55.20		
35	1	FENDER PANEL FRT LH	\$	11	414.40		
36	1	WHEELARCH FRT LH	\$	12	112.30		
37	1	FENDER BRACKET LOWER LH	\$	12	11.80		
38	1	FENDER INSULATOR LH	\$	12	65.50		
39	1	FENDER PANEL FRT RH	\$	11	437.10		
40	1	WHEELARCH FRT RH	\$	12	191.40		
41	1	FENDER BRACKET LOWER RH	\$	12	11.80		
42	1	FENDER INSULATOR RH	\$	12	66.30		
43	1	WIPER RESERVOIR	\$	12	179.60		
44	1	WIPER RESERVOIR NECK	\$	12	29.30		
45	1	WIPER RESERVOIR MOTOR	\$	12	82.60		
46	1	AIR CLEANER BOX	\$	12	464.20		
47	1	AIR CLEANER HOSE	\$	12	175.85		
48	1	AIR CLEANER LOWER	\$	12	271.26		
TOTAL			\$		12,868.09		
10%			\$		1,286.81		
			\$		11,581.28		

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	sm	14.50	
8	1	RADIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	

Trans-cab Auto Services Pte Ltd**AAD1909-126**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 673G

10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
11	1SET	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
13	1	Windscreen moulding	\$	nn	120.00	X
14	1	FRONT WINDSCREEN SEALANT	\$	nn	253.80	X
15	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
16	1	Front licence plate with holder	\$	B1	80.00	45.00
17	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
18	1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	X
19	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	X
20	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	X
21	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	X
TOTAL			\$		1,021.77	

TOTAL PARTS	\$	12,603.05
--------------------	-----------	------------------

Labour

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		4,500.00	2000
To rust-proofing of the affected areas.	\$	nn	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1909-126**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 673G

To Transfer Of Front Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 *X*

To transfer of bonnet fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X*

Putty and spray painting of the affected portion.

\$ 4,500.00 *2200*

To transfer of front bumper fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of front windscreen glass to facilitate
bodywork repair.

\$ *nn* 200.00 *X***TOTAL \$ 11,620.00****Over All Total \$ 24,223.05****(LUMP SUM) Repair Days****~~15~~ DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: