



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

19/09/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPCling
Asher

Accident date: 19/09/2019

Estimated repair cost for vehicle no: SJR5493P NISSAN MARCH 1.4 A '09

CHASSIS: JN1FBAK12Z0020070

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bumper <i>Deformed</i>		\$343.00 ✓
2	8	Front Bumper Clip <i>new</i>	\$6.80	\$54.40 30
3	1	Front Bumper Grille <i>new</i>		\$183.50 ✓
4	1	Front Bumper Reinforcement <i>Bent</i>		\$193.90 ✓
5	2	Front Head Lamp <i>Replaced</i>	\$618.30	\$1,236.60 618.30

1338.70
1204.83

Subtotal :- \$2,011.40

Labour charges

To check wiring

\$80.00 30

Tuff kote

\$100.00 *

Panel beating

430


~~\$600.00~~ 200

Spray painting

~~\$600.00~~ 200

Subtotal :- \$1,380.00

Total:- \$3,391.40



total 1634.83

L/S 1.3K

02 Days

13K