

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

KALVIN

DOI: 20/09/19

Date / Time: 20/09/19

Registered in Merimen: —

Pre-assign / CCU / FTE



Insured Vehicle No. : GBH 9918C
 Name of Insured : M/S AL-REHMAT TRADING PTE LTD
 Insured Tel No. : HP: —
 Excess Sec II :SS D.O.A: 18/09/2019 19:30
 Is driver the owner? (YES / NO) Nature of Accident : —

Claim No. : SNM19D2044440218 (chugpu)
 Policy No. : DMCVSN1837901800
 Make / Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR
 Place of Accident : ARAB ST

If NO, Driver Name / Age : ABDOLRAZAGH VOJODI GHAAHVEHCHI OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No. : +65-86248633 (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SHC 5452K



INSRS:
WSP: TRANS-CAB
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SHC 5452K - CC3/AIG13008362/Kk1t2w2; DOA:6/5/13	Non-Reporting ltr (1st):	
	GBH 9918C NA/CTI19016595/z4 ; DOA: 18/09/19	Non-Reporting ltr (2nd):	
	- MINUTED	Non-Reporting ltr (Final):	
14/10/19	- THE REVIEWED. OI REPORTED HIS	Notification ltr (if non-pickup):	
	REFUSED TO PICK UP WHEN HIT BY	Call OI:	
	TRUCK TP. SEND LETTER TO OI TO	After call ltr to OI: 14/10/19 - VIC	
	NOTIFY TP CLAIM IN NCB ISSUES.	Documentation Check List: Handler Typist	
14/10/19	- TYPE REPORT WHILE PENDING TP LOD	Notification ltr (if non-pickup)	☐
	- REPORT DONE	After call ltr to OI:	☒
	- ORIGINAL TP LOD IN	Authorisation To Act:	☒
23/02/2020	- SEEK MANDATE APPROVAL TO OI	Release Voucher:	☒
	- TP TO AWARD TAX INVOICE & LOD.	Final Repair Bill:	☒
	- OI APPROVED MANDATE	Car Rental Invoice:	☒
28/02/2020	- SEND SET OFFER TO TP	Towing Invoice	☐
02/03/2020	- TP ACCEPTED OFFER.	LTA / GIA :	☒
	- ALL DOCS IN ORDER.	Medical Bill:	☐
	- TO CLOSE	PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time: 24/09/19 Sent By: 93

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: L16	SS 4,400.00 (4 days) Reduction: 88 %		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 02/03/20	Confirm with: WAH YIN	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 2A		If NO or B 28, Ass. Lia :
Repair Cost: (w/gst)	SS 4,708.00		(OLD REJECTED TO PHEN)
Loss of Rental (LOR):	SS 581.94 (6 days) x 96.99		
Loss of Use (LOU):	SS — (\$ x days)		
Loss of Income (LOI):	SS 300.00 (\$50 x 6 days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]			
GIA/LTA Search	SS 7.49		
Medical:	SS —		
Disbursement:	SS — (e.g. Tow/ Independent)		
Legal Cost	SS —		
Total:	SS 5,597.43	Global Sum SS: —	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 5,597.43	Name 1: TRANS-CAB AUTO SERVICES PTE LTD	
Payee 2: (Strike if N.A.)	SS —	Name 2: —	
Payee 3: (Strike if N.A.)	SS —	Name 3: —	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19016751/K1ha3

Date: 24/09/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SHC 5452K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/09/2019 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	36,888.70	
Revised Estimate Amount	: S\$	4,400.00	
"Check" Items Amount	: S\$	-	
Total (Including Check Items)	: S\$	4,400.00	
Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:
The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHC5452K

Vehicle to be Exported: Yes

Intended Deregistration Date: 19 Sep 2019

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C002130

Chassis No.: VF1ABL15AUC280274

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 19 Nov 2014

First Registration Date: 19 Nov 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Nov 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 18 Nov 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$51,337.00

COE Rebate Amount: \$20,313.00

Total Rebate Amount: \$29,686.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Sep 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1909-170

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

U/s \$4400 / 40-71

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5452K

VF1ABL15AUC280274

RENAULT

LATITUDE

18.9.19

CHINA TAIPING

19/11/2014

PART		LIST	
1	DOOR PANEL FRONT RH - <i>2/2/14</i>	\$	2,844.66 -
1	DOOR GUIDE FRONT RH X <i>see</i>	\$	176.82
1	DOOR LOCK FRONT RH X <i>see</i>	\$	908.75
1	DOOR CATCH FRONT RH X <i>see</i>	\$	131.23
1	DOOR HANDLE OUTER FRONT RH - <i>in</i>	\$	477.76 -
1	DOOR HANDLE COVER FRONT RH X <i>1/4/14</i>	\$	13.22
1	DOOR HANDLE MODULE FRONT RH X <i>see</i>	\$	133.60
1	DOOR REGULATOR FRONT RH X <i>see</i>	\$	505.19
1	DOOR REGULATOR MOTOR FRONT RH X <i>see</i>	\$	796.46
1	DOOR REGULATOR GUIDE FRONT RH X <i>see</i>	\$	120.97
1	DOOR WHEATHESTRIIP FRONT RH X <i>see</i>	\$	410.27
1	DOOR SEAL FRONT RH X <i>see</i>	\$	72.82
1	DOOR WAIST SEAL OUTER FRONT RH X <i>see</i>	\$	291.27
1	DOOR GLASS RUNNER SEAL FRONT RH X <i>see</i>	\$	626.36
1	DOOR BLIND FRONT RH X <i>see</i>	\$	506.90
1	DOOR PANEL REAR RH - <i>2/2/14</i>	\$	758.70 -
1	DOOR GUIDE REAR RH X <i>see</i>	\$	176.82
1	DOOR HINGE UPPER RH X <i>see</i>	\$	241.60
1	DOOR HINGE LOWER RH X <i>see</i>	\$	169.90
1	DOOR CHECK REAR RH X <i>see</i>	\$	114.90
1	DOOR LOCK REAR RH X <i>see</i>	\$	467.30
1	DOOR CATCH REAR RH X <i>see</i>	\$	131.23
1	DOOR HANDLE OUTER REAR RH X <i>1/4/14</i>	\$	42.10
1	DOOR HANDLE COVER REAR RH X <i>1/4/14</i>	\$	57.90
1	DOOR HANDLE MODULE REAR RH X <i>see</i>	\$	111.00
1	DOOR REGULATOR REAR RH X <i>see</i>	\$	758.10
1	DOOR REGULATOR MOTOR REAR RH X <i>see</i>	\$	450.60

Trans-cab Auto Services Pte Ltd**AAD1909-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

1	DOOR REGULATOR GUIDE REAR RH	X su	\$	120.97
1	DOOR SEAL REAR RH	X su	\$	119.80
1	DOOR WHEATHESTRIIP REAR RH	X su	\$	311.60
1	ROCKER PANEL INNER GARNISH RH	X su	\$	466.51
1	ROCKER PANEL INNER RH	X su	\$	1,024.79
1	ROCKER PANEL OUTER RH	X su	\$	1,184.99
1	ROCKER PANEL CENTER RH	X su	\$	990.25
1	DOOR MIRROR ASSY RH	X su	\$	1,483.40
1	DOOR HARNESS WIRE RH	X su	\$	2,670.00
1	DOOR WAIST SEAL OUTER REAR RH	X su	\$	99.40
1	DOOR BLIND REAR RH	X su	\$	506.90
1	DOOR GLASS RUNNER SEAL REAR RH	X su	\$	116.10
1	FENDER PANEL REAR RH	X su	\$	1,933.20
1	FENDER PANEL INNER TRIM REAR RH	X su	\$	671.45
1	WHEELARCH REAR RH	X su	\$	275.40
TOTAL			\$	23,471.19
10%			\$	2,347.12
			\$	21,124.07

Special Nett

1	REAR DOOR STICKER '6555-3333'	/ su	\$	300.00
1	FRONT DOOR STICKER 'Trans-Cab'	/ su	\$	80.00
1	FRONT DOOR STICKER 'Classic'	/ su	\$	80.00
1	DOOR CHECK BOLT	X su	\$	22.69
1	DOOR GUIDE SCREW	X su	\$	10.85
1	DOOR HINGE BOLT	X su	\$	10.85
1	DOOR HINGE NUT RH	X su	\$	14.60
1	DOOR CHECK BOLT	X su	\$	22.69
1	DOOR CHECK NUT	X su	\$	3.75
1	DOOR LOCK SCREW L70Y	X su	\$	6.12
1	DOOR CATCH SCREW L70Y	X su	\$	10.06
1	REAR RIGHT TYRE	X su	\$	300.00
1	REAR RIGHT TYRE RIM	X su	\$	380.00
1	FENDER INNER TRIM CLIP RH	X su	\$	28.00
1	FENDER WHEELARCH REAR RH CLIP	X su	\$	35.00
2	REAR WINDSCREEN SEALANT	X su	\$	80.00
1	WINDSCREEN MOULDING	X su	\$	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	X su	\$	100.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

LKK Auto Consultant hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AAD1909-170

Acknowledged by Repairer	TOTAL \$	1,584.63
Signature:	TOTAL PARTS \$	22,708.70
Date:		

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00 880
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00 X 11
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	600 6,000.00
To check steering geometry and computer wheel alignment	\$	220.00 X 11
To Check Electrical Lighting Concerned.	\$	170.00 X 11
To rust-proofing of the affected areas.	\$	170.00 50
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X 11
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of tire, rim and on wheel balancing.	\$	170.00 X 11
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	180.00 X 11
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00 X 11

No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$	14,180.00
Over All Total \$	36,888.70

LUMP SUM (REPAIR DAY) 20 DAYS 68

Kahin 1CKK
20/9/19 1735L
4 Days
45
After Repair photo

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

U/s \$4400 / 4671

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5452K

VF1ABL15AUC280274

RENAULT

LATITUDE

18.9.19

CHINA TAIPING

19/11/2014

	PART		LIST
1	DOOR PANEL FRONT RH - <i>RAW</i>	\$	2,844.66
1	DOOR GUIDE FRONT RH X <i>see</i>	\$	176.82
1	DOOR LOCK FRONT RH X <i>see</i>	\$	908.75
1	DOOR CATCH FRONT RH X <i>see</i>	\$	131.23
1	DOOR HANDLE OUTER FRONT RH - <i>see</i>	\$	477.76
1	DOOR HANDLE COVER FRONT RH X <i>RAW</i>	\$	13.22
1	DOOR HANDLE MODULE FRONT RH X <i>see</i>	\$	133.60
1	DOOR REGULATOR FRONT RH X <i>see</i>	\$	505.19
1	DOOR REGULATOR MOTOR FRONT RH X <i>see</i>	\$	796.46
1	DOOR REGULATOR GUIDE FRONT RH X <i>see</i>	\$	120.97
1	DOOR WHEATHESTRIIP FRONT RH X <i>see</i>	\$	410.27
1	DOOR SEAL FRONT RH X <i>see</i>	\$	72.82
1	DOOR WAIST SEAL OUTER FRONT RH X <i>see</i>	\$	291.27
1	DOOR GLASS RUNNER SEAL FRONT RH X <i>see</i>	\$	626.36
1	DOOR BLIND FRONT RH X <i>see</i>	\$	506.90
1	DOOR PANEL REAR RH - <i>RAW</i>	\$	758.70
1	DOOR GUIDE REAR RH X <i>see</i>	\$	176.82
1	DOOR HINGE UPPER RH X <i>see</i>	\$	241.60
1	DOOR HINGE LOWER RH X <i>see</i>	\$	169.90
1	DOOR CHECK REAR RH X <i>see</i>	\$	114.90
1	DOOR LOCK REAR RH X <i>see</i>	\$	467.30
1	DOOR CATCH REAR RH X <i>see</i>	\$	131.23
1	DOOR HANDLE OUTER REAR RH X <i>RAW</i>	\$	42.10
1	DOOR HANDLE COVER REAR RH X <i>RAW</i>	\$	57.90
1	DOOR HANDLE MODULE REAR RH X <i>see</i>	\$	111.00
1	DOOR REGULATOR REAR RH X <i>see</i>	\$	758.10
1	DOOR REGULATOR MOTOR REAR RH X <i>see</i>	\$	450.60

Trans-cab Auto Services Pte Ltd**AAD1909-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

1	DOOR REGULATOR GUIDE REAR RH	X sue	\$	120.97
1	DOOR SEAL REAR RH	X sue	\$	119.80
1	DOOR WHEATHESTRIIP REAR RH	X sue	\$	311.60
1	ROCKER PANEL INNER GARNISH RH	X sue	\$	466.51
1	ROCKER PANEL INNER RH	X repl sue	\$	1,024.79
1	ROCKER PANEL OUTER RH	X repl	\$	1,184.99
1	ROCKER PANEL CENTER RH	X repl	\$	990.25
1	DOOR MIRROR ASSY RH	X sue	\$	1,483.40
1	DOOR HARNESS WIRE RH	X sue	\$	2,670.00
1	DOOR WAIST SEAL OUTER REAR RH	X sue	\$	99.40
1	DOOR BLIND REAR RH	X sue	\$	506.90
1	DOOR GLASS RUNNER SEAL REAR RH	X sue	\$	116.10
1	FENDER PANEL REAR RH	X repl	\$	1,933.20
1	FENDER PANEL INNER TRIM REAR RH	X sue	\$	671.45
1	WHEELARCH REAR RH	X sue	\$	275.40
TOTAL				\$ 23,471.19
10%				\$ 2,347.12
				\$ 21,124.07

Special Nett

1	REAR DOOR STICKER '6555-3333'	/ sue	\$	300.00 80.00
1	FRONT DOOR STICKER 'Trans-Cab'	/ sue	\$	80.00
1	FRONT DOOR STICKER 'Classic'	/ sue	\$	80.00
1	DOOR CHECK BOLT	X m	\$	22.69
1	DOOR GUIDE SCREW	X m	\$	10.85
1	DOOR HINGE BOLT	X m	\$	10.85
1	DOOR HINGE NUT RH	X m	\$	14.60
1	DOOR CHECK BOLT	X m	\$	22.69
1	DOOR CHECK NUT	X m	\$	3.75
1	DOOR LOCK SCREW L70Y	X m	\$	6.12
1	DOOR CATCH SCREW L70Y	X m	\$	10.06
1	REAR RIGHT TYRE	X sue	\$	300.00
1	REAR RIGHT TYRE RIM	X sue	\$	380.00
1	FENDER INNER TRIM CLIP RH	X m	\$	28.00
1	FENDER WHEELARCH REAR RH CLIP	X m	\$	35.00
2	REAR WINDSCREEN SEALANT	X m	\$	80.00
1	WINDSCREEN MOULDING	X m	\$	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	X m	\$	100.00

Trans-cab Auto Services Pte Ltd

AAD1909-170

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5452K

TOTAL	\$	1,584.63
TOTAL PARTS	\$	22,708.70

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00 880
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X "
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00 600
To check steering geometry and computer wheel alignment	\$	220.00 X "
To Check Electrical Lighting Concerned.	\$	170.00 X "
To rust-proofing of the affected areas.	\$	170.00 50
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X "
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of tire, rim and on wheel balancing.	\$	170.00 X "
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	180.00 X "
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00 X "

• No Work
• Supplier
is subject to
Signature:
Date:

TOTAL	\$	14,180.00
Over All Total	\$	36,888.70

LUMP SUM (REPAIR DAY)

20 DAYS

Kohli (CKK)
20/9/19 1735L
4 Rep
45
After Repair photo

Mei Kwan (LKKAUTO)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Wednesday, 25 September, 2019 11:44 AM
To: Ong Chin Kiat; Alfred Toh; Chee So Chow; Mei Kwan (LKKAUTO); Vic (LKKAUTO)
Subject: OUR REF: SNM19D204444-GBH9918C-OCK - Direct Settlement - Accident Involving GBH9918C (OI : CTI - TBA) and SHC5452K (TP : LKK REF - CC3/CTI19016751/K1ha3) on 18/09/2019
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf
Categories: HMK

Dear Chin Kiat,

Please revert LKK.

Note : officer in charge – Chin Kiat 63896174.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, September 24, 2019 5:07 PM
To: Claims Dept of CTI
Cc: CS A Team; Admin A; Vic (LKKAUTO)
Subject: Direct Settlement - Accident Involving GBH9918C (OI : CTI - TBA) and SHC5452K (TP : LKK REF - CC3/CTI19016751/K1ha3) on 18/09/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5452K at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Vic (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 5 March, 2020 1:14 PM
To: Vic (LKKAUTO)
Cc: Admin A; 'Amanda Tay'; 'claims'
Subject: FW: TCS REF: AAD1909-170--Accident involving GBH9918C(CTI) & SHC5452K on 18.09.19 // LKK Ref: CC3/CTI19016751/K1ha3
Attachments: AAD1909-170 DV.pdf; AAD1909-170 AMEND LOD+INVOICE.pdf

Without prejudice

Dear Vic

Attach duly signed DV and amended LOD + invoice for your action.

Original hard copy will pass to Kenneth's to bring back your office.

Hope to receive your payment soon.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]
Sent: Friday, 28 February, 2020 4:45 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; 'claims' <claims@transcab.com.sg>; amanda.tay@transcab.com.sg
Subject: TCS REF: AAD1909-170--Accident involving GBH9918C(CTI) & SHC5452K on 18.09.19 // LKK Ref: CC3/CTI19016751/K1ha3

Without Prejudice

Dear Wai Yin,

We refer to the subject matter and we confirmed in receipt of your LOD.

Based on our surveyor recommendation, the adjusted COR is at L/S **\$4,400.00**. Please refer to the attached marked estimate.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we are prepared to settle your client's claim as below:

Cost of Repair (w/gst) @ L/S \$4,400.00	\$ 4,708.00
Loss of Rental (\$96.99 x 6 days)	\$ 581.94
Loss of Income (\$50 x 6 days)	\$ 300.00
LTA Search Fee	\$ 7.49
TOTAL	\$ 5,597.43

If agreeable, kindly chop and sign the attached DV and **forward back to us (LKK) the original signed hard copy together with the amended LOD and Repair Invoice** for payment processing.

The above amount is to be made payable to **TRANS-CAB AUTO SERVICES PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ALPEH
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI19016751/K1ha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 13-03-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 9918C	Veh. Inspected	SHC 5452K	
Policy No.	DMCVSN1837901800	Coverage (\$)	0.00	
Claim No.	SNM19D204444C02/8	Excess (\$)	0.00	
Assign From		Assign Date	20/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280274	Colour	RED / WHITE	
Odometer	503716	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI COMFORT	7 mm	
L/H Front Tyre	215/60 R16	GITI COMFORT	7 mm	
R/H Rear Tyre	215/60 R16	GITI COMFORT	7 mm	
L/H Rear Tyre	215/60 R16	GITI COMFORT	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/09/2019	Inspection Date	20/09/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5452K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRONT RH	BUCKLED	2,844.66	2,844.66
1	DOOR GUIDE FRONT RH	SERVICEABLE	176.82	-
1	DOOR LOCK FRONT RH	SERVICEABLE	908.75	-
1	DOOR CATCH FRONT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRONT RH	CRACKED	477.76	477.76
1	DOOR HANDLE COVER FRONT RH	TO REPAIR SEE LABOUR	13.22	-
1	DOOR HANDLE MODULE FRONT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRONT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRONT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRONT RH	SERVICEABLE	120.97	-
1	DOOR WEATHERSTRIP FRONT RH	SERVICEABLE	410.27	-
1	DOOR SEAL FRONT RH	SERVICEABLE	72.82	-
1	DOOR WAIST SEAL OUTER FRONT RH	SERVICEABLE	291.27	-
1	DOOR GLASS RUNNER SEAL FRONT RH	SERVICEABLE	626.36	-
1	DOOR BLIND FRONT RH	SERVICEABLE	506.90	-
1	DOOR PANEL REAR RH	BUCKLED	758.70	758.70
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	SERVICEABLE	241.60	-
1	DOOR HINGE LOWER RH	SERVICEABLE	169.90	-
1	DOOR CHECK REAR RH	SERVICEABLE	114.90	-
1	DOOR LOCK REAR RH	SERVICEABLE	467.30	-
1	DOOR CATCH REAR RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER REAR RH	TO REPAIR SEE LABOUR	42.10	-
1	DOOR HANDLE COVER REAR RH	TO REPAIR SEE LABOUR	57.90	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	111.00	-
1	DOOR REGULATOR REAR RH	SERVICEABLE	758.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	450.60	-
1	DOOR REGULATOR GUIDE REAR RH	SERVICEABLE	120.97	-
1	DOOR SEAL REAR RH	SERVICEABLE	119.80	-

Report Ref No. CC3/CTI19016751/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	311.60	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE RH	SERVICEABLE	2,670.00	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	99.40	-
1	DOOR BLIND REAR RH	SERVICEABLE	506.90	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	116.10	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
	LESS 10% DISCOUNT		-2,347.12	-408.11
			21,124.07	3,673.01
SPECIAL NETT ITEMS				
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	300.00	80.00
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	80.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
1	REAR RIGHT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FENDER INNER TRIM CLIP RH (SN)	SERVICEABLE	28.00	-

Report Ref No. CC3/CTI19016751/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,584.61	240.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	880.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HANDLE COVER FRONT RH,DOOR HANDLE OUTER REAR RH,DOOR HANDLE COVER REAR RH,ROCKER PANEL INNER RH,ROCKER PANEL OUTER RH,ROCKER PANEL CENTER RH AND FENDER PANEL REAR RH.		6,000.00	600.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	50.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	50.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	50.00
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
			14,180.00	1,630.00
	GRAND TOTAL		36,888.68	5,543.01

Report Ref No. CC3/CTI19016751/K1ha3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,400.00
---	--	--	----------

Report Ref No. CC3/CTI19016751/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.