

Trans-cab Auto Services Pte Ltd**AAD1909-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z*US \$5600 / 15 ltr*

Vehicle No.:

SHC 5072Z

Chassis No.:

VF1ABL15AUC276166

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

19.9.19

Third Party Insurer :

EQ

Date of Registration :

2/12/2013

		PART		LIST	
1	1	BUMPER COVER REAR	— <i>Paint</i>	\$	561.70
2	1	BUMPER LOWER REAR	— <i>on</i>	\$	411.90
3	1	BUMPER BRACKET CTR REAR	<i>X see</i>	\$	98.10
4	1	BUMPER BRACKET SIDE RH REAR	<i>X see</i>	\$	82.10
5	1	BUMPER RETAINER RH REAR	<i>X see</i>	\$	59.80
6	1	BUMPER REFLECTOR RH	— <i>on</i>	\$	16.60
7	1	BUMPER BRACKET SIDE LH REAR	<i>X see</i>	\$	80.80
8	1	BUMPER RETAINER LH REAR	<i>X see</i>	\$	54.20
9	1	BUMPER REFLECTOR LH	<i>X see</i>	\$	16.60
10	1	BUMPER BEAM REAR	— <i>Beep</i>	\$	547.80
11	1	BUMPER BEAM BRACKET LH REAR	<i>X see</i>	\$	114.50
12	1	BUMPER BEAM BRACKET RH REAR	— <i>Beep</i>	\$	100.90
13	1	OUTER PANEL REAR (End Panel)	— <i>Roll</i>	\$	745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	<i>X see</i>	\$	404.56
15	1	TAILLAMP RH	— <i>on</i>	\$	313.10
16	1	TAILLAMP PANEL RH	<i>X repair</i>	\$	401.40
17	1	TAILLAMP LH	<i>X see</i>	\$	401.40
18	1	TAILLAMP PANEL LH	<i>X see</i>	\$	401.40
19	1	BOOT REAR	— <i>Roll</i>	\$	1,677.20
20	1	BOOT FINISHER	<i>X see</i>	\$	344.70
21	1	BOOT WHEATERSTRIP	<i>X — torn</i>	\$	178.20
22	1	BOOT REFLECTOR LAMP LH	<i>X see</i>	\$	277.70
23	1	BOOT REFLECTOR LAMP RH	— <i>on</i>	\$	277.70
24	1	BOOT BADGE 'RENAULT'	— <i>new</i>	\$	82.40
25	1	BOOT BADGE	— <i>new</i>	\$	95.80
26	1	BOOT STRUT LH	<i>X see</i>	\$	145.10
27	1	BOOT STRUT RH	<i>X see</i>	\$	145.10

Trans-cab Auto Services Pte Ltd**AAD1909-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

28	1	BOOT HINGE LH	X	see	\$	254.20
29	1	BOOT HINGE RH	X	see	\$	253.80
30	1	BOOT INNER TRIM BOARD	X	see	\$	611.00
31	1	BOOT SWITCH	X	see	\$	113.00
32	1	BOOT LOCK	X	see	\$	246.60
33	1	BOOT LOCK CATCH	X	see	\$	41.70
34	1	EXHAUST CAP REAR	/	see	\$	125.40
35	1	EXHAUST REAR	X	see	\$	5,263.60
36	1	FENDER PANEL REAR RH	X	see	\$	1,933.20
37	1	WHEELARCH REAR RH	X	see	\$	275.40
38	1	FENDER PANEL INNER TRIM REAR RH	X	see	\$	671.45
39	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X	see	\$	1,229.40
40	1	SPARE WHEEL PANEL TRIM	X	see	\$	612.21
TOTAL					\$	19,667.52
10%					\$	1,966.75
					\$	17,700.77

Special Nett

1	1SET PARKING AID	/	shitel	\$	700.00
2	1SET REAR BUMPER CLIP	/	see	\$	66.00
3	1SET BUMPER BRACKET CTR CLIP	X	see	\$	33.00
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X	see	\$	10.00
5	1SET BUMPER RETAINER RH CLIP RR	X	see	\$	20.00
6	1SET BUMPER BRACKET SIDE CLIP LH RR	X	see	\$	10.00
7	1SET BUMPER RETAINER CLIP LH RR	X	see	\$	20.00
8	1SET BUMPER LOWER REAR RIVET	/	see	\$	22.00
9	1SET BUMPER LOWER REAR CLIP	/	see	\$	66.00
10	1 BOOT STICKER "Trans-cab"	/	see	\$	30.00
11	1 BOOT STICKER "6555-3333"	/	see	\$	30.00
12	1 EXHAUST MOUNTING REAR	X	see	\$	16.00
13	2 REAR WINDSCREEN SEALANT	X	see	\$	80.00
14	1 WINDSCREEN MOULDING	X	see	\$	100.00
15	1 REAR WINDSCREEN INNER SPONGE SEAL	X	see	\$	100.00
16	1 BOOT INNER TRIM CLIP	X	see	\$	45.00
17	1SET BOOT FINISHER CLIP	X	see	\$	24.20
18	1 TAILLAMP CLIP LH	X	see	\$	5.00
19	1 TAILLAMP CLIP RH	/	see	\$	5.00

Trans-cab Auto Services Pte Ltd**AAD1909-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

20	1	Rear Bumper Protector	✓	all	\$	100.00 50
21	1	SET FENDER WHEELARCH REAR RH CLIP	✓	2	\$	35.00
22	1	FENDER INNER TRIM CLIP RH	✓	2	\$	28.00
23	1	REAR RIGHT TYRE	✓	5	\$	300.00
24	1	REAR RIGHT TYRE RIM	✓	5	\$	380.00
25	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	✓	5	\$	380.00
26	1	SPARE TYRE	✓	5	\$	300.00
TOTAL					\$	2,905.20
TOTAL PARTS					\$	20,605.97

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 50
To remove and refit interior fittings, trimings,	\$	380.00 1
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To Check Electrical Lighting Concerned.	\$	170.00 30
To transfer of tire, rim and on wheel balancing.	\$	170.00 1
To reinstall rear bumper parking sensor.	\$	170.00 30
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00 800
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00 1
To check steering geometry and computer wheel alignment	\$	220.00 1

Trans-cab Auto Services Pte Ltd**AAD1909-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X 1.2
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X 1.2
Putty and spray painting of the affected portion.	\$	9,000.00 660
To repair and realign rear exhaust pipe.	\$	170.00 X 1.2
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 1.2
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X 1.2
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X 1.2
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X 1.2
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X 1.2

TOTAL \$ 22,200.00**Over All Total \$ 42,805.97****LUMP SUM (REPAIR DAY)****30 DAYS**

Kahin 10/10/19

M

20/9/19 1745hrs.

5 Days

4/5

After Repair photo

I hereby acknowledge and agree to notify the insurer of the following:	
• Putty and spray painting	
• Damaged parts requiring resurvey	
• Parts and materials used in the repair	
• Third party survey on a "Without Prejudice" basis	
• No financial modification is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	