

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5933P

VF1ABL15AUC281004

RENAULT

LATITUDE

19.9.19

EQ

24/12/2014

		PART		LIST
1	1	BUMPER COVER REAR	✓	\$ 561.70
2	1	BUMPER LOWER REAR	✓	\$ 411.90
3	1	BUMPER BRACKET CTR REAR	✗	\$ 98.10
4	1	BUMPER BRACKET SIDE RH REAR	✗	\$ 82.10
5	1	BUMPER RETAINER RH REAR	✗	\$ 59.80
6	1	BUMPER REFLECTOR RH	✗	\$ 16.60
7	1	BUMPER BRACKET SIDE LH REAR	✗	\$ 80.80
8	1	BUMPER RETAINER LH REAR	✗	\$ 54.20
9	1	BUMPER REFLECTOR LH	✓	\$ 16.60
10	1	BUMPER BEAM REAR	✓	\$ 547.80
11	1	BUMPER BEAM BRACKET LH REAR	✗	\$ 114.50
12	1	BUMPER BEAM BRACKET RH REAR	✗	\$ 100.90
13	1	OUTER PANEL REAR (End Panel)	✗ <i>ry</i>	\$ 745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	✗	\$ 404.56
15	1	TAILLAMP RH	✗	\$ 313.10
16	1	TAILLAMP PANEL RH	✗	\$ 401.40
17	1	TAILLAMP LH	✓	\$ 401.40
18	1	TAILLAMP PANEL LH	✗	\$ 401.40
19	1	BOOT REAR	✓	\$ 1,677.20
20	1	BOOT FINISHER	✗	\$ 344.70
21	1	BOOT WHEATERSTRIP	✗	\$ 178.20
22	1	BOOT REFLECTOR LAMP LH	✓	\$ 277.70
23	1	BOOT REFLECTOR LAMP RH	✗	\$ 277.70
24	1	BOOT BADGE 'RENAULT'	✓	\$ 82.40
25	1	BOOT BADGE	✓	\$ 95.80
26	1	BOOT STRUT LH	✗	\$ 145.10
27	1	BOOT STRUT RH	✗	\$ 145.10
28	1	BOOT HINGE LH	✗	\$ 254.20
29	1	BOOT HINGE RH	✗	\$ 253.80

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

30	1	BOOT INNER TRIM BOARD ✕	\$	611.00
31	1	BOOT SWITCH ✕	\$	113.00
32	1	BOOT LOCK ✕	\$	246.60
33	1	BOOT LOCK CATCH ✕	\$	41.70
34	1	EXHAUST CAP REAR ✕	\$	125.40
35	1	EXHAUST REAR ✕	\$	5,263.60
36	1	SPARE WHEEL PANEL (Luggage Floor Panel) ✕	\$	1,229.40
37	1	SPARE WHEEL PANEL TRIM ✕	\$	612.21
TOTAL			\$	16,787.47
10%			\$	1,678.75
			\$	15,108.72

			Special Nett	
1	1SET	PARKING AID	\$	700.00 650
2	1SET	REAR BUMPER CLIP	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00
10	1	REAR BOOT ADVERTISEMENT STICKER ✕	\$	300.00
11	1	REAR FENDER ADVERTISEMENT STICKER ✕	\$	300.00
12	1	EXHAUST MOUNTING REAR ✕	\$	16.00
13	2	REAR WINDSCREEN SEALANT ✕	\$	80.00
14	1	WINDSCREEN MOULDING ✕	\$	100.00
15	1	REAR WINDSCREEN INNER SPONGE SEAL ✕	\$	100.00
16	1	BOOT INNER TRIM CLIP ✕	\$	45.00
17	1SET	BOOT FINISHER CLIP ✕	\$	24.20
18	1	TAILLAMP CLIP LH	\$	5.00
19	1	TAILLAMP CLIP RH ✕	\$	5.00
20	1	Rear Bumper Protector ✕	\$	100.00
21	1	REAR LEFT TYRE ✕	\$	300.00
22	1	REAR LEFT TYRE RIM ✕	\$	380.00
23	1	SPARE TYRE RIM (ROUE 7J 16H 2547) ✕	\$	380.00
24	1	SPARE TYRE ✕	\$	300.00
TOTAL			\$	3,382.20

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

TOTAL PARTS	\$	18,490.92
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 40
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To Check Electrical Lighting Concerned.	\$	170.00 30
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 30
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00 800
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 30
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

Putty and spray painting of the affected portion.	\$	9,000.00 ⁶⁶⁰
To repair and realign rear exhaust pipe.	\$	170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
TOTAL	\$	22,200.00
Over All Total	\$	40,690.92

LUMP SUM (REPAIR DAY)**30 DAYS**

Kalin 1/11/19

20/9/19 1720

4 Days.

L/s

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: