



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2005790  
INV Date 24/08/2020  
Reference CC3/CTI19016759/K1ka3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1835K  
Insured Veh. GBB 6357Y  
Claim No. SNM19D204475  
Policy No. DMCVSN3063111900  
Accident Date 20/09/2019  
Inspection Date 20/09/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19016759/K1ka3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-08-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBB 6357Y	<b>Veh. Inspected</b>	SHD 1835K
<b>Policy No.</b>	DMCVSN3063111900	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM19D204475	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	20/09/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2013
<b>Chassis No.</b>	JTDKN36U405614624	<b>Colour</b>	SILVER
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>L/H Front Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>R/H Rear Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>L/H Rear Tyre</b>	195/65 R15	MAXXIS	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/09/2019	<b>Inspection Date</b>	20/09/2019
<b>Survey held at</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1835K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	458.60	458.60
2	REAR BUMPER N/S & O/S SIDE RETAINER @\$94.80	SERVICEABLE	189.60	-
2	REAR BUMPER N/S STAY @\$139.60	SERVICEABLE	279.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	205.70	-
1	N/S TAIL LAMP LOWER BRACKET	SERVICEABLE	35.70	-
1	REAR BUMPER LH LOWER LIP	SERVICEABLE	118.10	-
	LESS 25% DISCOUNT		-321.73	-114.65
			965.17	343.95
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			458.00	98.00
	<b><u>LABOUR</u></b>			
	TOWING FEE.		50.00	50.00
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE AND RENEW THE REVERSE SENSOR TO THE NEW BUMPER,RESET OF THE SAME.		120.00	30.00
	TO DISMANTLE AND REPLACE THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE END PANEL,ETC.		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,END PANEL.		400.00	180.00
	TO APPLY RUSTPROOFING ONTO THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,390.00	460.00
	<b>GRAND TOTAL</b>		<b>2,813.17</b>	<b>901.95</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>700.00</b>

Report Ref No. CC3/CTI19016759/K1ka3n2



Report Ref No. CC3/CTI19016759/K1ka3n2

A handwritten signature in black ink, appearing to be 'W' followed by a stylized 'K'.

**KALVIN ANG WEI KUN**

**Automotive Assessor / Investigator**

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1835K

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1835K

RE-INSPECTION

